

22/03/2002

ASS. REC. BY:

REF: CS/INC19066842K9d3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Anne Koh

of

INC

Date/Time: 17.4.2019 9:30a.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJN9186X

Insured: SKJ 2406 S

at Workshop m/s HC Auto

Tel: 94570678

of 160 Ss ming Drive # 05-09

Policy No:

Claim No: MT / 1040136 - 002

Sum Insured:

Excess:

Make of Veh:

D.O.A. 14.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 17.4.2019 9:30a.m.

Person Contacted: Joe

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJN9186X - X

SKJ 2406S - X

4/6 61 Lm 8500d email & confirm. (Ref \$11572.16, 70%)

(08/11/19)

REF: INC

Surveyor

ASSIGNMENT

From:

Date:

17.4.2019

Estimated Cost:

OD ☒ TP ☒ WS ☒ TP RES ☒ OD RES ☒ EVA ☒ INV ☒ MV

To Inspect Vehicle No:

SJN 9186X

at Workshop m/s

Hc Auto

of 160 sin ming Drive #05-09

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Before go call 94570678 after lunch

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

859K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"w"

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJN 9186X Yr Regn: 03, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Wish

C.C

1794

Colour

M. Black

A/C: Insured / Std / NI / NA

Sp. Reading

189233

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

8NE10 0412688

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Kapsen 195/65R15

R: Grandp

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

8 8

mm

L/Bal.

7

mm

L/Bal.

8 7

mm

D.O.A.

14/4/19

D.O.I.

17/4/19

Survey held at

1053am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S & RM

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 06 JUN 2019

Date/Time, File Pass to?



: Preli. Report

1) 06/6 1919



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

To

Lump Sum / I.B.I. (\$)

5000

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Wednesday, 17 April 2019 10:44 AM
To: 'assignments@lkkauto.com'
Subject: RE: TP CASES FARMED OUT TO LKK ON 17/04/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg

income
made different



From: Annie Koh
Sent: Wednesday, 17 April 2019 9:30 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 17/04/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	OI/VEH	DOA
----	-----	-----------	---------	---------------	------------------	------------------	--------	-----

1	Cyndie Yong	MT/1040136-002	SIN9186X	H C AUTO PTE LTD	160 SIN MING DRIVE, #05-09 SIN MING AUTO CITY	Mr. Joe Chee / 94570678	SKJ2406S	14/4/19
2	Jared Liu	MT/1040311-002	SCP5010T	KUAN SERVICES AND REPAIR	BLK 160 SIN MING DRIVE #04-13 SIN MING AUTOCITY	Susan / 91004390	SHC6914M	14/4/19

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7899
www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



SINGAPORE POLICE FORCE



T/20190415/2169

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

1 of 4

Report No. T/20190415/2169

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/04/2019 19:42	Vide Report No.:	Station Diary No.: 238
--	------------------	---------------------------

Informant's Particulars

Name of Informant: BADRUL HISHAM BIN MOHAMED YAHAYA			Address: APT BLK 165 YISHUN RING ROAD #13-713 SINGAPORE 760165		
ID Type / ID No.: NRIC NO / S1533820B			Contact No.: Home/Office: Mobile: 90225909		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 56	Date of Birth: 14/10/1962	Type of Informant: Driver		
Race: Malay			Language: English		Institution / School Name:
Occupation: Grab Driver			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 14/04/2019 11:30	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 CENTRAL EXPRESSWAY				
CTE towards City				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Chain Collision				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJN9186X	Car	TOYOTA	Wish	Black	Slightly Damaged	2
SKJ2406S	Car	VOLKSWAGO N	Golf	White	Slightly Damaged	0
SLA9598K	Car	MERCEDES BENZ	E200	Blue	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20190415/2169

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJN9186X	NTUC Income Insurance Co-Operative Limited	5087446647-01	24/11/2018	23/11/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	BADRUL HISHAM BIN MOHAMED YAHAYA		ID No.	S1533820B
Related Vehicle	SJN9186X (Car)		Contact No.	90225909
Hospital/Clinic	KHOO TECK PUAT HOSPITAL		Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	15/04/2019		Date Discharge	15/04/2019
No. of Days granted Medical Leave		05	Degree of Injury	Slight
Driver				
Name	Chew Heng Heng		ID No.	S7597015C
Related Vehicle	SKJ2406S (Car)		Contact No.	96954950
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Driver				
Name	Ong		ID No.	S7504864E
Related Vehicle	SLA9598K (Car)		Contact No.	98527862
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL



Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

3 of 4

Report No. T/20190415/2169

CONTINUATION OF REPORT

Brief Details.


On 14.04.2019 at 11.30am, I was driving my vehicle of registration no. SJN9186X along CTE towards City. I was driving along lane 1 and there were 2 passengers in my vehicle. While travelling, the front vehicle of registration no. SLA9598K suddenly applied emergency brake. Upon seeing the driver action, I managed to stop my vehicle in time behind the front vehicle.

All of a sudden, there was an incoming vehicle from the rear of registration no. SKJ2406S unable to stop in time and collided onto the rear portion of my vehicle. As a result, my vehicle moved forward and hit onto the front vehicle due to the impact. Nobody was injured during the accident. The damages on my vehicle are as follows:

1. The front bonnet of the vehicle.
2. There rear bumper of the vehicle.

The cost of repair is unknown.

On 15.04.2019 at 11.00am, I felt pain on my body and decided to seek treatment at Khoo Teck Puat hospital. I was given 5 days of medical leave.





**SINGAPORE
POLICE FORCE**



T/20190415/2169

4 of 4

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20190415/2169

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

L /

Sr Staff Sgt SAIFUDIN BIN HASSAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

15/04/2019 19:42

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Classification Of Case:

SN 005

Authentication Stamp

NP168

Signature:

Singapore Police Force

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date : 17 / 04 / 2019

ESTIMATE COSTS OF REPAIR

M/s C H Automotive Services (79433)

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

*Not Authorised
Using \$5000/
Reserve After Repair
Today*

Dear Sir / Madam ,

Vehicle no. : SJN 9186 X - Toyota Wish 1.8 (A)

Accident date : 14 / 04 / 2019

Quantity	Descriptions	Amount (S\$)
1	1 pc bonnet	\$ 763.84 X
2	1 pc bonnet lock	\$ 76.65 X
3	1 pc bonnet insulator	\$ 410.42 X
4	1 pc bonnet chrome molding	\$ 221.90 X
5	1 pc front bumper fascia <i>481.10</i>	\$ 1,111.35 ✓
6	2 pcs front bumper side retainer 1 @ 92.56	\$ 185.12 X
7	1 pc front bumper reinforcement	\$ 275.24 ✓
8	1 pc front bumper sponge	\$ 95.97 ✓
9	2 pcs front bumper fog lamp cover 1 @ 37.24	\$ 74.48 X
10	10 pcs front bumper clips 1 @ 9.80	\$ 58.80 ✓
11	1 pc front bumper grille	\$ 110.22 ✓
12	1 pc front brace bracket	\$ 119.39 X
13	1 pc front support panel top garnish	\$ 135.78 X
14	1 pc front grille	\$ 109.19 ✓
15	2 pcs front grille clip 1 @ 25.96	\$ 51.92 ✓
16	2 pcs front head lamp 1 @ 790.36	\$ 1,580.72 ✓
17	2 pcs front head lamp lower bracket 1 @ 135.90	\$ 271.80 X
18	2 pcs radiator side garnish 1 @ 124.25	\$ 248.50 ✓
19	1 pc rear windscreen glass molding	\$ 117.50 ✓
20	1 pc tail gate	\$ 1,209.65 ✓
21	1 pc tail gate weather strip	\$ 303.79 X
22	1 pc tail gate inner lock	\$ 509.10 X
23	1 pc tail gate Toyota Logo	\$ 47.67 ✓
24	1 pc tail gate outer molding	\$ 227.57 X
	Balance C/FD	\$ 8,316.57

Not Authorised

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Balance B/FD (SJN 9186 X)

\$ 8,316.57

25	1 pc	tail gate inner trim board
26	1 pc	tail gate lower holder
27	1 pc	rear spare tyre carrier
28	1 pc	rear end panel
29	1 pc	rear end panel inner garnish
30	1 pc	rear bumper fascia 491.90
31	2 pcs	rear bumper bracket 1 @ 44.43
32	2 pcs	rear bumper side bracket 1 @ 38.67
33	2 pcs	rear bumper reflector 1 @ 47.60
34	2 pcs	rear bumper side retainer 1 @ 57.05
35	2 pcs	rear fender inner garnish 1 @ 625.51
36	1 pc	rear exhaust box
37	2 pcs	tail lamp 1 @ 491.60
38	2 pcs	tail lamp lower clip 1 @ 45.00

\$	328.22	X
\$	35.70	X
\$	265.79	X
\$	540.20	X
\$	201.60	X
\$	1,377.10	X
\$	88.86	X
\$	77.34	X
\$	95.20	X
\$	114.10	X
\$	1,251.02	X
\$	732.00	X
\$	983.20	X
\$	90.00	X
\$	14,496.90	

Less 25%

\$ 3,624.23

\$ 10,872.68

39	1 pc	rear reverse sensor
40	2 pcs	no. plate 1 @ 50.00
41	1 pc	rear panel inner seal
42	1 pc	rear windscreen inner seal
43	1 pc	rear windscreen inner gum

\$	400.00	sn 200sn
\$	100.00	sn 40sn
\$	250.00	sn X
\$	60.00	sn 30sn
\$	60.00	sn 40sn
\$	11,742.68	

Labour charges	\$ 1,800.00
To putty and spray painting	\$ 1,200.00
Re-seal anti rust	\$ 250.00
Remove and refix exhaust box	\$ 120.00
To check wiring	\$ 120.00
Remove and refix reverse sensor	\$ 100.00
Remove and refix rear windscreen glass	\$ 160.00

\$	1,800.00	800l
\$	1,200.00	1000l
\$	250.00	30l
\$	120.00	60l
\$	120.00	40l
\$	100.00	50l
\$	160.00	120l
\$	15,492.68	

Add : 7% GST

\$ 1,084.49

Grand Total

\$ 16,577.16

LKK Auto Consultants Price not the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19006842/Kqd3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 19-06-2019



ATTN: CYNDIE YONG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKJ 2406S	Veh. Inspected	SJN 9186X
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1040136-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	17/04/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH (A)	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	ZNE100412668	Colour	METALLIC BLACK
Odometer	189233 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	KAPSEN	7 mm
L/H Front Tyre	195/65 R15	KAPSEN	7 mm
R/H Rear Tyre	195/65 R15	GRENDIA	8 mm
L/H Rear Tyre	195/65 R15	GRENDIA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND FRONT PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	14/04/2019	Inspect Date / Time	17/04/2019 (10:53 AM)
Survey held at	160 SIN MING DRIVE #05-09		
Repairer	HC AUTO & MOTORS SERVICE		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 9186X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	TO REPAIR SEE LABOUR	763.84	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	76.65	-
1	BONNET INSULATOR	SERVICEABLE	410.42	-
1	BONNET CHROME MOULDING	SERVICEABLE	221.90	-
1	FRONT BUMPER FASCIA	BUCKLED	1,111.35	481.10
2	FRONT BUMPER SIDE RETAINER @\$92.56	SERVICEABLE	185.12	-
1	FRONT BUMPER REINFORCEMENT	BUCKLED	275.24	275.24
1	FRONT BUMPER SPONGE	CRACKED	95.97	95.97
2	FRONT BUMPER FOG LAMP COVER @\$37.24	SERVICEABLE	74.48	-
10	FRONT BUMPER CLIPS	NECESSARY	58.80	58.80
1	FRONT BUMPER GRILLE	CRACKED	110.22	110.22
1	FRONT BRACE BRACKET	TO REPAIR SEE LABOUR	119.39	-
1	FRONT SUPPORT PANEL TOP GARNISH	SERVICEABLE	135.78	-
1	FRONT GRILLE	CRACKED	109.19	109.19
2	FRONT GRILLE CLIP @\$25.96	NECESSARY	51.92	51.92
2	FRONT HEAD LAMP @\$790.36	N/S MTG CRACKED	1,580.72	790.36
2	FRONT HEAD LAMP LOWER BRACKET @\$135.90	TO REPAIR SEE LABOUR	271.80	-
2	RADIATOR SIDE GARNISH @\$124.25	SERVICEABLE	248.50	-
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	117.50	117.50
1	TAIL GATE	BENT	1,209.65	1,209.65
1	TAIL GATE WEATHER STRIP	SERVICEABLE	303.79	-
1	TAIL GATE INNER LOCK	TO REPAIR SEE LABOUR	509.10	-
1	TAIL GATE TOYOTA LOGO	NECESSARY	47.67	47.67
1	TAIL GATE OUTER MOULDING	SERVICEABLE	227.57	-
1	TAIL GATE INNER TRIM BOARD	SERVICEABLE	328.22	-
1	TAIL GATE LOWER HOLDER	SERVICEABLE	35.70	-
1	REAR SPARE TYRE CARRIER	TO REPAIR SEE LABOUR	265.79	-

Report Ref No. CS/INC19006842/Kqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL	TO REPAIR SEE LABOUR	540.20	-
1	REAR END PANEL INNER GARNISH	SERVICEABLE	201.60	-
1	REAR BUMPER FASCIA	BENT	1,377.10	491.90
2	REAR BUMPER BRACKET @\$44.43	TO REPAIR SEE LABOUR	88.86	-
2	REAR BUMPER SIDE BRACKET @\$38.67	O/S DISTORTED	77.34	38.67
2	REAR BUMPER REFLECTOR @\$47.60	SERVICEABLE	95.20	-
2	REAR BUMPER SIDE RETAINER @\$57.05	O/S DISTORTED	114.10	57.05
2	REAR FENDER INNER GARNISH @\$625.51	SERVICEABLE	1,251.02	-
1	REAR EXHAUST BOX	BENT	732.00	732.00
2	TAIL LAMP @\$491.60	O/S MTG CRACKED	983.20	491.60
2	TAIL LAMP LOWER CLIP @\$45.00	NOT NECESSARY	90.00	-
	LESS 25% DISCOUNT		-3,624.22	-1,289.71
			10,872.68	3,869.13
	<u>SPECIAL NETT ITEMS</u>			
1	REAR REVERSE SENSOR (SN)	DENTED / SHORTED	400.00	200.00
2	NO. PLATE @\$50.00 (SN)	BENT (FRONT ONLY)	100.00	40.00
1	REAR PANEL INNER SEAL (SN)	NOT NECESSARY	250.00	-
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	60.00	30.00
1	REAR WINDSCREEN INNER GUM (SN)	NECESSARY	60.00	40.00
			870.00	310.00
	<u>LABOUR</u>			
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF BONNET, BONNET LOCK, FRONT BRACE BRACKET, FRONT HEAD LAMP LOWER BRACKET, TAIL GATE INNER LOCK, REAR SPARE TYRE CARRIER, REAR END PANEL AND REAR BUMPER BRACKET.		1,800.00	800.00
	TO PUTTY AND SPRAY PAINTING.		1,200.00	1,000.00
	RE-SEAL ANTI RUST.		250.00	30.00
	REMOVA AND REFIX EXHAUST BOX.		120.00	60.00
	TO CHECK WIRING.		120.00	40.00
	REMOVE AND REFIX REVERSE SENSOR.		100.00	50.00

Report Ref No. CS/INC19006842/Kqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIX REAR WINDSCREEN GLASS.		160.00	120.00
			3,750.00	2,100.00
GRAND TOTAL			15,492.68	6,279.13
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				5,000.00

Report Ref No. CS/INC19006842/Kqd3e2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.