

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Tel : 6844-1985 Fax : 6844-5185

Reg : 201838521G

Repair Estimate

Date :16/04/2019

Reference: CHEVROLET

Make: CAPTIVA

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SKH3042L

CHASSIS NO.: KL1CA2641BB111785

ENGINE NO.: LE5112230227

Name of insured :KASMADI BIN SUDIN

Date of accident.: 11/04/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	RR BUMPER <i>Rehanded</i>	\$ 1,528.00
2	1	RR BUMPER SIDE RETAINER RH <i>new</i>	\$ 128.00
3	1	RR BUMPER TOP CHROME MLDG <i>new</i>	\$ 275.00
4	1	RR MUD FLAT RH <i>new</i>	\$ 135.00
5	1	RR TAILLAMP RH <i>new</i>	\$ 623.00
6	1	RR FENDER RH <i>Distorted.</i>	\$ 2,243.00
7	1	RR FENDER WHEELARCH GARNISH RH <i>new</i>	\$ 188.00
8	1	RR FENDER INNERSHIELD RH <i>new</i>	\$ 152.00
9	1	RR FENDER AIR DUCT RH <i>new</i>	\$ 125.00
10	1	RR FENDER QUARTER GLASS ASSY RH <i>new</i>	\$ 607.00
11	1	RR DOOR RH <i>Reps</i>	\$ 2,927.00
12	1	RR DOOR PROTECTOR RH <i>new</i>	\$ 214.00
13	1	RR RIM RH <i>new</i>	\$ 800.00

5843
5258.70

Parts Total: \$ 9,945.00

Less 10%: \$ 994.50

Total : \$ 8,950.50

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,000.00
2	Carry out spray painting on affected area, RR BUMPER, RR FENDER RH, RR DOOR RH, RR WHEELHOUSE PANEL RH	\$ 1,000.00

600

600

<u>3</u>		To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 180.00	30
<u>4</u>		Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 400.00	80
<u>5</u>		To remove and refix reverse sensor and conduct test	\$ 80.00	50
<u>6</u>		Transfer of internal mechanism from old door panel to new door panel	\$ 200.00	40
<u>7</u>		To remove and refix rear quarter glass	\$ 160.00	60
<u>8</u>		To conduct 4 wheel alignment	\$ 160.00	80

1500

Others

Labour Total : \$ 3,180.00

Other Description

No.			Price (SGD)	
<u>1</u>	10	FENDER INNERSHIELD CLIP	\$ 60.00	4
<u>2</u>	10	RR BUMPER CLIP	\$ 60.00	30
<u>3</u>	10	RR FENDER PROTECTOR CLIP	\$ 60.00	20
<u>4</u>	1	RR QUARTER GLASS SOLAR FILM	\$ 120.00	80
<u>5</u>	1	RR QUARTER GLASS SEALANT	\$ 65.00	30
<u>6</u>	1	RR QUARTER GLASS INNER SEAL	\$ 40.00	30

190

Other Total: \$ 405.00

TOTAL: \$ 12,535.50

GRAND TOTAL : \$ 12,535.50

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor
Kelvin Chew
HP: 8292 5595 Fax: 68445185

Adrian Ling
1/5 22/04/19
06 days
Total: 6948.70
1/5: 4.4K
(Net Value)

AHC

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Witnessed by Repairer