



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 7103A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR COMFORT LOGO,RH (N)	NECESSARY	75.00	75.00
1	REAR DOOR COMFORT & APPS STICKER,RH (N)	NECESSARY	80.00	80.00
1	FRONT DOOR (RH) (NPA) (N)	TO REPAIR SEE LABOUR	-	-
1	REAR DOOR (RH) (NPA) (N)	TO REPAIR SEE LABOUR	-	-
1	ROCKER PANEL GARNISH (NPA) (N)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-	-15.50
			155.00	139.50
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT DOOR (RH),REAR DOOR (RH) AND ROCKER PANEL GARNISH.		400.00	200.00
	SPRAY PAINTING CHARGE.		800.00	600.00
	TUFF KOTE.	NOT NECESSARY	50.00	-
			1,250.00	800.00
	GRAND TOTAL		1,405.00	939.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			750.00

Report Ref No. NS/INC19006889/K1sd3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.