

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: 19.26851

Date: 03rd May 2019

Our Ref: CS3/ASM19001959/Gvd3e2-1

M/s AXA Insurance Pte Ltd

C/O: Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SME 99K INSURED VEHICLE: SBH 1010Z

ACCIDENT DATE: 28/01/2019

We thank you for your instruction on 14/04/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SME 99K from M/s Par Automotive Consultancy.
- b) Singapore Accident Statement of Vehicles SME 99K and SBH 1010Z.
- c) Final Repair Bill of SME 99K from M/s Precision Motorworks Pte Ltd.
- d) Colour damaged vehicle photographs of SME 99K.

Pre-Repair Inspection Date: 30/01/2019 at M/s Precision Motorworks Pte Ltd, 68 Kaki Bukit Ave 6 #01-02 ARK @ KB, Singapore 417896.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: SME 99K

Make & Model

: Mercedes Benz CLA180 AMG

Year of Registration

: 2017

Chassis Number

: WDD1173422N414038

Engine Capacity

: 1595 cc

- 2. We recommend that the repairs of the entire damage require about <u>7 (Seven)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.