

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19006934/ABA3Q2

**Date:** 30/06/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100316907-06

**Claimant**  
**Vehicle No :** SMF3791U **Insured Vehicle No :** SCN8019K

**Date of Loss:** 14/04/2019 **Nature of Claim:** TP **Claim No:** 1180731415SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMF3791U</b>				
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)		Engine No:	LEB5580923	
Reg. Date:	07/11/2018 (Man. Year: 2017)		Chassis No:	GB71051091	
Colour:	Blue		Odometer:	34243 km	
Engine Capacity:	1496 cc				
Market Value/New Car Price:	N/A				
Sum Insured (S\$):	<b>Market Value/New Car Price</b>				

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,979.12	3,200.00	2,779.12	46.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,840.00	1,510.00	2,330.00	60.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,819.12</b>	<b>4,710.00</b>	<b>5,109.12</b>	<b>52.03</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,750.00</b>		
<b>(S\$)</b>	9,819.12	3,750.00	6,069.12	61.81
<b>+ GST 7.00/7.00% (S\$)</b>	687.34	262.50	424.84	61.81
<b>Nett Amount (S\$)</b>	<b>10,506.46</b>	<b>4,012.50</b>	<b>6,493.96</b>	<b>61.81</b>
<b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b>		360.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,379.95</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,350.00</b>		

### INSPECTION

Date of Assignment: 17/04/2019

Date Inspected: 17/04/2019 Inspected At:

MG Solution Pte Ltd (HQ)  
23 Kaki Bukit Avenue 4 #02-03B,  
VICOM Inspection Centre  
Singapore 415933

Estimated Period of Repair: 4.0 days

---

**Adjuster:** ADRIAN LING**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Dented	1,460.30 FL	*1,280.00 FL
2	1		*TAIL GATE LOGO	Necessary	72.30 FL	*72.30 FL
3	1		*TAIL GATE EMBLEM FREED	Necessary	76.40 FL	*76.40 FL
4	1		*TAIL GATE EMBLEM HYBRID	Necessary	76.40 FL	*76.40 FL
5	1		*TAIL GATE INNER HOLDER	Not Necessary	80.00 FL	*- FL
6	1		*TAIL GATE INNER TRIM	Not Necessary	460.00 FL	*- FL
7	1		*TAIL GATE TOP LOCK	Damaged	255.90 FL	*255.90 FL
8	1		*TAIL GATE WEATHERSTRIP	Cut	241.70 FL	*241.70 FL
9	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	194.20 FL	*194.20 FL
10	1		*SET NUMBER PLATE LAMP	Not Necessary	168.50 FL	*- FL
11	1		*REAR BUMPER	Deformed	1,155.60 FL	*1,155.60 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	139.40 FL	*70.00 FL
13	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	55.90 FL	*- FL
14	2		*REAR BUMPER INNER HOLDER	Not Necessary	161.00 FL	*- FL
15	1		*REAR END PANEL (OUTER)	Repair	655.50 FL	*- FL
16	1		*REAR END PANEL (INNER)	Repair	530.80 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH	Cracked	190.00 FL	*190.00 FL
18	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
19	1		*SET TAIL GATE INNER TRIM CLIP	Not Necessary	20.00 FS	*- FS
20	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	100.00 FS	*40.00 FS
21	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
22	1		*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
23	1		*REAR END PANEL INSULATOR SEAL (OUTER)	Not Necessary	120.00 FS	*- FS
24	1		*REAR END PANEL INSULATOR SEAL (INNER)	Not Necessary	120.00 FS	*- FS
25	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
26	1		*REAR REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
27	1		*REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>7,173.90</b>	<b>3,922.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>1,194.78</b>	<b>722.50</b>
<b>Total Parts (S\$)</b>	<b>5,979.12</b>	<b>3,200.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING ,WELDING ,CUTTING ,GRAZING ADJUST ,KNOCK STRAIGHTEN	New	1,400.00	600.00
2	TO PUTTY ,SPRAY PAINT ,POLISH WAX	New	1,400.00	600.00
3	TO APPLY RUST PROOFING /UNDER COAT	New	250.00	0.00
4	WIRNING ,BULB CHECKING	New	80.00	0.00
5	REMOVE AND REFIX UPHOLSTERY ,CUSHION ,SEAT TO FACILITATE REPAIR	New	250.00	60.00
6	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
7	TO TRANSFER TAIL GATE MECHANISM	New	80.00	80.00
8	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
9	REMOVE AND REFIX REAR REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
10	REMOVE AND REFIX REAR REVERSE CAMERA AND DISTANCE SETTING	New	80.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,840.00</b>	<b>1,510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >