

ASS. REC. BY:

REF: CS/MSG19006951/ KSD3

Special Instruction:

menmen

Surveyor: Kemel ASSIGNMENT (Office)

From (Person): Cchia MYUE Pui of MSG Date/Time: 18.4.19 15:45p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLX 6625 P Insured: FBC 5610S

at Workshop m/s Tong Luck Auto Tel: 6250 0088

of 160 sin ming Drive, #07-01/06

Policy No: MSD/VMT/18-991315 Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 15.4.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS "up" H.O.D. Endorsement: _____

Date/Time: 18.4.19 3:54p.m Person Contacted: Candy Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLX 6625 P - X
	FBC 5610 S - NA / MSG 19006806 / 24 D.O.A - 15/04/2019
22/4@3	01pm - revised. LA via menmen.
29/5	82514.72 Confirmed
	(\$ 3,379.76 Red - 61%)

ASS. REC. BY:

REF: MSG/

Hennerh

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Tony Luck

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B.1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S2 X 8625P Yr Regn: 04, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or A) Wagon

Make: Honda Odyssey C.C. 2356

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 14772 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: J77MRC1880JC 200979

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD Rlm or

Tyre Size: F: 215/55R17

R: _____

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 15/4/19

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 18/4/19

Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

RECEIVED 30 MAY 2019.

Date/Time, File Pass to?

30/05/19

1) Typist
Date/Time, File Return to?

: Prel. Report

: Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation: 150
S-RS: 10

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Fuel

Others

TOTAL

160

Report Format :

Lump Sum / I.B.I. (\$) 0,514.72 p/p

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 22 Apr 2019

Preliminary Advice

Insured Vehicle No	: FBC5610S	Accident Date	: 15/04/2019
TP Vehicle No	: SLX6625P	Assignment Date	: 18/04/2019
Make	: HONDA ODYSSEY	Est. Duration of Repair	: 4.00
Date of Inspection	: 18/04/2019		
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01/06 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,394.48
Revised Amount	:S\$	2,514.72
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,514.72
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Apr 2019		18 Apr 2019 15:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	SUGUNESAN S/O SINNAPAYAN, ID: S7273123I								
Main Claimant:	RMG RENT-A-CAR PTE LTD, Co. Reg. No.: 199100384R								
Vehicle Reg. No.:	SLX6625P	Date of Loss:	15/04/2019 18:00 - :59 [12 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMT/18-991315 (Third Party Only) Coverage: 05/04/2018 - 25/04/2019						
Vehicle Reg. No. (Insured):	FBC5610S	Policy No. (Claimant):							
		Excess:							
Repairer:	Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01/06 Sin Ming Autocity, 575722 Sin Ming - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/04/2019]								
Driver/Custodian (Insured):	SUGUNESAN S/O SINNAPAYAN (46 / Male) , NRIC: S7273123I Email:								
Adj Asg. Remarks:	on WP. (MANUALLY ASSIGNED) LIAB: 100%. TP AGREE ON SJE - ASSIGN LKK. CONTACT: CANDY ONG @ 6250 0088								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : RMG RENT-A-CAR PTE LTD
10 JALAN KILANG
#01-01/02 SIME DARBY ENTERPRISE CENTRE
SINGAPORE 159410

TEL : 6235 1311 FAX : 6235 5256

ATTN : ACCOUNTS DEPT

YOUR REF NO : FBC5610S
CLAIM TYPE : THIRD PARTY
TP INS. CO. : MSIG INSURANCE (SINGAPORE) PTE LTD
ACCIDENT DATE : 15/04/2019
TP VEH REG NO : FBC5610S

ESTIMATE

NO : QUOT201904-000059(00)
DATE : 17/04/2019
POLICY NO : SD18V04077/VPZ/R05
VEH REG NO : SLX6625P
MAKE/MODEL : HONDA ODYSSEY 2.4 EX-S
CVT
CHASSIS NO : JHMRC1880JC200979
ENGINE NO : K24W72400388
REG. DATE : 2017

Not Authorised
Approved by part
4 days

Winnie = 65942886

Estimate Repair Cost to Vehicle No : SLX6625P

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Tailgate	1	1,216.80	1,216.80 X
2 Tailgate 'ODYSSEY' emblem	1	45.80	45.80 ✓
3 Tailgate reflector - LH	1	386.20	386.20 ✓
4 Tailgate lock	1	185.40	185.40 X
5 Taillamp assy - LH	1	838.10	838.10 ✓
6 Rear bumper	1	598.30	598.30 ✓
7 Rear bumper sensors	2	467.50	935.00 X
			4,205.60
		Less 20%	841.12
			3,364.48
SPECIAL NET			
8 Rear windscreen sealant	1	60.00	60.00 X
			60.00
LABOUR			
9 To remove and refit rear bumper sensors	1	100.00	100.00 50¢
10 To transfer damaged tailgate interior mechanism to new tailgate	1	160.00	160.00 X
11 To check and rectify wiring system	1	80.00	80.00 20¢
12 To panel beat and straighten rear end panel, rear chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 400¢
13 To remove and refit rear interior garnish and trimboard to facilitates the repairs	1	120.00	120.00 X
14 To putty and spray paint on affected areas	1	1,200.00	1,200.00 550¢
15 To apply rust proofing on repaired and replaced panels	1	160.00	160.00 X
16 To remove and refit rear windscreen glass	1	150.00	150.00 X
			2,970.00
		TOTAL	S\$ 6,394.48
		ADD GST @ 7%	447.61
		GRAND TOTAL	S\$ 6,842.09

LKK Auto Consultants hence notify the Repaired of the following:

- To ensure correct wiring painting
- To ensure correct fitment of wiring
- Paint process subject to final check
- Third party services on "Without Prejudice" basis
- Material not covered is ignored
- Damage not covered is removed and replaced to meet approval from insurance Company

Authorised by Repairer
Signature:
Date:

SINGAPORE DOLLAR SIX THOUSAND EIGHT HUNDRED FORTY-TWO AND CENTS NINE ONLY



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : RMG RENT-A-CAR PTE LTD
10 JALAN KILANG
#01-01/02 SIME DARBY ENTERPRISE CENTRE
SINGAPORE 159410

TEL : 6235 1311 FAX : 6235 5256

ATTN : ACCOUNTS DEPT

YOUR REF NO : FBC5610S
CLAIM TYPE : THIRD PARTY
TP INS. CO. : MSIG INSURANCE (SINGAPORE) PTE LTD
ACCIDENT DATE : 15/04/2019
TP VEH REG NO : FBC5610S

ESTIMATE

NO : QUOT201904-000059(00)
DATE : 17/04/2019
POLICY NO : SD18V04077/VPZ/R05
VEH REG NO : **SLX6625P**
MAKE/MODEL : HONDA ODYSSEY 2.4 EX-S
CVT
CHASSIS NO : JHMRC1880JC200979
ENGINE NO : K24W72400388
REG. DATE : 2017

Estimate Repair Cost to Vehicle No : SLX6625P

Description	Quantity	Unit Price	Amount
		₹	₹

FOR TONG LUCK AUTO PTE LTD



AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19006951/KSD3N2

Date: 30/05/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/18-991315
Claimant Vehicle No :	SLX6625P	Insured Vehicle No :	FBC5610S
Date of Loss:	15/04/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-000444

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX6625P	Engine No:	K24W72400388
Make & Model:	HONDA ODYSSEY, 2.4 EX-S (RC1) (A)	Chassis No:	JHMRC1880JC200979
Reg. Date:	04/04/2018 (Man. Year: 2017)	Odometer:	14772 km
Colour:	Metallic Pearl White		
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Dunlop 9 mm	Rear Left Side:	Dunlop 9 mm
Front Right Side:	Dunlop 9 mm	Rear Right Side:	Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,424.48	1,494.72	1,929.76	56.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,970.00	1,020.00	1,950.00	65.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,394.48	2,514.72	3,879.76	60.67
+ GST 7.00/7.00% (S\$)	447.61	176.03	271.58	60.67
Nett Amount (S\$)	6,842.09	2,690.75	4,151.34	60.67

INSPECTION

Date of Assignment:	18/04/2019		
Date Inspected:	18/04/2019	Inspected At:	Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01/06 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2019)
Parts: M1-MPV	HONDA ODYSSEY 2.4 EX-S (RC1) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX6625P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,216.80 FL	*- FL
2	1		*TAILGATE ODYSSEY EMBLEM	Necessary	45.80 FL	*45.80 FL
3	1		*TAILGATE REFLECTOR-LH	Cut	386.20 FL	*386.20 FL
4	1		*TAILGATE LOCK	Repair	185.40 FL	*- FL
5	1		*TAILLAMP ASSY-LH	Cut	838.10 FL	*838.10 FL
6	1		*REAR BUMPER	Buckled	598.30 FL	*598.30 FL
7	2		*REAR BUMPER SENSORS	Serviceable	935.00 FL	*- FL
8	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,265.60	1,868.40
- List Item Discount on L Items 20.00/20.00% (S\$)	841.12	373.68
Total Parts (S\$)	3,424.48	1,494.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT REAR BUMPER SENSORS	New	100.00	50.00
2	TO TRANSFER DAMAGED TAILGATE INTERIOR MECHANISM TO NEW TAILGATE	New	160.00	0.00
3	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
4	TO PANEL BEAT AND STRAIGHTEN REAR END PANEL, REAR CHASSIS FRAME, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,000.00	400.00
5	TO REMOVE AND REFIT REAR INTERIOR GARNISH AND TRIMBOARD TO FACILITATES THE REPAIRS	New	120.00	0.00
6	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	550.00
7	TO APPLY RUST PROOFING ON REPAIRED AND REPLACED PANELS	New	160.00	0.00
8	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	0.00
Gross Labour Cost (S\$)			2,970.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >