

REP: CS/AWA19007042/And3 ^{m2}
 ASSIGNMENT (Office)
 From/Person: Tony Ben of AWAC Date/Time: 18/4/19 @ 4:27pm
 Estimated Cost: Bill to:

OD: WS/TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SKF 2062X Insured: SLP 3280
 at Workshop no: New Hycle Teck Tel: 67979241
 of: 1 kuki Bukit Ave 6 #01-43 Autobay
 Policy No: AVPPSBOSS1571800 Claim No: NSV1900205/BT
 Sum Insured: Excess:
 Make of Vch: D.O.A. 17/4/2019
 (Client's Record)

CA / REV / REP / REV 24 HRS ^{up}
 Date/Time: 4:49pm 18/4/19 Person Contacted: Suleyi Vehicle IN OUT

Date/Time	Action/Instruction (-) Estimate
	SKF 2062X - CC3/ATG/5001412/T/qbk3 DUA: 22/1/15
	SLP 3280D - X
	US \$9800, 12 days (Red B (8497, 65%))

Nivitha (LKK Auto)

From: Tang, Ben <Ben.Tang@awac.com> on behalf of Motorsurvey
<Motorsurvey@awac.com>
Sent: Thursday, 18 April 2019 4:27 PM
To: 'assignments@lkkauto.com'
Cc: 'sur@lkkauto.com'; 'Admin nht'
Subject: TP Survey assignment for SKF 2062 X DOA:17/04/2019 Our ref: NSV1900205/BT

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us **do have** consensus in the appointment of Mr Mohammed Rasul as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SKF 2062 X
Insured Vehicle	:	SLP 328 D
Policy Number	:	AVPPSB0551571800
Name of Workshop	:	New Hock Teck Motor Pte Ltd
Contact Number	:	6747 9241
Person to Contact	:	Ms Sukyi Chong / Ms Reena
Estimated Cost of repairs	:	\$ NA

Regards,
Claims Division

Copy to New Hock Teck Motor Pte Ltd (Your Ref: SKF 2062 X) via Email

- Note -
- (x)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
 2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
 3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
 4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards
Motor Claims
Claims Group

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



SEARCH
Price Range
Depreciation
Year Reg
Vehicle Type
Search View All Advanced Search

Used Car Comparison

--- Comparing 2 Vehicles ---

Mitsubishi Lancer EX 1.5A Elegance



[Add to Shortlist](#)

Mitsubishi Lancer EX 1.6A



[Add to Shortlist](#)



NO IMAGE AVAILABLE

Use search bar above to select another car to compare.



NO IMAGE AV

Use search bar above to se to compare.

[Clear All](#) [Add all to Shortlist](#) [Back to search result](#)

CAR DETAILS				
Price	\$24,800	\$42,800	-	-
Instalment	\$911	\$740	-	-
Registration Date	19-Jan-2011	25-Jan-2013	-	-
Manufactured	2010	2012	-	-
Mileage	88,767 km	-	-	-
Transmission	Auto	Auto	-	-
Engine Cap	1,499 cc	1,590 cc	-	-
Road Tax	\$684 /yr	\$738 /yr	-	-
Power	80.0 kW (107 bhp)	86.0 kW (115 bhp)	-	-
Curb Weight	1,313 kg	1,322 kg	-	-
Features	1.5L 16 Valves DOHC MIVEC Engine, 107 BHP, 4 Speed Automatic Transmission, SRS Airbags, ABS, Digital Climatic Aircon Controls, Knockdown Rear Seats.	1.6L, 4-Cylinder 16-Valve DOHC MIVEC, Producing 115bhp, 4-Speed Automatic Transmission, Keyless Entry Start/Stop, Airbags, ABS,	-	-
Accessories	Leather Seats, Sports Rims, Built In Audio System With Steering Controls, Retractable Side Mirrors, Reverse Sensors, Solar Film.	Sports Rims, Leather Seats, CD Player, Reverse Sensors, Fog Lamps, Full Bodykit.	-	-
Description	Like New Condition Lancer 1.5A, See To Certify! Serviced At Reputable Workshop With Prof. Genuine Low Mileage Done 88767km. 1 Owner. Road Tax Till Jul 19. New Paintwork. 100% Accident Free. Call Now!	6 Months Warranty. Good Condition, Sporty Look, High Coe, Bank Loan In House Loan Available.	-	-
COE	\$36,162	\$66,889	-	-
OMV	\$16,930	\$16,673	-	-
ARF	\$16,930	\$16,673	-	-
Depreciation	\$9,360 /yr	\$9,160 /yr	-	-
No. of Owners	1	1	-	-
Type of Vehicle	Sedan	Sedan	-	-
Category	PARF Car, Premium Ad Car	PARF Car	-	-
Availability	Available	Available	-	-
SELLER INFORMATION				
Seller	Lake View Credit Pte Ltd	StarBright Auto	-	-
Address	61 Ubi Avenue 2 #03-08/09		-	-

[Home](#) > [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 8279A

Vehicle Details

Vehicle No.: SKF2062X

Vehicle to be Exported: No

Intended Deregistration Date: 17 Apr 2019

Vehicle Make: MITSUBISHI

Vehicle Model: LANCER EX 1.6 AUTO ABS
D/AB 2WD 4DR

Primary Colour: Black

Manufacturing Year: 2012

Engine No.: 4A92AX5609

Chassis No.: JMYSRCY1ACU000640

Maximum Power Output: 86.0 kW (115 bhp)

Open Market Value: \$16,676.00

Original Registration Date: 08 May 2012

First Registration Date: 08 May 2012

Transfer Count: 0

Actual ARF Paid: \$16,676.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 07 May 2022

PARF Rebate Amount: \$10,839.00

Intended COE Rebate Details

COE Expiry Date: 07 May 2022

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$56,501.00

COE Rebate Amount: \$17,260.00

Total Rebate Amount: \$28,099.00

The information contained herein is correct as at 17 Apr 2019

OK

MSME19050579 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME 18/04/2019 12:37
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/04/2019 12:37
Date Of Accident	17/04/2019 12:10
Exact Location Of Accident	LOK YANG WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKF2062X
Insured/Policyholder	
Name Of Registered Owner	GOH CHENG SWEE
NRIC No	S1398279A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97533908
Alternative Phone No	OFFICE-97533908

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100298823-06
Cover Note Number	

Driver

Name of Driver	GOH CHENG SWEE
NRIC No	S1398279A
Date Of Birth	07/04/1959
Occupation	INDOOR
Date Of Driving Pass	20/01/1981
Driving Experience	38 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97533908
Fax Number	
Contact Number	OFFICE-97533908
Email Address	NOEMAIL

Address	BLK 11 PINE CLOSE #14-115
Postcode	391011
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG LOK YANG WAY. SUDDENLY, VEHICLE B SWERVED HER VEHICLE TO THE LEFT LANE AND THEN MADE AN U-TURN WITHOUT ANY SIGNAL NOR CHECKING FOR ONCOMING TRAFFIC. I TRIED TO STOP BUT COULD NOT AVOID AND COLLIDED. DUE TO THE IMPACT, VEHICLE B DID NOT STOP AND IT DRAG MY VEHICLE ALONG WITH HER VEHICLE. MY BUMPER WAS BEING DRAGGED OUT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP328D
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	LUO
NRIC/Passport Number	
Contact Number	90693778
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling straight along lok yang way
suddenly, vehicle B sensed her vehicle to the left lane and then
made a u-turn, without any signal nor checking for oncoming traffic.

I tried to stop but could not avoid and collided. Due to the
impact, vehicle B did not stop and it drag my vehicle along
with her vehicle. My bumper was being dragged out.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Ric

Policyholder's Signature
Date & Time:

Ric

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



新福德車廠私人有限公司

8.9

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

GOH CHENG SWEE

18/04/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAWA
Xiao Chun

Accident date: 17/04/2019

JMYSRCY1AC4000640

Estimated repair cost for vehicle no: SKF2062X MITSUBISHI LANCER EX 1.6 A '12

CHASSIS: JMYSRCY1ACU000640

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet Distorted		\$908.00 ✓
2	2	Front Bonnet Hinge Bent	\$58.00	\$116.00 ✓
3	1	Front Bonnet Insulator 2nd		\$105.00 x
4	8	Front Bonnet Insulator Clip 1st	\$6.50	\$52.00 x
5	1	Front Bonnet Lock 2nd		\$92.00 x
6	1	Front Bonnet Inner Rubber Not new		\$68.00 x
7	2	Front Head Lamp Cracked	\$792.00	\$1,584.00 ✓
8	2	Front Head Lamp Lower Bracket Not new	\$28.00	\$56.00 x
9	1	Front Bumper Distorted		\$985.00 825
10	8	Front Bumper Clip New	\$6.50	\$52.00 30
11	2	Front Bumper Side Retainer New	\$24.00	\$48.00 ✓
12	1	Front Bumper Emblem Logo New		\$47.00 ✓
13	1	Front Bumper Number Plate Not new		\$50.00 x
14	1	Front Bumper Chrome Cracked		\$555.00 185
15	1	Front Bumper Grille Cracked		\$374.00 ✓
16	1	Front Bumper Center Lower Garnish Cracked		\$307.00 139
17	1	Front Bumper Towing Cover Damaged		\$26.00 ✓
18	1	Front Bumper Top Beam Bent		\$134.00 ✓
19	1	Front Bumper Reinforcement Bent		\$390.00 ✓
20	2	Front Bumper Fog Lamp Cracked LH	\$426.00	\$852.00 282
21	2	Front Bumper Fog Lamp Cover LH & RH	\$46.00	\$92.00 46
22	1	Front L/H Fender Distorted		\$588.00 ✓
23	1	Front L/H Fender Inner Panel Distorted		\$1,458.00 497
24	1	Front L/H Fender Signal Lamp Not new		\$40.00 x
25	1	Front L/H Fender Cowling Torn		\$103.00 ✓
26	6	Front L/H Fender Cowling Clip New	\$6.50	\$39.00 30
27	1	Front Fuse Box Assy Cracked		\$862.00 ✓
28	1	Front Support Panel Buckled		\$297.00 ✓

29	1	Front Support Panel Top Cover	cracked	\$83.00	✓	
30	1	Front Support Panel Top Air Duct	new	\$136.00	+	
31	1	Front L/H Support Side Panel	Distorted	\$97.00	✓	
32	1	Front L/H Chassis	Repair	\$1,458.00	+	
33	1	Front L/H Tyre	new	\$350.00	+	
34	1	Front L/H Rim	cut	\$692.00	400(SM)	
35	1	Front L/H Lower Arm	Best	\$304.00	✓	
36	1	Front L/H Knuckle Arm	Best	\$321.00	✓	
37	1	Front L/H Knuckle Arm Bearing	new	\$143.00	✓	
38	1	Front L/H Shock Absorber	Best	\$417.00	✓	
39	1	Front L/H Drive Shaft	new	\$1,159.00	+	
40	1	Front Stabilizer Bar	new	\$286.00	+	
41	1	Front Steering Rack	new	\$2,602.00	+	
42	4	Front Engine Mounting (1 Set)	new	\$501.00	+	
43	1	Front Windscreen	cracked	\$987.00	✓	
44	1	Front Windscreen Seal	new	\$65.00	✓	
45	1	Front Windscreen Moulding	new	\$124.00	✓	
46	1	Front Windscreen Erp Bracket	new	\$35.00	25(SM)	
47	1	Front Wiper Garnish	new	\$124.00	+	
48	1	Front L/H Door	Repair	\$1,075.00	+	
49	2	Front L/H Door Hinge	} new	\$38.00	\$76.00	+
50	1	Front L/H Door Lock		\$287.00	+	
51	1	Front L/H Door Inner Rubber		\$155.00	+	

Subtotal :- \$21,757.00

9955
895950

S N: 425

Labour charges

To remove & refit front L/H door, glass, gear motor, lock, rubber & trim board	\$280.00	X
To remove & refit front windscreen	\$120.00	✓
Gum <i>NEL</i>	\$50.00	✓
To remove & refit front engine	\$480.00	X
To remove & refit front L/H undercarriage	\$380.00	220
To remove & refit front L/H drive shaft & steering rack	\$380.00	X
To check wheel alignment	\$150.00	80
To check wiring	\$100.00	30
Tuff kote	\$150.00	60
Towing fee	\$150.00	60
Panel Beating	\$2,500.00	1200
Spray painting	\$1,800.00	1200

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3020.

Subtotal :- \$6,540.00
Total:- \$28,297.00

total 12404.50
L/S: 9.8K (Nett Value)

12 Days.
9.8K



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA19007042/Aqd3n2

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Date : 15-05-2019



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLP 328D	Veh. Inspected	SKF 2062X
Policy No.	AVPPSB0551571800	Coverage (\$)	0.00
Claim No.	NSV1900205/BT	Excess (\$)	0.00
Assign From	BEN TANG	Assign Date	18/04/2019

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI LANCER	c.c	1590
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	JMYSRCY1ACU000640	Colour	BLACK
Odometer	180537	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	MAXXIS	6 mm
L/H Front Tyre	225/50 R17	MAXXIS	6 mm
R/H Rear Tyre	225/50 R17	MAXXIS	6 mm
L/H Rear Tyre	225/50 R17	MAXXIS	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/04/2019	Inspection Date	22/04/2019
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 2062X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	DISTORTED	908.00	908.00
2	FRONT BONNET HINGE @\$58.00	BENT	116.00	116.00
1	FRONT BONNET INSULATOR	NOT NECESSARY	105.00	-
8	FRONT BONNET INSULATOR CLIP @\$6.50	NOT NECESSARY	52.00	-
1	FRONT BONNET LOCK	NOT NECESSARY	92.00	-
1	FRONT BONNET INNER RUBBER	NOT NECESSARY	68.00	-
2	FRONT HEAD LAMP @\$792.00	CRACKED	1,584.00	1,584.00
2	FRONT HEAD LAMP LOWER BRACKET @\$28.00	NOT NECESSARY	56.00	-
1	FRONT BUMPER	DISTORTED	985.00	825.00
8	FRONT BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
2	FRONT BUMPER SIDE RETAINER @\$24.00	NECESSARY	48.00	48.00
1	FRONT BUMPER EMBLEM LOGO	NECESSARY	47.00	47.00
1	FRONT BUMPER NUMBER PLATE	NOT NECESSARY	50.00	-
1	FRONT BUMPER CHROME	CRACKED	555.00	185.00
1	FRONT BUMPER GRILLE	CRACKED	374.00	374.00
1	FRONT BUMPER CENTER LOWER GARNISH	CRACKED	307.00	139.00
1	FRONT BUMPER TOWING COVER	DAMAGED	26.00	26.00
1	FRONT BUMPER TOP BEAM	BENT	134.00	134.00
1	FRONT BUMPER REINFORCEMENT	BENT	390.00	390.00
2	FRONT BUMPER FOG LAMP @\$426.00	N/S CRACKED	852.00	282.00
2	FRONT BUMPER FOG LAMP COVER @\$46.00	N/S DEFORMED	92.00	46.00
1	FRONT L/H FENDER	DISTORTED	588.00	588.00
1	FRONT L/H FENDER INNER PANEL	DISTORTED	1,458.00	497.00
1	FRONT L/H FENDER SIGNAL LAMP	NOT NECESSARY	40.00	-
1	FRONT L/H FENDER COWLING	TORN	103.00	103.00
6	FRONT L/H FENDER COWLING CLIP @\$6.50	NECESSARY	39.00	30.00
1	FRONT FUSE BOX ASSY	CRACKED	862.00	862.00
1	FRONT SUPPORT PANEL	BUCKLED	297.00	297.00
1	FRONT SUPPORT PANEL TOP COVER	CRACKED	83.00	83.00
1	FRONT SUPPORT PANEL TOP AIR DUCT	NOT NECESSARY	136.00	-
1	FRONT L/H SUPPORT SIDE PANEL	DISTORTED	97.00	97.00
1	FRONT L/H CHASSIS	TO REPAIR SEE LABOUR	1,458.00	-
1	FRONT L/H TYRE	NOT NECESSARY	350.00	-

Report Ref No. CS/AWA19007042/Aqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT L/H LOWER ARM	BENT	304.00	304.00
1	FRONT L/H KNUCKLE ARM	BENT	321.00	321.00
1	FRONT L/H KNUCKLE ARM BEARING	NECESSARY	143.00	143.00
1	FRONT L/H SHOCK ABSORBER	BENT	417.00	417.00
1	FRONT L/H DRIVE SHAFT	NOT NECESSARY	1,159.00	-
1	FRONT STABILIZER BAR	NOT NECESSARY	286.00	-
1	FRONT STEERING RACK	NOT NECESSARY	2,602.00	-
4	FRONT ENGINE MOUNTING (1 SET)	NOT NECESSARY	501.00	-
1	FRONT WINDSCREEN	CRACKED	987.00	987.00
1	FRONT WINDSCREEN SEAL	NECESSARY	65.00	65.00
1	FRONT WINDSCREEN MOULDING	NECESSARY	124.00	124.00
1	FRONT WIPER GARNISH	NOT NECESSARY	124.00	-
1	FRONT L/H DOOR	TO REPAIR SEE LABOUR	1,075.00	-
2	FRONT L/H DOOR HINGE @\$38.00	NOT NECESSARY	76.00	-
1	FRONT L/H DOOR LOCK	NOT NECESSARY	287.00	-
1	FRONT L/H DOOR INNER RUBBER	NOT NECESSARY	155.00	-
	LESS 10% DISCOUNT		-	-1,005.20
			21,030.00	9,046.80
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT L/H RIM (SN)	CUT	692.00	400.00
1	FRONT WINDSCREEN ERP BRACKET (SN)	NECESSARY	35.00	25.00
1	GUM (SN)	NECESSARY	50.00	50.00
			777.00	475.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT FRONT L/H DOOR, GLASS, GEAR MOTOR, LOCK, RUBBER & TRIM BOARD.	NOT NECESSARY	280.00	-
	TO REMOVE & REFIT FRONT WINDSCREEN.		120.00	120.00
	TO REMOVE & REFIT FRONT ENGINE.	NOT NECESSARY	480.00	-
	TO REMOVE & REFIT FRONT L/H UNDERCARRIAGE.		380.00	220.00
	TO REMOVE & REFIT FRONT L/H DRIVE SHAFT & STEERING RACK.	NOT NECESSARY	380.00	-
	TO CHECK WHEEL ALIGNMENT.		150.00	80.00
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.		150.00	60.00
	TOWING FEE.		150.00	60.00

Report Ref No. CS/AWA19007042/Aqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT L/H CHASSIS AND FRONT L/H DOOR.		2,500.00	1,200.00
	SPRAY PAINTING.		1,800.00	1,200.00
			6,490.00	2,970.00
GRAND TOTAL			28,297.00	12,491.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,800.00

Report Ref No. CS/AWA19007042/Aqd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.