



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 9122S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SIDE LAMP (CONSISTENT)	SCRATCHED	160.00	160.00
1	COMPARTMENT DOOR (CONSISTENT)	DENTED	950.00	950.00
	LESS 10% DISCOUNT		-111.00	-111.00
			999.00	999.00
	<u>LABOUR</u>			
	TO PUTTY AND SPRAY ON LEFT HAND SIDE LUGGAGE COMPARTMENT ,WHEEL ARCH PROTECTOR AND ALL AFFECTED ACCIDENT PARTS (THREE COLOUR PAINT).		1,650.00	1,200.00
	TO CHECK THE WIRING OF WIPER AND ELECTRICAL WING MIRROR CONNECTED WITH GPS.		150.00	40.00
	TO KNOCK AND STRAIGHTEN ALL NECESSARY PARTS INCLUDING REPAIRING AND CHANGING ALL DAMAGED APRTS AND ALIGN SAME.SIDE COMPARTMENT DOOR.		1,200.00	1,000.00
			3,000.00	2,240.00
	GRAND TOTAL		3,999.00	3,239.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITIONG)			2,590.00

Report Ref No. CC4/ASM19007067/Jga3q2

ONG HWEE JIE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.