



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD	Ref : CC4/ASM19007067/Jga3q2
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN	Date : 13-04-2020 Code : ASM



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 2853L	Veh. Inspected	PC 9122S
Policy No.	VCX/P2213858	Coverage (\$)	0.00
Claim No.	S9M01KGF	Excess (\$)	0.00
Assign From		Assign Date	18/04/2019

2. Vehicle Particulars & Condition

Make & Model	HIGER	c.c	6692
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	LKLR1HSJ49B514501	Colour	MULTI COLOUR
Odometer	592370	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	FALKEN	7 mm
L/H Front Tyre	295/80 R22.5	FALKEN	7 mm
R/H Rear Tyre	295/80 R22.5 (D)	FALKEN	7/7 mm
L/H Rear Tyre	295/80 R22.5 (D)	FALKEN	7/7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/04/2019	Inspection Date	24/04/2019
Survey held at	CROWN ASIA BUS BUILDER PTE LTD NO. 44 SUNGEI KADUT STREET 1 SINGAPORE 729349		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**