

Dm / type:

Registered in Meritindex

ASSIGNMENT

(V/L: YES/NO)

Place of Accident :

Insured Liability : 2 % Final ? Yes / No

RMKS

RMKS:

RMKS:-

RMKS

DATE / PIC

Others

Sent By:

Confirm with:

Confirm by:

Emul)		Call	
-------	--	------	--

Email	☒	Call	☐
-------	-------------------------------------	------	--------------------------

If NO or B 28, Ass. Lin: 100

3 VEH C C, 01 LAS-

COPY SENT
7/3/19

1) Claim status: Normal/Reject/Private Settle

2) Report Format

3) Survey fee:

Email Call

NOTES LTD

© 2006 The Authors
Journal compilation © 2006 Blackwell Publishing Ltd

1. *Journal of the American Medical Association*, 1997; 277: 1033-1036.

[illegible]

41 67

Toufexis

Ha-

Re

D.O.

The **UIC / Chassis frame / Body Structure** affected due to collision

Report Unit 978K, e-mail to Mary

(P/P \$ 39,734.99 | Red \$ 3,606.99 | 8%)

(68 + 60 + 50 + 40 + 30 + 20 + 10)

30 days + 3 pps + 7 weekends (14) $\uparrow$ 1 pps = 48

WR - 21 days

4th June
19.

Resurvey No. of Trip:

Add Fee: : Site Insp (\$☐ Interview (S)

Tech. inv. (\$)

Lump Sum / I.B.B. ☐☐ Weekend \$

Survey Fee

Copyright © 2004 by John Wiley & Sons, Inc.

July 1991

11. **Teacher's**

1. *Journal of Management Studies*, 1996, 33, 1.

H5A1

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401539W GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2235269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

180, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motocrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50885
Date Estimated : 16/04/2019
Prepared By : Han Kwan Yong

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -

Goh Bee Ling, Joyce Mrs. Fung Joyce
48 KISMIS AVENUE

SINGAPORE 598225

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKU7972H	V247314	18/08/2015	I3 REX	0

DESCRIPTION

To replace front & rear bumper & attachments, bonnet, boot lid, front center air including to knock out dented area caused by the accident (REFER TO FINAL REPORT).

To respray front bumper, rear bumper and bonnet (REFER TO FINAL REPORT)

To replace air con condenser including to vacuum system, top up freon gas and check for leak

To replace left headlight

To replace right headlight

To remove and transfer rear windscreen from old to new boot

To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function.

To check electrical wiring system of the front and rear section for proper function including to aim headlights

To supply and install front and rear Emboss number plate

Sundries

5000 ~~5000~~ VALUE
5,950.00

3,036 ~~3,036~~ 3,374.00

plus 8527 1,003.00

408/3 481.00

X 408? 481.00

X 487. 574.00

451/ 531.00

250/ 295.00

83/ b1/ 140.00

/ 150.00

Total Labour 1: 12,979.00

DESCRIPTION

C CLIP FOR PLASTIC NUT
TAILGATE WITH REAR WINDOW
FASTENING SET REAR LID TRIM PANEL
COVER BUMPER FRT
TRIM BUMPER FRT LH

QTY	PRIC
10	1.00
1	1,570.85
1	35.85
1	153.00
1	56.25

VALUE
net 10.00
car 1,570.85
nut 35.85
del 153.00
net 56.25

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255289)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63448773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50885
Date Estimated : 16/04/2019
Prepared By : Han Kwan Yong

Page No. : 2 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKU7972H	V247314	18/08/2015	I3 REX	0

DESCRIPTION	QTY	PRIC	VALUE
# TRIM BUMPER FRT RH	1	56.25	unp 56.25
# FRT BUMPER TOP CARRIER	1	390.55	br 390.55
# FRT LH DEFORMATION ELEMENT	1	105.15	de 105.15
# FRT RH DEFORMATION ELEMENT	1	105.15	de 105.15
# FRT BUMPER BOTTOM CARRIER	1	138.20	un 138.20
# FRONT SHOCK ABSORBER	1	31.70	de 31.70
FRT LH BOTTOM DEFORMATION ELEMENT	1	89.25	un 89.25
FRT RH BOTTOM DEFORMATION ELEMENT	1	89.25	un 89.25
# INSERT AIR INLET MIDDLE	1	106.65	de 106.65
# FRONT BUMPER PANEL PRIMED	1	719.10	car 719.10
COVER TOWING EYE FRT PRIMED	1	42.85	un 42.85
# GUIDE	1	70.15	de 70.15
# REAR BUMPER CARRIER	1	282.90	un 282.90
# CENTRE BRACKET BUMPER	1	67.15	de 67.15
# HOLDER AERIAL	1	25.65	de 25.65
# REAR BUMPER TRIM PANEL	1	879.25	de 879.25
# REAR BUMPER COVER PRIMED	1	143.40	de 143.40
# DEFORMATION ELEMENT LH	1	119.70	de 119.70
# DEFORMATION ELEMENT RH	1	119.70	rot 119.70
GRILLE FRT LH (BLUE)	1	80.00	un 80.00
GRILLE FRT RH (BLUE)	1	80.00	un 80.00
REAR BMW BADGE	1	71.25	na 71.25
LETTERING I3	1	46.30	na 46.30
LETTERING E DRIVE	1	96.15	na 96.15
# HOLDER for emblem	1	31.00	na 31.00
GAS PRESSURIZED SPRING HOOD	2	124.00	2 248.00
# BONNET LH HINGE	1	70.80	br 70.80
# BONNET RH HINGE	1	70.80	br 70.80
BMW EMBLEM	1	71.25	na 71.25
BONNET	1	652.75	de 652.75
TRUNK LID LOCK	1	159.60	2 159.60
# STRIKER TRUNK LID	1	58.25	2 58.25
FRT LH BOTTOM STRUT	1	26.70	2 26.70
FRT RH BOTTOM STRUT	1	26.70	2 26.70
# FRONT STORAGE COMPARTMENT	1	154.35	2 154.35
AIR DUCT CENTRE FRT	1	106.20	2 106.20
AIR DUCT MIDDLE LOWER SECTION	1	106.20	2 106.20
# AIR DUCT	1	111.50	2 111.50
# AIR DUCT SERVICE CAP	1	53.10	2 53.10
TOP LEFT COVER	1	45.95	2 45.95
Cover, upper	1	48.05	2 48.05
TRUNK LID GASKET	1	177.80	2 177.80
HEADLIGHT BUMPER LH	1	243.85	2 243.85
# HEADLIGHT BUMPER RH	1	243.85	2 243.85
LH HEADLIGHT LED TECHNOLOGY	1	2,641.50	2 2,641.50
# RH HEADLIGHT LED TECHNOLOGY	1	2,641.50	2 2,641.50
# REAR LIGHT BUMPER LH	1	243.50	2 243.50
# REAR LIGHT BUMPER RH	1	243.50	2 243.50
# PRINT CIRC. BOARD REAR LID L	1	237.20	2 237.20



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

260, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796626 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50885
Date Estimated : 16/04/2019
Prepared By : Han Kwan Yong

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKU7972H	V247314	18/08/2015	I3 REX	0

DESCRIPTION

PRINT CIRC. BOARD REAR LID L
NUMBER PLATE LIGHT LED
CONDENSER AIR CONDITIONING
ULTRASONIC SENSOR BLACK
DECOUPING RING PDC TORQUE CONVERTER
REVERSING CAMERA

QTY	PRIC	VALUE
1	237.20	237.20
2	25.00	50.00
1	1,028.45	1,028.45
8	248.70	1,989.60
8	5.05	40.40
1	718.40	718.40

Total Parts : 18,559.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Report No. Claim No.

Date/Time Excess \$

Insured's Name Sign

Surveyor's Tel. Authorised Yes / No

Appointment Date Time

REFUSE TO TAKE PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's Email

No. of Working Days Recommend

18/4/19 12:00 pm
Taufik
92445743
WP
19 days - 10 days
To check repair limit.

Labour 1	:	12,979.00
Parts	:	18,559.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,207.70
Grand Total	:	33,746.30

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 50885
Date Estimated : 16/04/2019
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Goh Bee Ling, Joyce Mrs. Fung Joyce
48 KISMIS AVENUE

- ACCOUNT - 40000
Cash Sales - Service
Singapore

SINGAPORE 598225

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKU7972H	V247314	18/08/2015	I3 REX	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

- | | | | | |
|-------|--|-------------|-----------|---|
| 5,000 | * To replace front bumper and attachments, rear bumper and attachments, tail end panel, bottom trunk floor, cross member, rear top cross member, LH/RH reinforcement cross member plate, tailgate, bonnet and attachments, front LH/RH deformation element, LH/RH column 'A' cover, front support panel, front air duct, rear engine compartment shielding, LH/RH headlight bumper, rear LH/RH light bumper include making good the LH roof frame trim panel and knocking out dents caused by the accident | 13600.00 | 13,600.00 | ✓ |
| | 8,500 (A) | | | |
| | 3036 | | | |
| | * To respray front bumper, rear bumper, bonnet and LH roof frame trim panel - 540 (A) | 3576.00 | 3,576.00 | ✓ |
| | * To replace air con condenser including to vacuum system, top up freon gas and conducting checks for leak | 852.00 | 852.00 | ✓ |
| | * To replace LH LED technology headlight include programming and conducting tests for proper function | 408.00 | 408.00 | ✓ |
| | To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function | 451.00 | 451.00 | ✓ |
| | * To check electrical wiring system at the front and rear section for proper function | 250.00 | 250.00 | ✓ |
| | To supply and install front Emboss number plate | 83.00 | 83.00 | ✓ |
| # | To remove and install battery to facilitate repairs, perform high current tests and charge up battery | 451.00 (A) | 451.00 | |
| # | To remove and install complete electrical machine with rear axle to facilitate repairs include conducting tests for proper function | 2000.00 (A) | 2,000.00 | |
| # | To replace front PDC wire harness set include resetting and conducting checks for proper function | 360.00 (A) | 360.00 | |
| # | To conduct water leak tests | 75.00 (A) | 75.00 | |

Performance Motors Limited

A member of the Sims Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

# To replace rear reversing camera include programming and conducting checks for proper function	266.00 (A)	266.00
# To remove and install radiator assembly to facilitate repairs include pressure tests, bleed cooling system and conducting checks for leak	673.00 (A)	673.00
# To remove and install charging power socket and interface module to facilitate repairs include programming and encoding control unit and conducting checks for function	950.00 (A)	950.00
Sundries	150.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
C CLIP FOR PLASTIC NUT	1.00	10.00		10.00
# SCREW THERMOPLASTIC *	3.70	2.00		(A) 7.40 ✓
# HEX BOLT *	1.45	10.00		(A) 14.50 ✓
# ASA BOLT M12X80 *	15.55	2.00		(A) 31.10 ✓
# COLLAR BOLT WITH COMPRESSION SPRING *	18.15	2.00		(A) 36.30 ✓
# 3M S/F PREMIUM REAR WINDSCREEN	252.34	1.00		(A) 252.34 ✓
# TAIL PANEL *	159.45	1.00		(A) 159.45 ✓
# CROSS MEMBER TRUNK FLOOR BOTTOM *	948.15	1.00		(A) 948.15 ✓
# CROSS MEMBER REAR TOP *	163.20	1.00		(A) 163.20 ✓
# REINFORCEMENT PLATE CROSSMEMBER MID *	113.20	1.00		(A) 113.20 ✓
# LH REINFORCEMENT PLATE CROSS MEMBER *	145.50	1.00		(A) 145.50 ✓
# RH REINFORCEMENT PLATE CROSS MEMBER *	145.50	1.00		(A) 145.50 ✓
# TAILGATE WITH REAR WINDOW *	1,570.85	1.00		1,570.85 ✓
# FOAM BELT *	30.10	2.00		(A) 60.20 ✓
COVER BUMPER FRT	153.00	1.00		153.00 ✓
TRIM BUMPER FRT LH	56.25	1.00		56.25 ✓
FRT BUMPER TOP CARRIER *	390.55	1.00		390.55 ✓
# FRT LH DEFORMATION ELEMENT *	105.15	1.00		105.15 ✓
FRT RH DEFORMATION ELEMENT	105.15	1.00		105.15 ✓
FRONT SHOCK ABSORBER	31.70	1.00		31.70 ✓
INSERT AIR INLET MIDDLE	106.65	1.00		106.65 ✓
# FRONT BUMPER PANEL PRIMED *	719.10	1.00		719.10 ✓
GUIDE	70.15	1.00		70.15 ✓
# COUNTER SUPPORT REAR VIEW CAMERA *	8.50	1.00		(A) 8.50 ✓
CENTRE BRACKET BUMPER	67.15	1.00		67.15 ✓
# HOLDER AERIAL *	25.65	1.00		25.65 ✓
REAR BUMPER TRIM PANEL	879.25	1.00		879.25 ✓
REAR BUMPER COVER PRIMED	143.40	1.00		143.40 ✓
# GRILLE FRT LH (GREY) *	80.00	1.00		80.00 ✓
# GRILLE FRT RH (GREY) *	80.00	1.00		80.00 ✓
# LH COLUMN A COVER *	118.30	1.00		(A) 118.30 ✓
# RH COLUMN A COVER *	118.30	1.00		(A) 118.30 ✓
REAR BMW BADGE	71.25	1.00		71.25 ✓
LETTERING I3	46.30	1.00		46.30 ✓
LETTERING E DRIVE	96.15	1.00		96.15 ✓
# HOLDER *	31.00	1.00		31.00 ✓
BONNET LH HINGE	70.80	1.00		70.80 ✓
# BONNET RH HINGE *	70.80	1.00		70.80 ✓
BMW EMBLEM	71.25	1.00		71.25 ✓

Performance Motors Limited

A member of the Sims Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

BONNET	652.75	1.00	652.75
# ROOF FRAME STRIP CLIP *	4.80	20.00	(A) 95.00 ✓
# FRONT PANEL *	287.25	1.00	(A) 287.25 ✓
AIR DUCT	111.50	1.00	111.50
# RR ENGINE COMPARTMENT SHIELDING *	259.65	1.00	(A) 259.65 ✓
# REAR REPAIR CABLE *	408.20	1.00	(A) 408.20 ✓
# BUSHING CONTACT NANOMQS 0.22-0.35MM *	2.60	1.00	(M) 2.60 ✓
# BUSHING CONTACT NANOMQS 0.22-0.35MM *	2.60	7.00	(M) 18.20 ✓
# SOCKET HOUSING *	25.70	1.00	(A) 25.70 ✓
HEADLIGHT BUMPER LH	243.85	1.00	243.85
HEADLIGHT BUMPER RH	243.85	1.00	243.85
LH HEADLIGHT LED TECHNOLOGY	2,641.50	1.00	2,641.50
REAR LIGHT BUMPER LH	243.50	1.00	243.50
REAR LIGHT BUMPER RH	243.50	1.00	243.50
NUMBER PLATE LIGHT LED	25.00	1.00	25.00
# NUMBER PLATE LIGHT LED *	25.00	1.00	25.00
CONDENSER AIR CONDITIONING	1,028.45	1.00	1,028.45
DECOUPING RING PDC TORQUE CONVERTER	5.05	8.00	40.40
REVERSING CAMERA	718.40	1.00	718.40
# LABEL COOLANT 750+/-10G *	23.25	1.00	(A) 23.25 ✓
# (S/L) CLEANER R2 500ML *	12.50	1.00	(A) 12.50 ✓
# (SL/DG) BODY ADHESIVE K2 (2X290ML) *	676.15	1.00	(A) 676.15 ✓
# (DG/SL) REFRIGERANT OIL SANDEN 250ML *	169.20	1.00	(A) 169.20 ✓
# (S/L) ANTI FREEZE 1.5 LITRES *	20.10	1.00	(A) 20.10 ✓

SUPPLEMENTARY ITEMS ✓

Total Labour :	24,145.00
Total Parts :	15,589.99
Total Labour & Parts :	39,734.99
Deduction for Excess :	
Total Repair Costs less Excess:	39,734.99
GST @7%:	2,781.45
Grand Total :	42,516.44

Performance Motors Limited

A member of the Sims Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

# FRT LH DEFORMATION ELEMENT *	105.15	1.00	105.15
# FRONT BUMPER PANEL PRIMED *	719.10	1.00	719.10
# COUNTER SUPPORT REAR VIEW CAMERA *	8.50	1.00	8.50
# HOLDER AERIAL *	25.65	1.00	25.65
# GRILLE FRT LH (GREY) *	80.00	1.00	80.00
# GRILLE FRT RH (GREY) *	80.00	1.00	80.00
# LH COLUMN A COVER *	118.30	1.00	118.30
# RH COLUMN A COVER *	118.30	1.00	118.30
# HOLDER *	31.00	1.00	31.00
# BONNET RH HINGE *	70.80	1.00	70.80
# ROOF FRAME STRIP CLIP *	4.80	20.00	96.00
# FRONT PANEL *	287.25	1.00	287.25
# RR ENGINE COMPARTMENT SHIELDING *	259.65	1.00	259.65
# REAR REPAIR CABLE *	408.20	1.00	408.20
# BUSHING CONTACT NANOMQS 0.22-0.35MM *	2.60	1.00	2.60
# BUSHING CONTACT NANOMQS 0.22-0.35MM *	2.60	7.00	18.20
# SOCKET HOUSING *	25.70	1.00	25.70
# NUMBER PLATE LIGHT LED *	25.00	1.00	25.00
# LABEL COOLANT 750+/-10G *	23.25	1.00	23.25
# (S/L) CLEANER R2 500ML *	12.50	1.00	12.50
# (SL/DG) BODY ADHESIVE K2 (2X290ML) *	676.15	1.00	676.15
# (DG/SL)REFRIGERANT OIL SANDEN 250ML *	169.20	1.00	169.20
# (S/L) ANTI FREEZE 1.5 LITRES *	20.10	1.00	20.10

Total Labour :	4,775.00
Total Parts :	7,028.29
Total Labour & Parts :	11,803.29

Performance Motors Limited

A member of the Sims Carby Group
Co. Reg. No. 187401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To remove and install battery to facilitate repairs, perform high current tests and charge up battery	451.00		451.00
# To remove and install complete electrical machine with rear axle to facilitate repairs include conducting tests for proper function	2000.00		2,000.00
# To replace front PDC wire harness set include resetting and conducting checks for proper function	360.00		360.00
# To conduct water leak tests	75.00		75.00
# To replace rear reversing camera include programming and conducting checks for proper function	266.00		266.00
# To remove and install radiator assembly to facilitate repairs include pressure tests, bleed cooling system and conducting checks for leak	673.00		673.00
# To remove and install charging power socket and interface module to facilitate repairs include programming and encoding control unit and conducting checks for function	950.00		950.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SCREW THERMOPLASTIC *	3.70	2.00		7.40
# HEX BOLT *	1.45	10.00		14.50
# ASA BOLT M12X80 *	15.55	2.00		31.10
# COLLAR BOLT WITH COMPRESSION SPRING *	18.15	2.00		36.30
# 3M S/F PREMIUM REAR WINDSCREEN	252.34	1.00		252.34
# TAIL PANEL *	159.45	1.00		159.45
# CROSS MEMBER TRUNK FLOOR BOTTOM *	948.15	1.00		948.15
# CROSS MEMBER REAR TOP *	163.20	1.00		163.20
# REINFORCEMENT PLATE CROSSMEMBER MID *	113.20	1.00		113.20
# LH REINFORCEMENT PLATE CROSS MEMBER *	145.50	1.00		145.50
# RH REINFORCEMENT PLATE CROSS MEMBER *	145.50	1.00		145.50
# TAILGATE WITH REAR WINDOW *	1,570.85	1.00		1,570.85
# FOAM BELT *	30.10	2.00		60.20

Total Labour & Parts :39,734.99

Repair days - 37 days

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5025Z
Vehicle Details	
Vehicle No.:	SKU7972H
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Apr 2019
Vehicle Make:	B.M.W.
Vehicle Model:	BMW I3 REX LED NAV
Primary Colour:	Orange
Secondary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	1814009415W20K06A
Chassis No.:	WBY1Z42060V247314
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$44,923.00
Original Registration Date:	18 Aug 2015
First Registration Date:	18 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$24,893.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Aug 2025
PARF Rebate Amount:	\$18,669.00
Intended COE Rebate Details	
COE Expiry Date:	17 Aug 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$60,789.00
COE Rebate Amount:	\$38,417.00
Total Rebate Amount:	\$57,086.00

The information contained herein is correct as at 22 Apr 2019

OK



BMW i3

Price Range

Depreciation

Year Reg

Vehicle Type

Search

Home » Used Cars » Munich Automobiles (2018) Pte Ltd » BMW i3s Electric Range Extender

BMW i3s Electric Range Extender

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price	\$188,888	Fuel Type	Petrol-Electric
Depreciation ⓘ	\$16,500 /yr View models with similar depre	Reg Date	20-Jul-2018 (9yrs 2mths 27days COE left)
Mileage	4,668 km	Manufactured ⓘ	2018
Road Tax ⓘ	N.A.	Transmission	Auto
Dereg Value ⓘ	\$83,038 as of today (change)	OMV ⓘ	\$55,825
COE ⓘ	\$31,001	ARF ⓘ	\$72,485
Engine Cap	647 cc	No. of Owners ⓘ	1
Curb Weight ⓘ	1,385 kg		
Type of Vehicle	Hatchback		

Features

BMW's 0.6L Electric Motor Producing 181 Hp, Churning A Torque Of 269Nm, Sprinting From 0-100 Km/H In 6.8 Secs And Achieving A Top Speed Of 150 Km/H.

Accessories

20 Inch Wheels. Revised Tuning, Springs, Dampers And Anti-Roll Bars.

Description

The Perfect Day To Day City Car And Loads Of Acceleration On Tap. The Only One PML Unit BMW i3s In Singapore Comes With 3 Years Warranty And A Much Sportier Side Than Its Predecessors. Much Improved Stability, Better Range And All Round Performance. The Perfect Car For The Eco Warrior To Show Up In Style With.

Category

PARF Car, Almost New Car, Low Mileage Car, Hybrid Cars

Status

Available

Resources



Car Valuation - Free

Get the market value of your existing car for free. Get started

Compare



Shortlist

Compare

Report Error

More Acti

Seller Information

Company	Munich Autor Pte Ltd » dealer's priceli » 4 vehs sold 5
Address	30 Teban Gardei Search cars near
Office No	68963933
Contact Person(s)	Aaron Ang Nycky Lim Marcus Chew

Khanchna (LKK Auto)

From: Taufikh (LKKAuto)
Sent: Tuesday, 30 July 2019 10:51 AM
To: 'PBSP'
Cc: Celine Fong (LKKAuto); CS A Team; SUR; Khanchna (LKK Auto)
Subject: RE: FINAL REPORT / SKU7972H

Hi Caroline,

COR \$39,734.99 , 30 DAYS.

Regards
Taufikh
Lkk Auto

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Tuesday, 23 July 2019 3:41 PM
To: taufikh@lkkauto.com; SUR; CS A Team
Cc: Celine Fong (LKKAuto)
Subject: Re: FINAL REPORT / SKU7972H

Dear Celine and Taufikh

Need your assistance to expedite to confirm this Final Report.

Many thanks.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP
Sent: Saturday, 20 July 2019 11:58:02 AM
To: taufikh@lkkauto.com <taufikh@lkkauto.com>; SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Cc: Celine Fong (LKKAuto) <celinefong@lkkauto.com>
Subject: FINAL REPORT / SKU7972H

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour :24,145.00
Total Parts :15,589.99

Khanchna (LKK Auto)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 12 November 2019 6:29 PM
To: Khanchna (LKK Auto)
Cc: Admin A
Subject: Re: 3rd: LOD REMINDER - SKU7972H & SLW1704H ON 16/04/2019

Without Prejudice

Dear Khanchna

Strictly for the purpose of an early and amicable settlement, we will proceed to close the matter as per your revised LOU + Rental.

Do expedite payment.

Please note that this acceptance should not be construed as a precedent for future settlements.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Sent: Tuesday, 12 November 2019 4:56 PM
To: PBSP <pml-pbsp@simedarby.com.sg>
Cc: 甯瑤 @ <admin-a@lkkauto.com>
Subject: RE: 3rd: LOD REMINDER - SKU7972H & SLW1704H ON 16/04/2019

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 42,516.44
2. Loss of Use & Loss of rental (w/GST)	\$ 2,712.90
3. LTA Search	\$ 2.00
Total	\$ 45,231.34

Please confirm acceptance.

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 12 November 2019 4:57 PM
To: PBSP
Cc: Admin A
Subject: RE: 3rd: LOD REMINDER - SKU7972H & SLW1704H ON 16/04/2019

Tracking:	Recipient	Delivery
	PBSP	
	Admin A	
	shupeil@lkkauto.com	Delivered: 12/11/2019 4:57 PM
	Meikwan@lkkauto.com	Delivered: 12/11/2019 4:57 PM
	olivialau@lkkauto.com	Delivered: 12/11/2019 4:57 PM

**Without Prejudice
(save as to costs)**

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 42,516.44
2. Loss of Use & Loss of rental (w/GST)	\$ 2,712.90
3. LTA Search	\$ 2.00
Total	\$ 45,231.34

Please confirm acceptance.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 12 November 2019 4:31 PM

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19007078/T1JA3Q2
Date: 23/10/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800009811
Claimant Vehicle No :	SKU7972H	Insured Vehicle No :	SLW1704H
Date of Loss:	16/04/2019	Nature of Claim:	TP
		Claim No:	5624666040SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU7972H	Engine No:	1814009415W20K06A
Make & Model:	BMW I3, 647cc (A)	Chassis No:	WBY1Z42060V247314
Reg. Date:	18/08/2015 (Man. Year: 2014)	Odometer:	81217 km
Colour:	Orange/Black		
Engine Capacity:	647 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/60 R19	Rear Tyre Size:	175/60 R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,170.34	15,822.99	7,347.35	31.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	26,504.00	23,912.00	2,592.00	9.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	49,674.34	39,734.99	9,939.35	20.01
+ GST 7.00/7.00% (S\$)	3,477.20	2,781.45	695.75	20.01
Nett Amount (S\$)	53,151.54	42,516.44	10,635.10	20.01
+ Loss of Use (27.0 x S\$60.00/day) (S\$)		1,620.00		
+ Car Rental (21.0 x S\$70.00/day + 7.00% GST) (S\$)		1,572.90		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		45,711.34		

INSPECTION

Date of Assignment:	18/04/2019	Performance Motors Limited (Alexandra)
Date Inspected:	18/04/2019 Inspected At:	303 Alexandra Road, Sime Darby Performance Centre
Estimated Period of Repair:	30.0 days	Singapore 159941

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 23 October 2019 11:36 AM
To: Syed-Yusoff, Saliha
Cc: Admin A
Subject: Mandate Request - TP repairer breakdown on LOR + LOU [AIG REF: TP / 5624666040SG] [ACCIDENT INVOLVING SLW1704H (AIG) / SKU7972H / OTHERS ON 16/04/2019]

Dear Ms. Saliha,

We refer to the above matter and your instructions dated 21/10/2019 appended below for your easy reference.

<-- Original Message -->

From: AIG_SG_EXPRESS

To: LKK_HQ

Sent On: 21/10/2019 03:43 PM

Subject: Alert - Adj Mandate Maintained - SKU7972H - Claim Handler: Syed-Yusoff, Saliha

Maintained: Please justify the claim for LOU at 27 days on top of LOR at 21 days. Vehicle surveyed on 18/04/19 and TP only activated his rental car on 25/04/19? Please get the work chart from w/shop

As requested, Third party repairer explained :

- Vehicle was surveyed on 18/4/2019.
- Liability clearance given on 25/4/2019 and Third party took the rental vehicle on 25/4/2019 but returned on 16/5/2019 and claim LOU instead.
- Repair started on 25/4/2019 until 19/6/2019 and there were 16 days (weekends) and 3 public holidays.

In summary, they are claiming:-

LOR = 21 days (25/4/2019-16/5/2019)

LOU = 34 days (16/5/2019-19/6/2019)

We suggest :

**** 30 days recommendation for repair + 3 PH + 7 weekends (i.e. 14 days) + 1 PRS = 48 days**

LOR: 21 days (from DOI onwards)

LOU: 27 days (i.e. 48 days-21 days(LOR))

Thank you.

Best Regards,
Khanchna | Case Handler

Khanchna (LKK Auto)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 22 October 2019 6:09 PM
To: Khanchna (LKK Auto)
Cc: Admin A
Subject: Re: 3rd: LOD REMINDER - SKU7972H & SLW1704H ON 16/04/2019

Dear Khanchna

ASK CHY

What kind of work chart are you looking at? Please provide a template.

Otherwise, here is what we have for you. Upon the date of the accident, our client's vehicle was badly damaged and the vehicle was grounded at our workshop. Upon our Motor Claims Advisor handed over the estimate on 18 April 2019, we initiated the TP Direct Settlement claim through LKK Auto.

Liability clear on 25 April 2019 and our customer proceeds to rent a replacement car. However, our customer decided to return the replacement vehicle on 16 May 2019 and claim for LOU instead.

Please note that the repair started from 25 April till 19 June 2019 and there were 16 days weekends and 3 PH (Labour day, Vesak Day and Hari Raya Puasa).

Please review and let us have your best offer and we will seek instructions from our customer.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

LOU (21 days) = 1512.00
LOU (35 x 21) = 2800.00
5312.00

From: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Sent: Monday, 21 October 2019 4:07 PM
To: PBSP <pml-pbsp@simedarby.com.sg>
Cc: 甯瑤 @ <admin-a@lkkauto.com>
Subject: RE: 3rd: LOD REMINDER - SKU7972H & SLW1704H ON 16/04/2019

WITHOUT PREJUDICE

Dear Caroline,

Please justify the claim for Loss of Use on top of LOR for 21 days. Vehicle surveyed on 18/04/19 but TP only activated his rental car on 25/04/19.

Please let us have the breakdown in work chart form.

Thank you.

Best Regards,

Print Received Message

This mail is associated with :

***SKU7972H (5624666040SG)**
[SLW1704H]
TP
JOYCE GOH BEE LING
Apr 16 2019 1:00PM
[POOJA ARORA]
Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 07/11/2019 14:35 PM
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$45231.34) - SKU7972H - Claim Handler: Syed-Yusoff, Saliha

Approved:45231.34:Pls do your utmost to negotiate at best per below: COR: \$42,516.44 (w/gst) LOR/LOU:
\$2172.90-2712.90 (*TP only did addendum from OD to TP on 25/04/19) GIA: \$2 TOTAL: \$44,691.34 - 45,231.34
Above subj to Final Repair Bill, R

Print Received Message

This mail is associated with :

***SKU7972H (5624666040SG)**
[SLW1704H]
TP
JOYCE GOH BEE LING
Apr 16 2019 1:00PM
[POOJA ARORA]
Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 07/11/2019 14:35 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$45231.34) - SKU7972H - Claim Handler: Syed-Yusoff, Saliha

Approved:45231.34:Pls do your utmost to negotiate at best per below: COR: \$42,516.44 (w/gst) LOR/LOU:
\$2172.90-2712.90 (*TP only did addendum from OD to TP on 25/04/19) GIA: \$2 TOTAL: \$44,691.34 - 45,231.34
Above subj to Final Repair Bill, R

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Apr 2019 Edit Reg		18 Apr 2019 00:00 Edit Adj Rpt	\$539,734.99 Edit Estimates	\$539,734.99 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	POOJA ARORA, ID: S7769153G								
Main Claimant:	JOYCE GOH BEE LING, ID: S18250252								
Vehicle Reg. No.:	SKU7972H	Date of Loss:	16/04/2019 13:00 - :59 [43 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5624666040SG	Policy/Cover Note No.:	1800009811 (Comprehensive) Coverage: 31/01/2019 - 30/01/2020						
Vehicle Reg. No. (Insured):	SLW1704H	Policy No. (Claimant):	P1648315						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 02/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (07/11/2019): Alert - Adj Mandate Approved (\$45231.34) - SKU7972H - Claim Handler: Syed-Yusof... - AIG_SG_EXPRESS (21/10/2019): Alert - Adj Mandate Maintained - SKU7972H - Claim Handler: Syed-Yusoff, Saliha									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKU7972H (5624666040SG)
[SLW1704H]
TP
JOYCE GOH BEE LING
Apr 16 2019 1:00PM
[POOJA ARORA]
Performance Motors Limited

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Letters/Correspondences						1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown				 Edit	
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	21/10/19 11:53	General View				 Load JPG	☒
2	21/10/19 11:53	General View				 Load JPG	☒
3	21/10/19 11:53	General View				 Load JPG	☒
4	21/10/19 11:53	General View				 Load JPG	☒
5	21/10/19 11:53	General View				 Load JPG	☒
6	21/10/19 11:53	General View				 Load JPG	☒
7	21/10/19 11:53	General View				 Load JPG	☒
8	21/10/19 11:53	General View				 Load JPG	☒
9	21/10/19 11:53	General View				 Load JPG	☒
10	21/10/19 11:53	General View				 Load JPG	☒
11	21/10/19 11:53	General View				 Load JPG	☒
12	21/10/19 11:53	General View				 Load JPG	☒
13	21/10/19 11:53	General View				 Load JPG	☒
14	21/10/19 11:53	General View				 Load JPG	☒
15	21/10/19 11:53	General View				 Load JPG	☒
16	21/10/19 11:53	General View				 Load JPG	☒
17	21/10/19 11:53	General View				 Load JPG	☒
18	21/10/19 11:53	General View				 Load JPG	☒
19	21/10/19 11:53	General View				 Load JPG	☒
20	21/10/19 11:53	General View				 Load JPG	☒
21	21/10/19 11:53	General View				 Load JPG	☒
22	21/10/19 11:53	General View				 Load JPG	☒
23	21/10/19 11:53	General View				 Load JPG	☒
24	21/10/19 11:53	General View				 Load JPG	☒
25	21/10/19 11:53	General View				 Load JPG	☒
26	21/10/19 11:53	General View				 Load JPG	☒
27	21/10/19 11:53	General View				 Load JPG	☒
28	21/10/19 11:53	General View				 Load JPG	☒
29	21/10/19 11:53	General View				 Load JPG	☒
30	21/10/19 11:53	General View				 Load JPG	☒
31	21/10/19 11:53	General View				 Load JPG	☒
32	21/10/19 11:53	General View				 Load JPG	☒
33	21/10/19 11:53	General View				 Load JPG	☒
34	21/10/19 11:53	General View				 Load JPG	☒
35	21/10/19 11:53	General View				 Load JPG	☒
36	21/10/19 11:53	General View				 Load JPG	☒
37	21/10/19 11:53	General View				 Load JPG	☒
38	21/10/19 11:53	General View				 Load JPG	☒
39	21/10/19 11:53	General View				 Load JPG	☒
40	21/10/19 11:53	General View				 Load JPG	

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					☒
41	21/10/19 11:53	General View		Load JPG	☒
42	21/10/19 11:53	General View		Load JPG	☒
43	21/10/19 11:53	General View		Load JPG	☒
44	21/10/19 11:53	General View		Load JPG	☒
45	21/10/19 11:53	General View		Load JPG	☒
46	21/10/19 11:53	General View		Load JPG	☒
47	21/10/19 11:53	General View		Load JPG	☒
48	21/10/19 11:53	General View		Load JPG	☒
49	21/10/19 11:53	General View		Load JPG	☒
50	21/10/19 11:53	General View		Load JPG	☒
51	21/10/19 11:53	General View		Load JPG	☒
52	21/10/19 11:53	General View		Load JPG	☒
53	21/10/19 11:53	General View		Load JPG	☒
54	21/10/19 11:53	General View		Load JPG	☒
55	21/10/19 11:53	General View		Load JPG	☒
56	21/10/19 11:53	General View		Load JPG	☒
57	21/10/19 11:53	General View		Load JPG	☒
58	21/10/19 11:53	General View		Load JPG	☒
59	21/10/19 11:53	General View		Load JPG	☒
60	21/10/19 11:53	General View		Load JPG	☒
61	21/10/19 11:53	General View		Load JPG	☒
62	21/10/19 11:53	General View		Load JPG	☒
63	21/10/19 11:53	General View		Load JPG	☒
64	21/10/19 11:53	General View		Load JPG	☒
65	21/10/19 11:53	General View		Load JPG	☒
66	21/10/19 11:53	General View		Load JPG	☒
67	21/10/19 11:53	General View		Load JPG	☒
68	21/10/19 11:53	General View		Load JPG	☒
69	21/10/19 11:53	General View		Load JPG	☒
70	21/10/19 11:53	General View		Load JPG	☒
71	21/10/19 11:53	General View		Load JPG	☒
72	21/10/19 11:53	General View		Load JPG	☒
73	21/10/19 11:53	General View		Load JPG	☒
74	21/10/19 11:53	General View		Load JPG	☒
75	21/10/19 11:53	General View		Load JPG	☒
76	21/10/19 11:53	General View		Load JPG	☒
77	21/10/19 11:53	General View		Load JPG	☒
78	21/10/19 11:53	General View		Load JPG	☒
79	21/10/19 11:54	Reinspection Photo		Load JPG	☒
80	21/10/19 11:54	Reinspection Photo		Load JPG	☒
81	21/10/19 11:54	Reinspection Photo		Load JPG	☒
82	21/10/19 11:54	Reinspection Photo		Load JPG	☒
83	21/10/19 11:54	Reinspection Photo		Load JPG	☒
84	21/10/19 11:54	Reinspection Photo		Load JPG	☒
85	21/10/19 11:54	Reinspection Photo		Load JPG	☒
86	21/10/19 11:54	Reinspection Photo		Load JPG	☒
87	21/10/19 11:54	Reinspection Photo		Load JPG	☒
88	21/10/19 11:54	Reinspection Photo		Load JPG	☒
89	21/10/19 11:54	Reinspection Photo		Load JPG	☒
90	21/10/19 11:54	Reinspection Photo		Load JPG	☒
91	21/10/19 11:54	Reinspection Photo		Load JPG	☒
92	21/10/19 11:54	Reinspection Photo		Load JPG	☒
93	21/10/19 11:54	Reinspection Photo		Load JPG	☒
94	21/10/19 11:54	Reinspection Photo		Load JPG	☒
95	21/10/19 11:54	Reinspection Photo		Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
97	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
98	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
99	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
100	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
101	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
102	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
103	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
104	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
105	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
106	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
107	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
108	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
109	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
110	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
111	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
112	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
113	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
114	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
115	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
116	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
117	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
118	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
119	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
120	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
121	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
122	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
123	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
124	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
125	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
126	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
127	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
128	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
129	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
130	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
131	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
132	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
133	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
134	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
135	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
136	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
137	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
138	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
139	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
140	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
141	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
142	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
143	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
144	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
145	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
146	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
147	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
148	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
149	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
150	21/10/19 11:54	Reinspection Photo	 Load JPG	☒
151	21/10/19 11:54	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
152	21/10/19 11:54	Reinspection Photo		☒
153	21/10/19 11:54	Reinspection Photo		☒
154	21/10/19 11:54	Reinspection Photo		☒
155	21/10/19 11:54	Reinspection Photo		☒
156	21/10/19 11:54	Reinspection Photo		☒
157	21/10/19 11:54	Reinspection Photo		☒
158	21/10/19 11:54	Reinspection Photo		☒
159	21/10/19 11:54	Reinspection Photo		☒
160	21/10/19 11:54	Reinspection Photo		☒
161	21/10/19 11:54	Reinspection Photo		☒
162	21/10/19 11:54	Reinspection Photo		☒
163	21/10/19 11:54	Reinspection Photo		☒
164	21/10/19 11:54	Reinspection Photo		☒
165	21/10/19 11:54	Reinspection Photo		☒
166	21/10/19 11:54	Reinspection Photo		☒
167	21/10/19 11:54	Reinspection Photo		☒
168	21/10/19 11:54	Reinspection Photo		☒
169	21/10/19 11:54	Reinspection Photo		☒
170	21/10/19 11:54	Reinspection Photo		☒
171	21/10/19 11:54	Reinspection Photo		☒
172	21/10/19 11:54	Reinspection Photo		☒
173	21/10/19 11:54	Reinspection Photo		☒
174	21/10/19 11:54	Reinspection Photo		☒
175	21/10/19 11:54	Reinspection Photo		☒
176	21/10/19 11:54	Reinspection Photo		☒
177	21/10/19 11:54	Reinspection Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/04/19 19:42	TP ESTIMATE + DOCS		☐
2	22/04/19 19:42	TP GIA REPORT		☐
3	24/04/19 11:20	TP ESTIMATE - MARKED		☐
4	29/04/19 13:35	EMAIL TO OI		☐
5	23/10/19 11:18	Email from TP workshop breakdown		☐
6	23/10/19 11:37	Email from LKK to AIG - breakdown on LOU and LOR		☐
7	14/11/19 10:52	WORKSHOP INVOICE		☐
8	14/11/19 10:52	AUTHORISATION TO ACT FORM		☐
9	14/11/19 10:52	Release Voucher		☐
10	14/11/19 10:52	RENTAL RECEIPT		☐
11	14/11/19 10:52	GIA SEARCH		☐
12	14/11/19 10:52	LOD		☐
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	23/04/19 10:48	OI GIA REPORT		☐

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLW1704H (Insd veh)	Model:	BMW I3 647CC (A)
	SKU7972H (TP veh)		
Date of Accident:	16/04/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	53,151.54
Final Repair Cost	:	\$	42,516.44
Loss of Use	:	\$	1,140.00
Rental (if any)	:	\$	1,572.90
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	45,231.34

19.00 days at \$60.00 per day
21 days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/~~No~~ BOLA Scenario No: _____
 28
 BOLA Liability: _____ 100 (%) Assessed Liability (*): _____ 100 (%)
** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 45,231.34
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

14 Nov
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
 Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19007078/T1KA3Q2

Date: 14/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800009811
 Claimant Vehicle No : SKU7972H Insured Vehicle No : SLW1704H
 Date of Loss: 16/04/2019 Nature of Claim: TP Claim No: 5624666040SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU7972H**
 Make & Model: BMW I3, 647cc (A) Engine No: 1814009415W20K06A
 Reg. Date: 18/08/2015 (Man. Year: 2014) Chassis No: WBY1Z42060V247314
 Colour: Orange/Black Odometer: 81217 km
 Engine Capacity: 647 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/60 R19 Rear Tyre Size: 175/60 R19
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,170.34	15,822.99	7,347.35	31.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	26,504.00	23,912.00	2,592.00	9.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	49,674.34	39,734.99	9,939.35	20.01
+ GST 7.00/7.00% (S\$)	3,477.20	2,781.45	695.75	20.01
Nett Amount (S\$)	53,151.54	42,516.44	10,635.10	20.01
+ Loss of Use (19.0 x S\$60.00/day) (S\$)		1,140.00		
+ Car Rental (21.0 x S\$70.00/day + 7.00% GST) (S\$)		1,572.90		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		45,231.34		

INSPECTION

Date of Assignment: 18/04/2019
 Date Inspected: 18/04/2019 Inspected At: Performance Motors Limited
 (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941

Estimated Period of Repair: 30.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT AND REAR EMBOSS NUMBER PLATE	Bent	140.00 FS	*83.00 FS
2	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
3	10		*C CLIP FOR PLASTIC NUT	Necessary	10.00 FS	*10.00 FS
4	1		*TAILGATE WITH REAR WINDOW	Cracked	1,570.85 FS	*1,570.85 FS
5	1		*FASTENING SET REAR LID TRIM PANEL	Not Necessary	35.85 FS	*- FS
6	1		*COVER BUMPER FRT	Deformed	153.00 FS	*153.00 FS
7	1		*TRIM BUMPER FRT LH	Cut	56.25 FS	*56.25 FS
8	1		*TRIM BUMPER FRT RH	Not Necessary	56.25 FS	*- FS
9	1		*FRT BUMPER TOP CARRIER	Bent	390.55 FS	*390.55 FS
10	1		*FRT LH DEFORMATION ELEMENT	Deformed	105.15 FS	*105.15 FS
11	1		*FRT RH DEFORMATION ELEMENT	Deformed	105.15 FS	*105.15 FS
12	1		*FRT BUMPER BOTTOM CARRIER	Not Necessary	138.20 FS	*- FS
13	1		*FRONT SHOCK ABSORBER	Deformed	31.70 FS	*31.70 FS
14	1		*FRT LH BOTTOM DEFORMATION EMBLEM	Not Necessary	89.25 FS	*- FS
15	1		*FRT RH BOTTOM DEFORMATION EMBLEM	Not Necessary	89.25 FS	*- FS
16	1		*INSERT AIR INLET MIDDLE	Deformed	106.65 FS	*106.65 FS
17	1		*FRONT BUMPER PANEL PRIMED	Cracked	719.10 FS	*719.10 FS
18	1		*COVER TOWING EYE FRT PRIMED	Not Necessary	42.85 FS	*- FS
19	1		*GUIDE	Deformed	70.15 FS	*70.15 FS
20	1		*REAR BUMPER CARRIER	Not Necessary	282.90 FS	*- FS
21	1		*CENTRE BRACKET BUMPER	Deformed	67.15 FS	*67.15 FS
22	1		*HOLDER AERIAL	Deformed	25.65 FS	*25.65 FS
23	1		*REAR BUMPER TRIM PANEL	Deformed	879.25 FS	*879.25 FS
24	1		*REAR BUMPER COVER PRIMED	Deformed	143.40 FS	*143.40 FS
25	1		*DEFORMATION ELEMENT LH	Not Necessary	119.70 FS	*- FS
26	1		*DEFORMATION ELEMENT RH	Not Necessary	119.70 FS	*- FS
27	1		*GRILLE FRT LH (BLUE)	Cut	80.00 FS	*80.00 FS
28	1		*GRILLE FRT RH (BLUE)	Cut	80.00 FS	*80.00 FS
29	1		*REAR BMW BADGE	Necessary	71.25 FS	*71.25 FS
30	1		*LETTERING I3	Necessary	46.30 FS	*46.30 FS
31	1		*LETTERING E DRIVE	Necessary	96.15 FS	*96.15 FS
32	1		*HOLDER FOR EMBLEM	Necessary	31.00 FS	*31.00 FS
33	2		*GAS PRESSURIZED SPRING HOOD	Not Necessary	248.00 FS	*- FS
34	1		*BONNET LH HINGE	Bent	70.80 FS	*70.80 FS
35	1		*BONNET RH HINGE	Bent	70.80 FS	*70.80 FS
36	1		*BMW EMBLEM	Necessary	71.25 FS	*71.25 FS
37	1		*BONNET	Distorted	652.75 FS	*652.75 FS
38	1		*TRUNK LID LOCK	Not Necessary	159.60 FS	*- FS
39	1		*STRIKER TRUNK LID	Not Necessary	58.25 FS	*- FS
40	1		*FRT LH BOTTOM STRUT	Not Necessary	26.70 FS	*- FS
41	1		*FRT RH BOTTOM STRUT	Not Necessary	26.70 FS	*- FS
42	1		*FRONT STORAGE COMPARTMENT	Not Necessary	154.35 FS	*- FS
43	1		*AIR DUCT CENTRE FRT	Not Necessary	106.20 FS	*- FS
44	1		*AIR DUCT MIDDLE LOWER SECTION	Not Necessary	106.20 FS	*- FS
45	1		*AIR DUCT	Deformed	111.50 FS	*111.50 FS
46	1		*AIR DUCT SERVICE CAP	Not Necessary	53.10 FS	*- FS
47	1		*TOP LEFT COVER	Not Necessary	45.95 FS	*- FS
48	1		*COVER ,UPPER	Not Necessary	48.05 FS	*- FS
49	1		*TRUNK LID GASKET	Not Necessary	177.80 FS	*- FS
50	1		*HEADLIGHT BUMPER LH	Cracked	243.85 FS	*243.85 FS
51	1		*HEADLIGHT BUMPER RH	Cracked	243.85 FS	*243.85 FS
52	1		*LH HEADLIGHT LED TECHNOLOGY	Cracked	2,641.50 FS	*2,641.50 FS
53	1		*RH HEADLIGHT LED TECHNOLOGY	Not Necessary	2,641.50 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*REAR LIGHT BUMPER LH	Cracked	243.50 FS	*243.50 FS
55	1		*REAR LIGHT BUMPER RH	Cracked	243.50 FS	*243.50 FS
56	1		*PRINT CIRC ,BOARD REAR LID L	Not Necessary	237.20 FS	*- FS
57	1		*PRINT CIRC ,BOARD REAR LID L	Not Necessary	237.20 FS	*- FS
58	2		*NUMBER PLATE LIGHT LED	Missing	50.00 FS	*50.00 FS
59	1		*CONDENSER AIR CONDITIONING	Bent	1,028.45 FS	*1,028.45 FS
60	8		*ULTRASONIC SENSOR BLACK	Not Necessary	1,989.60 FS	*- FS
61	8		*DECOUPING RING PDC TORQUE CONVERTER	Necessary	40.40 FS	*40.40 FS
62	1		*REVERSING CAMERA	Missing	718.40 FS	*718.40 FS
63	2		*SCREW THERMOPLASTIC	Necessary	7.40 FS	*7.40 FS
64	10		*HEX BOLT	Necessary	14.50 FS	*14.50 FS
65	2		*ASA BOLT M12X80	Necessary	31.10 FS	*31.10 FS
66	2		*COLLAR BOLT WITH COMPRESSION SPRING	Necessary	36.30 FS	*36.30 FS
67	1		*3M S/F PREMIUM REAR WINDSCREEN	Necessary	252.34 FS	*252.34 FS
68	1		*TAIL PANEL	Cracked	159.45 FS	*159.45 FS
69	1		*CROSS MEMBER TRUNK FLOOR BOTTOM	Bent	948.15 FS	*948.15 FS
70	1		*CROSS MEMBER REAR TOP	Bent	163.20 FS	*163.20 FS
71	1		*REINFORCEMENT PLATE CROSSMEMBER MID	Bent	113.20 FS	*113.20 FS
72	1		*LH REINFORCEMENT PLATE CROSS MEMBER	Bent	145.50 FS	*145.50 FS
73	1		*RH REINFORCEMENT PLATE CROSS MEMBER	Bent	145.50 FS	*145.50 FS
74	2		*FOAM BELT	Necessary	60.20 FS	*60.20 FS
75	1		*COUNTER SUPPORT REAR VIEW CAMERA	Distorted	8.50 FS	*8.50 FS
76	1		*LH COLUMN A COVER	Deformed	118.30 FS	*118.30 FS
77	1		*RH COLUMN A COVER	Deformed	118.30 FS	*118.30 FS
78	20		*ROOF FRAME STRIP CLIP	Deformed	96.00 FS	*96.00 FS
79	1		*FRONT PANEL	Deformed	287.25 FS	*287.25 FS
80	1		*RR ENGINE COMPARTMENT SHIELDING	Distorted	259.65 FS	*259.65 FS
81	1		*REAR REPAIR CABLE	Distorted	408.20 FS	*408.20 FS
82	1		*BUSHING CONTACT NANOMQS 0.22-0.35MM	Necessary	2.60 FS	*2.60 FS
83	7		*BUSHING CONTACT NANOMQS 0.22-0.35MM	Necessary	18.20 FS	*18.20 FS
84	1		*SOCKET HOUSING	Distorted	25.70 FS	*25.70 FS
85	1		*LABEL COOLANT 750+/-10G	Necessary	23.25 FS	*23.25 FS
86	1		*(S/L) CLEANER R2 500ML	Necessary	12.50 FS	*12.50 FS
87	1		*(SL/DG) BODY ADHESIVE K2 (2X290ML)	Necessary	676.15 FS	*676.15 FS
88	1		*(DG/SL) REFRIGERANT OIL SANDEN 250ML	Necessary	169.20 FS	*169.20 FS
89	1		*(S/L) ANTI FREEZE 1.5 LITRES	Necessary	20.10 FS	*20.10 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **23,170.34** **15,822.99**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT & REAR BUMPER & ATTACHMENTS ,BONNET ,BOOT LID ,FRONT CENTER AIR INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	5,950.00	5,100.00
2	TO RESPRAY FRONT BUMPER ,REAR BUMPER AND BONNET	New	3,374.00	3,036.00
3	TO REPLACE AIR CON CONDENSER INCLUDING TO VACUUM SYSTEM,TOP UP FREON GAS AND CHECK FOR LEAK	New	1,003.00	852.00
4	TO REPLACE LEFT HEADLIGHT	New	481.00	408.00
5	TO REPLACE RIGHT HEADLIGHT	New	481.00	0.00
6	TO REMOVE AND TRANSFER REAR WINDSCREEN FROM OLD TO NEW BOOT	New	574.00	0.00
7	TO TRSFER LOCK MECHANISM FROM OLD TO NEW BOOT LID INCLUDE CONDUCTING CHECKS ON NEW BOOT LID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
8	TO CHECK ELECTRICAL WIRING SYSTEM OF THE FRONT AND REAR SECTION FOR PROPER FUNCTION INCLUDING TO AIM HEADLIGHTS	New	295.00	250.00
9	TO REMOVE AND INSTALL BATTERY TO FACILITATE REPAIRS ,PERFORM HIGH CURRENT TEST AND CHARGE UP BATTERY	New	451.00	451.00
10	TO REMOVE AND INSTALL COMPLETE ELECTRICAL MECHINE WITH REAR AXLE TO FACILITATE REPAIRS INCLUDE CONDUCTING TESTS FOR PROPER FUNCTION	New	2,000.00	2,000.00
11	TO REPLACE FRONT PDC WIRE HARNESS SET INCLUDE RESETING AND CONDUCTING CHECKS FOR PROPER FUNCTION	New	360.00	360.00
12	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
13	TO REPLACE REAR REVERSING CAMERA INCLUDE PROGRAMMING AND CONDUCTING CHECKS FOR PROPER FUNCTION	New	266.00	266.00
14	TO REMOVE AND INSTALL RADIATOR ASSEMBLY TO FACILITATE REPAIRS INCLUDE PRESSURE TESTS ,BLEED COOLING SYSTEM AND CONDUCTING CHECKS FOR LEAK	New	673.00	673.00
15	TO REMOVE INSTALL CHARGING POWER SOCKET AND INTERFACE MODULE TO FACILITATE REPAIRS INCLUDE PROGRAMMING AND ENCODING CONTROL UNIT AND CONDUCTING CHECKS FOR FUNCTION	New	950.00	950.00
16	TO REPLACE TAIL END PANEL ,BOTTOM ,TRUNK FLOOR ,CROSS MEMBER ,REAR TOP CROSS MEMBER ,LH/RH REINFORCEMENT CORSS MEMBER PLATE ,TAILGATE,BONNET AND ATTACHMENTS,FRONT LH/RH DEFORMATION ELEMENT ,LH/RH COLUMN A COVER,FRONT SUPPORT PANEL ,FRONT AIR DUCT ,REAR ENGINE COMPARTMENT SHIELDING ,LH/RH HEADLIGHT BUMPER ,REAR LH/RH LIGHT BUMPER INCLUDE MAKING GOOD THE LH ROOF FRAME TRIM PANEL AND }	New	8,500.00	8,500.00
17	KNOCKING OUT DENTS CAUSED BY THE ACCIDENT }	New	0.00	0.00
18	TO RESPRAY LH ROOF FRAME TRIM PANEL	New	540.00	540.00
Gross Labour Cost (\$\$)			26,504.00	23,912.00

Report was unsubmitted during this print-out.

No	Particulars	Lab.Type	Repairer's	Amount
Report was unsubmitted during this print-out.				

< END OF ESTIMATES >