

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: MC/MC12006/2018 Date: 13th May 2019

Our Ref: CS1/LAW19007101/Usd3s2

M/s ComLaw LLC

64 Cecil Street #06-01 IOB Building Singapore 049711

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJT 5443Z INSURED VEHICLE: SJY 9376G ACCIDENT DATE: 20/10/2017

We thank you for your instruction on 17/04/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJT 5443Z from M/s Premier Appraiser Services.
- b) Survey report by FormTeam Consultancy Pte Ltd with colour photographs.
- c) Final Repair Bill of SJT 5443Z from M/s Precise Auto Service.
- d) Singapore Accident Statement of Vehicles SJT 5443Z and SJY 9376G.
- e) Colour damaged vehicle photographs of SJT 5443Z.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SJT 5443Z Make & Model : B.M.W. 320I Year of Registration : 2009

Chassis Number : WBAPG56000NM17505

Engine Capacity : 1995 cc

- We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.