

23/03/2018

ASS. REC. BY:

REF: CS3/LPC18018014/Usd302-1 Instruction:

Surveyor

MARCUS

ASSIGNMENT (Office)

From (Person):

Ong Hi Hi

of

LPC

Date/Time:

4/10/18 @ 12:58pm

Estimated Cost:

Bill to:

OD ☒ TP AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD1215C

Insured:

SJK 4944Z

at Workshop m/s:

Precise Auto

Tel:

6745 7367

of

1 Kaki Bkt Ave 6 # 02-34

Policy No:

Claim No:

17/18/18 / VP05 / 020982

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

4/10/18

CA / REV / REP. / REV 24 HRS ^{up}

H.O.D. Endorsement:

Date/Time:

3pm @ 4/10/18

Person Contacted:

Aine

Vehicle

☒ IN / OUT

Date/Time

Action/Instruction (X) Estimate

SLD1215C - X

SJK 4944Z - CS3/LPC17013292/Kvbe2-1

DOA: 5/7/17

Submit PRS report.

26/4/19

10k

10 day

confund 1/5 \$10,000 10 day with yshong
(\$3,000/- Rd - 23%)

26/4/2019

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val. Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Date/Time. File Pass to?

1)

Date/Time. File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$)

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS \$

) Phone

) Others

TOTAL

450

Veh No: SLD1215C Yr Regn: 6110

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 10 OCT 2018

CHARTERED AUTO ASSESSORS

17 Joo Seng Road #08-129 Joo Seng Heights Singapore 360017 Reg No. 26910200X
Tel: +65 9631 7008 Fax: +65 6281 9989 Email: charteredauto@gmail.com

BKW Rent-A-Car Private Limited
120 Lower Delta Road
#02-15 Cendex Centre
Singapore 169208

Your Ref : SLD 1215 C
Our Ref : 201810232/CA
Date : 24 February, 2019
Survey : Third Party

SURVEY REPORT

PARTICULARS OF VEHICLE

Vehicle No.	: SLD 1215 C	Propellant	: Petrol, Auto
Make	: Hyundai	Capacity	: 1600 cc
Type of Body	: 4 Doors Saloon	Mileage	: 46711
Year & Model	: 2016, Elantra	Engine No	: G4FGGU189846
Colour	: Silver	Chassis No	: KMHD841CMHU195703
Passenger-cap	: 4	Road Tax	: December, 2018

TYRES CONDITIONS

Front Left	: Hankook	Worn	: 30%	Size	: 195/65 R15
Front Right	: Hankook	Worn	: 30%	Size	: 195/65 R15
Rear Left	: Luxotik	Worn	: 30%	Size	: 195/65 R15
Rear Right	: Hankook	Worn	: 30%	Size	: 195/65 R15

PRE-ACCIDENT CONDITION (Static Test Only)

Handbrake	: Serviceable	Steering	: Serviceable
Footbrake	: Serviceable	Paintwork	: Good

QUANTUM

Repair Estimate : \$ 19,344.60
Revised Amount : \$ 13,000.00 (Lump-sum Without Prejudice)

Under normal circumstances, the repair period would be: **twelve (12)** days.
We have not authorised repairs.

Survey Done At : Precise Auto Service
1 Kaki Bukit Avenue 6, #02-34/36
Autobay @ Kaki Bukit
Singapore, 417883

Assignment Date : 05 October, 2018
Survey Date : 05 October, 2018
Accident Date : 04 October, 2018
Assignment Given By : BKW Rent-A-Car Private Limited

Our Ref: 201810232/CA

Vehicle No. SLD 1215 C

Description	Qty	Repair Estimate	Revised Amount	Remarks
Front bumper fascia	1 <i>Torn</i>	659.40	659.40	Torn/Deformed ✓
Front bumper side retainer	2 <i>11</i>	112.20	112.20	To replace X
Front bumper fog lamp garnish	2 <i>Tw</i>	139.80	139.80	Holder Broken ✓
Front bumper reinforcement	1 <i>Bent</i>	429.80	429.80	Bent ✓
Front bumper lower beam	1 <i>11</i>	245.00	245.00	Bent X
Front bumper sponge	1 <i>Torn</i>	149.50	149.50	Torn/Deformed ✓
Front bumper clip	10 <i>all</i>	50.00	50.00	To replace ✓
Front bumper inner bracket	2 <i>Bent</i>	139.40	139.40	To replace ✓
Front bumper number plate plinth	1 <i>Re</i>	54.10	54.10	Bent/Deformed ✓
Front grille	1 <i>cr</i>	460.20	460.20	Broken ✓
Front grille clip	6 <i>all</i>	30.00	30.00	To replace ✓
Front grille emblem	1 <i>all</i>	45.00	45.00	To replace ✓
Front grille inner bracket	2 <i>all</i>	75.20	75.20	Bent X
Headlamp n/s	1 <i>cr</i>	1,198.00	1,198.00	Broken ✓
Headlamp lower bracket n/s	1 <i>11</i>	48.10	48.10	To replace X
Front support panel	1 <i>cr</i>	821.40	821.40	Bent/Broken ✓
Front support panel top garnish	1 <i>Torn</i>	107.40	107.40	Torn/Deformed ✓
Front support panel top garnish clip	6 <i>11</i>	30.00	30.00	To replace X
Rear bootlid	1 <i>Bent</i>	1,147.50	1,147.50	Bent ✓
Rear bootlid lock	1 <i>Tw</i>	199.30	199.30	Bent ✓
Rear bootlid lock striker	1 <i>11</i>	42.10	42.10	Bent X
Rear bootlid rubber stopper	2 <i>11</i>	24.00	24.00	To replace X
Rear bootlid weatherstrip	1 <i>Tw</i>	186.70	186.70	Torn/Deformed ✓
Rear bootlid LOGO emblem	1 <i>all</i>	49.10	49.10	To replace ✓
Rear bootlid ELANTRA emblem	1 <i>all</i>	55.00	55.00	To replace ✓
Rear bootlid GLS emblem	1 <i>all</i>	41.20	41.20	To replace ✓
Rear bootlid outer keyless sensor	1 <i>11</i>	175.40	175.40	Malfunctioned X
Rear bumper fascia	1 <i>D.S</i>	654.80	654.80	Torn/Deformed ✓
Rear bumper side retainer	2 <i>Bent</i>	99.40	99.40	To replace ✓
Rear bumper reinforcement	1 <i>D.S</i>	386.90	386.90	Bent ✓
Rear bumper reinforcement bracket	2 <i>Bent</i>	158.80	158.80	Bent ✓
Rear bumper upper bracket	2 <i>all</i>	94.20	94.20	To replace ✓
Rear bumper clip	10 <i>all</i>	50.00	50.00	To replace ✓
Rear bumper lower diffuser	1 <i>D.S</i>	362.50	362.50	Torn/Deformed ✓
Rear bumper side reflector	2 <i>cr</i>	92.20	92.20	Cracked/Missing ✓
Rear bumper lower side dust cover n/s	1 <i>Torn</i>	79.40	79.40	Torn/Deformed ✓
Rear bumper lower side dust cover clip n/s	6 <i>all</i>	30.00	30.00	To replace ✓
Taillamp assy	2 <i>cr</i>	988.40	988.40	Grazed/Broken ✓
Taillamp clip	2 <i>11</i>	10.00	10.00	To replace X

Page Total :

9,721.40

9,721.40

Our Ref: 201810232/CA

Vehicle No. SLD 1215 C

Description	Qty	Repair Estimate	Revised Amount	Remarks
Balance brought forward		9,721.40	9,721.40	
Rear end panel	1	574.90 DD	574.90	Badly Dented ✓
Rear end panel top trim	1	141.80 TWI	141.80	Torn/Deformed ✓
Rear end panel top trim clip	6	30.00 11	30.00	To replace X
Rear exhaust silencer	1	596.10 R	596.10	Bent X
Rear exhaust silencer hook	2	72.20 11	72.20	To replace X
Rear trunk panel board	1	574.20 11	574.20	Torn/Deformed X
Rear trunk panel insulation cloth	1 set	299.80 11	299.80	To replace X
Rear fender inner trimboard	2	890.20 DE	890.20	Torn/Deformed ✓
Rear fender inner trimboard clip	12	60.00 11	60.00	To replace X
		12,960.60	12,960.60	
		-	2,592.12	Less 20%
		12,960.60	10,368.48	

SPECIAL NETT

Rear number plate (emboss)	1 11	29.00	29.00	Grazed/Bent X
Rear number plate casing	1 11	45.00	45.00	Damaged X
Rear bumper reverse sensor c/w control box	1 11	380.00	380.00	Damaged 200

10566.3
845304

Total Materials Cost :	13,414.60	10,822.48
-------------------------------	------------------	------------------

Labour & Miscellaneous Charges

To provide towing service.	80.00	70.00 60
To set vehicle on chassis alignment bench, inclusive of all necessary preparatory works.	380.00 11	320.00 X
To apply underseal and rust-proofing on the front and rear affected areas.	250.00	220.00 80
To remove/refit exhaust assembly with all attachments, brackets and holders.		
To straighten and align centre exhaust pipe.	280.00	250.00 60

Page Total:	14,404.60	11,682.48
--------------------	------------------	------------------

Our Ref: 201810232/CA

Vehicle No. SLD 1215 C

Description	Qty	Repair Estimate	Revised Amount	Remarks
Balance brought forward		14,404.60	11,682.48	
To remove/refit front and rear wire harness, all related connectors. Check proper function. Focus headlights.		180.00	150.00	30
To remove/refit boot garnishes, speakers, interior garnishes, carpets where necessary.		180.00	150.00	80
To transfer trunklid mechanisms and all attachments.		180.00	120.00	60
To install reverse sensors, control unit. Re-connect wires harness. Check function.		180.00	150.00	50
To remove/refit radiator assembly with all connecting hoses. Replenish cooling agent and check for proper function (include coolant).		200.00	180.00	100
To remove/refit air-con condenser with all necessary pipes and hoses. Vacuum and replenish cooling agent. Check for proper function.		220.00	180.00	
To putty and spray paint front bumper, both front fenders, rear bumper, rear bootlid, rear panel, rear trunk panel, both rear fenders and etc., inclusive of preparatory works and painting materials.		2,000.00	1,800.00	✓
To remove all damaged parts with all necessary components/attachments. To apply hot-works where necessary, straighten chassis members, repair/reshape dented body panels, in accordance with factory specifications. Replace damaged parts, refit and align into position. Refit all necessary components/attachments.		1,800.00	1,600.00	✓

Grand Total:

19,344.60

16,012.48

4120
12573
10058

Summary

Total Material	13,414.60	10,822.48
Total Labour/Painting	5,930.00	5,190.00
Grand Total	19,344.60	16,012.48
Lump-sum Amount		<u>13,000.00</u>

Our Ref: 201810232/CA

Vehicle No. SLD 1215 C

CAUSE OF DAMAGE

The vehicle sustained impact to the rear and front.

REMARKS

Having checked the scope of repair works we were satisfied that it was in accordance with the damage sustained. We also checked each item and have indicated its nature of damage. It was our opinion that these items were found damaged beyond repair and require replacement.

We checked the damage carefully and were of the opinion that the vehicle could be repaired.
We would therefore recommend repairs to be carried out at: **\$ 13,000.00** on a lump-sum basis.

The survey was conducted on a without prejudice basis and we submit this report for your consideration.

CHARTERED AUTO ASSESSORS



Tan Chin Suan (Licensed Appraiser)
A.M.I.M.L. T Eng (CEI) A.L.L.M. (U.K)

MSME18120030 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 04/10/2018 17:41
SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 04/10/2018 17:41
Date Of Accident 04/10/2018 08:00
Exact Location Of Accident ALONG KPE TWDS MCE (BEFORE KPE TUNNEL)
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLD1215C
Insured/Policyholder
Name Of Registered Owner BKW RENT-A-CAR PTE LTD
Co Reg No 200106276D
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-67387777
Vehicle Particulars
Manufacturer HYUNDAI
Model ELANTRA
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 999994892/100783995-00000
Cover Note Number
Driver
Name of Driver LIM ZIJIE
NRIC No S8433577J
Date Of Birth 05/11/1984
Occupation INDOOR
Date Of Driving Pass 30/12/2005
Driving Experience 12 YEARS AND 9 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-90062311
Fax Number
Contact Number
EMail Address NOEMAIL

Address BLK 666A PUNGGOL DRIVE #16-548
 Postcode 821666
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : XIE MEILAN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 04/10/2018 AT ABOUT 080HRS, I WAS DRIVING MY CAR (SLD1215C) ALONG KPE TOWARDS MCE IN THE EXTREME RIGHT LANE (BEFORE KPE TUNNEL) WITH ONE PASSENGER (MY WIFE). VEHICLE IN FRONT OF ME STOP SO I SLOW DOWN AND STOP IN TIME TOO. SUDDENLY, I FELT AN IMPACT FROM BEHIND AND DUE TO HUGE IMPACT, MY CAR BEING PUSHED FORWARD AND HIT ONTO THE REAR PORTION OF VEHICLE IN FRONT OF ME. WHEN I CAME OUT TO INSPECT MY CAR, I REALISED THAT I WAS INVOLVED IN A 3 CARS CHAIN COLLISION. HENCE, I HERE TO LODGE THIS REPORT TO CLAIM AGAINST VEHICLE B (SJK4944Z)'S INSURANCE FOR MY ACCIDENT DAMAGES. ME AND MY PASSENGER WILL GO TO SEE DOCTOR IF FEEL ANY UNCOMFORTABLE AFTER THIS.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJK4944Z
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver ISHAK BIN MOHAMED SALLEH
 NRIC/Passport Number
 Contact Number 91730227
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJL4961T

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE C

Vehicle Category

PRIVATE CAR

Name of Driver

LEONG TAK CHOI

NRIC/Passport Number

S2005707F

Contact Number

97354218

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

XIE MEILAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLD1215C

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Tuesday, 23 April 2019 10:43 AM
To: assignments
Cc: Admin A
Subject: FW: SKW8933D claim against PA928D _ DOA 20.04.2019 _ (AIG / AXA)
Attachments: SKW8933D.pdf

11.44am @ 23/4/19
person @ Andrew
Vehicle

****SMARTCLAIM NEWCASE****

KINDLY ARRANGE SURVEY

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CDGE Braddell Private Cars Crash Repair Operation <braddell_operation@sparkcarcare.com>
Sent: Monday, 22 April 2019 4:16 PM
To: LOW Garnet <garnet.low@axa.com.sg>; NGUETTE Kadi <kadidiatou.nguette@axa.com.sg>; SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Cc: Denis Teo Chin Chye <denisteo@sparkcarcare.com>
Subject: SKW8933D claim against PA928D _ DOA 20.04.2019 _ (AIG / AXA)

Dear Sir / Madam

Please advice on the liability of the accident.

Your insured vehicle number PA928D.

And to arrange survey the car at CDGE, Braddell.

Andrew

Best Regards

External Business | ComfortDelGro Engineering Pte Ltd

Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767

www.SPARKcarcare.com

Nivitha (LKK Auto)

From: Claims <claims@crownasia.com.sg>
Sent: Tuesday, 23 April 2019 9:44 AM
To: 'Mei Kwan (LKKAuto)'
Cc: 'CS A Team'; 'Admin A'; 'Joy Irene (LKKAuto)'; 'assignments'
Subject: RE: Acknowledgement Your ref : PC9122S Our ref : S9M01KGFMC/KC *** LKK REF: CC4/ASM19007067/ja3
Attachments: PC9122S GIA.pdf

Dear Mei Kwan,

Please find the clear copy of GIA report and could you help me to arrange the survey on tomorrow between 0900-1100 ?

Thanks and Best Regards,
Jayden



Crown Asia Bus Builder Pte Ltd
Tel: 6966 9995 / 6996 9995 Fax: 6469 4319
Email: jayden@crownasia.com.sg
44 Sungei Kadut Ave, Singapore 729667

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Monday, 22 April, 2019 6:07 PM
To: Claims <claims@crownasia.com.sg>
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: Acknowledgement Your ref : PC9122S Our ref : S9M01KGFMC/KC *** LKK REF: CC4/ASM19007067/ja3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to our tele-conversation last Thursday.

As spoken, OI has yet to report the accident and we are currently **pending verification for direct settlement.**

Please provide us the following and arrange for TP survey.

- evidence i.e. video/ scene photo
- estimated cost of repair
- GIA report (clear copy)

Please note that for liability, claim negotiation and settlement, please contact Joy at 6841 2409.

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Nivitha (LKK Auto)

From: Mars Ler <mars.ler@ccfulco.com.sg>
Sent: Tuesday, 23 April 2019 9:50 AM
To: 'admin-a@lkkauto.com'
Cc: assignments (assignments@lkkauto.com); Chris Bulaclac; Renemer Bagang
Subject: Re:Accident On 16/04/2019 Involving Our Insured SMA7772A And Your Insured SLF7824U
Attachments: SMA7772A.pdf

Dear Motor Claims ,

Our client is looking to make a claim against your insurer for property damage caused to her vehicle.

Please confirm if your insurance company is prepared to engage in a direct settlement for property damage only.

This settlement excludes out client's right to recover further loss arising from rental of alternative / replacement vehicle.

As our client requires the use of a vehicle during this period that her vehicle is in our workshop, our client has will rented a vehicle and will be looking towards your company to make good her loss/rental cost.

Please confirm that you understand that any direct settlement reached for the cost of repairs to our client's vehicle does not prejudice her rights to recover any other damages he has suffered.

Please arrange for survey on 26/04/2019 Friday 02.00pm .

Thank You,

Thank you,

Best regards

Mars Ler
B & P Service Advisor
Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3 Singapore 408650
D/D 65949163 H/P 91792566

Nivitha (LKK Auto)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Monday, 22 April 2019 11:51 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims; Joanne Yong Lai fong
Subject: REQUEST OF SURVEY REPORT-OUR REF:D16010205MFSH;ACCIDENT INVOLVING SHD3997M AND PC3663L ON 10-10-2016

Dear Sir,

We received LOD from workshop/solicitor.

Please let us have the **Survey Report including Vehicle Inspection Photos & Survey Fees Invoice** asap.

Kindly upload the survey report through CWS from document management screen by selecting option Survey report.

Thanks & Regards,
Motor Claims Department
MS First Capital Insurance Ltd
cwsmotorclaims@msfirstcapital.com.sg

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 23 April 2019 10:09 AM
To: 'SUR' (sur@lkkauto.com); Admin-D (LKKAuto)
Cc: MT_Claim_SG
Subject: YOUR REF: CS3/LPC18018014/USD3N2 OUR REF: 17/18/18/VP05/020982 [External General]
Attachments: 20982 TPD SURVEY REPORT1.pdf

Lonpac External - General

Dear Sir/Mdm

Attached is the TP survey report (part1), please let us have your surveyor's review/report.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC18018014/Usd3e2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 29-04-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJK 4944Z	Veh. Inspected	SLD 1215C	
Policy No.		Coverage (\$)	0.00	
Claim No.	17/18/18/VP05/020982	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	04/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHD841CMHU195703	Colour	SILVER	
Odometer	46710	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	HANKOOK	6 mm	
L/H Front Tyre	195/65 R15	HANKOOK	6 mm	
R/H Rear Tyre	195/65 R15	HANKOOK	6 mm	
L/H Rear Tyre	195/65 R15	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/10/2018	Inspection Date	04/10/2018	
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 1215C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER FASCIA	TORN	659.40	659.40
2	FRONT BUMPER SIDE RETAINER	NOT NECESSARY	112.20	-
2	FRONT BUMPER FOG LAMP GARNISH	TWISTED	139.80	139.80
1	FRONT BUMPER REINFORCEMENT	BENT	429.80	429.80
1	FRONT BUMPER LOWER BEAM	NOT NECESSARY	245.00	-
1	FRONT BUMPER SPONGE	TORN	149.50	149.50
10	FRONT BUMPER CLIP	NECESSARY	50.00	50.00
2	FRONT BUMPER INNER BRACKET	BENT	139.40	139.40
1	FRONT BUMPER NUMBER PLATE PLINTH	DEFORMED	54.10	54.10
1	FRONT GRILLE	CRACKED	460.20	460.20
6	FRONT GRILLE CLIP	NECESSARY	30.00	30.00
1	FRONT GRILLE EMBLEM	NECESSARY	45.00	45.00
2	FRONT GRILLE INNER BRACKET	NOT NECESSARY	75.20	-
1	HEADLAMP N/S	CRACKED	1,198.00	1,198.00
1	HEADLAMP LOWER BRACKET N/S	NOT NECESSARY	48.10	-
1	FRONT SUPPORT PANEL	CRACKED	821.40	821.40
1	FRONT SUPPORT PANEL TOP GARNISH	TORN	107.40	107.40
6	FRONT SUPPORT PANEL TOP GARNISH CLIP	NOT NECESSARY	30.00	-
1	REAR BOOTLID	BENT	1,147.50	1,147.50
1	REAR BOOTLID LOCK	TWISTED	199.30	199.30
1	REAR BOOTLID LOCK STRIKER	NOT NECESSARY	42.10	-
2	REAR BOOTLID RUBBER STOPPER	NOT NECESSARY	24.00	-
1	REAR BOOTLID WEATHERSTRIP	TWISTED	186.70	186.70
1	REAR BOOTLID LOGO EMBLEM	NECESSARY	49.10	49.10
1	REAR BOOTLID ELANTRA EMBLEM	NECESSARY	55.00	55.00
1	REAR BOOTLID GLS EMBLEM	NECESSARY	41.20	41.20
1	REAR BOOTLID OUTER KEYLESS SENSOR	NOT NECESSARY	175.40	-
1	REAR BUMPER FASCIA	DISTORTED	654.80	654.80
2	REAR BUMPER SIDE RETAINER	BENT	99.40	99.40
1	REAR BUMPER REINFORCEMENT	DISTORTED	386.90	386.90
2	REAR BUMPER REINFORCEMENT BRACKET	BENT	158.80	158.80

Report Ref No. CS3/LPC18018014/Usd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BUMPER UPPER BRACKET	BENT	94.20	94.20
10	REAR BUMPER CLIP	NECESSARY	50.00	50.00
1	REAR BUMPER LOWER DIFFUSER	DISTORTED	362.50	362.50
2	REAR BUMPER SIDE REFLECTOR	CRACKED	92.20	92.20
1	REAR BUMPER LOWER SIDE DUST COVER N/S	TORN	79.40	79.40
6	REAR BUMPER LOWER SIDE DUST COVER CLIP N/S	NECESSARY	30.00	30.00
2	TAILLAMP ASSY	CRACKED	988.40	988.40
2	TAILLAMP CLIP	NOT NECESSARY	10.00	-
1	REAR END PANEL	DENTED	574.90	574.90
1	REAR END PANEL TOP TRIM	TWISTED	141.80	141.80
6	REAR END PANEL TOP TRIM CLIP	NOT NECESSARY	30.00	-
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	596.10	-
2	REAR EXHAUST SILENCER HOOK	NOT NECESSARY	72.20	-
1	REAR TRUNK PANEL BOARD	NOT NECESSARY	574.20	-
1	SET REAR TRUNK PANEL INSULATION CLOTH	NOT NECESSARY	299.80	-
2	REAR FENDER INNER TRIMBOARD	DEFORMED	890.20	890.20
12	REAR FENDER INNER TRIMBOARD CLIP	NOT NECESSARY	60.00	-
	LESS 20% DISCOUNT		-	-2,113.26
			12,960.60	8,453.04
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (EMBOSS) (SN)	NOT NECESSARY	29.00	-
1	REAR NUMBER PLATE CASING (SN)	NOT NECESSARY	45.00	-
1	SET REAR BUMPER REVERSE SENSOR C/W CONTROL BOX (SN)	SHORTED	380.00	200.00
			454.00	200.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.		80.00	60.00
	TO SET VEHICLE ON CHASSIS ALIGNMENT BENCH, INCLUSIVE OF ALL NECESSARY PREPARATORY WORKS.	NOT NECESSARY	380.00	-
	TO APPLY UNDERSEAL AND RUST-PROOFING ON THE FRONT AND REAR AFFECTED AREAS.		250.00	80.00

Report Ref No. CS3/LPC18018014/Usd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE / REFIT EXHAUST ASSEMBLY WITH ALL ATTACHMENTS, BRACKETS AND HOLDERS. TO STRAIGHTEN AND ALIGN CENTRE EXHAUST PIPE.		280.00	60.00
	TO REMOVE / REFIT FRONT AND REAR WIRE HARNESS, ALL RELATED CONNECTORS. CHECK PROPER FUNCTION. FOCUS HEADLIGHTS.		180.00	30.00
	TO REMOVE / REFIT BOOT GARNISHES, SPEAKERS, INTERIOR GARNISHES, CARPETS WHERE NECESSARY.		180.00	80.00
	TO TRANSFER TRUNKLID MECHANISMS AND ALL ATTACHMENTS.		180.00	60.00
	TO INSTALL REVERSE SENSORS. CONTROL UNIT. RE-CONNECT WIRES HARNESS. CHECK FUNCTION.		180.00	50.00
	TO REMOVE / REFIT RADIATOR ASSEMBLY WITH ALL CONNECTING HOSES. REPLENISH COOLING AGENT AND CHECK FOR PROPER FUNCTION (INCLUDE COOLANT). }		200.00	100.00
	TO REMOVE / REFIT AIR-CON CONDENSER WITH ALL NECESSARY PIPES AND HOSES. VACUUM AND REPLENISH COOLING AGENT. CHECK FOR PROPER FUNCTION. }		220.00	-
	TO PUTTY AND SPRAY PAINT FRONT BUMPER, BOTH FRONT FENDERS, REAR BUMPER, REAR BOOTLID, REAR PANEL, REAR TRUNK PANEL, BOTH REAR FENDERS AND ETCs., INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS.		2,000.00	1,800.00
	TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENTS / ATTACHMENTS. TO APPLY HOT-WORKS WHERE NECESSARY, STRAIGHTEN CHASSIS MEMBERS, REPAIR / RESHAPE DENTED BODY PANELS, IN ACCORDANCE WITH FACTORY SPECIFICATIONS. REPLACE DAMAGED PARTS, REFIT AND ALIGN INTO POSITION. REFIT ALL NECESSARY COMPONENTS / ATTACHMENTS. INCLUSIVE OF THE REPAIR OF REAR EXHAUST SILENCER.		1,800.00	1,600.00
			-	-
			-	-
			5,930.00	3,920.00
GRAND TOTAL			19,344.60	12,573.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,000.00

Report Ref No. CS3/LPC18018014/Usd3e2-1



Report Ref No. CS3/LPC18018014/Usd3e2-1

A handwritten signature in black ink, appearing to be 'Ch' followed by a stylized flourish.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.