

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:
 Assessment number: YN3199X - OD MSIG
 Version: 1810
 Date calculated: 04/22/2019 03:19 PM

Full Report
 Registration: YN3199X
 Printed: 22/04/2019 3:19 PM

Extras

Code	Description	Price SGD
1000	FRT NUMBER PLATE ✓	20.00*
1003	ERP BRACKET - ✓	26.00*
1004	DIAGNOSE & RESET FAULT CODE ✓	180.00*
Total Extras		226.00

Final Calculation

	SGD	SGD
Parts	12,084.00	
Addition(+10.00%)	1,208.40	
Total Parts		13,292.40
Labour Time Base 10 WU/h		
Total 235.0 WU X 50.00 SGD/h	1,175.00	
Total of Labour		1,175.00
Total Of Extras		226.00
Paint Work Time Base 10 WU/h		
Labour Cost 98.0 WU X 50.00 SGD/h	490.00	
Material Cost	173.40	
Total Paint Including Material		663.40
Repair Cost Excludes GST		15,356.80
GST (+7.0%)		1,074.98
Repair Cost Included GST		16,431.78

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:
Assessment number: YN3199X - OD MSIG
Version: 1810
Date calculated: 13/05/2019 5:36 PM

Full Report
Registration: YN3199X
Printed: 24/06/2019 6:50 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	SNG AH TEE	Currency:	SGD
Claim Reference:		Date of Incident:	16/04/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	FUSO		
Model:	CANTER		
Sub Model:	FB83S		
Model Sheet Number:	32 67 24		
Registration:	YN3199X		
VIN number:			
Odometer:			
Model Specs			
FROM 11/2010	AIR CONDITIONING	3.0 LTR 92KW	DRIVER/PASS AIRBAG
SINGLE CAB	PREPARE OFF VEHICLE	BASECOAT CLEAR	

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:
 Assessment number: YN3199X - OD MSIG
 Version: 1810
 Date calculated: 13/05/2019 5:36 PM

Full Report
 Registration: YN3199X
 Printed: 24/06/2019 6:50 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADJUST HEADLAMPS		2.0	10.00
NO NUMBER	RENEW FRONT PANEL (FRONT SCREEN AND INSTRUMENT PANEL REMOVED) INCLUDES: R + R FRONT GRILLE, HEADLAMPS AND CORNER PANEL		67.0	335.00
NO NUMBER	R + R LEFT HEADLAMP		7.0	35.00
NO NUMBER	R + R FRONT NUMBER PLATE		1.0	5.00
423121 10	R + R WINDSCREEN		25.0	125.00
513010 10	R + R RIGHT MIRROR		4.0	20.00
522020 10	R + R R/SEAT BELT		4.0	20.00
523112 10ZAX	R + R INSTRUMENT PANEL CPL INCLUDES: R + R COMBINATION INSTRUMENT		45.0	225.00
528511 10	R + R AIRBAG CONTROL UNIT		4.0	20.00
551110 10	R + R COMPLETE HEATER (INSTRUMENT PANEL AND FRONT GRILLE		13.0	65.00

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:
 Assessment number: YN3199X - OD MSIG
 Version: 1810
 Date calculated: 13/05/2019 5:36 PM

Full Report
 Registration: YN3199X
 Printed: 24/06/2019 6:50 PM

Code	Description	WU	Price SGD
525010 10	REMOVED)	5.0	25.00
0281	R + R DRIVER AIRBAG	10.0*	50.00
	FRONT BUMPER REPAIR		
	Labour Cost	Hrs	WU
	Panel / Mechanical Labour	18.70	187.0
	Total of Labour		935.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - BASECOAT CLEAR	WU Price SGD
	FRONT BUMPER NEW PART PAINTING	11.0
	R/F CORNER PANEL NEW PART PAINTING	7.0
	FRONT PANEL NEW PART PAINTING	30.0
	FRONT GRILLE NEW PART PAINT K1R	8.0
	GRILLE NEW PART PAINT K1R	7.0

Paint Material Per Part

Code	Description	Price SGD
0281	FRONT BUMPER NEW PART PAINTING	24.77
0888	R/F CORNER PANEL NEW PART PAINTING	6.19
0900	FRONT PANEL NEW PART PAINTING	41.80
0410	FRONT GRILLE NEW PART PAINT K1R	30.50
0415	GRILLE NEW PART PAINT K1R	27.06

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	50.00 SGD/h		
Time Paint		63.0	
Preparation Main Work Metal	2.50	25.0	125.00
Preparation Comp. Work Plastic	0.50	5.0	25.00
Total	10 WU/h	93.0	465.00

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:
 Assessment number: YN3199X - OD MSIG
 Version: 1810
 Date calculated: 13/05/2019 5:36 PM

Full Report
 Registration: YN3199X
 Printed: 24/06/2019 6:50 PM

Material Cost - Paint	Price SGD
New Part Painting	72.76
New Part Painting - Plastic K1R	57.56
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	167.92

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0257	FRONT NUMBER PLATE	NO NUMBER		0.00
0410	FRONT GRILLE	MK614810		330.00
0561	LEFT HEADLAMP ASSY	MK486505		350.00
0678	R/F INDICATOR	MK486510		135.00
0718	R/POSITION LAMP	MK486522	(A) dis✓	100.00
0888	R/F CORNER PANEL	MK997198		250.00
0900	FRONT PANEL	MK997155		750.00
1392	FRONT PANEL TRIM	MK487201		260.00
1401	WINDSCREEN	MK488920		750.00
1410	WINDSCREEN SEAL	MK548236		200.00
1411	BONDING KIT	Z2156507		0.00
1738	R/MIRROR HEAD	MK486109		65.00
4446	HEATER CPL	MK513194		1,500.00
4662	RIGHT SEAT BELT	MK509144	(A) act✓	750.00
7411	DRIVER AIRBAG	MK569058		2,400.00
7443	AIRBAG CONTROL UNIT	MK387908		1,900.00
1002	SIDE MIRROR(LH)	ROUND		35.00
1006	AIR CON INLET&OUTLET PIPE		(A) bt✓	150.00
1007	CANTER STICKER	WIPER GARNISH	(A) nec✓	60.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			9,985.00
u: Used parts	Addition(+15.00%)			1,497.75
	Total			11,482.75

Extras

Code	Description	Price SGD
1000	FRT NUMBER PLATE	20.00*
1003	ERP BRACKET -	26.00*
1004	DIAGNOSE & RESET FAULT CODE	180.00*
1005	AIR CON GAS TOP UP	100.00*

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:
 Assessment number: YN3199X - OD MSIG
 Version: 1810
 Date calculated: 13/05/2019 5:36 PM

Full Report
 Registration: YN3199X
 Printed: 24/06/2019 6:50 PM

Code	Description	Price SGD
	Total Extras	326.00

Final Calculation

	SGD	SGD
Parts	9,985.00	
Addition(+15.00%)	1,497.75	
Total Parts		11,482.75
Labour Time Base 10 WU/h		
Total 187.0 WU X 50.00 SGD/h	935.00	
Total of Labour		935.00
Total Of Extras		326.00
Paint Work Time Base 10 WU/h		
Labour Cost 93.0 WU X 50.00 SGD/h	465.00	
Material Cost	167.92	
Total Paint Including Material		632.92
Repair Cost Excludes GST		13,376.67
GST (+7.0%)		936.37
Repair Cost Included GST		14,313.04
Deductions (Excludes GST)		
Repair Cost Discount (+20.00%)	-2,675.33	
Total Of Deductions (Excludes GST)		-2,675.33
Grand Total Excludes GST		10,701.34
GST (+7.0%)		749.09
Grand Total Included GST		11,450.43

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Finalised

Claim Reference:
Assessment number: YN3199X - OD MSIG
Version: 1810
Date calculated: 26/06/2019 3:13 PM

Full Report
Registration: YN3199X
Printed: 26/06/2019 3:17 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	16/04/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	FUSO		
Model:	CANTER		
Sub Model:	FB83S		
Model Sheet Number:	32 67 24		
Registration:	YN3199X		
VIN number:			
Odometer:			
Model Specs			
FROM 11/2010	AIR CONDITIONING	3.0 LTR 92KW	DRIVER/PASS AIRBAG
SINGLE CAB	PREPARE OFF VEHICLE	BASECOAT CLEAR	

LKK Auto Consultants

#01-25 Paya Ubi Industrial Park,

51 Ubi Avenue 1

408933

Claim Reference:

Assessment number: YN3199X - OD MSIG

Version: 1810

Date calculated: 26/06/2019 3:13 PM

Full Report

Registration: YN3199X

Printed: 26/06/2019 3:17 PM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADJUST HEADLAMPS		2.0	10.00
NO NUMBER	RENEW FRONT PANEL (FRONT SCREEN AND INSTRUMENT PANEL REMOVED) INCLUDES: R + R FRONT GRILLE, HEADLAMPS AND CORNER PANEL		67.0	335.00
NO NUMBER	R + R LEFT HEADLAMP		7.0	35.00
NO NUMBER	R + R FRONT NUMBER PLATE		1.0	5.00
423121 10	R + R WINDSCREEN		25.0	125.00
513010 10	R + R RIGHT MIRROR		4.0	20.00
522020 10	R + R R/SEAT BELT		4.0	20.00
523112 10ZAX	R + R INSTRUMENT PANEL CPL INCLUDES: R + R COMBINATION INSTRUMENT		45.0	225.00
528511 10	R + R AIRBAG CONTROL UNIT		4.0	20.00
551110 10	R + R COMPLETE HEATER (INSTRUMENT PANEL AND FRONT GRILLE		13.0	65.00

LKK Auto Consultants

#01-25 Paya Ubi Industrial Park,

51 Ubi Avenue 1

408933

Claim Reference:

Assessment number: YN3199X - OD MSIG

Version: 1810

Date calculated: 26/06/2019 3:13 PM

Full Report

Registration: YN3199X

Printed: 26/06/2019 3:17 PM

Code	Description	WU	Price SGD
	REMOVED)		
525010 10	R + R DRIVER AIRBAG	5.0	25.00
0281	FRONT BUMPER REPAIR	10.0*	50.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		18.70	187.0
Total of Labour			935.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h
Code	Description - BASECOAT CLEAR	WU	Price SGD
	FRONT BUMPER NEW PART PAINTING	11.0	
	R/F CORNER PANEL NEW PART PAINTING	7.0	
	FRONT PANEL NEW PART PAINTING	30.0	
	FRONT GRILLE NEW PART PAINT K1R	8.0	
	GRILLE NEW PART PAINT K1R	7.0	

Paint Material Per Part

Code	Description	Price SGD
0281	FRONT BUMPER NEW PART PAINTING	24.77
0888	R/F CORNER PANEL NEW PART PAINTING	6.19
0900	FRONT PANEL NEW PART PAINTING	41.80
0410	FRONT GRILLE NEW PART PAINT K1R	30.50
0415	GRILLE NEW PART PAINT K1R	27.06

Labour Cost - Paint

	Factor	50.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			63.0	
	Preparation Main Work Metal		2.50	25.0	125.00
	Preparation Comp. Work Plastic		0.50	5.0	25.00
Total		10 WU/h	9.30	93.0	465.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: YN3199X - OD MSIG
 Version: 1810
 Date calculated: 26/06/2019 3:13 PM

Full Report
 Registration: YN3199X
 Printed: 26/06/2019 3:17 PM

Material Cost - Paint	Price SGD
New Part Painting	72.76
New Part Painting - Plastic K1R	57.56
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	167.92

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0257	FRONT NUMBER PLATE	NO NUMBER		0.00
0410	FRONT GRILLE	MK614810		330.00
0561	LEFT HEADLAMP ASSY	MK486505		350.00
0678	R/F INDICATOR	MK486510		135.00
0718	R/POSITION LAMP	MK486522		100.00
0888	R/F CORNER PANEL	MK997198		250.00
0900	FRONT PANEL	MK997155		750.00
1392	FRONT PANEL TRIM	MK487201		260.00
1401	WINDSCREEN	MK488920		750.00
1410	WINDSCREEN SEAL	MK548236		200.00
1411	BONDING KIT	Z2156507		0.00
1738	R/MIRROR HEAD	MK486109		65.00
4446	HEATER CPL	MK513194		1,500.00
4662	RIGHT SEAT BELT	MK509144		750.00
7411	DRIVER AIRBAG	MK569058		2,400.00
7443	AIRBAG CONTROL UNIT	MK387908		1,900.00
1002	SIDE MIRROR(LH)	ROUND		35.00
1006	AIR CON INLET&OUTLET	PIPE		150.00
1007	CANTER STICKER	WIPER GARNISH		60.00
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 9,985.00
u: Used parts				Addition(+15.00%) 1,497.75
				Total 11,482.75

Extras

Code	Description	Price SGD
1000	FRT NUMBER PLATE	20.00*
1003	ERP BRACKET -	26.00*
1004	DIAGNOSE & RESET FAULT CODE	180.00*
1005	AIR CON GAS TOP UP	100.00*

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: YN3199X - OD MSIG
 Version: 1810
 Date calculated: 26/06/2019 3:13 PM

Full Report
Registration: YN3199X
Printed: 26/06/2019 3:17 PM

Code	Description	Price SGD
	Total Extras	326.00

Final Calculation

	SGD	SGD
Parts	9,985.00	
Addition(+15.00%)	1,497.75	
Total Parts		11,482.75
Labour Time Base 10 WU/h		
Total 187.0 WU X 50.00 SGD/h	935.00	
Total of Labour		935.00
Total Of Extras		326.00
Paint Work Time Base 10 WU/h		
Labour Cost 93.0 WU X 50.00 SGD/h	465.00	
Material Cost	167.92	
Total Paint Including Material		632.92
Repair Cost Excludes GST		13,376.67
GST (+7.0%)		936.37
Repair Cost Included GST		14,313.04
Deductions (Excludes GST)		
Repair Cost Discount (+20.00%)	-2,675.33	
Total Of Deductions (Excludes GST)		-2,675.33
Grand Total Excludes GST		10,701.34
GST (+7.0%)		749.09
Grand Total Included GST		11,450.43

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Veron Chen (LKKAUTO)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Wednesday, 26 June 2019 4:55 PM
To: Veron Chen (LKKAUTO)
Subject: RE: YN 3199X REPAIR LIMIT-DOA: 16/4/2019

Hi Veron

We confirm.
Thanks.

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



-Please note that all offer/acceptance is made without prejudice.-

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Wednesday, June 26, 2019 3:26 PM
To: Sharon Sng <sharon@sngahtee.com>; 'Janice Chang' <janice@sngahtee.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; sngahtee@singnet.com.sg
Cc: 'ADMIN SNGAHTEE' <admin@sngahtee.com>; SUR <sur@lkkauto.com>
Subject: RE: YN 3199X REPAIR LIMIT-DOA: 16/4/2019

Dear Sharon,

Offer Lump Sum \$10,700 before excess \$700 @ 9 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Monday, 24 June 2019 6:53 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; 'Janice Chang' <janice@sngahtee.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; sngahtee@singnet.com.sg

Cc: 'ADMIN SNGAHTEE' <admin@sngahtee.com>
Subject: RE: YN 3199X REPAIR LIMIT-DOA: 16/4/2019

Hi

Audatex sent back. Please check.

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



-Please note that all offer/acceptance is made without prejudice.-

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Thursday, June 20, 2019 4:07 PM
To: Janice Chang <janice@sngahtee.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; sngahtee@singnet.com.sg;
'Sharon Sng' <sharon@sngahtee.com>
Cc: ADMIN SNGAHTEE <admin@sngahtee.com>
Subject: RE: YN 3199X REPAIR LIMIT-DOA: 16/4/2019

Dear Sharon/Janice,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Thursday, 13 June 2019 4:33 PM
To: Janice Chang <janice@sngahtee.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; sngahtee@singnet.com.sg
Cc: 'Sharon Sng' <sharon@sngahtee.com>; ADMIN SNGAHTEE <admin@sngahtee.com>
Subject: RE: YN 3199X REPAIR LIMIT-DOA: 16/4/2019

Dear Janice,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 23 May 2019 11:35 AM

To: Janice Chang <janice@sngahtee.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; sngahtee@singnet.com.sg

Cc: 'Sharon Sng' <sharon@sngahtee.com>; ADMIN SNGAHTEE <admin@sngahtee.com>

Subject: RE: YN 3199X REPAIR LIMIT-DOA: 16/4/2019

Dear Janice,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Friday, 26 April 2019 9:55 AM

To: Janice Chang <janice@sngahtee.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; sngahtee@singnet.com.sg

Cc: 'Sharon Sng' <sharon@sngahtee.com>; ADMIN SNGAHTEE <admin@sngahtee.com>; SUR <sur@lkkauto.com>

Subject: RE: YN 3199X REPAIR LIMIT-DOA: 16/4/2019

Dear Janice,

As instructed by our client , please proceed to repair the **insured vehicle YN 3199X on Lump Sum Repair Not Exceeding \$11,500/- or which ever lower (Excess \$700/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Chang <janice@sngahtee.com>

Sent: Thursday, 25 April 2019 5:21 PM

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; sngahtee@singnet.com.sg

Cc: 'Sharon Sng' <sharon@sngahtee.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; ADMIN SNGAHTEE <admin@sngahtee.com>

Subject: RE: YN 3199X REPAIR LIMIT

Hi All,

We accept offer as below email, please let us know once it authorize repair.
Thank You.

Best Regards

Janice Chang | Senior Admin

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



-All offers/acceptances are made, based without prejudice.-

From: Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Sent: Wednesday, 24 April 2019 11:49 AM

To: sngahtee@singnet.com.sg

Cc: 'Sharon Sng' <sharon@sngahtee.com>; 'Janice Chang' <janice@sngahtee.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: YN 3199X REPAIR LIMIT

Hi,

Please take note repair limit for this lorry is \$11,500. Please revert if can repair within repair limit as we need to revert to MSIG.

Thank you.

Regards

Taufikh

Lkk AUTO

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Apr 2019 15:22 Sendback Est	22 Apr 2019 15:23 S\$15,356.80	22 Apr 2019 17:29 Edit Adj Rpt	S\$10,700.00 Edit Estimates	S\$10,700.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SHAFT BUILD CONSTRUCTION PTE LTD , Co. Reg. No.: 198700103K		
Vehicle Reg. No.:	YN3199X	Date of Loss:	16/04/2019 14:00 - :59 [82 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 591072	Policy/Cover Note No.:	29084255MKC (Comprehensive) Coverage: 12/06/2018 - 11/06/2019
		Excess:	S\$700.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Nor Azian Binte Noordin - 6594 2558]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 22/05/2019]		
Driver/Custodian:	PARAMASIVAM RAMESH (41 / Male) , NRIC: F8140737K, Tel: +6584325900 Email: NOEMAIL		
Adj Asg. Remarks:	Pls revert with MV		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (27/06/2019): Alert - Adj Mandate Approved (S\$10700.00) - YN3199X - Claim Handler: Nor Azian B...
- MSIG_SG (26/04/2019): Alert - Adj Mandate Approved (S\$11500.00) - YN3199X - Claim Handler: Nor Azian B...
- MSIG_SG (26/04/2019): Alert - Adj Mandate Approved (S\$10231.90) - YN3199X - Claim Handler: Nor Azian B...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

YN3199X (591072)
OD
Apr 16 2019 2:00PM
[SHAFT BUILD CONSTRUCTION PTE LTD]
Sng Ah Tee Motor & Panel Service Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	17/04/19 17:33	Accident Statement	 Load HTM	☐
2	22/04/19 15:23	Repairer Estimates	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/04/19 14:15	Adjuster Immediate Advice	 Load HTM	☐
2	25/04/19 17:36	Adjuster Immediate Advice	 Load HTM	☐
3	26/06/19 17:20	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	17/04/19 17:20	Accident Photo [Linked Accident Report Documents]	 Load JPG ☒	☒
2	17/04/19 17:20	Accident Photo [Linked Accident Report Documents]	 Load JPG ☒	☒
3	17/04/19 17:20	Accident Photo [Linked Accident Report Documents]	 Load JPG ☒	☒
4	17/04/19 17:20	Accident Photo [Linked Accident Report Documents]	 Load JPG ☒	☒
5	17/04/19 17:20	Accident Photo [Linked Accident Report Documents]	 Load JPG ☒	☒
6	17/04/19 17:20	Accident Photo [Linked Accident Report Documents]	 Load JPG ☒	☒
7	17/04/19 17:20	Accident Photo [Linked Accident Report Documents]	 Load JPG ☒	☒
8	17/04/19 17:20	Accident Photo [Linked Accident Report Documents]	 Load JPG ☒	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/04/19 11:28	General View	 Load JPG ☒	☒
2	24/04/19 11:28	General View	 Load JPG ☒	☒
3	24/04/19 11:28	General View	 Load JPG ☒	☒
4	24/04/19 11:28	General View	 Load JPG ☒	☒
5	24/04/19 11:28	General View	 Load JPG ☒	☒
6	24/04/19 11:28	General View	 Load JPG ☒	☒
7	24/04/19 11:28	General View	 Load JPG ☒	☒
8	24/04/19 11:28	General View	 Load JPG ☒	☒
9	24/04/19 11:28	General View	 Load JPG ☒	☒
10	24/04/19 11:28	General View	 Load JPG ☒	☒
11	24/04/19 11:28	General View	 Load JPG ☒	☒
12	24/04/19 11:28	General View	 Load JPG ☒	☒
13	24/04/19 11:28	General View	 Load JPG ☒	☒
14	24/04/19 11:28	General View	 Load JPG ☒	☒
15	24/04/19 11:28	General View	 Load JPG ☒	☒
16	24/04/19 11:28	General View	 Load JPG ☒	☒
17	24/04/19 11:28	General View	 Load JPG ☒	☒
18	24/04/19 11:28	General View	 Load JPG ☒	☒

Assessment Reports			1 per page	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
19	24/04/19 11:28	General View	 Load JPG	☒
20	24/04/19 11:28	General View	 Load JPG	☒
21	24/04/19 11:28	General View	 Load JPG	☒
22	24/04/19 11:28	General View	 Load JPG	☒
23	24/04/19 11:28	General View	 Load JPG	☒
24	24/04/19 11:28	General View	 Load JPG	☒
25	24/04/19 11:28	General View	 Load JPG	☒
26	24/04/19 11:28	General View	 Load JPG	☒
27	24/04/19 11:28	General View	 Load JPG	☒
28	24/04/19 11:28	General View	 Load JPG	☒
29	24/04/19 11:28	General View	 Load JPG	☒
30	24/04/19 11:28	General View	 Load JPG	☒
31	24/04/19 11:28	General View	 Load JPG	☒
32	24/04/19 11:28	General View	 Load JPG	☒
33	24/04/19 11:28	General View	 Load JPG	☒
34	24/04/19 11:28	General View	 Load JPG	☒
35	24/04/19 11:28	General View	 Load JPG	☒
36	24/04/19 11:28	General View	 Load JPG	☒
37	24/04/19 11:28	General View	 Load JPG	☒
38	24/04/19 11:28	General View	 Load JPG	☒
39	24/04/19 11:28	General View	 Load JPG	☒
40	24/04/19 11:28	General View	 Load JPG	☒
41	24/04/19 11:28	General View	 Load JPG	☒
42	24/04/19 11:28	General View	 Load JPG	☒
43	24/04/19 11:28	General View	 Load JPG	☒
44	24/04/19 11:28	General View	 Load JPG	☒
45	24/04/19 11:28	General View	 Load JPG	☒
46	26/06/19 15:28	Reinspection Photo	 Load JPG	☒
47	26/06/19 15:28	Reinspection Photo	 Load JPG	☒
48	26/06/19 15:28	Reinspection Photo	 Load JPG	☒
49	26/06/19 15:28	Reinspection Photo	 Load JPG	☒
50	26/06/19 15:28	Reinspection Photo	 Load JPG	☒
51	26/06/19 15:28	Reinspection Photo	 Load JPG	☒
52	26/06/19 15:28	Reinspection Photo	 Load JPG	☒
53	26/06/19 15:28	Reinspection Photo	 Load JPG	☒
54	26/06/19 15:28	Reinspection Photo	 Load JPG	☒
55	26/06/19 15:28	Reinspection Photo	 Load JPG	☒
56	26/06/19 15:28	Reinspection Photo	 Load JPG	☒
57	26/06/19 15:28	Reinspection Photo	 Load JPG	☒
58	26/06/19 15:28	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/04/19 15:00	Valid DL	 Load PDF	
2	22/04/19 15:16	COE / PARF Value	 Load PDF	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	22/04/19 15:24	E-filed GIA report	 Load PDF	
2	22/04/19 15:24	AUDATEX REPORT	 Load PDF	
3	22/04/19 15:24	IC,DL,CI	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print

Assessment Reports				1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	24/04/19 11:32	MARK ESTIMATE		Load PDF	
2	27/06/19 09:22	SUPPLEMENTARY		Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	17/04/19 17:33	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	17/04/19 17:20	Accident Photo	 Load JPG	☒
2	17/04/19 17:20	Accident Photo	 Load JPG	☒
3	17/04/19 17:20	Accident Photo	 Load JPG	☒
4	17/04/19 17:20	Accident Photo	 Load JPG	☒
5	17/04/19 17:20	Accident Photo	 Load JPG	☒
6	17/04/19 17:20	Accident Photo	 Load JPG	☒
7	17/04/19 17:20	Accident Photo	 Load JPG	☒
8	17/04/19 17:20	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	17/04/19 17:20	Sketch Plan	 Load TIF	
2	17/04/19 17:21	IC,DL,CI	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Repairer ☐ Handling Insurer				
Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19007120/T1VD3S2

Date: 27/06/2019

REFERENCE

Insured/Claimant: SHAFT BUILD CONSTRUCTION PTE LTD
Date of Loss: 16/04/2019Policy No: 29084255MKC
Nature of Claim: OD Claim No: 591072

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN3199X	Engine No:	4M42A90401
Make & Model:	MITSUBISHI FE83PE6SRDEB, 3.9 D (M)	Chassis No:	FE83BEA20827
Reg. Date:	12/06/2012 (Man. Year: 2011)	Odometer:	0 km
Colour:	White		
Engine Capacity:	2977 cc		
Market Value/New Car Price:	S\$31,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	17.00 R16	Rear Tyre Size:	17.00 R16 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,292.40	11,482.75	1,809.65	13.61
Miscellaneous Items	226.00	146.00	80.00	35.40
Paintwork Materials	173.40	167.92	5.48	3.16
Labour	1,175.00	1,115.00	60.00	5.11
Paintwork Labour	490.00	465.00	25.00	5.10
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,356.80	13,376.67	1,980.13	12.89
Approved Total (Overridden) (S\$)		10,700.00		
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	14,656.80	10,000.00	4,656.80	31.77
+ GST 7.00/7.00% (S\$)	1,025.98	700.00	325.98	31.77
Nett Amount (S\$)	15,682.78	10,700.00	4,982.78	31.77

INSPECTION

Date of Assignment:	22/04/2019	Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	23/04/2019	Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	9.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Jun 2019)	
Parts:	N/A	MITSUBISHI FE83PE6SRDEB 3.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN3199X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPARE PARTS (WCP)		13,292.40 F	*- F
2	1		*FRONT NUMBER PLATE (NPA) (WCP)	Repeated	-	*- F
3	1		*FRONT BUMPER (WCP)	Repair	-	*- F
4	1		*FRONT GRILLE (WCP)	Cracked	-	*330.00 F
5	1		*LEFT HEADLAMP ASSY (WCP)	Cracked	-	*350.00 F
6	1		*RIGHT HEADLAMP ASSY (WCP)	Not Necessary	-	*- F
7	1		*L/F INDICATOR (WCP)	Not Necessary	-	*- F
8	1		*R/F INDICATOR (WCP)	Cracked	-	*135.00 F
9	1		*R/F CORNER PANEL (WCP)	Bent	-	*250.00 F
10	1		*FRONT PANEL (WCP)	Bent	-	*750.00 F
11	1		*FRONT PANEL TRIM (WCP)	Cracked	-	*260.00 F
12	1		*WINDSCREEN (WCP)	Cracked	-	*750.00 F
13	1		*WINDSCREEN SEAL (WCP)	Necessary	-	*200.00 F
14	1		*BONDING KIT (NPA) (WCP)	Necessary	-	*- F
15	1		*L/WIPER ARM/BADGE (WCP)	Not Necessary	-	*- F
16	1		*R/F DOOR TRIM (WCP)	Not Necessary	-	*- F
17	1		*R/F DOOR SWITCH (WCP)	Not Necessary	-	*- F
18	1		*R/MIRROR HEAD (WCP)	Cracked	-	*65.00 F
19	1		*R/INSTR PANEL COVER (WCP)	Not Necessary	-	*- F
20	1		*L/OUTER CONNECTION (WCP)	Not Necessary	-	*- F
21	1		*HEATER BLOWER (WCP)	Not Necessary	-	*- F
22	1		*HEATER CPL (WCP)	Cracked	-	*1,500.00 F
23	1		*DRIVER AIRBAG (WCP)	Activated	-	*2,400.00 F
24	1		*AIRBAG CONTROL UNIT (WCP)	Activated	-	*1,900.00 F
25	1		*FRT HEADLAMP (WCP)	Not Necessary	-	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*SIDE MIRROR (LH) (WCP)	Cracked	-	*35.00 F
27	1		*R/POSITION LAMP (WCP)	Distorted	-	*100.00 F
28	1		*RIGHT SEAT BELT (WCP)	Activated	-	*750.00 F
29	1		*AIR CON INLET & OUTLET (WCP)	Bent	-	*150.00 F
30	1		*CANTER STICKER (WCP)	Necessary	-	*60.00 F

F=Franchise part.

Sub Total (\$\$)	13,292.40	9,985.00
+ Margin on L,N Items 0.00/15.00% (\$\$)	0.00	1,497.75
Total Parts (\$\$)	13,292.40	11,482.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Materials				
1	1	TOTAL PAINTWORK MATERIALS	173.40	167.92
Miscellaneous Items				
2	1	AIR CON GAS TOP UP (NECESSARY)	-	100.00
3	1	ERP BRACKET (NECESSARY)	-	26.00
4	1	FRT NUMBER PLATE (BENT)	-	20.00
5	1	SPECIAL NETT ITEM	226.00	0.00
Sub Total (S\$)			399.40	313.92

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TOTAL PAINTWORK LABOUR	New	490.00	465.00
Labour Items				
2	TOTAL PANEL/MECHANICAL LABOUR	New	1,175.00	935.00
3	DIAGNOSTIC & RESET FAULT CODE.	New	-	180.00
Gross Labour Cost (S\$)			1,665.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >