

Hwee Jie

REF: MS16

CC3/MSG19007137/JTD322

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured PBB7742 L

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No. SHC 4491 D Yr Regn: 9 Apr 2014Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1797Colour: White A/C: Insured / Std / NI / NASp. Reading: 590238 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN36U X05740924Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195 / 65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 18/4/19 D.O.I. 22/4/19Survey held at SmartDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHC 4491D - CS / TTD 8012332 / TW

DOA: 11/4/2008

04/19/2081

FBB 7742L - NA / MSG 18004059 / KA

DOA: 31/12/17

FBB 7742L

23/4 @ 5:19pm - sent GIA k estimate via email.

Lump Sum \$2000 - (Red: 8374.59 : 80%)

RECEIVED 14 MAY 2019

Date/Time: File Pass to?

☐ : Preli. Report

1) 14/5 Typist

☒ : Final Report

Date/Time: File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) ___ \$ + PS. ___ \$

) Photos

) Others

TOTAL

Report Format: TPLump Sum / I.B.I. (\$) 2000Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

10

160

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 23 April 2019 5:19 PM
To: 'yiqian_low@sg.msig-asia.com'
Cc: SUR; KKLau; Accounts (LKKAuto)
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICES PTE LTD (TP VEHICLE: SHC 4491D, INSURED VEHICLE: FBB 7792L, DOA: 18/04/2019)
Attachments: SHC 4491D ESTIMATE.pdf; SHC 4491D GIA.pdf

Dear Yi Qian,

Please be informed that we had inspected the vehicle **SHC 4491D** at M/s: SMRT AUTOMOTIVE SERVICES PTE LTD, 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705.

Enclosed herewith a copy of TP's GIA report and estimate.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Thank you.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHC4491D
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR1353851
Chassis No.:	JTDKN36UX05740924
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	09 Apr 2014
First Registration Date:	09 Apr 2014
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Apr 2022
PARF Rebate Amount:	\$5,857.00
Intended COE Rebate Details	
COE Expiry Date:	08 Apr 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$59,871.00
COE Rebate Amount:	\$22,155.00
Total Rebate Amount:	\$28,012.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 23 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/04/2019 08:41
Date Of Accident	18/04/2019 22:00
Exact Location Of Accident	CTE TOWARDS WOODLANDS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4491D
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	LEE BENG CHYE PAUL
NRIC No	S1168451C
Date Of Birth	27/04/1956
Occupation	OUTDOOR
Date Of Driving Pass	23/06/1976
Driving Experience	42 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : UNKNOWN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG CTE TOWARDS WOODLANDS WITH ONE PASSENGER (FEMALE CHINESE) ON BOARD. A VEHICLE IN FRONT OF MY TAXI CAME TO A HALT. I APPLIED MY BRAKE TO STOP AND MANAGED TO STOP IN TIME. AFTER WHICH I FELT AN IMPACT AT THE REAR OF MY TAXI. A MOTORCYCLE FBB7742L HAD COLLIDED ONTO THE REAR OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	FBB7742L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	MUHAMMAD NUR HADI
NRIC/Passport Number	S9725327G
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature _____

Name: _____

NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GiA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GiA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GiA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

 20/4/2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:



 20/4/2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Section A - Accident Details

Registration Number	SHC4491D
Case Reference Number	TAX/04/19/2081
Registration Date	9/4/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	LEE BENG CHYE PAUL
Type of Accident	Head to Rear
Accident Date and Time	18/4/2019 10:00 PM
Accident Reported Date and Time	20/4/2019 8:48 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101129
Special Instruction to ARC, if any	DROVE IN / TP/ MSIG - LKK
Prepared Date and Time	22/4/2019 1:12 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$400.00
Total Spray Cost	\$1,296.00	\$400.00
Total Spare Part Cost	\$3,855.67	\$868.43
Total Other Cost	\$896.88	\$336.88
TOTAL COST	\$6,893.55	\$2,005.31
Lump Sum Total	\$6,900.00	\$2,000.00 (L/S)
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / MSIG
ARC / Surveyor Sign Off Date	24/04/2019 3:06 PM	24/04/2019 2:51 PM
Signature		
Remarks	SUP = 1 DAYS	L/S REPAIR, PHOTO AFTER REPAIR.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1905-0075	Invoice Number	
Quotation Date	04.05.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$845.00	\$400.00
Total Labour	\$845.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,296.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO REMOVE & REFIT EXHAUST	\$120.00	\$0.00
TO TEST AND REFIT REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND REFIT WIRE HARDESS	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
Total Other Costs	\$896.88	\$336.88

4333.88

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	30.00	\$321.02	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	30.00	\$11.27	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given

Def
wec
BT
nn
nn
nn
Short ed
nec
nn
Def

	76891-47020	BUMPER LIP REAR	1.00	\$228.90	30.00	\$160.23	Replace	Replace	✓
	52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given	X
	52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X
	52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X
	58308-47011	UNDER COVER SUBASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given	X
	17430-37380	EXHAUST TAIL PIPE	0.00	\$656.20	0.00	\$0.00	Replace	Not Given	X
	67005-47241	TAILGATE ASY	1.00	\$1,007.90	100.00	\$0.00	Replace	Repair	✓
	76801-47070-B0	TAILGATE OUTSIDE GARNISH	0.00	\$504.90	0.00	\$0.00	Replace	Not Given	X
	75310-47020	EMBLEM REAR	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X
	75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X
	75442-47030	NAME PLATE (PRIUS)	0.00	\$60.80	0.00	\$0.00	Replace	Not Given	X
	75443-47030	NAME PLATE (TOYOTA)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X
	76085-47910	SPOILER REAR	0.00	\$953.70	0.00	\$0.00	Replace	Not Given	X
	81006-47011	3RD BRAKE LAMP	0.00	\$231.30	0.00	\$0.00	Replace	Not Given	X
		SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
		STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
Total				\$6,139.81		\$792.52			

SCR

nn

nn

6040.81

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	30.00	\$143.99	Replace	Replace
		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	30.00	\$82.67	Replace	Replace
		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	30.00	\$66.36	Replace	Replace
Total					418.60		293.02		

1085.54

- 202

868.43

+ 400.00

+ 736.88

2005.31

45 \$2000/-

9292.18



Case Details

Case Reference Number : TAX/04/19/2081
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4491D

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-6561-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : MSIG Insurance (S) Pte Ltd
 Accident Date and Time : 18/04/2019 02:00 PM
 Vehicle Age(In Months) : 60

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	30.00	321.02	Replace	1	321.02	Replace ▾	DEF
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	30.00	11.27	Replace	10	11.27	Replace ▾	rec
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	30.00	143.99	Replace	0	0	Check ▾	
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	30.00	97.72	Replace	0	0	Check ▾	
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	30.00	97.72	Replace	0	0	Check ▾	
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Not Give ▾	nn
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace ▾	Shorted
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾	rec
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	30.00	50.54	Replace	0	0	Not Give ▾	nn
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	30.00	82.67	Replace	0	0	Not Give ▾	nn

Total Spare Part Cost 4,526.57

Surveyor Total 792.52

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 3,603.98

Final Sur Total 634.02

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	30.00	160.23	Replace	1	160.23	Replace	SCR
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	30.00	45.99	Replace	0	0	Not Give	}
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	30.00	66.36	Replace	0	0	Not Give	
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	30.00	66.36	Replace	0	0	Not Give	
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	30.00	360.15	Replace	0	0	Not Give	
One Time Key In	Main			EXHAUST TAIL PIPE	1	656.20	656.20	30.00	459.34	Replace	0	0	Not Give	
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	30.00	705.53	Replace	1	0	Repair	
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	30.00	353.43	Replace	0	0	Not Give	}
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	30.00	42.21	Replace	0	0	Not Give	
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	30.00	36.33	Replace	0	0	Not Give	
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.80	60.80	30.00	42.56	Replace	0	0	Not Give	
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	30.00	36.33	Replace	0	0	Not Give	
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	30.00	667.59	Replace	0	0	Not Give	
One Time Key In	Main			3RD BRAKE LAMP	1	231.30	231.30	10.00	208.17	Replace	0	0	Not Give	
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	

Total Spare Part Cost 4,526.57

Surveyor Total 792.52

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 3,603.98

Final Sur Total 634.02

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	
Total Spare Part Cost									4,526.57	Surveyor Total				792.52
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)				20
Final Spare Part Cost									3,603.98	Final Sur Total				634.02

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	845.00	400	
Total:			845.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY TAIL GATE	378.00	200	
4	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0	
5	Main	TO RESPRAY REAR SPOILER	180.00	0	
Total:			1,296.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO REMOVE & REFIT EXHAUST	120.00	0	
3	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
4	Main	TO REMOVE AND REFIT WIRE HARDESS	120.00	0	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			896.88	336.88	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
6	Main	TO WASH AND VACUUM	60.00	0	
7	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	
Total:			896.88	336.88	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,603.98	634.02
Total Labour Cost	845.00	400.00
Total Spray Painting	1,296.00	400.00
Other	896.88	336.88
Overall Total	6,641.86	1,770.90
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	6,650.00	1,750.00
Surveyor Approved Amount		1,750.00
No of Repair Days*	6	3
Remarks	-	L/S REPAIR, PHOTO AFTER REPAIR.
Surveyor Name		Hwee Jie
Signature		 24/4/19
Survey Date	22/04/2019	<input type="button" value="Save"/> <input type="button" value="Clear"/>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Apr 2019		24 Apr 2019 09:58 Edit Adj Rpt	S\$2,000.00 Edit Estimates	S\$2,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SXZ MOTOR , Co. Reg. No.: 53361105M								
Main Claimant:	SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHC4491D	Date of Loss:	18/04/2019 22:00 - :59 [60 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/19-000463	Policy/Cover Note No.:	MSD/VMT/18-386021 (Third Party Only) Coverage: 17/07/2018 - 17/07/2019						
Vehicle Reg. No. (Insured):	FBB7742L	Policy No. (Claimant):							
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Imm.Advice due 25/04/2019]								
Driver/Custodian (Insured):	MUHAMMAD NUR HADI BIN MOHD GHAZALI (21 / Male) , NRIC: S9725327G Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC4491D (MSC/V/19-000463)
[FBB7742L]
TP
SMRT TAXIS PTE LTD
Apr 18 2019 10:00PM
[SXZ MOTOR]
SMRT Automotive Services Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	25/04/19 08:41	General View						 Load JPG	<input checked="" type="checkbox"/>	
2	25/04/19 08:41	General View						 Load JPG	<input checked="" type="checkbox"/>	
3	25/04/19 08:41	General View						 Load JPG	<input checked="" type="checkbox"/>	
4	25/04/19 08:41	General View						 Load JPG	<input checked="" type="checkbox"/>	
5	25/04/19 08:41	General View						 Load JPG	<input checked="" type="checkbox"/>	
6	25/04/19 08:41	General View						 Load JPG	<input checked="" type="checkbox"/>	
7	25/04/19 08:41	General View						 Load JPG	<input checked="" type="checkbox"/>	
8	25/04/19 08:41	General View						 Load JPG	<input checked="" type="checkbox"/>	
9	25/04/19 08:41	General View						 Load JPG	<input checked="" type="checkbox"/>	
10	25/04/19 08:41	General View						 Load JPG	<input checked="" type="checkbox"/>	
11	25/04/19 08:41	General View						 Load JPG	<input checked="" type="checkbox"/>	
12	25/04/19 08:41	General View						 Load JPG	<input checked="" type="checkbox"/>	
13	25/04/19 08:41	General View						 Load JPG	<input checked="" type="checkbox"/>	
14	25/04/19 08:41	General View						 Load JPG	<input checked="" type="checkbox"/>	
15	25/04/19 08:41	General View						 Load JPG	<input checked="" type="checkbox"/>	
16	25/04/19 08:41	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
17	25/04/19 08:41	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
18	25/04/19 08:41	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
19	25/04/19 08:41	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
20	25/04/19 08:41	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
21	25/04/19 08:41	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
22	25/04/19 08:41	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
23	25/04/19 08:41	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
24	13/05/19 09:43	Photo After Spray						 Load JPG	<input checked="" type="checkbox"/>	
25	13/05/19 09:43	Photo After Spray						 Load JPG	<input checked="" type="checkbox"/>	
26	13/05/19 09:43	Photo After Spray						 Load JPG	<input checked="" type="checkbox"/>	
27	13/05/19 09:43	Photo After Spray						 Load JPG	<input checked="" type="checkbox"/>	
Documentation								1 per page		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	24/04/19 09:51	estimate repair						 Load PDF		
2	24/04/19 09:51	OI Accident Report						 Load PDF		
3	24/04/19 09:51	TP SHC4491D E-REPORT						 Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
----------------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19007137/JTD3E2

Date: 16/05/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/18-386021
Claimant Vehicle No :	SHC4491D	Insured Vehicle No :	FBF7742L
Date of Loss:	18/04/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-000463

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4491D	Engine No:	2ZR1353851
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKN36UX05740924
Reg. Date:	09/04/2014 (Man. Year: 2014)	Odometer:	590238 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,214.30	1,085.54	5,128.76	82.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,037.88	1,136.88	1,901.00	62.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,252.18	2,222.42	7,029.76	75.98
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	9,252.18	2,000.00	7,252.18	78.38

INSPECTION

Date of Assignment:	24/04/2019	
Date Inspected:	22/04/2019 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	4.0 days	

Adjuster: ONG HWEE JIE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 May 2019)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC4491D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR (DISC 30%)	Deformed	458.60 F	*321.02 F
2	1		*BUMPER CLIPS (DISC 30%) (10PCS)	Necessary	16.10 F	*11.27 F
3	1		*BUMPER REINFORCEMENT REAR (DISC 30%)	Bent	205.70 F	*143.99 F
4	1		*BUMPER LIP COVER RR/RH (DISC 30%)	Deformed	118.10 F	*82.67 F
5	1		*BUMPER LIP REAR (DISC 30%)	Scratched	228.90 F	*160.23 F
6	1		*BUMPER SIDE RETAINER RR/RH (DISC 30%)	Cracked	94.80 F	*66.36 F
7	1		*ARM SUB-ASSY, RR BUMPER LH	Not Necessary	139.60 F	*- F
8	1		*ARM SUB-ASSY, RR BUMPER RH	Not Necessary	139.60 F	*- F
9	1		*BUMPER LIP COVER RR/LH	Not Necessary	72.20 F	*- F
10	1		*BUMPER SEAL, RR RH	Not Necessary	65.70 F	*- F
11	1		*BUMPER SIDE RETAINER RR/LH	Not Necessary	94.80 F	*- F
12	1		*UNDER COVER SUBASSY, RR FLOOR	Not Necessary	514.50 F	*- F
13	1		*EXHAUST TAIL PIPE	Not Necessary	656.20 F	*- F
14	1		*TAILGATE OUTSIDE GARNISH	Not Necessary	504.90 F	*- F
15	1		*EMBLEM REAR	Not Necessary	60.30 F	*- F
16	1		*NAME PLATE (HYBRID)	Not Necessary	51.90 F	*- F
17	1		*NAME PLATE (TOYOTA)	Not Necessary	51.90 F	*- F
18	1		*SPOILER REAR	Not Necessary	953.70 F	*- F
19	1		*3RD BRAKE LAMP	Not Necessary	231.30 F	*- F
20	1		*SMRT LOGO	Not Necessary	7.80 F	*- F
21	1		*STICKER DECAL 6555 8888	Not Necessary	21.60 F	*- F
22	1		*TAILGATE ASY	Repair	1,007.90 F	*- F
23	1		*SENSOR REVERSE (SN)	Shorted	180.00 F	*180.00 F
24	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
25	1		*ANTENNA, ELECTRICAL LOWER REAR	Not Necessary	157.40 F	*- F
26	1		*NAME PLATE (PRIUS)	Not Necessary	60.80 F	*- F
					Total Parts (\$\$)	6,214.30 1,085.54

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	845.00	400.00
2	SPRAY PAINT	New	1,296.00	400.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO REMOVE & REFIT EXHAUST	New	120.00	0.00
5	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
6	TO REMOVE AND REFIT WIRE HARDESS	New	120.00	0.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
8	TO WASH AND VACUUM	New	60.00	0.00
9	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER	New	296.88	296.88
Gross Labour Cost (\$\$)			3,037.88	1,136.88

Report was unsubmitted during this print-out.

< END OF ESTIMATES >