



Your Ref : DM19HO00818-JG

Date: 15th August 2019

Our Ref : CC4/EQI19007170/Uwb3s2

M/s EQ Insurance Company Ltd

5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FS 5573J
ACCIDENT ON 21/03/2019 INSURED VEHICLE SLB 303Z**

Instruction was received to inspect the vehicle Reg. No. FS 5573J. The inspection was conducted on 24/04/2019 at the premises of AHM Performance, Blk 1 Kaki Bukit Ave 6 #02-46 Singapore 417883.

The following vehicle information was recorded:


Registration Number	: FS 5573J
Make/Model	: Honda RVF 400
Year of Registration	: 2000
Body Colour	: Black
Chassis Number	: NC351102878
Engine Capacity	: 399 cc
Speedometer Reading	: 37029 km

The vehicle sustained damages at the o/s and n/s body. The chassis frame affected due to collision. (Details see photographs enclosed)


In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$	2,500.00
Less: LTA Reimbursement Value (RV)	(S\$	284.00)
Nett Liability	S\$	<u>2,216.00</u>

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K.LAU
*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.