

Repair Estimate

Date : 25/4/2019

Reference: SLT5810Z
 OPEL MOKKA X
 Make: 1.6 CDTI 6AT
 (LED)

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLT5810Z
CHASSIS NO.:W0LJD7EC5HB124364
ENGINE NO.:A3163105GU7X0819

TPAXA.
 Cecilia.

Name of insured :ALPINE CAR RENTAL PTE LTD
 Date of accident.: 19/04/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	LHR Taillamp <i>cracked</i>	\$ 470.00 ✓
2	1	LHR Taillamp Panel <i>regris</i>	\$ 210.00 +
3	1	Rear Bumper Upper <i>3rd hand</i>	\$ 1,258.00 ✓
4	1	Rear Bumper Lower	\$ 883.00 ✓
5	1	Rear Bumper Sill Plate <i>reld.</i>	\$ 296.00 ✓
6	1	Rear Bumper Towing Cover <i>new</i>	\$ 25.00 +
7	1	LHR Bumper Reflector - LH Rear <i>cracked</i>	\$ 132.00 ✓
8	1	Rear Bumper Absorber - LH <i>reld.</i>	\$ 45.00 ✓
9	1	Rear Bumper Reinforment Bar <i>Best</i>	\$ 951.00 ✓
10	1	Reverse Sensor Wiring Harness <i>new</i>	\$ 325.00 +
11	1	Rear Bumper Air Ventilator <i>new</i>	\$ 85.00 +
12	1	LHR Bumper Bracket, Guide	\$ 58.00 ✓
13	1	RHR Bumper Bracket, Guide <i>4459</i>	\$ 58.00 ✓
14	1	LHR Bumper Lower Bracket <i>4013.10</i>	\$ 55.00 ✓
15	1	RHR Bumper Lower Bracket	\$ 55.00 ✓
16	1	Rear End Panel <i>new</i>	\$ 1,217.00 +
17	1	Rear End Panel Trim <i>new</i>	\$ 220.00 +.
18	1	LHR Fender Inner Trim <i>new</i>	\$ 458.00 +
19	1	LHR Fender Protector <i>3rd hand cracked</i>	\$ 198.00 ✓
20	1	LHR Fender Liner <i>new</i>	\$ 146.00 +

Parts Total: \$ 7,145.00
Less 10%: \$ 714.50

Total : \$ 6,430.50

Labour**Labour Description****No.****Price (SGD)****Rear portion**

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 PER DAY)	\$ 1,000.00	400
2	Carry out spray painting on accident affected area (\$200 PER PANEL)	\$ 1,000.00	400
3	To conduct anti rust of under carriage tuff coat	\$ 120.00	+
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	✓
5	To remove and refix reverse sensor and conduct test	\$ 80.00	50

880

Labour Total : \$ 2,230.00**Others****Other Description****No. Qty****Price (SGD)****Rear portion**

1	10	Rear bumper clip	\$ 65.00	30
2	6	Rear fender liner clips	\$ 39.00	+
3	6	Rear fender protector clips	\$ 39.00	30
4	8	Rear end panel trim clip	\$ 52.00	+
5	8	LHR Fender Inner Trim Clip	\$ 52.00	+
6	1	Reverse sensor (1 set)	\$ 720.00	350
7	1	Rear end panel insulation seal	\$ 80.00	+

410

Other Total: \$ 1,047.00**GRAND TOTAL: \$ 9,707.50**

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Advisor

Suhaimi

HP : 9189 2617 Email - aceautosolution@gmail.com

APPROVER DETAILS

SURVEYOR : _____

CONTACT NO : _____

PART BY PART / LUMP SUM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- The survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling
H/S 25/04/19

total: 5303.10

L/S: 4250.

03 days

Finalisation

Ace Auto Solution

Registration number : 53228991M

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

INVOICE

To : AXA Insurance singapore Pte Ltd
Cecil Street #01-01 GB Building
Singapore 069542

Invoice No: ACC-2015001
Invoice Date:

Vehicle No: SLT5810Z
Chassis No: W0LJD7EC5HB124364
Engine No: A3163105GU7X0819

DESCRIPTION	AMOUNT SGD
-------------	---------------

Parts

No.	Qty.		Price (SGD)
<u>1</u>	1	LHR Taillamp	\$ 470.00
<u>2</u>	1	Rear Bumper Upper	\$ 1,258.00
<u>3</u>	1	Rear Bumper Lower	\$ 883.00
<u>4</u>	1	Rear Bumper Sill Plate	\$ 296.00
<u>5</u>	1	LHR Bumper Reflector - LH Rear	\$ 132.00
<u>6</u>	1	Rear Bumper Absorber - LH	\$ 45.00
<u>7</u>	1	Rear Bumper Reinforment Bar	\$ 951.00
<u>8</u>	1	LHR Bumper Bracket, Guide	\$ 58.00
<u>9</u>	1	RHR Bumper Bracket, Guide	\$ 58.00
<u>10</u>	1	LHR Bumper Lower Bracket	\$ 55.00
<u>11</u>	1	RHR Bumper Lower Bracket	\$ 55.00
<u>12</u>	1	LHR Fender Protector	\$ 198.00

Total: \$ 4,459.00
Less 10%: \$ 445.90
Parts Total : \$ 4,013.10

Labour

No.		Price (SGD)
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 PER DAY)	\$ 400.00
<u>2</u>	Carry out spray painting on accident affected area (\$200 PER PANEL)	\$ 400.00
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
<u>4</u>	To remove and refix reverse sensor and conduct test	\$ 50.00

Labour Total : \$ 880.00

Other

No. Price (SGD)

1	10	Rear bumper clip	\$ 30.00
2	6	Rear fender protector clips	\$ 30.00
3	1	Reverse sensor (1 set)	\$ 360.00

Other Total : \$ 420.00

Total : \$ 5,313.10

Less lump sum 20%: \$ 1,062.62

Grand Total: \$ 4,250.00

Yours Faithfully,



Suhaimi

Service Executive

Tel: 9189 2617 Fax:6844 5185

Email : aceautosolution@gmail.com

E & O E

ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "**ACE AUTO SOLUTION**".

PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

Please check and finalize with me this invoice