



Case Details

Case Reference Number : TAX/04/19/2079
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB203B

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-6587-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 18/04/2019 07:40 AM
 Vehicle Age(In Months) : 17

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	933.10	933.10	25.00	699.83	Replace	1	699.83	Replace ▾	BVC
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace ▾	nee
One Time Key In	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	0	0	Not Give ▾	nn
One Time Key In	Main			WHEEL, DISC FRONT	1	1,555.10	1,555.10	25.00	1,166.32	Replace	0	0	Not Give ▾	nn
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	25.00	937.20	Replace	1	0	Repair ▾	
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace ▾	nee
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	89.50	89.50	25.00	67.13	Replace	0	0	Not Give ▾	nn
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL , RH	1	576.00	576.00	25.00	432.00	Replace	0	0	Not Give ▾	nn
Total Spare Part Cost									3,550.95	Surveyor Total				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)				
Final Spare Part Cost									3,550.95	Final Sur Total				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	845.00	400	
Total:			845.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
2	Main	TO RESPRAY RIM	180.00	0	
3	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
4	Main	TO RESPRAY VIEW MIRROR	180.00	0	
5	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	0	
Total:			1,296.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
3	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
5	Main	TO REMOVE AND REFIX VIEW MIRROR	120.00	0	
6	Main	TO TRANSFER DOOR MECHANISM	120.00	0	
7	Main	TO WASH AND VACUUM	60.00	0	
8	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			820.00	20.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,550.95	799.50

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Labour Cost	845.00	400.00
Total Spray Painting	1,296.00	400.00
Other	820.00	20.00
Overall Total	6,511.95	1,619.50
Lump Sum Repair Option		☐
Lump Sum Total	0.00	1,619.50
Surveyor Approved Amount		1,619.50
No of Repair Days*	5	3
Remarks	-	P/P REPAIR, PHOTO BEFORE PAINT.
Surveyor Name		Hwee jie
Signature		
Survey Date	23/04/2019	Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: