



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 4325T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REPLACEMENT OF PARTS	DAMAGED		
	RH WING MIRROR ASSY (CONSISTENT)		1,180.00	1,180.00
	LESS 40% DISCOUNT		-472.00	-472.00
			708.00	708.00
	LABOUR			
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE & ALIGN REPAIR / REPLACEMENT PARTS.		300.00	100.00
	CARRY OUT SPRAY PAINTING ON AFFECT AREA RH SIDE PORTION.		300.00	100.00
	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIR, RECONNECT & CHECK ELECTRICAL FUNCTION AFTER REPAIR.		50.00	30.00
			650.00	230.00
GRAND TOTAL			1,358.00	938.00
RECOMMENDED COST OF REPAIRS				938.00

Report Ref No. CC4/ASM19007238/Apa3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.