



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 9753X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT MUDGUARD (CONSISTENT)	SCRATCHED	68.00	68.00
2	FRONT FORK ASSY RH & LH @ \$185.00 (CONSISTENT)	TO REPAIR SEE LABOUR	370.00	-
1	STEM STEERING (CONSISTENT)	NOT NECESSARY	145.00	-
1	SET CONE BEARING (CONSISTENT)	NOT NECESSARY	60.00	-
1	WINDSHIELD (CONSISTENT)	CRACKED	45.00	45.00
1	FRONT COWLING (CONSISTENT)	NOT NECESSARY	185.00	-
1	STAY, FRONT COWLING (CONSISTENT)	NOT NECESSARY	75.00	-
1	HEADLAMP COMP (CONSISTENT)	SCRATCHED	350.00	350.00
1	METER ASSY (CONSISTENT)	SCRATCHED	390.00	390.00
2	FRONT SIGNAL RH & LH @ \$58.00 (CONSISTENT)	O/S SCRATCHED	116.00	58.00
1	FRONT LICENCE PLATE (CONSISTENT)	NECESSARY	15.00	15.00
1	BRAKE LEVER (CONSISTENT)	SCRATCHED	15.00	15.00
1	HANDLEBAR (CONSISTENT)	NOT NECESSARY	68.00	-
1	BALANCER (CONSISTENT)	MISSING	12.00	12.00
1	HANDLE GRIP (CONSISTENT)	NOT NECESSARY	40.00	-
1	SIDE MIRROR (CONSISTENT)	SCRATCHED	50.00	50.00
1	IU UNIT (CONSISTENT)	SCRATCHED	160.00	160.00
1	FUEL TANK COMP (CONSISTENT)	NOT NECESSARY	495.00	-
1	FUEL TANK COVER (CONSISTENT)	NOT NECESSARY	85.00	-
1	STAY, FRONT MUDGUARD (CONSISTENT)	NOT NECESSARY	15.00	-
1	FRONT FOOTRESTBAR (CONSISTENT)	BENT	65.00	65.00
2	FOOTREST RUBBER @ \$8.00 (CONSISTENT)	CUT	16.00	16.00
1	BRAKE PEDAL (CONSISTENT)	NOT NECESSARY	58.00	-
1	MUFFLER (CONSISTENT)	SCRATCHED	1,500.00	1,500.00
1	HEAT PROTECTION, CHROME (CONSISTENT)	SCRATCHED	65.00	65.00
1	HEAT PROTECTION, RUBBER (CONSISTENT)	SCRATCHED	150.00	150.00
1	REAR SIGNAL (CONSISTENT)	SCRATCHED	55.00	55.00
1	TOP BOX BRACKET (CONSISTENT)	NOT NECESSARY	115.00	-
1	REAR FOOTREST RH (CONSISTENT)	SCRATCHED	28.00	28.00
1	REAR FOOTREST BRACKET RH (CONSISTENT)	NOT NECESSARY	75.00	-

Report Ref No. CC4/ASM19007240/R1ga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-	-304.20
			4,886.00	2,737.80
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TOP BOX (SN) (CONSISTENT)	SCRATCHED	260.00	150.00
			260.00	150.00
	<u>LABOUR</u>			
	WORKMANSHIP. INCLUSIVE OF THE REPAIR OF FRONT FORK ASSY RH & LH.		350.00	250.00
	TRANSPORTATION TP-IDAC-SHOP.		100.00	40.00
	BODY CHASSIS REPAIR.	NOT NECESSARY	250.00	-
	TRANSPORTATION 2 WAY TO REPAIR CHASSIS.	NOT NECESSARY	100.00	-
			800.00	290.00
GRAND TOTAL			5,946.00	3,177.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,550.00

Report Ref No. CC4/ASM19007240/R1ga3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.