

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFY 709L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING (N) (CONSISTENT)	NECESSARY	28.00	28.00
1	REAR FENDER RH (N) (CONSISTENT)	DENTED	666.00	666.00
1	REAR END PANEL (N) (CONSISTENT)	DENTED	495.00	495.00
1	REAR TAIL LAMP RH (N) (CONSISTENT)	BROKEN	421.00	421.00
1	REAR TAIL LAMP BUSH (TOP) RH (N) (CONSISTENT)	NECESSARY	6.00	6.00
1	REAR TAIL LAMP BUSH (LOWER) RH (N) (CONSISTENT)	NECESSARY	6.00	6.00
1	REAR BUMPER (N) (CONSISTENT)	BROKEN	689.00	689.00
1	REAR BUMPER LOWER SPOILER (N) (CONSISTENT)	DISLODGE	688.00	688.00
1	REAR BUMPER BEAM RH (N) (CONSISTENT)	BENT	56.00	56.00
1	REAR BUMPER CENTRE BEAM (N) (CONSISTENT)	SERVICEABLE	209.00	-
1	REAR BUMPER INNER SHIELD RH (N) (CONSISTENT)	TORN	38.00	38.00
3	REAR BUMPER INNER SHIELD CLIPS RH (N) (CONSISTENT)	NECESSARY	16.50	16.50
	LESS 10% DISCOUNT		-331.85	-310.95
			2,986.65	2,798.55
	SPECIAL NETT ITEMS			
1	SEALANT (SN) (CONSISTENT)	NECESSARY	40.00	40.00
			40.00	40.00
	LABOUR			
	TO REMOVE +REFIX REAR WINDSCREEN .		140.00	140.00
	TO DISMANTLE+REFIX REAR CUSHION ASSY+REAR SPEAKER BOARD ,ETC.		120.00	80.00
	TO DISMANTLE +RENEW REAR BUMPER LOWER SPOILER +TRANSFER PARKING SENSORS.		160.00	140.00
	TO STRAIGHTEN REAR BODY INCLUDING CUTTING AND WELDING ,TO KNOCK DENTS ON REAR SPARE TYRE PANEL RH AND RENEW OF PARTS.		1,100.00	1,000.00
	TO SPRAY PAINT.		1,000.00	900.00
			2,520.00	2,260.00
	GRAND TOTAL		5,546.65	5,098.55

Report Ref No. CC4/ASM19007247/Bpa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,100.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM19007247/Bpa3q2

LIM TEOW GUAN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor