

01/01/2019

ASS. REC. BY:

REP:

CS/FCI19007265/Kgd302

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Joanne Yong (CWS)

FCI

Date/Time: 24/4/2019

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EYA / INV / MV / CS

To Inspect Vehicle No: SHC 5464B

Insured: SHA 1797C

at Workshop in/ Frane-cab.

Tel:

of 2 AMK 863

Policy No:

Claim No: D19002675 MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 20/4/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 5464B - X

SHA 1797C - X

24/4/19@ 24hrs revised to Joanne Yong by email.

ASS. REC. BY:

REF:

F02/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S/H054843 Yr Regn: 12, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Peugeot Latitude c.c. 1995

Colour: m White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 431782 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VFIABL15AUC. 280949

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 20/4/19

Survey held at

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 24/4/19

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S body

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 26 APR 2019

Date/Time, File Pass to?

11/26/14 _____ : Prell. Report

_____ : Final Report

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / I.B.J. (\$) 5950

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: 750

Transportation:

S + RS. SI

Fees/OS

Others

TOTAL

750



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002675MFSH

Date: 25 April 2019

Our Ref: CS/FCI19007265/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5464B .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 24/04/2019 at the premises of M/s TRANS-CAB, and have the following to report:-

Workshop Estimate Amount	: S\$ 41,011.67 .
Revised Estimate Amount	: S\$ 6,565.70 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the n/s body.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	22-04-2019	Our Ref No. D19002675MFSH
Accident Date	20-04-2019	Claim Type. Third Party
Insured Vehicle	SHA1797C	Third Party Vehicle. SHC5464B
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	AMANDA TAY	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

*Renneth***IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Thursday, 25 April 2019 4:02 PM
To: Shiau Chan (LKKAuto)
Subject: RE: TP VEHICLE SHC 5464B (DOA: 20/04/2019) -- AAD1904-198
Attachments: image001.wmz

Hi Shiau Chan

We confirmed COR amount \$ 5,250.00 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Thursday, 25 April, 2019 2:47 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: TP VEHICLE SHC 5464B (DOA: 20/04/2019)

Dear Wai Yin,

Based on our surveyor's marking estimate, the calculation of repair cost will be at Lump Sum \$5,250.00 and 4 repair days.

Kindly check.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 25 April 2019 2:44 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002675MFSH/1
Attachments: CSFCI19007265Kqd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SHC 5464B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 24 April 2019 2:19 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002675MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 24 April 2019 9:56 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002675MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHC5464B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Apr 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002429
Chassis No.:	VF1ABL15AUC280949
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	18 Dec 2014
First Registration Date:	18 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Dec 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	17 Dec 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,668.00
COE Rebate Amount:	\$23,581.00
Total Rebate Amount:	\$32,954.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Apr 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5464B

AAD1904-198

Not Authored
61 Sep @ 5250h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5464B

VF1ABL15AUC280949

RENAULT

LATITUDE

20.4.2019

FCIL

18/12/2014

PART**LIST**

1	BUMPER COVER FRT	\$	<i>R</i>	1,259.42	X
1	HEADLAMP LH	\$	<i>R</i>	1,184.43	X
1	HEADLAMP HARNESS	\$	<i>R</i>	928.29	X
1	FENDER PANEL FRT LH	\$	<i>R</i>	783.83	X
1	WHEELARCH FRT LH	\$	<i>R</i>	278.84	X
1	FENDER BRACKET LOWER LH	\$	<i>R</i>	15.79	X
1	FENDER INSULATOR LH	\$	<i>R</i>	130.84	X
1	DOOR PANEL FRT LH	\$	<i>B1/way</i>	2,844.66	X
1	DOOR HINGE UPPER LH	\$	<i>R</i>	261.28	X
1	DOOR HINGE LOWER LH	\$	<i>R</i>	300.55	
1	DOOR CHECK FRT LH	\$	<i>R</i>	194.77	
1	DOOR LOCK FRT LH	\$	<i>R</i>	908.75	
1	DOOR CATCH FRT LH	\$	<i>R</i>	131.23	
1	DOOR HANDLE OUTER FRT LH	\$	<i>R</i>	477.76	
1	DOOR HANDLE COVER FRT LH	\$	<i>R</i>	13.22	
1	DOOR HANDLE MODULE FRT LH	\$	<i>R</i>	133.60	
1	DOOR REGULATOR FRT LH	\$	<i>R</i>	505.19	
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>R</i>	796.46	
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>R</i>	120.97	
1	DOOR PANEL REAR LH	\$	<i>R</i>	2,844.66	
1	DOOR GUIDE REAR LH	\$	<i>R</i>	176.82	
1	DOOR HINGE UPPER LH	\$	<i>R</i>	274.50	
1	DOOR HINGE LOWER LH	\$	<i>R</i>	300.55	
1	DOOR CHECK REAR LH	\$	<i>R</i>	203.06	X
1	DOOR LOCK REAR LH	\$	<i>R</i>	908.75	
1	DOOR HANDLE OUTER REAR LH	\$	<i>R</i>	126.49	
1	DOOR HANDLE CAP REAR LH	\$	<i>R</i>	35.52	
1	DOOR HANDLE SEAL REAR LH	\$	<i>R</i>	7.89	
1	DOOR HANDLE COVER REAR LH	\$	<i>R</i>	13.22	X
1	DOOR HANDLE MODULE REAR LH	\$	<i>R</i>	133.60	
1	DOOR REGULATOR REAR LH	\$	<i>R</i>	1,135.10	

Trans-cab Auto Services Pte Ltd**AAD1904-198**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5464B

1	DOOR REGUALTOR MOTOR REAR LH	\$	893.75	
1	DOOR REGULATOR NUT REAR LH	\$	12.43	
1	DOOR REGUALTOR MOTOR SCREW REAR L70Y	\$	6.31	
1	DOOR FINISHER REAR LH	\$	423.10	
1	DOOR MOULDING REAR LH	\$	176.82	
1	DOOR MOULDING CLIP L70Y	\$	5.92	
1	DOOR MOULDING SCREW L70Y	\$	6.91	
1	DOOR CASING REAR LH	\$	1,509.06	
1	DOOR WATER SHIELD REAR LH	\$	30.39	
1	DOOR CASING CLIP	\$	12.63	
1	DOOR CASING LIGHT L70Y	\$	48.74	
1	DOOR FINISHER INNER REAR LH	\$	323.44	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	46.97	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33	
1	DOOR GRAB HANDLE REAR LH	\$	210.96	
1	DOOR BLIND REAR LH	\$	741.80	
1	DOOR WHEATHESTRIIP REAR LH	\$	410.66	
1	DOOR SEAL REAR LH	\$	162.02	
1	DOOR GLASS RUNNER SEAL REAR LH	\$	229.31	
1	DOOR WAIST SEAL OUTER REAR LH	\$	334.69	
1	DOOR WAIST SEAL INNER REAR LH	\$	115.64	
1	FENDER PANEL REAR LH	\$	3,299.13	
1	FENDER PANEL INNER TRIM REAR	\$	671.45	
1	WHEELARCH REAR LH	\$	543.47	
1	DOOR MIRROR ASSY LH	\$	1,483.40	
1	ROCKER PANEL INNER GARNISH LH	\$	466.51	X
1	ROCKER PANEL INNER LH	\$	1,024.79	X
1	ROCKER PANEL CENTER LH	\$	990.25	X
1	BUMPER COVER REAR	\$	1,108.46	X
		\$	32,780.05	
10%		\$	3,278.00	
		\$	29,502.04	

Specical Nett

1SET	BUMPER CLIP FRT	\$	66.00	X
1	BUMPER BRACKET CLIP FRT LH	\$	12.00	X
1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	X

Trans-cab Auto Services Pte Ltd**AAD1904-198**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5464B

1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00	60sn
1	FRONT DOOR STICKER 'Chassis'	\$	nn	50.00	15sn
1	REAR DOOR STICKER '6555 3333'	\$	nn	80.00	60sn
1	DOOR CHECK BOLT	\$	nn	22.69	} X
1	DOOR GUIDE SCREW	\$	nn	10.85	
1	DOOR HINGE BOLT	\$	nn	10.85	
1	DOOR HINGE NUT RH	\$	nn	14.60	
1	DOOR CHECK BOLT	\$	nn	22.69	
1	DOOR CHECK NUT	\$	nn	3.75	
1	DOOR LOCK SCREW L70Y	\$	nn	6.12	
1	DOOR CATCH SCREW L70Y	\$	nn	10.06	
1	FRONT LEFT TYRE RIM	\$	nn	380.00	} 61
1	FRONT LEFT TYRE	\$	nn	330.00	
TOTAL		\$		1,329.63	
TOTAL PARTS		\$		30,831.67	

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 4,200.00 6001

To apply paint protection system (PPS) maintain and enhancement

\$ nn 380.00 X

Putty and spray painting of the affected portion.

\$ 4,200.00 11501

To rust-proofing of the affected areas.

\$ 170.00 601

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

Trans-cab Auto Services Pte Ltd

AAD1904-198

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5464B

To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 2cl
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X
Towing Fee	\$	nn 120.00 X
TOTAL	\$	10,180.00
Over All Total	\$	41,011.67

LUMP SUM(REPAIR DAY)

20 DAYS

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19007265/Kqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSES SINGAPORE 068877		Date : 07-05-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1797C	Veh. Inspected	SHC 5464B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002675MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	24/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC280949	Colour	METALLIC WHITE / RED	
Odometer	431782	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/04/2019	Inspection Date	24/04/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5464B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	TO REPAIR SEE LABOUR	1,259.42	-
1	HEADLAMP LH	SERVICEABLE	1,184.43	-
1	HEADLAMP HARNESS	SERVICEABLE	928.29	-
1	FENDER PANEL FRT LH	BENT	783.83	783.83
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH	TO REPAIR SEE LABOUR	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	DOOR PANEL FRT LH	BENT / WARPED	2,844.66	2,844.66
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT LH	SERVICEABLE	194.77	-
1	DOOR LOCK FRT LH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT LH	SERVICEABLE	131.23	-
1	DOOR HANDLE OUTER FRT LH	TO REPAIR SEE LABOUR	477.76	-
1	DOOR HANDLE COVER FRT LH	TO REPAIR SEE LABOUR	13.22	-
1	DOOR HANDLE MODULE FRT LH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT LH	SERVICEABLE	505.19	-
1	DOOR REGULATOR MOTOR FRT LH	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT LH	SERVICEABLE	120.97	-
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR GUIDE REAR LH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH	SERVICEABLE	203.06	-

Report Ref No. CS/FCI19007265/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR LOCK REAR LH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR HANDLE OUTER REAR LH	TO REPAIR SEE LABOUR	126.49	-
1	DOOR HANDLE CAP REAR LH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR LH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR LH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR LH	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR LH	SERVICEABLE	1,135.10	-
1	DOOR REGULATOR MOTOR REAR LH	SERVICEABLE	893.75	-
1	DOOR REGULATOR NUT REAR LH	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR LH	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR LH	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y	SERVICEABLE	5.92	-
1	DOOR MOULDING SCREW L70Y	SERVICEABLE	6.91	-
1	DOOR CASING REAR LH	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD REAR LH	SERVICEABLE	30.39	-
1	DOOR CASING CLIP	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y	SERVICEABLE	48.74	-
1	DOOR FINISHER INNER REAR LH	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER REAR LH	TO REPAIR SEE LABOUR	46.97	-
1	DOOR FINISHER BRACKET INNER REAR LH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR LH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR LH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR GRAB HANDLE REAR LH	SERVICEABLE	210.96	-
1	DOOR BLIND REAR LH	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR LH	SERVICEABLE	410.66	-
1	DOOR SEAL REAR LH	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL REAR LH	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR LH	SERVICEABLE	334.69	-

Report Ref No. CS/FCI19007265/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR WAIST SEAL INNER REAR LH	SERVICEABLE	115.64	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL INNER TRIM REAR	SERVICEABLE	671.45	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	DOOR MIRROR ASSY LH	CRACKED	1,483.40	1,483.40
1	ROCKER PANEL INNER GARNISH LH	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER LH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL CENTER LH	TO REPAIR SEE LABOUR	990.25	-
1	BUMPER COVER REAR	TO REPAIR SEE LABOUR	1,108.46	-
	LESS 10% DISCOUNT		-3,278.00	-511.19
			29,502.04	4,600.70
	SPECIAL NETT ITEMS			
1	SET BUMPER CLIP FRT (SN)	NOT NECESSARY	66.00	-
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER "CHASSIS" (SN)	NECESSARY	50.00	15.00
1	REAR DOOR STICKER "65553333" (SN)	NECESSARY	80.00	60.00
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE BOLT (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE NUT RH (SN)	NOT NECESSARY	14.60	-
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR CHECK NUT (SN)	NOT NECESSARY	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	NOT NECESSARY	6.12	-

Report Ref No. CS/FCI19007265/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR CATCH SCREW L70Y (SN)	NOT NECESSARY	10.06	-
1	FRONT LEFT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	FRONT LEFT TYRE (SN)	SERVICEABLE	330.00	-
			1,329.61	135.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME. }		4,200.00	600.00
	INCLUSIVE OF THE REPAIR OF BUMPER COVER FRT,FENDER BRACKET LOWER LH,DOOR HINGE UPPER LH,DOOR HINGE LOWER LH,DOOR LOCK FRT LH,DOOR HANDLE OUTER FRT LH,DOOR HANDLE COVER FRT LH,DOOR PANEL REAR LH,DOOR HINGE UPPER LH,DOOR HINGE LOWER LH,DOOR LOCK REAR LH,DOOR HANDLE OUTER REAR LH,DOOR FINISHER BRACKET INNER REAR LH,FENDER PANEL REAR LH,ROCKER PANEL INNER LH,ROCKER PANEL CENTER LH AND BUMPER COVER REAR. }		-	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,200.00	1,150.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TOWING FEE.	NOT NECESSARY	120.00	-
			10,180.00	1,830.00
	GRAND TOTAL		41,011.65	6,565.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,250.00

Report Ref No. CS/FCI19007265/Kqd3n2



Report Ref No. CS/FCI19007265/Kqd3n2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.