Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19007281/UKA3Q2

Date: 23/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SKJ1416U Insured Vehicle No: SDX328G

Vehicle No:

Date of Loss: 09/04/2019 Nature of Claim: TP Claim No: 0833210027SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKJ1416U

Make & Model: HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR Engine No: G4FGCU663591

(A)

Reg. Date: 25/02/2013 (Man. Year: 2012) Chassis No: KMHDH41CMDU679919

Colour: White Odometer: 123488 km

Engine Capacity: 1591 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
Front Right Side: Michelin 7 mm
Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	792.80	0.00	792.80	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	600.00	600.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,992.80	600.00	1,392.80	69.89
+ GST 7.00/7.00% (S\$)	139.50	42.00	97.50	69.89
Nett Amount (S\$)	2,132.30	642.00	1,490.30	69.89

INSPECTION

Date of Assignment: 25/04/2019

Date Inspected: 25/04/2019 Inspected At: Hock Wah Motor Workshop Pte Ltd

(Tampines)

0.00

Blk 900B, Tampines Street 93,, Tampines Industrial Park A, #01-204

Singapore 528840

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA Manager: Khanchna Pothuraj

Global Sum Settlement (S\$)

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*FRT BUMPER	Repair	450.00 FL	*-FL		
2	2		*FRT BUMPER SIDE RETAINER LH & RH	Not Necessary	36.00 FL	*- FL		
3	12		*FRT BUMPER CLIPS	Not Necessary	60.00 FL	*-FL		
4	1		*FRT FENDER LH	Repair	445.00 FL	*- FL		
F=Franchise part. L=ListItemDisc.								
Sub Total (S\$)					991.00	0.00		
- List Item Discount on L Items 20.00/20.00% (S\$)				198.20	0.00			
				Total Parts (S\$)	792.80	0.00		
Report was unsubmitted during this print-out.								

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	SPRAY PAINT ON THE AFFECTED AREAS	New	600.00	200.00
2	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	New	600.00	400.00
	Gross Labo	ur Cost (S\$)	1,200.00	600.00
Г	Daniel von von den itte de den			
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >