

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19007300/UGA3Q2

Date: 11/08/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJX7211S	Insured Vehicle No :	SHC8164Y
Date of Loss: 30/03/2019	Nature of Claim: TP	Claim No: MCT19030821

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX7211S	Engine No:	CAV190400
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 L (A)	Chassis No:	WVWZZZ13ZAV443100
Reg. Date:	06/07/2010 (Man. Year: 2010)	Odometer:	84762 km
Colour:	Grey		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40Z R18	Rear Tyre Size:	235/40Z R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,196.55	0.00	1,196.55	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	180.00	1,120.00	86.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	2,496.55	180.00	2,316.55	92.79
+ Loss of Use (2.0 x S\$50.00/day) (\$\$)		100.00		
	Nett Liability (\$\$)	280.00		

INSPECTION

Date of Assignment:	25/04/2019		
Date Inspected:	25/04/2019	Inspected At:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53 Singapore 417808
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jul 2020)
Parts:	144	VOLKSWAGEN SCIROCCO 1.4 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX7211S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIGHT WING MIRROR	Repair	695.00 FL	*- FL
2	1		*FRONT RIGHT WING MIRROR GARNISH	Not Necessary	107.00 FL	*- FL
3	1		*FRONT RIGHT WING MIRROR SIGNAL LAMP	Not Necessary	175.00 FL	*- FL
4	1		*FRONT RIGHT MIRROR SPONGE BASED	Not Necessary	57.00 FL	*- FL
5	1		*FRONT RIGHT DOOR (NPA)	Not Necessary	0.00 FL	*- FL
6	1		*FRONT RIGHT DOOR GLASS OUTER MOULDING	Not Necessary	175.00 FL	*- FL
7	1		*FRONT RIGHT DOOR INNER TRIMBOARD CLIPS	Not Necessary	48.00 FS	*- FS
					Sub Total (\$\$)	1,257.00 0.00
					- List Item Discount on L Items 5.00/5.00% (\$\$)	60.45 0.00
					Total Parts (\$\$)	1,196.55 0.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REPAIR & RENEW AFFECTED ACCIDENT AREAS }	New	400.00	180.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS }	New	400.00	0.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	0.00
4	TO CONDUCT DIAGNOSTIC & RESET ENGINE MANGEMENT	New	450.00	0.00
Gross Labour Cost (S\$)			1,300.00	180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >