

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19007303/AGA3Q2

**Date:** 17/04/2020

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SGM5660K	<b>Insured Vehicle No :</b>	SHC8122T
Date of Loss: 21/04/2019	Nature of Claim:	TP Claim No: MCT19040609

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGM5660K	Engine No:	CYG022614
Make & Model:	AUDI A6, 1.8 TFSI Ultra (PI) (NAV) (A)	Chassis No:	WAUZZZ4G9JN027725
Reg. Date:	17/05/2018 (Man. Year: 2017)	Odometer:	29342 km
Colour:	Bronze		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,711.00	864.00	7,847.00	90.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,372.00	1,842.00	1,530.00	45.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>12,083.00</b>	<b>2,706.00</b>	<b>9,377.00</b>	<b>77.60</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>845.81</b>	<b>189.42</b>	<b>656.39</b>	<b>77.60</b>
<b>Nett Amount (S\$)</b>	<b>12,928.81</b>	<b>2,895.42</b>	<b>10,033.39</b>	<b>77.60</b>
<b>+ Car Rental (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,202.87</b>		

#### INSPECTION

Date of Assignment:	25/04/2019	
Date Inspected:	30/04/2019	Inspected At:
		Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 12 Apr 2020)
<b>Parts:</b> 143	AUDI A6 1.8 TFSI Ultra (PI) (NAV) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGM5660K)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT DOOR -LH	Repair	3,374.00 FS	*- FS	
2	1		*FRONT DOOR STONE GUARD FILM -LH	Necessary	110.00 FS	*110.00 FS	
3	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	173.00 FS	*- FS	
4	1		*FRONT DOOR OUTER SEAL -LH	Not Necessary	212.00 FS	*- FS	
5	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS	
6	1		*CLEANING SOLATION	Not Necessary	65.00 FS	*- FS	
7	1		*APPLICATOR	Not Necessary	7.00 FS	*- FS	
8	1		*FRONT DOOR CATCH -LH	Not Necessary	109.00 FS	*- FS	
9	1		*FRONT DOOR HANDLE -LH	Cut	537.00 FS	*537.00 FS	
10	1		*FRONT DOOR HANDLE CAP -LH	Cut	102.00 FS	*101.50 FS	
11	1		*FRONT DOOR HANDLE CAP HOUSING -LH	Not Necessary	7.00 FS	*- FS	
12	1		*FRONT DOOR HANDLE SENSOR -LH	Not Necessary	237.00 FS	*- FS	
13	1		*FRONT DOOR SLOT SEAL CHROME TRIM	Not Necessary	310.00 FS	*- FS	
14	1		*FRONT WIND MIRROR MOUNTING -LH	Not Necessary	1,291.00 FS	*- FS	
15	1		*FRONT WIND MIRROR COVER -LH	Repair	195.00 FS	*- FS	
16	1		*FRONT WIND MIRROR TURN SIGNAL -LH	Cut	116.00 FS	*115.50 FS	
17	1		*FRONT WIND MIRROR WARNING DISPLAY -LH	Not Necessary	189.00 FS	*- FS	
18	1		*FRONT WIND MIRROR GLASS -LH	Not Necessary	1,132.00 FS	*- FS	
19	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS	
					<b>Total Parts (S\$)</b>	<b>8,711.00</b>	<b>864.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI LOCK SYSTEMS AND POWER WINDOW DEVICES ,INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	280.00	0.00
2	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS WING MIRROR ASSY .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,400.00	700.00
3	TO RESPRAY LHS FRONT DOOR ,DOOR HANDLE AND LHS WING MIRROR COVER	New	1,500.00	950.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,372.00</b>	<b>1,842.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >