

REPAIR ESTIMATE*

VEHICLE NO : SH 6203A

DATE 24/4/2019 15:00

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>X 1442</i>			\$ 418.30
	Front Bumper Centre Moulding <i>X</i>			\$ 188.00
	Front Bumper Clips 10 pcs <i>X</i>			\$ 22.00
	SUB TOTAL			\$ 628.30
	LESS 20%			\$ 125.66
	DISCOUNTED TOTAL			\$ 502.64
	Labour Charge			<i>100</i>
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
				<i>200</i>
	TOTAL LABOUR			\$ 700.00
	ESTIMATE TOTAL			\$ 1,202.64
<p><i>Ka luh 10004</i></p> <p><i>24/4/19 1505L</i></p> <p><i>2 Rep</i></p> <p><i>PP</i></p> <p><i>After Repair photo</i></p> <div data-bbox="876 1365 1429 1848" data-label="Text"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before later spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from insurance company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				