

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : AXA INSURANCE SINGAPORE PTE LTD

PARTICULARS OF CLAIM			
Claim Type:	TP	Ref. No:	YTHQ/TP/1904/016
Policy No:	5107630825	Date of Loss:	18/04/2019
Vehicle Reg. No.:	SJK9581D	Driveable?	no
Driver Age:	19/04/1989	Third Party Vehicle No.:	SMD6210X, SLU5820P
Any Injuries?	no	Contact No:	94241355
Insured/Claimant:	SENIN BIN HASSAN	Driver:	MUHAMMAD SYAHMI BIN SENIN

Make/Model:	Honda, FIT 1.3G A	Vehicle Reg. Date:	18/04/2019
Vehicle Colour:	BLUE	Engine Number:	L13A4122428
Chassis No:	GE61110497	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: CHAIN COLLISION
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS	Amount
Parts	8,309.40
Miscellaneous Items	1,133.00
Labour	2,190.00
Paintwork Labour	1,965.00
Towing	0.00
Gross Total(S\$):	13,597.40
GST 7.00%(S\$):	951.82
Nett Amount(S\$):	14,549.22

This claim is handled by: Sky Toh T C

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR TAILGATE <i>BVC</i>	0.00	260.00	+10.00	286.00
2	1	REAR TAILGATE LOCK <i>SVC X</i>	0.00	78.00	+10.00	85.80
3	1	REAR TAILGATE LOCK CATCH <i>nnx</i>	0.00	30.00	+10.00	33.00
4	1	REAR TAILGATE RUBBER <i>DEF</i>	0.00	50.00	+10.00	55.00
5	1	REAR TAILGATE INNER BOARD <i>!</i>	0.00	70.00	+10.00	77.00
6	1	REAR TAILGATE HINGE RH <i>nnx</i>	0.00	30.00	+10.00	33.00
7	1	REAR TAILGATE HINGE LH <i>nnx</i>	0.00	30.00	+10.00	33.00
8	1	REAR TAILGATE OUTER GARNISH <i>!</i>	0.00	70.00	+10.00	77.00
9	2	REAR NUMBER PLATE LAMP <i>nnx</i>	0.00	80.00	+10.00	88.00
10	1	REAR BUMPER <i>DEF</i>	0.00	160.00	+10.00	176.00
11	1	REAR BUMPER SIDE RETAINER LH <i>!</i>	0.00	15.00	+10.00	16.50
12	1	REAR BUMPER SIDE RETAINER RH <i>!</i>	0.00	15.00	+10.00	16.50
13	1	REAR BUMPER BRACKET RH <i>nnx</i>	0.00	13.00	+10.00	14.30
14	1	REAR BUMPER BRACKET LH <i>nnx</i>	0.00	13.00	+10.00	14.30
15	1	REAR BUMPER STAY RH <i>nnx</i>	0.00	25.00	+10.00	27.50
16	1	REAR BUMPER STAY LH <i>nnx</i>	0.00	25.00	+10.00	27.50
17	1	REAR BUMPER REINFORCEMENT <i>!</i>	0.00	180.00	+10.00	198.00
18	1	REAR BUMPER TOWING COVER <i>SCR</i>	0.00	13.00	+10.00	14.30
19	1	REAR TAILLAMP LH <i>!</i>	0.00	130.00	+10.00	143.00
20	1	REAR TAILLAMP RH <i>!</i>	0.00	130.00	+10.00	143.00
21	1	REAR TAILLAMP LOWER BRACKET RH <i>nnx</i>	0.00	28.00	+10.00	30.80
22	1	REAR TAILLAMP LOWER BRACKET LH <i>nnx</i>	0.00	28.00	+10.00	30.80
23	1	REAR END PANEL <i>!</i>	0.00	220.00	+10.00	242.00
24	1	REAR END PANEL INNER GARNISH <i>!</i>	0.00	60.00	+10.00	66.00
25	1	REAR SPARE TYRE PANEL <i>nnx</i>	0.00	370.00	+10.00	407.00
26	1	REAR SPARE TYRE BOARD <i>nnx</i>	0.00	130.00	+10.00	143.00
27	1	FRONT BUMPER <i>Repair X</i>	0.00	230.00	+10.00	253.00
28	1	FRONT BUMPER SIDE RETAINER RH <i>nnx</i>	0.00	18.00	+10.00	19.80
29	1	FRONT BUMPER SIDE RETAINER LH <i>nnx</i>	0.00	18.00	+10.00	19.80
30	1	FRONT BUMPER LOWER GRILLE <i>nnx</i>	0.00	300.00	+10.00	330.00
31	1	FRONT GRILLE <i>nnx</i>	0.00	85.00	+10.00	93.50
32	1	FRONT GRILLE LOGO <i>nnx</i>	0.00	30.00	+10.00	33.00
33	1	FRONT HEADLAMP RH <i>nnx</i>	0.00	400.00	+10.00	440.00
34	1	FRONT HEADLAMP LH <i>nnx</i>	0.00	400.00	+10.00	440.00
35	1	FRONT HEADLAMP PANEL RH <i>nnx</i>	0.00	22.00	+10.00	24.20
36	1	FRONT HEADLAMP PANEL LH <i>nnx</i>	0.00	22.00	+10.00	24.20
37	1	BONNET <i>nnx</i>	0.00	270.00	+10.00	297.00
38	1	BONNET HINGE RH <i>nnx</i>	0.00	35.00	+10.00	38.50
39	1	BONNET HINGE LH <i>nnx</i>	0.00	35.00	+10.00	38.50
40	1	BONNET HINGE LOCK <i>nnx</i>	0.00	75.00	+10.00	82.50
41	1	BONNET HINGE LOCK CATCH <i>nnx</i>	0.00	120.00	+10.00	132.00
42	1	FRONT SUPPORT PANEL <i>nnx</i>	0.00	200.00	+10.00	220.00
43	1	AIRCON CONDENSER <i>nnx</i>	0.00	300.00	+10.00	330.00
44	2	AIRCON CONDENSER AIR GUIDE <i>nnx</i>	0.00	52.00	+10.00	57.20
45	1	AIRCON CONDENSER FAN COWLING <i>nnx</i>	0.00	78.00	+10.00	85.80
46	1	AIRCON CONDENSER FAN MOTOR <i>nnx</i>	0.00	110.00	+10.00	121.00
47	1	AIRCON CONDENSER FAN BLADE <i>nnx</i>	0.00	95.00	+10.00	104.50
48	1	REAR FENDER RH <i>nnx</i>	0.00	400.00	+10.00	440.00
49	1	REAR FENDER LH <i>nnx</i>	0.00	400.00	+10.00	440.00
50	1	REAR FENDER INNER TRIM BOARD RH <i>nnx</i>	0.00	170.00	+10.00	187.00
51	1	REAR FENDER INNER TRIM BOARD LH <i>nnx</i>	0.00	170.00	+10.00	187.00
52	1	REAR FENDER INNER SHIELD RH <i>nnx</i>	0.00	57.00	+10.00	62.70
53	1	REAR FENDER INNER SHIELD LH <i>nnx</i>	0.00	57.00	+10.00	62.70

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
54	1	RADIATOR <i>nnx</i>	0.00	300.00	+10.00	330.00
55	1	RADIATOR FAN COWLING <i>nnx</i>	0.00	60.00	+10.00	66.00
56	1	RADIATOR FAN MOTOR <i>nnx</i>	0.00	200.00	+10.00	220.00
57	1	RADIATOR FAN BLADE <i>nnx</i>	0.00	70.00	+10.00	77.00
58	1	AIR CON SUCTION PIPE <i>nnx</i>	0.00	170.00	+10.00	187.00
59	1	AIR CON RETURN PIPE <i>nnx</i>	0.00	172.00	+10.00	189.20
60	1	AIR CON DISCHARGE PIPE <i>nnx</i>	0.00	180.00	+10.00	198.00

Total Parts (S\$) 8,309.40

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR TAILGATE INNER BOARD CLIPS ?	0.00	30.00	0.00	30.00
2	1	REAR NUMBER PLATE <i>nnx</i>	0.00	35.00	0.00	35.00
3	1	REAR BUMPER CLIPS <i>nec</i>	0.00	35.00	0.00	35.00
4	1	FRONT BUMPER CLIPS <i>nnx</i>	0.00	30.00	0.00	30.00
5	1	FRONT NUMBER PLATE <i>nnx</i>	0.00	35.00	0.00	35.00
6	1	REAR BUMPER LOWER SKIRT (SPORTS) <i>nnx</i>	0.00	350.00	0.00	350.00
7	1	FRONT BUMPER LOWER SKIRT (SPORTS) <i>nnx</i>	0.00	350.00	0.00	350.00
8	1	REAR WINDSCREEN SEALANT <i>nec</i>	0.00	48.00	0.00	48.00
9	1	REAR BUMPER SENSORS (1 SET) <i>shorted</i>	0.00	220.00	0.00	220.00

Sub Total (S\$) 1,133.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00 30
2	1	To Pressure Test Air Con Condenser and Radiator For Leakage.	120.00	120.00	0.00	120.00 X
3	1	To Transfer Rear Tailgate.	80.00	80.00	0.00	80.00 50
4	1	To Remove & Refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.	180.00	180.00	0.00	180.00 X
5	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 ✓
6	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	100.00	0.00	100.00 ✓
7	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	1,600.00	1,600.00	0.00	1,600.00 600

Gross Labour Cost (S\$) 2,190.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	40.00	0.00	40.00 X
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00	45.00 X
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	80.00	80.00	0.00	80.00 20
4	1	To Spray painting on the Replaced and Repair	1,800.00	1,800.00	0.00	1,800.00 650

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
		Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.				

Gross Labour Cost (\$\$)

1,965.00

< END OF ESTIMATES >

Three Jia - LKK

26/4/19

L/S 4 days



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: