



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 5868B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	1,196.44	-
1	REAR BUMPER LOWER (SN) (CONSISTENT)	CUT	690.66	690.66
1	REAR BUMPER MOULDING (SN) (CONSISTENT)	CUT	412.39	412.39
1	REAR BASIC MOUNTING FOR BUMPER (SN) (CONSISTENT)	SERVICEABLE	199.69	-
1	REAR NO PLATE WITH CASING (SN) (CONSISTENT)	NECESSARY	60.00	60.00
			2,559.18	1,163.05
	<u>LABOUR</u>			
	PANEL BEATING TO REPAIR AFFECTED AREAS ,REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.INCLUSIVE OF THE REPAIR OF REAR BUMPER .		1,200.00	960.00
	RESPRAY REAR BUMPER .		750.00	600.00
	USING XENTRY SYSTEM TO CHECK CONTROL UNITS ,RESET MEMORY TO STANDARD SETTINGS.		380.00	380.00
	CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE .		120.00	120.00
			2,450.00	2,060.00
GRAND TOTAL			5,009.18	3,223.05
RECOMMENDED COST OF REPAIRS				3,223.05

Report Ref No. CC4/ASM19007357/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.