

REF: CS3/LPC/18015893/GVD3-1

700 Qiang
Ong li li

ASSIGNMENT (Office)

lpc

Date/Time: 24/04/2019

Bill to

Q1: 2 X VEH RES / OD RES / EVA / INV / MV / C

Q2: X

SLQ 284AL

Insured: GBB 7479Y

Thup Lu Thut

Id: 96773832

Blk 1 Kaki Blk Ave 6 #01-35

Claim No: 18118/18/VCS/020862

Excess:

DOA 28/8/18

Q3: Q1 / REF. / REV 24 HRS lup?

10.02am

Person Contacted

Mr. Tan

H.O.D. Endorsement

Vehicle IN/OUT

Sub instruction (X) Estimate

GBB 7479Y - NA MSG 18015893/16/K4

DOA: 28/8/18

SLQ 284AL - NA MSG 18015893/16/K4

DOA: 28/8/18

Submit Pres report

~~\$5800~~ . 5 Days .

~~\$650~~

4

21/6/19

LS

(LS)

(Reel 5600, 4990)


20/6/2019

RECEIVED 21 JUN 2019

PAS
XAL


REF:

0993C /

ASSIGNMENT

From: _____ Date: _____
Estimate: _____
ODI: ☒ PRES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To: _____
at: _____
of: _____
Insured: _____
PPA: _____
C/O: _____
Sum: _____ Excess: _____
IC: _____
Mile: _____
F: _____
Rep: _____



Rep: _____
at the time of inspection.

Bel: _____
IDA: _____ Consistent? Yes or No
GIA: _____ Consistent? Yes or No
Est: _____ 4 days Res: Yes or No
Lur: _____ 20 % 3 Val: Yes or No

CA: _____ REP: 7 24 HRS

Dak: _____ Person Contacted

Vehicle: IN / OUT

Yr Regn: 03 Jul 2017
Type: ☒ M Car / ☐ M Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or
Make: Mazda 5 CC 1998
Colour: white A/C Insured / Std / NI / NA
Sp. Reading: 21821 T/Radio: Insured / Std / NI / NA

Eng. No: _____
C/No: IM6CW1071H0125825

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 205/55 R16
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
☒ TOYO / ☐ YOKO or

Front Rear
R/Bal: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A. D.O.I. 03-09-18

Survey held at: W/S 12pm

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Action / Instruction
\$3,000 - \$4,000

RECEIVED 15 OCT 2018

☐ Preli. Report
☒ Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee

Transportation

Site Insp. (\$)

Interview (\$)

Tech. Insp. (\$)

Weekend (\$)

TOTAL

450

Nivitha (LKK Auto)


From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 24 April 2019 3:32 PM
To: Nivitha (LKK Auto); assignments@lkkauto.com
Cc: 'SUR'
Subject: RE: Your Ref: LCH.ct/2KB02-80775.18 Our Ref: 18/18/18/VC05/020862 Accident involving GBB7479Y and SLQ2844L on 28/8/2018 [External General]
Attachments: 20862 TPD SURVEY REPORT.pdf

Lonpac External - General

Dear Nivitha

Attached is the TP survey report, please let us have your surveyor's review and report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 30 August, 2018 10:03 AM
To: ONG LI LI; assignments@lkkauto.com
Cc: 'SUR'
Subject: RE: Your Ref: LCH.ct/2KB02-80775.18 Our Ref: 18/18/18/VC05/020862 Accident involving GBB7479Y and SLQ2844L on 28/8/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Report Ref : TP18080021

Date: 12 MAR 2019

Wong Cheng Yeo Larry
c/o Hup Ley Huat Motor Spray Painting Services
Blk 1, #01- 35
Kaki Bukit Ave 6
Singapore 417883

THIRD PARTY SURVEY
ACCIDENT OCCURED ON 28 AUG 2018

Workshop Name and Address

Hup Ley Huat Motor Spray Painting Services
Blk 1, #01- 35
Kaki Bukit Ave 6
Singapore 417883

As per your instruction dated 03 Sept 2018
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

with regard to the above matter.
SLQ2844L

1. VEHICLE PARTICULARS

Registration No : SLQ2844L
Model : MAZDA5 SP
Year / Capacity : July 2017 / 1998 cc
Chassis No : JM6CW1071H0125825

Engine No : PE10503328
Mileage : n.a km
Colour : Meatlic White

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	195/50/R15	Bridgestone	9.00 mm	Sport
REAR O/S :	195/50/R15	Bridgestone	9.00 mm	Sport
FRONT N/S :	195/50/R15	Bridgestone	9.00 mm	Sport
REAR N/S :	195/50/R15	Bridgestone	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 06 working days to complete
5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SLQ2844L

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
-----	-------------------	-----------	---------------------------------	------------------------------------

List Items

1 pc	Front bumper	bent	\$ 838.10	\$ 838.10 /
2 pcs	Front bumper side retainer	bent	\$ 24.40	\$ 24.40 /
2 pcs	Front bumper bracket	distorted	\$ 78.20	\$ 78.20 X NV
1 pc	Front bumper reinforcement	necessary	\$ 328.80	\$ 328.80 /
10 pcs	Front bumper clips	necessary	\$ 45.00	\$ 45.00 /
2 pcs	Headlamp assembly	cracked	\$ 1,944.00	\$ 1,944.00 /
2 pcs	Headlamp bracket	distorted	\$ 58.00	\$ 58.00 X NV
1 pc	Bonnet	bent	\$ 990.20	\$ 990.20 /
2 pcs	Bonnet hinge	bent	\$ 77.80	\$ 77.80 X
2 pcs	Bonnet stopper	deformed	\$ 12.00	\$ 12.00 X NV
1 pc	Bonnet lock	distorted	\$ 95.00	\$ 95.00 X
1 pc	Bonnet lock cable	bent	\$ 63.80	\$ 63.80 X
2 pcs	Bonnet inner rubber beading	deformed	\$ 25.60	\$ 25.60 /
9 pcs	Bonnet inner rubber beading clips	necessary	\$ 27.00	\$ 27.00 /
2 pcs	Bonnet stand clips	necessary	\$ 8.00	\$ 8.00 X NV
1 pc	Front grille	cracked	\$ 558.40	\$ 558.40 /
1 pc	Front grille badge	damaged	\$ 34.00	\$ 34.00 /
6 pcs	Front grille clips	necessary	\$ 23.40	\$ 23.40 /
1 pc	Front support panel	bent	\$ 580.00	\$ 580.00 / 429.7
1 pc	Air cond condensor	damaged	\$ 1,029.40	\$ 1,029.40 / 725.5
2 pcs	Air cond condensor top mounting	bent	\$ 34.00	\$ 34.00 X
2 pcs	Air cond condensor bottom mounting	bent	\$ 34.00	\$ 34.00 X
1 pc	Air cond liquid pipe	bent	\$ 170.20	\$ 170.20 X NV
1 pc	Air cond suction pipe	bent	\$ 97.20	\$ 97.20 X
1 pc	Air cond discharge pipe	bent	\$ 201.80	\$ 201.80 X
1 pc	Air cond fan blade	bent	\$ 56.70	\$ 56.70 X
1 pc	Air cond fan motor	damaged	\$ 294.20	\$ 294.20 X
1 pc	Air cond fan cowling	bent	\$ 85.00	\$ 85.00 X
1 pc	Radiator assembly	damaged	\$ 1,507.40	\$ 1,507.40 / 685.2
2 pcs	Radiator top mounting	bent	\$ 24.00	\$ 24.00 X
2 pcs	Radiator bottom mounting	distorted	\$ 28.00	\$ 28.00 X NV
1 pc	Radiator top hose	deformed	\$ 26.70	\$ 26.70 X
1 pc	Radiator bottom hose	deformed	\$ 36.50	\$ 36.50 X
1 pc	Radiator fan assy	bent	\$ 809.90	\$ 809.90 /
1 pc	Radiator spare tank	damaged	\$ 72.90	\$ 72.90 X NV

	Parts Sub-Total	\$ 10,319.60	\$ 10,319.60
Discount	20.00%	\$ 2,063.92	\$ 2,063.92
		\$ 8,255.68	\$ 8,255.68

7489.2
20% = 5991.36

Vehicle Number : SLQ2844L

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
-----	-------------------	-----------	--------------------------	-----------------------------

Special Nett Items

1 pc	Number plate casing	bent	\$ 58.00	\$ 58.00 20
1 pc	Front number plate	damaged	\$ 45.00	\$ 45.00 20

Special Nett Sub-Total \$ 103.00 \$ 103.00 40

Spare Parts Total \$ 8,358.68 \$ 8,358.68

LABOUR COST


S/No	JOB DESCRIPTIONS	Workshop Estimation (\$)	Our Revised Estimation (\$)
------	------------------	--------------------------	-----------------------------

Spare Parts Total c/f \$ 8,358.68 \$ 8,358.68

1	Towing	\$ 150.00	\$ 150.00 50
2	To check and reconnect snap wiring	\$ 180.00	\$ 150.00 30
3	To tuff coat affected areas	\$ 180.00	\$ 150.00 60
4	To remove and refix interior upholstery	\$ 200.00	\$ 180.00 X 111
8	To remove and replace air cond condensor, piping vacuum and top up gas	\$ 180.00	\$ 150.00 60
9	To remove and replace radiator, hoses, fan and top up coolant	\$ 180.00	\$ 150.00 60
11	To respray affected areas	\$ 1,800.00	\$ 1,800.00 400 + 100 2
12	To renew damaged parts, straighten and repair front chassis member front fender inner, front door and aligned all parts.	\$ 2,000.00	\$ 1,800.00 400 + 200 2
Total		\$ 13,228.68	\$ 12,688.68 1060

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 11,500.00


Fong Kok Heng
Qualified Appraiser



7391.26
20% = 1478.26



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC18015893/Gvd3n2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 24-06-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 7479Y	Veh. Inspected	SLQ 2844L	
Policy No.	Z18VC05000409	Coverage (\$)	0.00	
Claim No.	18/18/18/VC05/020862	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	24/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 5	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6CW1071H0125825	Colour	WHITE	
Odometer	21821	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	TOYO	6 mm	
L/H Front Tyre	205/55 R16	TOYO	6 mm	
R/H Rear Tyre	205/55 R16	TOYO	6 mm	
L/H Rear Tyre	205/55 R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/08/2018	Inspection Date	03/09/2018	
Survey held at	HUP LEY HUAT MOTOR SPRAY PAINTING SVS BLK 1 KAKI BUKIT AVE 6, #01-35 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 2844L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BENT	838.10	838.10
2	FRONT BUMPER SIDE RETAINER	BENT	24.40	24.40
2	FRONT BUMPER BRACKET	NOT NECESSARY	78.20	-
1	FRONT BUMPER REINFORCEMENT	NECESSARY	328.80	328.80
10	FRONT BUMPER CLIPS	NECESSARY	45.00	45.00
2	HEADLAMP ASSEMBLY	CRACKED	1,944.00	1,944.00
2	HEADLAMP BRACKET	NOT NECESSARY	58.00	-
1	BONNET	BENT	990.20	990.20
2	BONNET HINGE	NOT NECESSARY	77.80	-
2	BONNET STOPPER	NOT NECESSARY	12.00	-
1	BONNET LOCK	NOT NECESSARY	95.00	-
1	BONNET LOCK CABLE	NOT NECESSARY	63.80	-
2	BONNET INNER RUBBER BEADING	DEFORMED	25.60	25.60
9	BONNET INNER RUBBER BEADING CLIPS	NECESSARY	27.00	27.00
2	BONNET STAND CLIPS	NOT NECESSARY	8.00	-
1	FRONT GRILLE	CRACKED	558.40	558.40
1	FRONT GRILLE BADGE	DAMAGED	34.00	34.00
6	FRONT GRILLE CLIPS	NECESSARY	23.40	23.40
1	FRONT SUPPORT PANEL	BENT	580.00	429.70
1	AIR COND CONDENSOR	DAMAGED	1,029.40	725.50
2	AIR COND CONDENSOR TOP MOUNTING	NOT NECESSARY	34.00	-
2	AIR COND CONDENSOR BOTTOM MOUNTING	NOT NECESSARY	34.00	-
1	AIR COND LIQUID PIPE	NOT NECESSARY	170.20	-
1	AIR COND SUCTION PIPE	NOT NECESSARY	97.20	-
1	AIR COND DISCHARGE PIPE	NOT NECESSARY	201.80	-
1	AIR COND FAN BLADE	NOT NECESSARY	56.70	-
1	AIR COND FAN MOTOR	NOT NECESSARY	294.20	-
1	AIR COND FAN COWLING	NOT NECESSARY	85.00	-
1	RADIATOR ASSEMBLY	DAMAGED	1,507.40	685.20
2	RADIATOR TOP MOUNTING	NOT NECESSARY	24.00	-
2	RADIATOR BOTTOM MOUNTING	NOT NECESSARY	28.00	-

Report Ref No. CS3/LPC18015893/Gvd3n2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR TOP HOSE	NOT NECESSARY	26.70	-
1	RADIATOR BOTTOM HOSE	NOT NECESSARY	36.50	-
1	RADIATOR FAN ASSY	BENT	809.90	809.90
1	RADIATOR SPARE TANK	NOT NECESSARY	72.90	-
	LESS 20% DISCOUNT		-2,063.92	-1,497.84
			8,255.68	5,991.36
	SPECIAL NETT ITEMS			
1	NUMBER PLATE CASING (SN)	BENT	58.00	20.00
1	FRONT NUMBER PLATE (SN)	DAMAGED	45.00	20.00
			103.00	40.00
	LABOUR			
	TOWING.		150.00	50.00
	TO CHECK AND RECONNECT SNAP WIRING.		180.00	30.00
	TO TUFF COAT AFFECTED AREAS.		180.00	60.00
	TO REMOVE AND REFIX INTERIOR UPHOLSTERY.	NOT NECESSARY	200.00	-
	TO REMOVE AND REPLACE AIR COND CONDENSOR,PIPING VACUUM AND TOP UP GAS.		180.00	60.00
	TO REMOVE AND REPLACE RADIATOR,HOSES,FAN AND TOP UP COOLANT.		180.00	60.00
	TO RESPRAY AFFECTED AREAS.		1,800.00	500.00
	TO RENEW DAMAGED PARTS,STRAIGHTEN AND REPAIR FRONT CHASSIS MEMBER FRONT FENDER INNER,FRONT DOOR AND ALIGNED ALL PARTS.		2,000.00	600.00
			4,870.00	1,360.00
	GRAND TOTAL		13,228.68	7,391.36
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,900.00

Report Ref No. CS3/LPC18015893/Gvd3n2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.