

Surveyor:

Bryen

ASSIGNMENT (Office)

From (Person):

Chong Boon Sun

of

CTI

Date/Time:

26/4/19 @ 8:29am

Estimated Cost:

Bill to:

OD / PH / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 8206 LX

Insured:

GBD 494M

at Workshop m/s:

Chunni Motor

Tel:

65425119

of

AMC Autopoint # 01-05/06

Policy No:

DMCVSN307421802

Claim No:

SNM 1902017 99 cor

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

22/4/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:45am @ 26/4/19

Person Contacted:

Lynn

Vehicle

IN

OUT

Date/Time

Action/Instruction (✓) Estimate

SHA 8206L - X

GBD 494M - X

REF:

ASSIGNMENT

COR Nov 2023

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA 8206X Yt Regt: 2015 Nov
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.G. 1685

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 524167 T/Radio: Insured / Std / NI / NA

Eng/No: D4FD FV553300

C/No: KMHLB41UMGU079811

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N / S / Rim / STD A/Rim or

Tyre Size: F: 205/60Z16

R: ———

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Radial

Front

Rear

P/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 22/04/2019 D.O.I. 25/04/2019

Survey held at Chummi AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

H/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

China Taping GBD 494M

27/05/19 Jmym 2/5 10,300/- with 7 days of repair
 (led to 17557.20, 55%)

RECEIVED 29 MAY 2019

Date/Time, File Pass to?

☐ : Preli. Report

1) 29/5 Mmym

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Others

TOTAL

220

Report Format: MTR-TP

Lump Sum / I.B.F. (\$) 10300

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 26 April 2019 8:29 AM
To: Chunni Motor
Cc: assignments@lkkauto.com
Subject: RE: Accient involving veh no: SHA 8206L & GBD 494M on 22.04.19 / our ref :s nm19d201799

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chunni Motor [mailto:chunnimotor@gmail.com]
Sent: Wednesday, 24 April, 2019 10:30 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: Accient involving veh no: SHA 8206L & GBD 494M on 22.04.19 / our ref :s nm19d201799

Dear Sir,

We appoint Henry Ng.

Thank you

Regards,
Chunni Motor Work P/L

On Wed, Apr 24, 2019 at 9:24 AM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chunni Motor [<mailto:chunnimotor@gmail.com>]

Sent: Tuesday, 23 April, 2019 4:31 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Accient involving veh no: SHA 8206L & GBD 494M on 22.04.19

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly survey at AMK Autopoint, Soon Hock Motor, #01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

MCD019052600 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 23/04/2019 15:39
 SUBMITTED BY: Huang XiaoYan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/04/2019 15:39
 Date Of Accident 22/04/2019 20:50
 Exact Location Of Accident FINLAYSON GREEN X RAFFLES QUAY
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHA8206X
 Insured/Policyholder
 Name Of Registered Owner CITYCAB PTE LTD
 Co Reg No 199502839G
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
 Vehicle Particulars
 Manufacturer HYUNDAI
 Model I40
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
 Insurance Company
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number D-18088937MFSH
 Cover Note Number
 Driver
 Name of Driver WILLIE KOH CHOON HEE
 NRIC No S7349462A
 Date Of Birth 23/10/1973
 Occupation OUTDOOR
 Date Of Driving Pass 19/04/2007
 Driving Experience 12 YEARS AND 0 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-86856806
 Fax Number
 Contact Number
 Email Address WILLIEKOHCH@GMAIL.COM

Address BLK 512B YISHUN ST 51 #07-487
 Postcode 762512
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons:
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD494M
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver MD SOHEL CHOWDHURY LATE ABDUL LATIF
 NRIC/Passport Number G8309490M
 Contact Number
 Address
 Postcode
 Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
 Nature Of Damage RIGHT REAR
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	WILLIE KOH CHOON HEE
Approximate Age	
Injuries Sustain	PAIN TO CHEST, NECK AND BACK
Injured person in which vehicle?	SHA8206X
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SHA 8206X

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,500.00 600/-
	Spray Painting Charge			\$ 250.00 600/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 50.00 22
	Towing Charge			\$ 50.00 22
	Remove/Refix Undercarriage (FRT)			\$ 200.00 150/-
	FRT Wheel Alignment			\$ 120.00 60/-
	Remove/Refix Aircon & Refill Gas		1820.00	\$ 150.00 22
	Remove/Refix Dashboard			\$ 450.00 180/-
	Remove/Refix Fuse Box			\$ 180.00 50/-
	Re-set Frt ABS System			\$ 200.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 150/-
	TOTAL LABOUR			\$ 4,180.00
	ESTIMATE TOTAL			\$ 21,746.80
	25/04/2019 @ 1030am		12928.08	
	NA Antenna		4/510300/-	
	L/Smm			
	7 days.			
	2kk Auto			
	8			
	<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

22957.20

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 8206X (Supplementary)

DATE : 25.04.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

✓ on me

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Headlamp (RH) <i>mainly broken</i>			\$ 1,388.00 ✓
	SUB TOTAL			\$ 1,388.00
	LESS 20%			\$ 277.60
	DISCOUNTED TOTAL			\$ 1,110.40
	<i>2 Kk Auto</i> <i>25/04/2019.</i>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 8206 X

Technician:

Mileage: 524167

Time Printed 25.4.19 11:00 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°47'		-3°00' 3°00'
4°16'		-0°19' 5°41'
2°54'		-1°30' 1°30'
16°40'		
15°53'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
0°01'		-3°00' 3°00'
4°15'		-0°19' 5°41'
-0°08'		-1°30' 1°30'
15°26'		
15°26'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°47'		-3°00' 3°00'
0°01'		-3°00' 3°00'
1°14'		-3°00' 3°00'
2°45'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-0°47'		-3°30' 2°30'
-0°14'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°04'		-3°30' 2°30'
-0°29'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°43'		-3°00' 3°00'
-0°42'		-3°00' 3°00'
0°07'		-3°00' 3°00'

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119007386/DQD3N2

Date: 30/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30374218022	
Claimant Vehicle No :	SHA8206X	Insured Vehicle No :	GBD494M	
Date of Loss:	22/04/2019	Nature of Claim:	TP	Claim No: SNM19D201799C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA8206X	Engine No:	D4FDFU553300
Make & Model:	HYUNDAI I40, 1.7 D (A)	Chassis No:	KMHLB41UMGU079811
Reg. Date:	12/11/2015 (Man. Year: 2015)	Odometer:	524167 km
Colour:	Yellow		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Radial 5 mm	Rear Left Side:	Radial 5 mm
Front Right Side:	Radial 5 mm	Rear Right Side:	Radial 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	18,677.20	12,218.48	6,458.72	34.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	1,820.00	2,360.00	56.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,857.20	14,038.48	8,818.72	38.58
Approved Total (Overridden) (S\$)		10,300.00		
(S\$)	22,857.20	10,300.00	12,557.20	54.94
+ GST 7.00/7.00% (S\$)	1,600.00	721.00	879.00	54.94
Nett Amount (S\$)	24,457.20	11,021.00	13,436.20	54.94

INSPECTION

Date of Assignment: 28/05/2019

Date Inspected: 25/04/2019 Inspected At:

Chunni Motor Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #03-19
AMK Autopoint
Singapore 568047

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG		Version: 1.0 (Last Synchronised: 29 May 2019)
Parts:	143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA8206X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Broken	1,110.10 FL	*1,110.10 FL
2	1		*RADIATOR GRILLE H EMBLEM	Necessary	120.30 FL	*120.30 FL
3	1		*FRONT BUMPER COVER	Broken	1,052.20 FL	*1,052.20 FL
4	1		*FRONT BUMPER SPONGE	Not Necessary	99.20 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	402.10 FL	*- FL
6	1		*FRONT BUMPER GRILLE (LH)	Not Necessary	93.60 FL	*- FL
7	1		*FRONT BUMPER GRILLE AIRDUCT (LH)	Not Necessary	26.20 FL	*- FL
8	1		*FRONT BUMPER BRACKET TOP (LH)	Not Necessary	22.40 FL	*- FL
9	1		*FRONT BUMPER BRACKET (LH)	Not Necessary	24.60 FL	*- FL
10	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
11	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
12	1		*HEADLAMP (LH)	Mounting Broken	1,388.00 FL	*1,388.00 FL
13	1		*FRONT FENDER (LH)	Dented	663.00 FL	*663.00 FL
14	1		*FRONT FENDER APRON PANEL (LH)	Dented	637.00 FL	*637.00 FL
15	1		*FRONT FENDER SHIELD (LH)	Not Necessary	174.90 FL	*- FL
16	1		*AIR CLEANER BOTTOM ASSY	Not Necessary	325.00 FL	*- FL
17	1		*FRONT WHEEL RIM (LH)	Distorted	325.30 FL	*325.30 FL
18	1		*FRONT WHEEL HUB CAP (LH)	Cut	107.10 FL	*107.10 FL
19	1		*FRONT WHEEL BEARING	Damaged	540.50 FL	*540.50 FL
20	1		*FRONT SHOCK ABSORBER (ASSY)(LH)	Distorted	342.20 FL	*342.20 FL
21	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	108.80 FL	*- FL
22	1		*FRONT DRIVE SHAFT (LH)	Damaged	1,030.80 FL	*1,030.80 FL
23	1		*RACK & PINION ASSY	Damaged	1,191.30 FL	*1,191.30 FL
24	1		*STG TIE END	Distorted	62.60 FL	*62.60 FL
25	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	529.30 FL	*529.30 FL
26	1		*KNUCKLE ARM (LH)	Distorted	552.00 FL	*552.00 FL
27	1		*ENGINE UNDER COVER	Not Necessary	334.60 FL	*- FL
28	1		*ENGINE CROSSMEMBER	Not Necessary	2,094.40 FL	*- FL
29	1		*ABS SENSOR (LH)	Not Necessary	234.00 FL	*- FL
30	1		*WIRING-ENGINE	Housing Cracked/Broken	3,326.00 FL	*3,326.00 FL
31	1		*ELECTRIC POWER STEERING	Not Necessary	3,641.00 FL	*- FL
32	1		*FRONT TYRE (LH)	Serviceable	216.00 FS	*- FS
33	1		*HEADLAMP (RH)	Mounting Broken	1,388.00 FL	*1,388.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,292.50	15,273.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,615.30	3,054.62
Total Parts (\$\$)	18,677.20	12,218.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,500.00	600.00
2	SPRAY PAINTING CHARGE	New	750.00	600.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	0.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	200.00	150.00
7	FRT WHEEL ALIGNMENT	New	120.00	60.00
8	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
9	REMOVE/REFIX DASHBOARD	New	450.00	180.00
10	REMOVE/REFIX FUSE BOX	New	180.00	50.00
11	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	150.00
12	RE-SET FRT ABS SYSTEM }	New	200.00	0.00
Gross Labour Cost (S\$)			4,180.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >