

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19007401/GPA3Q2

**Date:** 11/12/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> FX3336P	<b>Insured Vehicle No :</b>	SHA1841H
Date of Loss: 16/04/2019	Nature of Claim: TP	Claim No: MCT19040464

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FX3336P</b>		
Make & Model:	YAMAHA Y125Z, 125cc (M)	Engine No:	E101EK002877
Reg. Date:	29/10/2003 (Man. Year: 2003)	Chassis No:	PMYKE060030002877
Colour:	Yellow	Odometer:	46313 km
Engine Capacity:	125 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	70/90-17
Front Left Side:	Corsa 4 mm	Rear Left Side:	Corsa 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,959.10	1,104.10	855.00	43.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	290.00	490.00	62.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,739.10</b>	<b>1,394.10</b>	<b>1,345.00</b>	<b>49.10</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>2,739.10</b>	<b>1,100.00</b>	<b>1,639.10</b>	<b>59.84</b>
<b>+ Loss of Use (5.0 x S\$25.00/day) (S\$)</b>		125.00		
<b>Nett Liability (S\$)</b>		<b>1,225.00</b>		

### INSPECTION

Date of Assignment:	23/04/2019	
Date Inspected:	26/04/2019	Inspected At:
		Yp Motorsports Trading (HQ)
		Blk 9004 Tampines St 93, #01-92
		Singapore 528836
Estimated Period of Repair:	3.0 days	

**Adjuster:** XING GUO QIANG

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 13 Sep 2019)	
<b>Parts:</b>	N/A	YAMAHA Y125Z 125cc (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FX3336P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOP COWLING	Cracked	65.00 FL	*65.00 FL
2	1		*HEAD LAMP	Cracked	45.00 FL	*45.00 FL
3	1		*BRAKE LEVER	Broken	12.00 FL	*12.00 FL
4	1		*HANDLE BAR	Bent	85.00 FL	*85.00 FL
5	1		*HANDLE GRIP	Torn	12.00 FL	*12.00 FL
6	1		*FRONT CENTER PANEL	Cracked	35.00 FL	*35.00 FL
7	1		*FRONT SIDE PANEL (R/H)	Cracked	120.00 FL	*120.00 FL
8	1		*FRONT SIDE PANEL (L/H)	Cracked	120.00 FL	*120.00 FL
9	1		*FRONT MUDGUARD	Cracked	85.00 FL	*85.00 FL
10	1		*FORK TUBE (R/H)	Bent	80.00 FL	*80.00 FL
11	1		*FORK TUBE (L/H)	Bent	80.00 FL	*80.00 FL
12	1		*FORK UNDER BRACKET	Bent	180.00 FL	*180.00 FL
13	1		*FRONT RIM	Not Necessary	250.00 FL	*- FL
14	1		*FRONT BRAKE DISC	Not Necessary	120.00 FL	*- FL
15	1		*FRONT WHEEL AXLE	Cut	25.00 FL	*25.00 FL
16	1		*FRONT FOOTREST (R/H)	Bent	28.00 FL	*28.00 FL
17	1		*BRAKE PEDAL	Cut	30.00 FL	*30.00 FL
18	1		*REAR FOOTREST (R/H)	Cut	12.00 FL	*12.00 FL
19	1		*EXHAUST	Not Necessary	580.00 FL	*- FL
20	1		*METER TOP PANEL	Cracked	65.00 FL	*65.00 FL
21	2		*SET FORK OIL SEAL & DUST COVER	Necessary	50.00 FS	*50.00 FS
22	1		*SET CONE BEARING	Necessary	65.00 FS	*65.00 FS
23	1		*FORK OIL	Necessary	18.00 FS	*18.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>2,162.00</b>	<b>1,212.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	202.90	107.90
<b>Total Parts (\$)</b>	<b>1,959.10</b>	<b>1,104.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING TO IDAC AND WORKSHOP	New	100.00	30.00
2	FRONT FORK & WHEEL ALIGNMENT	New	180.00	80.00
3	LABOUR CHARGE TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,INCLUDING REPAIRING ,RE-FIXING ,ADJUSTING ,CHECKING ,ETC	New	500.00	180.00
<b>Gross Labour Cost (\$\$)</b>			<b>780.00</b>	<b>290.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >