

22/03/2002

ASS. REC. BY:

REF: CS / P-19003414 / GS ds / n2

Special Instruction:

CWS
SurvivorASSIGNMENT (Office)From (Person): man chun of FCI Date/Time: 26.4.19 235pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLP 54252 Insured: SHA 7070 Bat Workshop m/s N-51 Automotive Tel: 68420051of 2 Kaki Bukit Avenue 2 # 01-18Policy No: _____ Claim No: 019002770MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 24.4.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 26.4.19 2.48pm Person Contacted: 2i Ting H.O.D. Endorsement: _____Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLP 54252 - x
	SHA 7070B - (CS/TMJ18013236/ KHbe 2 D.O.A - 06/10/2018
16/05/19	@ 09:30 am reset pending estimate from rep to May via email.

MOTOR SURVEY ASSIGNMENT

Date	25-04-2019	Our Ref No. D19002770MFSH
Accident Date	21-04-2019	Claim Type. Third Party
Insured Vehicle	SHA7070B	Third Party Vehicle. SLP5425Z
Survey Location	2 KAKI BUKIT AVENUE 2 #01-18 KAKI BUKIT AUTOHUB	
Contact Person.	ZI TING	
Contact No.	68420051/ 67440510	Fax No. 67410510
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	N-51 AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 16 May 2019 9:30 AM
To: 'May Chua Hui Chin'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19002770MFSH/1

Dear May,

Please be informed that we have inspected the vehicle SLP 5425Z on 14/05/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 26 April 2019 2:49 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19002770MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 26 April, 2019 2:35 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002770MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	7200G
Vehicle No.:	SLP5425Z
Vehicle to be Exported:	No
Intended Deregistration Date:	14 May 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Gold
Manufacturing Year:	2016
Engine No.:	LEB5918360
Chassis No.:	RU31218348
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$28,274.00
Original Registration Date:	08 Jun 2017
First Registration Date:	08 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Jun 2027
PARF Rebate Amount:	\$3,750.00
COE Expiry Date:	07 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,110.00
COE Rebate Amount:	\$40,414.00
Total Rebate Amount:	\$44,164.00

The information contained herein is correct as at 14 May 2019

OK



N-51 AUTOMOTIVE PTE LTD

88235151

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 97395716

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- Damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

Repair Code : CLM14224

Date in : 21/04/2019

Vehicle Num. : SLP5425Z

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31218348/LEB5918360

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER / <i>Be</i>	1	801.70	801.70 /
FRONT BUMPER FOGLAMP GARNISH LH / <i>Be</i>	1	45.00	45.00 /
FRONT BUMPER LOWER LID / <i>Be</i>	1	381.00	381.00 /
FRONT BUMPER SIDE RETAINER L/R <i>LH - Cut, RH X NN</i>	2	20.60	41.20 20.6
FRONT HEADLAMP LH / <i>CRA</i>	1	1784.50	1,784.50 /
FRONT HEADLAMP LOWER BRACKET LH / <i>BR</i>	1	35.00	35.00 /
FRONT LH FENDER <i>X Repair.</i>	1	580.00	580.00 X
FRONT LH FENDER 'HYBRID' EMBLEM / <i>MC</i>	1	58.00	58.00 /
FRONT LH FENDER ARCH GARNISH / <i>Cut</i>	1	220.00	220.00 /
FRONT LH FENDER INNER SHIELD <i>X</i>	1	130.00	130.00 X
FRONT LH KNUCKLE ARM <i>X</i>	1	390.00	390.00 X
FRONT LH KNUCKLE ARM BEARING <i>X</i>	1	181.40	181.40 X
FRONT LH SPORT RIM <i>X Repair.</i>	1	765.80	765.80 X
ROCKER GARNISH LH / <i>Be</i>	1	377.50	377.50
Subtotal before discount			5,791.10
Percentage discount 20%			1,158.22
Sub-total 1			4,632.88
FRONT BUMPER CLIPS - SET / <i>MC</i>	1	80.00	80.00

372330
744.66
2978.64

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

*Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005 97395716

ESTIMATE

Repair Code : CLM14224

Date in : 21/04/2019

Vehicle Num. : SLP5425Z

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31218348/LEB5918360

FRONT LH FENDER ARCH GARNISH CLIPS - SET / MC	1	20	30.00	30.00
FRONT LH FENDER INNER SHIELD CLIPS - SET X NN	1	X	40.00	40.00
FRONT LH TYRE 215/60R16 / Cut	1	120	300.00	300.00
ROCKER GARNISH CLIPS LH - SET / MC.	1	30	50.00	50.00
Subtotal before discount				500.00
Percentage discount 0%				0.00
Sub-total 2				500.00
Parts-total				5,132.88

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	1,720.00
Parts & Labour Total	6,852.88

30 80.00
NN X 280.00
60 140.00
500 600.00
NN 400 500.00
X 120.00

990.00

4 Days.
umpsm repair
After repair photos.

*** This is a computer-generated document which requires no signature.***

page 2

Gua Qiaap

14 5/19.

4/5
3300.00

2978.64
210.00
990.00
4178.64
- 29 835.72
3342.91

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FC119007414/Gsd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 21-05-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7070B	Veh. Inspected	SLP 5425Z
Policy No.		Coverage (\$)	0.00
Claim No.	D19002770MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	26/04/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU31218348	Colour	BROWN
Odometer	161462	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	HABILEAD	6 mm
L/H Front Tyre	215/60 R16	HABILEAD	6 mm
R/H Rear Tyre	215/60 R16	HABILEAD	6 mm
L/H Rear Tyre	215/60 R16	HABILEAD	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/04/2019	Inspection Date	14/05/2019
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 5425Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	801.70	801.70
1	FRONT BUMPER FOGLAMP GARNISH LH	DEFORMED	45.00	45.00
1	FRONT BUMPER LOWER LID	DEFORMED	381.00	381.00
2	FRONT BUMPER SIDE RETAINER L/R @\$20.60	N/S CUT / O/S NOT NECESSARY	41.20	20.60
1	FRONT HEADLAMP LH	CRACKED	1,784.50	1,784.50
1	FRONT HEADLAMP LOWER BRACKET LH	BROKEN	35.00	35.00
1	FRONT LH FENDER	TO REPAIR SEE LABOUR	580.00	-
1	FRONT LH FENDER "HYBRID" EMBLEM	NECESSARY	58.00	58.00
1	FRONT LH FENDER ARCH GARNISH	CUT	220.00	220.00
1	FRONT LH FENDER INNER SHIELD	NOT NECESSARY	130.00	-
1	FRONT LH KNUCKLE ARM	NOT NECESSARY	390.00	-
1	FRONT LH KNUCKLE ARM BEARING	NOT NECESSARY	181.40	-
1	FRONT LH SPORT RIM	TO REPAIR SEE LABOUR	765.80	-
1	ROCKER GARNISH LH	DEFORMED	377.50	377.50
	LESS 20% DISCOUNT		-1,158.22	-744.66
			4,632.88	2,978.64
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	80.00	40.00
1	SET FRONT LH FENDER ARCH GARNISH CLIPS (SN)	NECESSARY	30.00	20.00
1	SET FRONT LH FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	40.00	-
1	FRONT LH TYRE 215/60R16 (SN)	CUT	300.00	120.00
1	SET ROCKER GARNISH CLIPS LH (SN)	NECESSARY	50.00	30.00
			500.00	210.00
LABOUR				
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING (TO FR).		80.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE,CHANGE FRONT SUSPENSION PARTS,ABSORBER,LOWER ARM,KNUCKLE ARM,WHEEL BEARING,BEARING HUB,DRIVE SHAFT,ANTI-ROLL BAR,TOP-ARM AND STEERING RACK AND PINION.	NOT NECESSARY	280.00	-
	TO ROAD TEST DRIVING,CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM.		140.00	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.		600.00	500.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF FRONT LH FENDER AND FRONT LH SPORT RIM.		500.00	400.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	120.00	-
			1,720.00	990.00
GRAND TOTAL			6,852.88	4,178.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,300.00

Report Ref No. CS/FCI19007414/Gsd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.