

ASS. REC. BY:

REF: CS / SMO19007417 / A+d3

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Hwang shiang Yi of SMO

Date/Time: 26.4.19 16:18 PM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLV 8650 M

Insured: SKE 4602 E

at Workshop m/s Liang Hui Motor

Tel: 97527252

of 1 Kati Butit Ave 6 #01-62

Policy No: DIA MTPV01003808

Claim No: (MTD) 1902059

Sum Insured:

Excess:

Make of Veh:

D.O.A. 23.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 26.4.19 4.43p.m

Person Contacted: David

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SLV 8650 M - X
	SKE 4602 E - X
21/5@15.34pm	Revised via menimen pending estimate.
17/6	Repair done. finalise

ASG REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

3 days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLV8650M Yr Regn: 2015 MayType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes BenzE200c.c. 1991Colour: Silver

A/C: Insured / Std / Nil / NA

Sp. Reading: 74896

T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WD D21203428136072Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 245/45 R17R: 245/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

D.O.I. 29/04/19Survey held at Liang Hee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP SampsLump Sum \$4000/- (Red: 6958, 63%)

mv:

pv:

Nett:

RECEIVED 08 JUL 2019

Date/Time, File Pass to?

Date/Time, File Return to?

1) BIT Typist

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Date:

35011361

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Apr 2019		26 Apr 2019 16:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		CLAUDIO BIZZONI, ID: S6860540G							
Main Claimant:		TAN TECK DU, ID: S1698640B							
Vehicle Reg. No.:		SLV8650M	Date of Loss:	23/04/2019 19:00 - :59					
Claim Type:		TP / CMTD1902059	Policy/Cover Note No.:	D19MTPV01003808 (Comprehensive)					
Vehicle Reg. No. (Insured):		SKE4602E	Policy No. (Claimant):						
		Excess:							
Repairer:		Liang Hee Motor Workshop (HQ) 1 KAKI BUKIT AVE 6 #01-62, AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 67474416							
Handling Insurer:		Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/05/2019]							
Adj Asg. Remarks:		WS: 9752 7252 (David) / 6747-4416 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SLV8650M (CMTD1902059)**
[SKE4602E]

TP
TAN TECK DU
Apr 23 2019 7:00PM
[CLAUDIO BIZZONI]
Liang Hee Motor Workshop

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **02/05/2019 15:34 PM.**
To SHANGYI.HWANG@SOMPO.COM.SG
Subject SLV8650M (CMTD1902059) [SKE4602E]

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLV 8650M on 29/04/2019
We are pending estimate from repairer.

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd

DOCUMENTS SUMMARY

There are no documents.

SLV 8650M 2015 May
 Mercedes Benz E200 1991cc
 WPD2120342B136072

7P Sampo
 Denise

Rear Bumper Deland	1540 ✓
Rear Bumper clips. new	50 ✓
Rear Bumper Side Holder x02 RH NA	69x2 = 138 69
Rear Bumper Reinforcement Best	727 ✓
Rear Bumper Tow Cover Deland.	67 ✓
Rear Bumper Chrome Moulding x02 new	128x2 = 256 ✓
Rear Bumper Lower Garnish. Deland	338 ✓
Rear Bumper Centre Guide could	155 ✓
Rear Bumper Autolock Sensor Cover. could.	198 ✓
Reverse Sensor x02 1 piece dryd	260x2 = 520 260
Tailclip RH could	536 ✓
Tailclip Lower Bracket RH. could	41 ✓
Rear End Panel Reps	1196 +
Bootlid	2439. +
Mercedes Benz Logo	75 +
E200 Wording	68 X
76-Tronic Wording	78 X
Cycle and Carriage Logo	38 X
Bootlid Auto Lock Sensor dryd	398 ✓

4635
 A171-50

HP
 New

SLV8650M

Panel Beating
Spray Painting

Wiring

To undersent

To remove upholstery.

To remove reuse sensor

1030

~~800~~ 300

~~800~~ 500

~~50~~ 30

150 X

~~150~~ 40

~~180~~ 60.

total: 5101.5

h/s: AK

03 Days.

Total 10953

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19007417/ATD3N2

Date: 09/07/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01003808
Claimant Vehicle No :	SLV8650M	Insured Vehicle No :	SKE4602E
Date of Loss:	23/04/2019	Nature of Claim:	TP
		Claim No:	CMTD1902059

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV8650M	Engine No:	27492030362526
Make & Model:	MERCEDES-BENZ E200 (R17), 2.0 (A)	Chassis No:	WDD2120342B136072
Reg. Date:	28/05/2015 (Man. Year: 2014)	Odometer:	74896 km
Colour:	Silver		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45R17	Rear Tyre Size:	245/45R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,858.00	4,171.50	4,686.50	52.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	930.00	1,170.00	55.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,958.00	5,101.50	5,856.50	53.44
Approved Total (Overridden) (\$\$)		4,000.00		
Nett Amount (\$\$)	10,958.00	4,000.00	6,958.00	63.50

INSPECTION

Date of Assignment:	26/04/2019	
Date Inspected:	29/04/2019 Inspected At:	Liang Hee Motor Workshop (HQ) 1 KAKI BUKIT AVE 6 #01-62, AUTOBAY @ KAKI BUKIT Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jul 2019)
Parts:	143	MERCEDES-BENZ E200 (R17) 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV8650M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	1,540.00 F	*1,540.00 FL
2	1	*REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
3	1	*REAR BUMPER SIDE HOLDER	N/s Necessary	138.00 F	*69.00 FL
4	1	*REAR BUMPER REINFORCEMENT	Bent	727.00 F	*727.00 FL
5	1	*REAR BUMPER TOW COVER	Deformed	67.00 F	*67.00 FL
6	2	*REAR BUMPER CHROME MOULDING	Necessary	256.00 F	*256.00 FL
7	1	*REAR BUMPER LOWER GARNISH	Deformed	338.00 F	*338.00 FL
8	1	*REAR BUMPER CENTRE GUIDE	Cracked	155.00 F	*155.00 FL
9	1	*REAR BUMPER AUTO LOCK SENSOR COVER	Cracked	198.00 F	*198.00 FL
10	1	*REVERSE SENSOR (2 Pcs)	Damaged (1 Pc only)	520.00 F	*260.00 FL
11	1	*TAILLAMP RH	Cracked	536.00 F	*536.00 FL
12	1	*TAILLAMP LOWER BRACKET RH	Cracked	41.00 F	*41.00 FL
13	1	*REAR END PANEL	Repair	1,196.00 F	*- FL
14	1	*BOOTLID	Not Necessary	2,439.00 F	*- FL
15	1	*MERCEDES BENZ LOGO	Not Necessary	75.00 F	*- FL
16	1	*E200 WORDING	Not Necessary	68.00 F	*- FL
17	1	*7G-TRONIC WORDING	Not Necessary	78.00 F	*- FL
18	1	*CYCLE AND CARRIAGE LOGO	Not Necessary	38.00 F	*- FL
19	1	*BOOTLID AUTO LOCK SENSOR	Damaged	398.00 F	*398.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	8,858.00	4,635.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	463.50
Total Parts (\$\$)	8,858.00	4,171.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	300.00
2	SPRAY PAINTING	New	800.00	500.00
3	WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	0.00
5	TO REMOVE UPHOLSTERY	New	150.00	40.00
6	TO REMOVE REVERSE SENSOR	New	150.00	60.00
Gross Labour Cost (\$\$)			2,100.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >