

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

000001

1000 CS3/LPC/19004253/Eqdb3-1⁰²

ASSIGNMENT (000001)

LPC

Date/Time

26/04/2019

000001

Injured

GAP 6571A

Tel

92718287 Terence Lau

Claim No

18/19/19/VE 00/020496

Event

DOA

05/3/19

000001

Vehicle 18/0001

Document created

000001

000001

000001

000001

000001

000001

000001

000001

000001

29/4/2019

RECEIVED 30 APR 2019

Steve

REF: lpc

ASSIGNMENT

From:

Date:

12/3/19

Estimated Cost:

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No.

GBH 92865

at Workshop in/s

Omega Auto

of 160 Sin Ming Drive # 06-06

Insured

Policy No.

Claims No.

Sum Insured

Excess


(Client's Record)

Make of Veh.

Before 12pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value

IDAC Accident Report

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est. Repairs

days

Res.

Yes or No

Lump Sum

%

3 Val.

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted

Veh No:

GBH 92865

Yr Regn

8/11/18

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

cc. 2982

Colour:

Silv.

A/C Insured / Std / NI / NA

Sp Reading

27563

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT 02 P 900 245696

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / Si/Rim / STD A/Rim or

Tyre Size

F:

195 R15C

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

5/3/19

D.O.I.

12/3/19

Survey held at

Omega Auto

11am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - 70,000
PV - 27,518
NV - 46,482

RECEIVED 25 JAN 2019

Date/Time: File Pass to?

☐

Preli. Report

11/24/19

☐

Final Report

Date/Time: File Return to?

2)

Report Format:

PFS

Lump Sum / I.B.F. (\$) 1

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation

S + RS \$

Photos

Extra

)

TOTAL:

450

Nivitha (LKK Auto)


From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 26 April 2019 9:11 AM
To: Admin-D (LKKAuto); MT_Claim_SG; assignments
Subject: RE: YRef: 18/19/19/VC00/021496 ORef: L19.0312.cj //ACCIDENT INVOLVING gbH9286S & GBA6571A ON 05.03.19 ALONG JURONG ISLAND EXPRESSWAY NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY [External General]
Attachments: 21496 TP SURVEY REPORT.pdf

Lonpac External - General

Dear Nivitha

Attached is the TP survey report, please let us have your surveyor's review/report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 8 March, 2019 8:52 AM
To: ONG LI LI; MT_Claim_SG; assignments
Subject: RE: YRef: 18/19/19/VC00/021496 ORef: L19.0312.cj //ACCIDENT INVOLVING gbH9286S & GBA6571A ON 05.03.19 ALONG JURONG ISLAND EXPRESSWAY NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY [External General]

Dear Li Li,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



KM AUTO ASSESSORS PTE. LTD.

Insurance Loss Assessors & Adjusters

4, Jalan Pinnang

#02-07 Hill View 2

Singapore 577200

Phone 6753 0065

Mobile 9765 8125

E-mail: kmassessors@gmail.com

Website: kmassessors.com

AUTOMOBILE INSPECTION REPORT

NO. 9/3/TP005/R

To OMEGA AUTO PTE LTD
160 SIN MING DRIVE #06-06 SIN MING AUTOCITY S'PORE 575722

General Condition: Poor/Fair/Good/Excellent

Reg No	GBH 9286 S			Make/Model	TOYOTA HIACE TURBO VAN (M)			Year	2018		
Engine No	1KD2828775			Chassis No.	JTFHT02P900245696			Colour	Metallic Silver		
Condition of Tyres					Speedometer Reading - Km					27563	
Front N/S	MICHELIN 195R15		worn	10	%	Front O/S	MICHELIN 195R15		worn	10	%
Rear N/S	B/STONE 195R15		worn	10	%	Rear O/S	B/STONE 195R15		worn	10	%
Is Requested By		YOURSELF				On		11-Mar-19		The Above Vehicle	
Was Inspected At (11-Mar-19) OMEGA AUTO PTE LTD 160 SIN MING DRIVE #06-06 SIN MING AUTOCITY S'PORE 575722											

Tailgate dented and bent, inner frame bent, lock assy. bent and jammed, bumper assy. dented, bent and deformed, reverse sensors dislodged and s/circuited, lower panel twisted and flattened, exhaust pipe bent and pushed inwards, both rear lamps grazed and shifted, both sides body panels bent, interior floorboard bent.

Photographs -	85 Copies	were taken at time of inspection and are attached
The Repairers estimate was for a total amount of	\$	9,760.86
After adjustment the estimate was revised and agreed at	\$	7,014.35

SPECIAL REMARKS

The Repairers were **NOT AUTHORISED** to proceed with the repairs.
Survey was carried out without prejudice.
The above were due to impact to the rear portion of the vehicle.

The Repairer had requested for repairs on a Lump Sum basis instead, which was agreed @\$5,600/- Nett.

MICHAEL EE Dip A Eng AMRTE AMSAE AMSOE AMMI MSAKA

Date 15-Mar-19

APPENDIX 'A'
TO REPORT NO:
REGN. NO:

9/3/TP005/R
GBH 9286 S



KM AUTO ASSESSORS PTE. LTD.
Insurance Loss Assessors / Adjusters
12 Jalan Perumahan
#02-07 Halcyon 2
Singapore 577200
Tel: 6733 5100
Fax: 6733 5101
E: kmm@kmmassessors.com.sg
App. No: 22/01/2016

Nature of Work and Materials	Repairers Estimate \$	Remarks	Amount Revised \$
1 pce tailgate	2,051.71	dented & bent	2,051.71 ✓
1 pce tailgate inner lock assy.	262.40	bent & jammed	262.40 ✓
1 pce tailgate inner lock catch	38.90	bent	38.90 X N/A
2 pcs tailgate dampers	491.20	bent & twisted	491.20 X N/A
1 pce tailgate rubber	329.70	twisted, kinked, torn	329.70 ✓ 211.96
1 pce tailgate emblem	75.80	necessary	75.80 ✓
1 pce tailgate "TOYOTA" sticker	36.10	necessary	36.10 ✓
1 pce tailgate "HIACE" sticker	47.60	necessary	47.60 ✓
1 pce rear bumper fascia	398.25	dented, bent, deformed	398.25 ✓
1 pce rear lower panel	325.70	twisted & flattened	325.70 ✓
1 pce rear exhaust tail pipe assy.	456.70	bent	456.70 X N/A
2 pcs rear exhaust mountings	77.20	1pce only - torn	38.60 X N/A
2 pcs rear lamps assy.	511.60	o/s only - shifted, fastener snapped	255.80 X N/A
		3409.52	4,808.46
		less 25% - 25%	1,202.12
	5,102.86	2557.14	3,606.35
S.NETT			
1 pce tailgate glass moulding	60.00	necessary	60.00 ✓
1 pce tailgate glass primer	100.00	necessary	100.00 30 ✓
1 pce tailgate glass sealant	60.00	necessary	60.00 50 ✓
1 set rear bumper clips	48.00	necessary	48.00 30 ✓
1 set reverse sensors	220.00	o/s unit dislodged, s/circuited	220.00 ✓ 200
1 pce rear lower panel sealant	60.00	necessary	60.00 30 ✓ 400 ✓
Transfer tailgate glass assy. to new tailgate assy. and refit.	200.00		120.00 100 ✓
Remove tailgate fittings, check, renew damaged fittings, transfer all fittings to new tailgate assy. and refit.	150.00		80.00 50 ✓
Remove rear interior floor aluminium covering assy. to enable necessary repairs, check, refit, supply and rivets same	400.00		250.00 100 ✓
Remove lamps, necessary wirings and electrical fittings to enable necessary repairs, check, replace damaged parts, refit same, test electrical-circuit.	60.00		30.00 ✓
Remove rear exhaust pipe and silencer assy., check, replace same with mounting and refit.	100.00		60.00 X
c/f	6,560.86		4,694.35
Total Amount Revised	\$		
Lump Sum Repairs Amount	\$		
It is estimated that the repairs will take		days to complete.	

APPENDIX 'A'
TO REPORT NO:
REGN: NO:

9/3/TP005/R
GBH 9286 S



KRM AUTO ASSESSORS PTE. LTD.
Insurance Loss Assessors / Adjusters
.....
G. Lakshminathan
80/207, Telok Ayer St.
Singapore 070240
T. 6342 2400
F. 6342 2401
E. krm@krmassessors.com
krmassessors.com

Nature of Work and Materials	Repairers Estimate \$	Remarks	Amount Revised \$
b/f	6,560.86		4,694.35
Remove damaged parts, jack and cut out damaged body panels, jack out, straighten up damaged body panels and repair body parts and fittings, whichever possible and necessary, replace and weld necessary damaged parts, refit and align whichever parts necessary (incl. alignment of body	1,400.00		1,000.00 700 ✓
Paint replacement parts and repaint damaged sections with welded portions in and outside.	1,600.00		1,200.00 600 ✓
Rustproof replacement parts and touch-up damaged sections.	200.00		120.00 30 ✓
			1610 ✓
TOTAL	9,760.86		7,014.35
		P- 2557.14 MI - 400 L - 1610 - 4567.14 L/S - 3653-71 = 3650 ✓ 6 days	
Total Amount Revised	\$	7,014.35	
Lump Sum Repairs Amount	\$	5,600.00	
It is estimated that the repairs will take		SEVEN	days to complete.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS3/LPC19004253/Eqd3n2-1		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 03-05-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 6571A	Veh. Inspected	GBH 9286S	
Policy No.	Z/18/VC00/102523	Coverage (\$)	0.00	
Claim No.	18/19/19/VC00/021496	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	26/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTFHT02P900245696	Colour	SILVER	
Odometer	27563	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	MICHELIN	7 mm	
L/H Front Tyre	195 R15C	MICHELIN	7 mm	
R/H Rear Tyre	195 R15C	MICHELIN	7 mm	
L/H Rear Tyre	195 R15C	MICHELIN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/03/2019	Inspection Date	12/03/2019	
Survey held at	160 SIN MING DRIVE# 06-06			
Repairer	OMEGA AUTO PL			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 9286S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	DENTED / BENT	2,051.71	2,051.71
1	TAILGATE INNER LOCK ASSY	BENT / JAMMED	262.40	262.40
1	TAILGATE INNER LOCK CATCH	NOT NECESSARY	38.90	-
2	TAILGATE DAMPERS	NOT NECESSARY	491.20	-
1	TAILGATE RUBBER	TWISTED / KINKED / TORN	329.70	211.96
1	TAILGATE EMBLEM	NECESSARY	75.80	75.80
1	TAILGATE "TOYOTA" STICKER	NECESSARY	36.10	36.10
1	TAILGATE "HIACE" STICKER	NECESSARY	47.60	47.60
1	REAR BUMPER FASCIA	DENTED / BENT / DEFORMED	398.25	398.25
1	REAR LOWER PANEL	TWISTED / FLATTENED	325.70	325.70
1	REAR EXHAUST TAIL PIPE ASSY	NOT NECESSARY	456.70	-
2	REAR EXHAUST MOUNTINGS	NOT NECESSARY	77.20	-
2	REAR LAMPS ASSY	NOT NECESSARY	511.60	-
	LESS 25% DISCOUNT		-	-852.38
			5,102.86	2,557.14
SPECIAL NETT ITEMS				
1	TAILGATE GLASS MOULDING (SN)	NECESSARY	60.00	60.00
1	TAILGATE GLASS PRIMER (SN)	NECESSARY	100.00	30.00
1	TAILGATE GLASS SEALANT (SN)	NECESSARY	60.00	50.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	30.00
1	SET REVERSE SENSORS (SN)	O/S UNIT DISLODGED / S/CIRCUITED	220.00	200.00
1	REAR LOWER PANEL SEALANT (SN)	NECESSARY	60.00	30.00
			548.00	400.00
LABOUR				
	TRANSFER TAILGATE GLASS ASSY TO NEW TAILGATE ASSY AND REFIT.		200.00	100.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE TAILGATE FITTINGS,CHECK,RENEW DAMAGED FITTINGS,TRANSFER ALL FITTINGS TO NEW TAILGATE ASSY AND REFIT.	NOT NECESSARY	150.00	50.00
	REMOVE REAR INTERIOR FLOOR ALUMINIUM COVERING ASSY.TO ENABLE NECESSARY REPAIRS,CHECK,REFIT,SUPPLY AND RIVETS SAME.		400.00	100.00
	REMOVE LAMPS,NECESSARY WIRINGS AND ELECTRICAL FITTINGS TO ENABLE NECESSARY REPAIRS,CHECK,REPLACE DAMAGED PARTS,REFIT SAME,TEST ELECTRICAL-CIRCUIT.		60.00	30.00
	REMOVE REAR EXHAUST PIPE AND SILENCER ASSY CHECK,REPLACE SAME WITH MOUNTING AND REFIT.		100.00	-
	REMOVE DAMAGED PARTS,JACK AND CUT OUT DAMAGED BODY PANELS,JACK OUT,STRAIGHTEN UP DAMAGED BODY PANELS AND REPAIR BODY PARTS AND FITTINGS,WHICHEVER POSSIBLE AND NECESSARY.REPLACE AND WELD NECESSARY DAMAGED PARTS,REFIT AND ALIGN WHICHEVER PARTS NECESSARY (INCL.ALIGNMENT OF BODY).		1,400.00	700.00
	PAINT REPLACEMENT PARTS AND REPAINT DAMAGED SECTIONS WITH WELDED PORTIONS IN AND OUTSIDE.		1,600.00	600.00
	RUSTPROOF REPLACEMENT PARTS AND TOUCH-UP DAMAGED SECTIONS.		200.00	30.00
			4,110.00	1,610.00
GRAND TOTAL			9,760.86	4,567.14
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,650.00

Report Ref No. CS3/LPC19004253/Eqd3n2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.