

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A
#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg
GST Reg No: M9-0009639-E

TP INSURER: India International Insurance Pte Ltd (HQ)
COMFORT TRANSPORTATION PTE LTD

Singapore

Claimant Insurer: EQ Insurance Company Ltd

SURVEYOR COPY

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/INDIA
Policy No:		Date of Loss:	23/04/2019
Vehicle Reg. No.:	SMJ9682R	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LI XINHAO		
Make/Model:	HONDA FIT, 1.3 GF CVT (A)	Vehicle Reg. Date:	26/03/2019
Vehicle Colour:	BLUE		
Engine No:	L13B1454476	Chassis No:	GK31345827
Odometer:	0 KM		

Paint Type:
List Item Discount: 20.00 %
Total Loss? NO
Est. Duration of Repair (day) 15 / 13 days

Not Notified
Repair by paint

Description of Accident/Loss: REFER TO THE ATTACHED SKETCH PLAN BY DRIVER.
Remarks: -

Present Location: AH LIM MOTOR COMPANY (AMK)

COST OF CLAIMS

	Amount
Parts	10,590.40
Miscellaneous Items	10.00
Labour	6,180.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	16,780.40
+ GST 7.00% (S\$)	1,174.63
Nett Amount (S\$)	17,955.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by
Signature:
Date:

This claim is handled by: EILEEN CHUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Apr 2019)

Parts: 143 HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ah Lim Motor Company/SMJ9682R/30/04/2019 09:54

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*FRONT BONNET	As	20.00	0.00	*550.00 FL	1
2	2		*FRONT BONNET HINGE LH & RH	R	20.00	0.00	*90.00 FL	X
3	2		*FRONT BONNET RUBBER CENTRE LH & RH	SL	20.00	0.00	*44.00 FL	X
4	2		*FRONT BONNET RUBBER SIDE LH & RH	SL	20.00	0.00	*28.60 FL	X
5	1		*FRONT BONNET INNER LOCK		20.00	0.00	*90.50 FL	?
6	1		*FRONT GRILLE		20.00	0.00	*352.90 FL	?
7	1		*FRONT GRILLE EMBLEM		20.00	0.00	*23.40 FL	?
8	1		*FRONT GRILLE CHROME MOULDING TOP	CR	20.00	0.00	*265.00 FL	1
9	1		*FRONT GRILLE CHROME MOULDING LOWER	SL	20.00	0.00	*225.00 FL	1
10	8		*FRONT GRILLE CLIPS		20.00	0.00	*31.20 FL	?
11	2		*HEADLAMP LH & RH		20.00	0.00	*1,590.00 FL	?
12	1		*FRONT BUMPER	Bu	20.00	0.00	*495.00 FL	1
13	2		*FRONT BUMPER SIDE RETAINERS LH & RH	ALDIT	20.00	0.00	*30.80 FL	4
14	15		*FRONT BUMPER CLIPS	SL	20.00	0.00	*58.50 FL	1
15	1		*FRONT BUMPER LOWER AIR GRILLE		20.00	0.00	*180.00 FL	?
16	1		*FRONT BUMPER REINFORCEMENT		20.00	0.00	*203.80 FL	?
17	2		*FOG LAMP COVER LH & RH	SL	20.00	0.00	*116.60 FL	X
18	1		*RADIATOR SUPPORT PANEL	R	20.00	0.00	*455.00 FL	X
19	1		*RADIATOR SUPPORT PANEL TOP GARNISH	SL	20.00	0.00	*12.40 FL	X
20	8		*RADIATOR SUPPORT PANEL TOP GARNISH CLIPS	an	20.00	0.00	*31.20 FL	X
21	1		*AIR CON CONDENSER		20.00	0.00	*810.00 FL	?
22	1		*RADIATOR ASSY	SL	20.00	0.00	*1,250.00 FL	X
23	1		*RADIATOR FAN MOTOR	SL	20.00	0.00	*336.00 FL	X
24	1		*RADIATOR FAN BLADE	SL	20.00	0.00	*78.00 FL	X
25	1		*RADIATOR FAN COWLING	SL	20.00	0.00	*150.00 FL	X
26	1		*REAR WINDSCREEN MOULDING	SL	20.00	0.00	*120.00 FL	1
27	1		*TAILGATE	Bu	20.00	0.00	*814.00 FL	1
28	1		*TAILGATE EMBLEM	SL	20.00	0.00	*15.70 FL	1
29	1		*TAILGATE FIT LOGO	SL	20.00	0.00	*35.00 FL	1
30	2		*TAILGATE LAMP LH & RH		20.00	0.00	*77.00 FL	?
31	1		*TAILGATE REVERSE CAMERA		20.00	0.00	*1,041.00 FL	?
32	1		*TAILGATE INNER LOCK	Refurn	20.00	0.00	*157.10 FL	1
33	1		*TAILGATE RUBBER	CR	20.00	0.00	*92.30 FL	1
34	2		*TAILAMP LH & RH	Bu	20.00	0.00	*474.80 FL	1
35	1		*REAR BUMPER	CR	20.00	0.00	*492.60 FL	1
36	2		*REAR BUMPER SIDE RETAINERS LH & RH	SL	20.00	0.00	*23.00 FL	1
37	15		*REAR BUMPER CLIPS	SL	20.00	0.00	*58.50 FL	1
38	1		*REAR BUMPER LOWER COVER	Bu	20.00	0.00	*130.60 FL	1
39	15		*REAR BUMPER CLIPS	SL	20.00	0.00	*58.50 FL	1
40	2		*REAR BUMPER SIDE GRILLE LH & RH	SL	20.00	0.00	*96.00 FL	X
41	1		*END PANEL	Bu	20.00	0.00	*390.00 FL	1
42	1		*END PANEL TOP GARNISH	Bu	20.00	0.00	*60.80 FL	1
43	1		*SPARE TYRE PANEL	Bu/Bu	20.00	0.00	*697.00 FL	1
44	1		*SPARE TYRE PANEL TOP TRIMBOARD -CHECK PRICE		20.00	0.00	*- FL	?
45	2		*REAR FENDER INNER TRIM LH & RH	Refurn	20.00	0.00	*331.20 FL	1

Ah Lim Motor Company/SMJ9682R/30/04/2019 09:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
46	2		*NUMBER PLATE <i>Assess x</i>	<i>14 cms</i> 0	0.00	*70.00 FS	<i>4</i>
47	2		*REVERSE SENSOR	<i>Ass</i> 0	0.00	*200.00 FS	<i>✓</i>
48	1		*INNER SEAL	<i>Ass</i> 0	0.00	*20.00 FS	<i>✓</i>
49	1		*SEALANT	<i>Ass</i> 0	0.00	*40.00 FS	<i>✓</i>
50	1		*COOLANT	0	0.00	*30.00 FS	<i>?</i>
51	1		*AIR CON CONDENSER	0	0.00	*100.00 FS	<i>?</i>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,123.00
- List Item Discount on L Items (\$\$)	2,532.60
Total Parts (\$\$)	10,590.40

Ah Lim Motor Company/SMJ9682R/30/04/2019 09:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (\$\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING. (FRONT)	New	40.00 <i>200</i>
2	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	New	60.00 <i>300</i>
3	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT FENDER LH & RH; INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	800.00 <i>5000</i>
4	TO SPRAY FRONT BONNET;FRONT BUMPER; FRONT FENDER LH & RH; RADIATOR SUPPORT PANEL.	New	800.00 <i>6000</i>
5	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.(REAR)	New	40.00 <i>200</i>
6	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00 <i>✓</i>
7	TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	150.00 <i>1000</i>
8	TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	New	300.00 <i>?</i>
9	TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	New	60.00 <i>✓</i>
10	TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	New	60.00 <i>500</i>
11	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	New	90.00 <i>✓</i>
12	TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	New	60.00 <i>✓</i>
13	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL,SPARE TYRE PANEL. TO KNOCK & REPAIR REAR FENDERLH & RH,REAR CHASSIS LH & RH,ROOF PANEL,INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	2,000.00 <i>12000</i>
14	TO SPRAY TAILGATE, REAR BUMPER,END PANEL, SPARE TYRE PANEL, REAR FENDER LH & RH, REAR CHASSIS LH & RH, ROOF PANEL	New	1,600.00 <i>10000</i>
Gross Labour Cost (\$\$)			6,180.00

Ah Lim Motor Company/SMJ9682R/30/04/2019 09:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >