

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

KMHJ3813MHU348114

ESTIMATE

CHIN BOON KHAI
83 TAMPINES AVENUE 1
#08-22
S 528686

TP ALG.
Joy

Date :07.05.2019
Vehicle no :SLL 6571 Z
Make/Model :HYUNDAI TUCSON
Accident date :22.03.2019

| No | Description | Qty | Amount (S\$) |
|----|-------------|-----|--------------|
|----|-------------|-----|--------------|

LIST ITEMS

| | | | |
|----|--|---|---------------------------|
| 1 | Rear windscreen rubber <i>new</i> | 1 | \$ 47.1 ✓ |
| 2 | Rear tailgate <i>Dented</i> | 1 | \$ 1790.8 ✓ |
| 3 | Rear tailgate hinges@47.10 <i>new</i> | 2 | \$ 94.2 x |
| 4 | Rear tailgate upper lock <i>Damaged</i> | 1 | \$ 74.6 ✓ |
| 5 | Rear tailgate reflector @958.80 <i>cracked RH</i> | 2 | \$ 1917.6 395 |
| 6 | Rear tailgate emblem <i>new</i> | 1 | \$ 46.9 ✓ |
| 7 | Rear tailgate TUCSON emblem <i>new</i> | 1 | \$ 43.6 ✓ |
| 8 | Rear tailgate inner board <i>cracked</i> | 1 | \$ 313.5 ✓ |
| 9 | Rear tailgate weather strip <i>lt</i> | 1 | \$ 174.9 ✓ |
| 10 | Rear tailgate shock absorber @142.60 <i>new</i> | 2 | \$ 285.2 x |
| 11 | Rear tailgate inner handle <i>Dented</i> | 1 | \$ 41.8 ✓ |
| 12 | Rear tailgate side inner rubber @80.10 <i>new</i> | 2 | \$ 160.2 x |
| 13 | Rear tailgate lower garnish <i>cracked</i> | 1 | \$ 579.7 ✓ |
| 14 | Rear number plate lamp @35.20 <i>new</i> | 2 | \$ 70.4 x |
| 15 | Rear end panel <i>Dented</i> | 1 | \$ 813.8 ✓ |
| 16 | Rear end panel inner top garnish <i>deformed</i> | 1 | \$ 94.2 ✓ |
| 17 | Rear bumper <i>Distorted</i> | 1 | \$ 544.5 ✓ |
| 18 | Rear bumper side holder @26.40 <i>new</i> | 2 | \$ 52.8 ✓ |
| 19 | Rear bumper reflector @112.90 <i>cracked</i> | 2 | \$ 225.8 ✓ |
| 20 | Rear bumper reverse sensor @138.40 <i>2 pieces damaged</i> | 4 | \$ 553.6 276.80 |
| 21 | Rear bumper lower lip <i>Distorted</i> | 1 | \$ 393.8 ✓ |
| 22 | Rear bumper towing hook cover <i>del</i> | 1 | \$ 30.8 ✓ |
| 23 | Rear bumper clips(1 set) <i>new</i> | 1 | \$ 85.50 ✓ |
| 24 | Rear bumper reinforcement <i>Distorted</i> | 1 | \$ 475.2 ✓ |
| 25 | Rear bumper bracket @90.30 <i>dam</i> | 2 | \$ 180.6 ✓ |
| 26 | Rear tailgate inner lock pump <i>Damaged</i> | 1 | \$ 283.8 ✓ |
| 27 | Rear tailgate sensor <i>cracked</i> | 1 | \$ 170.5 ✓ |
| 28 | Rear RH lamp <i>new</i> | 1 | \$ 1081.3 x |
| 29 | Rear tailgate outer handle <i>new</i> | 1 | \$ 69.1 x |
| 30 | Rear RH lamp housing <i>new</i> | 1 | \$ 275.7 x |
| 31 | Rear RH inner shield <i>to be</i> | 1 | \$ 320.1 ✓ |
| 32 | Rear RH lower side garnish <i>deformed</i> | 1 | \$ 325.4 ✓ |
| 33 | Rear exhaust <i>Bent</i> | 1 | \$ 1410.8 1282 |
| 34 | Rear exhaust mounting <i>new</i> | 1 | \$ 46.2 x |

13073.5

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

CHIN BOON KHAI

83 TAMPINES AVENUE 1

#08-22

S 528686

Date

:07.05.2019

Vehicle no

:SLL 6571 Z

Make/Model

:HYUNDAI TL TUCSON

Accident date

:22.03.2019

| No | Description | Qty | Amount (S\$) |
|----|---|---------------|---|
| 35 | Rear RH fender inner side garnish <i>cracked</i> | 1 | \$ 533.5 ✓ |
| 36 | Rear exhaust pipe top cover <i>crumpled</i> | 1 | \$ 101.9 ✓ |
| 37 | Rear spare tyre top board <i>Deformed</i> | 1 | \$ 528 ✓ |
| 38 | Rear spare tyre well <i>Brekked</i> | 1 | \$ 861.8 ✓ |
| 39 | Rear spare tyre well insulation @319.70 <i>per</i> | 2 | \$ 639.4 280(SW) <i>12430.58</i> |
| 40 | Rear RH lamp side cover <i>red</i> | 1 | \$ 52.3 ✓ <i>9944.40</i> |
| 41 | Rear centre exhaust pipe <i>Bent</i> | 1 | \$ 1582.5 1325 ✓ |
| 42 | Rear centre exhaust pipe mounting @46.20 <i>per m</i> | 2 | \$ 92.4 x <i>S N 280</i> |
| | | | \$ 17465.3 |
| | | Less 20% disc | \$ 3493.1 |
| | | Total | \$ 13972.2 |

Special Nett Items

| | | | |
|---|--|-------|--------------------------------|
| 1 | Rear number plate <i>Detec</i> | 1 | \$ 50 30 <i>AAO</i> |
| 2 | Rear number plate holder <i>Deformed</i> | 1 | \$ 50 30 |
| 3 | Rear tailgate camera <i>Damaged</i> | 1 | \$ 800 x 380 |
| | | Total | \$ 900 |

Labour Cost

| | | |
|----|---|-------------------------|
| 1 | Towing fee | \$ 150 x |
| 2 | To supply rear windscreen sealant | \$ 50 ✓ |
| 3 | To supply rear end panel inner sealant | \$ 200 60 |
| 4 | Remove & reinstall rear windscreen | \$ 200 120 |
| 5 | Remove & reinstall bootlid inner garnish | \$ 150 <i>3190</i> |
| 6 | Remove & reinstall exhaust pipe | \$ 300 160 |
| 7 | Remove & reinstall reverse sensor | \$ 180 60 |
| 8 | Remove & reinstall petrol tank | \$ 150 x 80 |
| 9 | Remove, replace & repair consistent to the accident | \$ 2500 1300 |
| 10 | Respray painting | \$ 1800 1200 |
| 11 | Tuff kote | \$ 150 80 |
| | Total | \$ 5830 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

IK
10 days

Grand Total \$ 20702.2

total 13854.40
HS IK 10 Days