



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7218B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	458.60	458.60
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER UNDERCOVER	SERVICEABLE	552.60	-
1	REAR BUMPER SIDE RETAINER-RH	SERVICEABLE	112.70	-
1	SEAL REAR BUMPER SIDE-RH	SERVICEABLE	148.40	-
1	REAR RH UPPER TAILLAMP	CRACKED	557.90	557.90
	LESS 25% DISCOUNT		-463.05	-259.63
			1,389.15	778.87
<u>LABOUR</u>				
	PANEL BEATING.		300.00	200.00
	SPRAY PAINTING CHARGE.		250.00	200.00
	REMOVE/REFIX REVERSE SENSOR.		100.00	30.00
			650.00	430.00
GRAND TOTAL			2,039.15	1,208.87
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				950.00

Report Ref No. NS/INC19007486/K1vd3e2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.