

ASS. REC. BY:

REF: CS/PC1900748A1

K9d3ⁿ²

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Joanny

of

PCI

Date/Time: 29.4.19 3.38pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 5432T

Insured: SHC 3607U

at Workshop m/s TRANS-CAB

Tel: 62876666

of M2. Amk series 63

Policy No:

Claim No: D19002812MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 26.4.2019

30.4.2019

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 29.4.19 3.50pm

Person Contacted:

Amanda

Vehicle: ☒ IN ☐ OUT

Date/Time	Action/Instruction
	Estimate (✓)
	SHC 5432T - CC3/TMI18011935/K9d3 ROA: 26/6/2018
	SHC 3607U - NSI/INC.19007277/K9d3 ROA: 23/04/2019
02/5/19@	10/30m revised to Joanne Yee by email.

REF: F2

ASSIGNMENT

From:

Date: 30.4.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHC 54327

at Workshop n/s: Trans-cab Auto

of M2 AMK Street 63

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lump Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

new

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHC 54327 Yr Regn: 11 / 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Logan c.c. 1995

Colour:

M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading:

424613 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF-1ABL15AUC 279858

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal.

7 mm

R/Bal.

7 mm

L/Bal.

7 mm

L/Bal.

7 mm

D.O.A.

26/4/19

D.O.I.

30/4/19

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear Ads

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11 Sep 2019 (Red to 40197.76, 83%)

RECEIVED 07 MAY 2019

Date/Time, File Pass to?



Preli. Report

0915 11/11/19



Final Report

Date/Time, File Return to?

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format:

7P

Lump Sum / I.B.F. (\$)

810

Survey Fee:

Transportation:

S + RS: \$4

Photos

Others

TOTAL

350



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002812MFSH

Date: 03 May 2019

Our Ref: CS/FCI19007489/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5432T

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/04/2019 at the premises of M/s TRANS-CAB, and have the following to report:-

Workshop Estimate Amount	: S\$ 48,297.16 .
Revised Estimate Amount	: S\$ 10,099.75 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	29-04-2019	Our Ref No. D19002812MFSH
Accident Date	26-04-2019	Claim Type. Third Party
Insured Vehicle	SHC3607U	Third Party Vehicle. SHC5432T
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	AMANDA TAY	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Tuesday, 7 May 2019 8:17 AM
To: Shiau Chan (LKKAUTO)
Subject: RE: TP VEHICLE SHC 5432T (DOA: 26/04/2019) -- AAD1904-251
Attachments: image001.wmz

Hi Shiau Chan

We confirmed COR amount \$ 8,100.00 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Friday, 3 May, 2019 10:33 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: TP VEHICLE SHC 5432T (DOA: 26/04/2019)

Dear Wai Yin,

Based on our surveyor's estimate marking, the calculation repair cost will be at Lump Sum \$8,100.00 and 5 repair days.

Kindly check.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 3 May 2019 10:30 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002812MFSH/1
Attachments: CSFCI19007489Kqd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SHC 5432T.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 29 April 2019 4:06 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <JoanneYong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002812MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that repairer agreed survey on 30/04/2019.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 29 April 2019 3:28 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <JoanneYong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002812MFSH/1

Dear Sir/Mdm,

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5432T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Apr 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002132
Chassis No.:	VF1ABL15AUC279858
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	19 Nov 2014
First Registration Date:	19 Nov 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Nov 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	
COE Expiry Date:	18 Nov 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,337.00
COE Rebate Amount:	\$22,867.00
Total Rebate Amount:	\$32,240.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Apr 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5432T**AAD1904-251***Not Authorized*
L1 Pmp 881006

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5432T

VF1ABL15AUC279858

RENAULT

LATITUDE

26.4.2019

FCIL

19/11/2014

PART**LIST**

- | | |
|----|-------------------------------|
| 1 | 1 BUMPER COVER REAR |
| 2 | 1 BUMPER LOWER REAR |
| 3 | 1 BUMPER BRACKET CTR REAR |
| 4 | 1 BUMPR BRACKET SIDE RH REAR |
| 5 | 1 BUMPR RETAINER RH REAR |
| 6 | 1 BUMPER REFLECTOR RH |
| 7 | 1 BUMPR BRACKET SIDE LH REAR |
| 8 | 1 BUMPR RETAINER LH REAR |
| 9 | 1 BUMPER REFLECTOR LH |
| 10 | 1 BUMPER BEAM REAR |
| 11 | 1 BUMPER BEAM BRACKET LH REAR |
| 12 | 1 BUMPER BEAM BRACKET RH REAR |
| 13 | 1 BOOT REAR |
| 14 | 1 BOOT FINISHER |
| 15 | 1 BOOT WHEATERSTRIP |
| 16 | 1 BOOT REFLECTOR LAMP LH |
| 17 | 1 BOOT REFLECTOR LAMP RH |
| 18 | 1 BOOT BADGE 'RENAULT' |
| 19 | 1 BOOT BADGE |
| 20 | 1 BOOT STRUT LH |
| 21 | 1 BOOT STRUT RH |
| 22 | 1 BOOT HINGE LH |
| 23 | 1 BOOT HINGE RH |
| 24 | 1 BOOT INNER TRIM |
| 25 | 1 BOOT SWITCH |
| 26 | 1 BOOT LOCK |
| 27 | 1 BOOT LOCK CATCH |
| 28 | 2 LICENCE PLATE LAMP |
| 29 | 2 BOOT RUBBER PLUG |

\$	<i>Bu</i>	1,108.46	—
\$	<i>nd</i>	768.84	—
\$	<i>Sn</i>	113.47	}
\$	<i>Sn</i>	135.97	
\$	<i>Sn</i>	44.99	
\$	<i>Sn</i>	43.61	
\$	<i>Sn</i>	135.97	
\$	<i>Sn</i>	44.99	}
\$	<i>Sn</i>	43.61	
\$	<i>B₁</i>	777.52	—
\$	<i>n</i>	225.95	X
\$	<i>B₁</i>	225.95	X
\$	<i>B₁</i>	2,872.68	—
\$	<i>Sn</i>	470.06	X
\$	<i>Sn</i>	323.05	X
\$	<i>Sn</i>	493.35	X
\$	<i>Sn</i>	493.35	X
\$	<i>Sn</i>	225.36	—
\$	<i>Sn</i>	225.36	—
\$	<i>Sn</i>	276.08	}
\$	<i>Sn</i>	276.08	
\$	<i>n</i>	367.84	
\$	<i>n</i>	367.84	
\$	<i>Sn</i>	586.45	
\$	<i>Sn</i>	168.13	
\$	<i>n</i>	202.67	
\$	<i>n</i>	74.40	
\$	<i>Sn</i>	50.52	}
\$	<i>Sn</i>	221.81	

Trans-cab Auto Services Pte Ltd**AAD1904-251**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5432T

30	1 FENDER PANEL REAR RH	\$	<i>N</i>	3,299.13	X
31	1 WHEELARCH REAR RH	\$	<i>Sn</i>	543.47	X
32	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>Sn</i>	671.45	X
33	1 FENDER PANEL REAR LH	\$	<i>N Sn</i>	3,299.13	X
34	1 WHEELARCH REAR LH	\$	<i>Sn</i>	543.47	X
35	1 TAILLAMP LH	\$	<i>mjm Sn</i>	552.55	✓
36	1 TAILLAMP PANEL LH	\$	<i>N</i>	986.70	X
37	1 TAILLAMP RH	\$	<i>Sn</i>	552.55	✓
38	1 TAILLAMP PANEL RH	\$	<i>N</i>	986.70	X
39	1 OUTER PANEL REAR (End Panel)	\$	<i>Bj</i>	1,471.77	✓
40	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>cm Sn</i>	404.56	✓
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>N</i>	2,189.88	X
42	1 SPARE WHEEL PANEL TRIM	\$	<i>Sn</i>	612.21	X
43	1 EXHAUST REAR	\$	<i>N</i>	7,489.05	X
44	1 EXHAUST CAP REAR	\$	<i>N</i>	230.49	X

47

TOTAL	\$	35,197.49
10%	\$	3,519.75
	\$	31,677.74

Special Nett

1	1SET PARKING AID	\$	<i>Shan</i>	700.00	<i>Goan</i>
2	1SET REAR BUMPER CLIP	\$	<i>nn</i>	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>nn</i>	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i>	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>nn</i>	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>nn</i>	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>nn</i>	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>nn</i>	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>nn</i>	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	<i>Sn</i>	17.82	X
11	1SET BOOT FINISHER CLIP	\$	<i>nn</i>	24.20	X
12	1 REAR BOOT STICKER 'TRANS-CAB'	\$	<i>nn</i>	80.00	<i>30sn</i>
13	1 REAR BOOT STICKER '6555-3333'	\$	<i>nn</i>	80.00	<i>30sn</i>

Trans-cab Auto Services Pte Ltd

AAD1904-251

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5432T

15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
18	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
19	1 TAILLAMP CLIP RH	\$	na	5.00	X
20	1 TAILLAMP CLIP LH	\$	na	5.00	✓
21	2 REAR WINDSCREEN SELANT	\$	na	80.00	X
22	1 WINDSCREEN MOULDING	\$	na	100.00	X
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	na	385.00	X
25	1 SPARE TYRE	\$	na	330.00	X

TOTAL \$ 2,280.02**TOTAL PARTS \$ 33,957.76****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	600
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	600
To Rust-Proofing Of The Affected Areas.	\$	170.00	60
To reinstall rear bumper parking sensor.	\$	170.00	60
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60
To repair and realign rear exhaust pipe.	\$	na	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1904-251**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5432T

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 170.00

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.

\$ 170.00

To supply and re-do rear luggage floor panel insulation padding.

\$ 380.00 X

To transfer of rear fender fittings, attachment and perform water seepage test.

\$ 380.00 X

To transfer of rear windscreen fittings and conduct water seepage test.

\$ 170.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 X

To transfer of rear door fittings, attachment and perform water seepage test.

\$ 380.00 X

TOTAL \$ 14,340.00**Over All Total \$ 48,297.76****(LUMP SUM)****(Repair Days)****20 DAYS****5 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19007489/Kqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-05-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3607U	Veh. Inspected	SHC 5432T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002812MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	29/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC279858	Colour	METALLIC WHITE / RED	
Odometer	424613	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	7 mm	
L/H Front Tyre	215/60 R16	GITI	7 mm	
R/H Rear Tyre	215/60 R16	GITI	7 mm	
L/H Rear Tyre	215/60 R16	GITI	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/04/2019	Inspection Date	30/04/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5432T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	BENT	225.95	225.95
1	BOOT REAR	BENT	2,872.68	2,872.68
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-

Report Ref No. CS/FCI19007489/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	TAILLAMP LH	MTG CRACKED	552.55	552.55
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	CRACKED	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
	LESS 10% DISCOUNT		-3,519.75	-863.31
			31,677.72	7,769.74
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SHORTED	700.00	600.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER LH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-

Report Ref No. CS/FCI19007489/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	REAR BOOT STICKER 'TRANS-CAB' (SN)	NECESSARY	80.00	30.00
1	REAR BOOT STICKER '6555-3333' (SN)	NECESSARY	80.00	30.00
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NECESSARY	5.00	5.00
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
			2,280.02	830.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	660.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, BOOT LOCK CATCH, FENDER PANEL REAR RH, FENDER PANEL REAR LH, TAILLAMP PANEL LH, TAILLAMP PANEL RH, SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL), EXHAUST REAR AND EXHAUST CAP REAR.		6,000.00	600.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-

Report Ref No. CS/FCI19007489/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.)		170.00	60.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.)		170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			14,720.00	1,500.00
	GRAND TOTAL		48,677.74	10,099.74
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,100.00

Report Ref No. CS/FC119007489/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.