

7/26/2003

ASS. REC. BY:

REP:

CS/SPF 19007500/Gtd 301

Special Instruction:

Survey'd

Quo Ori

ASSIGNMENT (Office)

From (Person):

Perry HE

of

SPF

Date/Time:

2/14/19 @ 1:51pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No.:

QX311A

Insured:

at Workshop m/s

Indeco

Tel:

97877084

of

39 Deference 12

Policy No:

Claim No:

MHA SPF 0300000113

Sum Insured:

Excess:

TBA

Make of Veh:

D.O.A.

(Client's Record)

CA / (REV) /

REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time:

25/4/19 @ 3:47pm

Person Contacted:

mike

Vehicle IN / (OUT)

Date/Time

Action/Instruction (✓) Estimate

30/4 @ 1:33pm - REUSED VIA EMAIL TO PERRY HE

Parts : \$5454


MAN HOUR: 43

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Indeco
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rport. _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: QX311A Yr Regn: - / 2008
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Police car.
 Make: Toyota Altis c.c. 1598
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: - T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MR053 ZEE 106109174
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or FALKEN
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 29-04-19
 Survey held at w/s 4pm
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>29/4</u>	<u>Finalised 43 Hr with Anson.</u>

RECEIVED 10 MAY 2019

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) 10/5 Typist
 Date/Time, File Return to?
 2) _____
 Report Format : OD
 Lump Sum / I.B.I: (\$) _____

Days Of Repair: _____
 Resurvey No. of Trip: -

Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Invs (\$) _____
 : Weekend (\$) _____

Survey Fee: 180
 Transportation: _____
 Photos _____
 Others _____
 TOTAL 180

Nivitha (LKK Auto)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Wednesday, 24 April 2019 1:51 PM
To: assignments
Cc: Kwee Huat TAN (SPF); Kim Pang CHAY (SPF); Ai Phing (LKKAuto); Shiau Chan (LKKAuto); Veron Chen (LKKAuto); Janice Lee (LKKAuto)
Subject: Appraisal Services for SPF vehicle at INDECO - QX311A

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at INDECO, with new contract rate.

Ref: MHASPF0300000113

Vehicle: QX311A

*mike @
97 87 7084*

Parts:

- 1 Scope Of Repairs
- 1.1 BONNET
- 1.2 BONNET HINGE RH
- 1.3 BONNET HINGE LH
- 1.4 BONNET LOCK
- 1.5 BONNET INSULATOR
- 1.6 BONNET INSULATOR CLIP
- 1.7 HEADLAMP LH COMPLETE
- 1.8 BODY WIRE HARDNESS 82111-0Z870/890
- 1.9 FRT BUMPER
- 1.10 FRT BUMPER RETAINER RH
- 1.11 FRT BUMPER RETAINER LH
- 1.12 FRT BUMPER CLIP
- 1.13 FRT GRILLE
- 1.14 TOYOTA LOGO
- 1.15 FRT BUMPER CENTER GRILLE
- 1.16 FOGLAMP COVER RH
- 1.17 FOGLAMP COVER LH
- 1.18 ENGINE UNDER COVER RH
- 1.19 ENGINE UNDER COVER LH
- 1.20 ENGINE UNDER COVER CLIP
- 1.21 LHF FENDER INNER SHIELD
- 1.22 RHF FENDER INNER SHIELD
- 1.23 LHF FENDER
- 1.24 LH WING MIRROR COMPLETE
- 1.25 FRT NUMBER PLATE
- 1.26 LHF DOOR
- 1.27 LH SIDE SKIRT
- 1.28 AIR RESONATOR BOX
- 1.29 AIR CLEANER INLET 1 17751-37060
- 1.30 FRT BUMPER RUBBER MOULDING
- 1.31 FRT BUMPER REINFORCEMENT
- 1.32 ENGINE WIRE HARDNESS 82121-02N10
- 1.33 AIR CLEANER INLET 2 17752-37070

Labour:

1.1	TO REPLACE AND RESPRAY BONNET	6 hrs
1.2	TO REPLACE AND RESPRAY FRT BUMPER	5 hrs
1.3	TO REPLACE AND RESPRAY LHF FENDER	4 hrs
1.4	TO REPLACE AND RESPRAY LHF DOOR	6 hrs
1.5	TO REPLACE AND RESPRAY REINFORCEMENT	1 hr
1.6	TO REPLACE AND RESPRAY LH WING MIRROR	2 hrs
1.7	TO REPLACE AND RESPRAY LH SIDE SKIRT	4 hrs
1.8	TO REPAIR AND RESPRAY RHF FENDER	5 hrs
1.9	TO REPLACE BODY AND ENGINE WIRE HARDNESS	10 hrs
1.10	TO REPAIR AND RESPRAY SUPPORT PANEL	2 hrs

Thank you.

Perry He Junyun
 Contract Management Engineer
 Automotive Engineering & Management Division
 Police Logistics Department
 Singapore Police Force
 DID: (65) 6478 4869 | HP: (65) 9191 5725



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



ACCIDENT/DAMAGE REPAIR AND AD HOC WORKS REQUEST FORM




ILMS Notification No	1100021990		
Vehicle No	QX311A	Division/Unit	E Div / BT NPC
Vehicle Type (e.g. FRC, minibus)	FRC	Date	9 April 2019
Vehicle Make & Model	Toyota Altis	Mileage (km)	

Description	Pls tick	Police Report No & Date of Accident (if applicable)
NP168 (Accident involve 3 rd Party)	✓	T/20190409/2016
NP168 (Accident do not involve 3 rd Party)		
NP299 Discovered Damage		
NP299 Vandalism		
Ad hoc, pls specify		

Description of affected area/required works (e.g. dented, cracked, grazed etc)

Whole front bumper damaged and dislodged, front left side of vehicle damaged

Pls mark affected area with **X**



Rank/Name
SSS Chan Guoyuan, Alan

Signature

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 30 April 2019 1:33 PM
To: Perry HE (SPF); assignments
Cc: Kwee Huat TAN (SPF); Kim Pang CHAY (SPF); Shiau Chan (LKKAuto); Veron Chen (LKKAuto)
Subject: RE: Appraisal Services for SPF vehicle at INDECO - QX311A
Attachments: QX 311A.xls; QX 311A photo.pdf

Dear Perry He,

Please refer attached of QX 311A.

Please take note Janice Lee and Ai Phing is no longer in our organization

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Wednesday, 24 April 2019 1:51 PM
To: assignments <assignments@lkkauto.com>
Cc: Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Ai Phing (LKKAuto) <aiphing@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Subject: Appraisal Services for SPF vehicle at INDECO - QX311A

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at INDECO, with new contract rate.

Ref: MHASPF0300000113

Vehicle: QX311A

Parts:

- 1 Scope Of Repairs
 - 1.1 BONNET
 - 1.2 BONNET HINGE RH
 - 1.3 BONNET HINGE LH
 - 1.4 BONNET LOCK
 - 1.5 BONNET INSULATOR
 - 1.6 BONNET INSULATOR CLIP
 - 1.7 HEADLAMP LH COMPLETE
 - 1.8 BODY WIRE HARDNESS 82111-0Z870/890
 - 1.9 FRT BUMPER
 - 1.10 FRT BUMPER RETAINER RH



Scope Of Work
Home Team Agency

SCOPE OF WORK

I provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	Indeco Engineers Pte Ltd	VEH TYPE :	UNIT :	E DIV	Reference No. MHA/SPF/2019/04-0019 1100021990
VEH NO :	QX311A	FRC	REPAIR TYPE:	ACCIDENT	
VEH MAKE/MODEL	TOYOTA ALTIS		Mileage:	NA	

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1 Scope Of Repairs						
1.1	BONNET / <i>Buc</i>	200.00	1	20%	240.00	240.00
1.2	BONNET HINGE RH / <i>GBT</i>	25.00	1	20%	30.00	30.00
1.3	BONNET HINGE LH	25.00	1	20%	30.00	30.00
1.4	BONNET LOCK / <i>Sm</i>	40.00	1	20%	48.00	48.00
1.5	BONNET INSULATOR / <i>re</i>	95.00	1	20%	114.00	114.00
1.6	BONNET INSULATOR CLIP / <i>acc.</i>	1.50	10	20%	1.80	18.00
1.7	HEADLAMP LH COMPLETE / <i>Dis</i>	195.00	1	20%	234.00	234.00
1.8	BODY WIRE HARDNESS 82111-0Z870/890 / <i>TN</i>	1950.00	1	20%	2340.00	2340.00
1.9	FRT BUMPER / <i>Mis</i>	170.00	1	20%	204.00	204.00
1.10	FRT BUMPER RETAINER RH / <i>CRA</i>	20.00	1	20%	24.00	24.00
1.11	FRT BUMPER RETAINER LH / <i>Mis</i>	20.00	1	20%	24.00	24.00
1.12	FRT BUMPER CLIP / <i>acc.</i>	1.50	10	20%	1.80	18.00
1.13	FRT GRILLE / <i>DR</i>	100.00	1	20%	120.00	120.00
1.14	TOYOTA LOGO / <i>Mis</i>	25.00	1	20%	30.00	30.00
1.15	FRT BUMPER CENTER GRILLE / <i>Mis</i>	40.00	1	20%	48.00	48.00
1.16	FOGLAMP COVER RH / <i>Mis</i>	30.00	1	20%	36.00	36.00
1.17	FOGLAMP COVER LH / <i>Mis</i>	30.00	1	20%	36.00	36.00
1.18	ENGINE UNDER COVER RH / <i>TN</i>	60.00	1	20%	72.00	72.00
1.19	ENGINE UNDER COVER LH / <i>TN</i>	60.00	1	20%	72.00	72.00
1.20	ENGINE UNDER COVER CLIP / <i>acc</i>	1.50	10	20%	1.80	18.00
1.21	LHF FENDER INNER SHIELD / <i>Mis</i>	45.00	1	20%	54.00	54.00
1.22	RHF FENDER INNER SHIELD / <i>TN</i>	45.00	1	20%	54.00	54.00
1.23	LHF FENDER / <i>Mis</i>	130.00	1	20%	156.00	156.00
1.24	LH WING MIRROR COMPLETE / <i>Dis</i>	265.00	1	20%	318.00	318.00
1.25	FRT NUMBER PLATE / <i>Mis</i>	20.00	1	20%	24.00	24.00
1.26	LHF DOOR / <i>Buc</i>	400.00	1	20%	480.00	480.00
1.27	LH SIDE SKIRT / <i>DR</i>	240.00	1	20%	288.00	288.00
1.28	AIR RESONATOR BOX / <i>Mis</i>	65.00	1	20%	78.00	78.00
1.29	AIR CLEANER INLET 1 17751-37060 / <i>re</i>	20.00	1	20%	24.00	24.00
1.30	FRT BUMPER RUBBER MOULDING / <i>Mis</i>	20.00	1	20%	24.00	24.00
1.31	FRT BUMPER REINFORCEMENT / <i>BT</i>	120.00	1	20%	144.00	144.00
1.32	ENGINE WIRE HARDNESS 82121-02N10 / <i>?</i>	1500.00	1	20%	1800.00	1800.00
1.33	AIR CLEANER INLET 2 17752-37070 / <i>DR</i>	45.00	1	20%	54.00	54.00
2 Additional Services						
Remarks:					Parts Total:	\$ 7,254.00

5454

Registration No. QX 311A

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	BONNET		BUCKLED	\$240.00	\$240.00	
1.2	BONNET HINGE RH		BENT	\$30.00	\$30.00	
1.3	BONNET HINGE LH		BENT	\$30.00	\$30.00	
1.4	BONNET LOCK		JAM	\$48.00	\$48.00	
1.5	BONNET INSULATOR		DEFORMED	\$114.00	\$114.00	
1.6	BONNET INSULATOR CLIP	10	NECESSARY	\$1.80	\$18.00	
1.7	HEADLAMP LH COMPLETE		DISTORTED	\$234.00	\$234.00	
1.8	BODY WIRE HARDNESS 82111-0Z870/890		TORN	\$2,340.00	\$2,340.00	
1.9	FRONT BUMPER		MISSING	\$204.00	\$204.00	
1.10	FRONT BUMPER RETAINER RH		CRACKED	\$24.00	\$24.00	
1.11	FRONT BUMPER RETAINER LH		MISSING	\$24.00	\$24.00	
1.12	FRONT BUMPER CLIP	10	NECESSARY	\$1.80	\$18.00	
1.13	FRONT GRILLE		BROKEN	\$120.00	\$120.00	
1.14	TOYOTA LOGO		MISSING	\$30.00	\$30.00	
1.15	FRONT BUMPER CENTER GRILLE		MISSING	\$48.00	\$48.00	
1.16	FOGLAMP COVER RH		MISSING	\$36.00	\$36.00	
1.17	FOGLAMP COVER LH		MISSING	\$36.00	\$36.00	

110	TO REPAIR AND RESPRAY SUPPORT PANEL				2
	COSTING				
		TOTAL PARTS COST	\$7,254.00		
		TOTAL MAN-HOUR		43	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19007500/Gtd3e2	
CONTRACT MANAGEMENT SECTION(SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333		Date : 21-05-2019	
ATTN : PERRY HE		Code : SPF3	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	QX 311A
Policy No.		Coverage (\$)	0.00
Claim No.	MHASPF0300000113	Excess (\$)	0.00
Assign From	PERRY HE	Assign Date	24/04/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053ZEE106109174	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date		Inspection Date	29/04/2019
Survey held at	INDECO ENGINEERS PTE LTD 39 DEFU LANE 12 . SINGAPORE 539139		
5a. Remarks			



Registration No. QX 311A

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	BONNET	1	BUCKLED	\$240.00	\$240.00	
1.2	BONNET HINGE RH	1	BENT	\$30.00	\$30.00	
1.3	BONNET HINGE LH	1	BENT	\$30.00	\$30.00	
1.4	BONNET LOCK	1	JAM	\$48.00	\$48.00	
1.5	BONNET INSULATOR	1	DEFORMED	\$114.00	\$114.00	
1.6	BONNET INSULATOR CLIP	10	NECESSARY	\$1.80	\$18.00	
1.7	HEADLAMP LH COMPLETE	1	DISTORTED	\$234.00	\$234.00	
1.8	BODY WIRE HARDNESS 82111-0Z870/890	1	TORN	\$2,340.00	\$2,340.00	
1.9	FRONT BUMPER	1	MISSING	\$204.00	\$204.00	
1.10	FRONT BUMPER RETAINER RH	1	CRACKED	\$24.00	\$24.00	
1.11	FRONT BUMPER RETAINER LH	1	MISSING	\$24.00	\$24.00	
1.12	FRONT BUMPER CLIP	10	NECESSARY	\$1.80	\$18.00	
1.13	FRONT GRILLE	1	BROKEN	\$120.00	\$120.00	
1.14	TOYOTA LOGO	1	MISSING	\$30.00	\$30.00	
1.15	FRONT BUMPER CENTER GRILLE	1	MISSING	\$48.00	\$48.00	
1.16	FOGLAMP COVER RH	1	MISSING	\$36.00	\$36.00	
1.17	FOGLAMP COVER LH	1	MISSING	\$36.00	\$36.00	
1.18	ENGINE UNDER COVER RH	1	TORN	\$72.00	\$72.00	
1.19	ENGINE UNDER COVER LH	1	TORN	\$72.00	\$72.00	
1.2	ENGINE UNDER COVER CLIP	10	NECESSARY	\$1.80	\$18.00	
1.21	LHF FENDER INNER SHIELD	1	MISSING	\$54.00	\$54.00	
1.22	RHF FENDER INNER SHIELD	1	TORN	\$54.00	\$54.00	
1.23	LHF FENDER	1	MISSING	\$156.00	\$156.00	
1.24	LH WING MIRROR COMPLETE	1	DISTORTED	\$318.00	\$318.00	
1.25	FRONT NUMBER PLATE	1	MISSING	\$24.00	\$24.00	

1.26	LHF DOOR	1	BUCKLED	\$480.00	\$480.00	
1.27	LH SIDE SKIRT	1	DEFORMED	\$288.00	\$288.00	
1.28	AIR RESONATOR BOX	1	MISSING	\$78.00	\$78.00	
1.29	AIR CLEANER INLET 1 17751-37060	1	DEFORMED	\$24.00	\$24.00	
1.3	FRONT BUMPER RUBBER MOULDING	1	MISSING	\$24.00	\$24.00	
1.31	FRONT BUMPER REINFORCEMENT	1	BENT	\$144.00	\$144.00	
1.32	ENGINE WIRE HARNESS 82121-02N10	1	UNCONFIRM	\$1,800.00	\$1,800.00	
1.33	AIR CLEANER INLET 2 17752-37070	1	DEFORMED	\$54.00	\$54.00	
1	LABOUR					
1.1	TO REPLACE AND RESPRAY BONNET					6
1.2	TO REPLACE AND RESPRAY FRONT BUMPER					5
1.3	TO REPLACE AND RESPRAY LHF FENDER					4
1.4	TO REPLACE AND RESPRAY LHF DOOR					6
1.5	TO REPLACE AND RESPRAY REINFORCEMENT					1
1.6	TO REPLACE AND RESPRAY LH WING MIRROR					2
1.7	TO REPLACE AND RESPRAY LH SIDE SKIRT					4
1.8	TO REPAIR AND RESPRAY RH FENDER					5
1.9	TO REPLACE BODY AND ENGINE WIRE HARDNESS					8
110	TO REPAIR AND RESPRAY SUPPORT PANEL					2
COSTING		TOTAL PARTS COST			\$7,254.00	
		TOTAL MAN-HOUR				43

Registration No. QX 311A

Vehicle Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

<p>DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.</p>
