

# Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point  
Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER: **Sompo Insurance Singapore Pte. Ltd. (HQ)**

## PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D19MTPV01003356	Date of Loss:	26/04/2019
Vehicle Reg. No.:	<b>SLL7895H</b>	Driveable?	NO
Driver Age/Info:	21 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	PIRAGASAM S/O MUNISAMY	Contact No:	+6597838360
Driver:	RAVEEN PIRAGASAM		

Make/Model:	HONDA VEZEL, 1.5 X CVT (A)	Vehicle Reg. Date:	10/03/2017
Vehicle Colour:	BLUE		
Engine No:	L15B4408293	Chassis No:	RU11208292
Odometer:	0 KM		

Paint Type:	
Total Loss?	<b>NO</b>
Est. Duration of Repair (day)	20

*Handwritten:*  
part by part.  
Resurvey before paint  
sure the work is done

*Handwritten:*  
Tanghan 97495749/67418134  
Not Authorise  
Ex: to be advise.  
10 days

Description of Accident/Loss

ON 26/04/2019 ABOUT 7.48PM, I WAS DRIVING ALONG AYE AROUND ALEXANDRA EXIT. CAR IN FRONT OF ME BRAKE TO A COMPLETE STOP, I FOLLOWED. HOWEVER MY CAR COULD NOT STOP IN TIME AND BUMP ONTO IS REAR. WE SUPPOSE TO EXCHANGE OUR PARTICULARS AT THE ROAD SHOULDER. BUT THE OTHER PARTY DROVE AWAY IGNORING ME. EMAS WENT LOOKING FOR THEM BUT COULD NOT FOUND.

Present Location: ACCORD AUTO SERVICES PTE LTD (AV) TEL: 6271 7433

## COST OF CLAIMS

	Amount
Parts	12,481.70
Miscellaneous Items	383.00
Labour	4,550.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>17,414.70</b>
<b>+ GST 7.00% (S\$)</b>	<b>1,219.03</b>
<b>Nett Amount (S\$)</b>	<b>18,633.73</b>

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

This claim is handled by: **SOE JIE YI (JESSY)**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS**

**Reference**

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 29 Apr 2019)  
**Parts:** M1-SUV      HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** Accord Auto Services Pte Ltd/SLL7895H/29/04/2019 16:23  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
						1250
1	1		*Front windscreen glass	0.00	1250 0.00	*1,300.00 F ✓
2	1		*Front windscreen glass moulding (top)	0.00	40 0.00	*30.00 F 40 ✓
3	1		*Front windscreen glass moulding (lower)	0.00	40 0.00	*30.00 F 40 ✓
4	1		*Front wiper garnish	0.00	0.00	nn X *135.00 F
5	1		*Bonnet	0.00	0.00	bt ✓ *400.00 F ✓
6	2		*Bonnet hinge	0.00	0.00	bt ✓ *60.00 F ✓
7	1		*Bonnet insulator pad	0.00	0.00	de ✓ *85.00 F ✓
8	4		*Bonnet seal	0.00	0.00	de ✓ *72.00 F
9	1		*Bonnet lock	0.00	85 0.00	jn ✓ *60.00 F ✓
10	1		*Bonnet lock cable	0.00	0.00	nn X *25.00 F
11	1		*Bonnet stand	0.00	15 0.00	mis ✓ *25.00 F ✓
12	1		*Bonnet stand clip	0.00	0.00	mis ✓ *3.00 F ✓
13	2		*Horn	0.00	0.00	nn X *50.00 F
14	1		*Front grille	0.00	220 0.00	de ✓ *190.00 F ✓
15	1		*Front grille outer garnish	0.00	230 0.00	de ✓ *130.00 F ✓
16	1		*Front grille lower moulding	0.00	30 0.00	ay ✓ *35.00 F ✓
17	1		*Front grille logo	0.00	18 0.00	de ✓ *15.00 F ✓
18	1		*Front grille upp center beam	0.00	0.00	de X *15.00 F
19	1		*Front grille up RH beam	0.00	0.00	de X *10.00 F
20	1		*Front grille up LH beam	0.00	0.00	de X *10.00 F
21	1		*LH headlamp (LED)	0.00	880 0.00	de ✓ *800.00 F ✓
22	1		*LH headlamp bracket	0.00	0.00	de ✓ *20.00 F ✓
23	1		*RH headlamp (LED)	0.00	880 0.00	de ✓ *800.00 F ✓
24	1		*RH headlamp bracket	0.00	0.00	de ✓ *20.00 F ✓
25	1		*Front bumper	0.00	280 0.00	de ✓ *190.00 F ✓
26	1		*Front bumper low grille	0.00	0.00	nn X *40.00 F
27	1		*Front bumper fog lamp (RH)	0.00	0.00	aw ✓ *120.00 F ✓
28	1		*Front bumper fog lamp cover (RH)	0.00	0.00	cut X *15.00 F nn
29	1		*Front bumper low lid	0.00	0.00	nn X *110.00 F
30	1		*Front bumper tow cover	0.00	12 0.00	ms ✓ *10.00 F 12 ✓
31	2		*Front bumper air guide	0.00	0.00	de X *24.00 F nn
32	1		*Front bumper reinforcement	0.00	0.00	bt ✓ *180.00 F ✓
33	2		*Front bumper reinforcement moulding	0.00	20 0.00	de ✓ *30.00 F ✓
34	2		*Front bumper side retainer	0.00	40 0.00	de ✓ *20.00 F ✓
35	1		*Support panel	0.00	350 0.00	bt ✓ *280.00 F
36	1		*Support panel top garnish	0.00	0.00	de X *38.00 F nn
37	1		*Front LH fender	0.00	180 0.00	bt ✓ *170.00 F ✓
38	1		*Front RH fender	0.00	180 0.00	bt ✓ *170.00 F ✓
39	1		*Front RH fender splash shield	0.00	0.00	nn ✓ *55.00 F
40	1		*Front RH fender protector	0.00	0.00	X *35.00 F nn
41	1		*Air-con condenser assy	0.00	280 0.00	bt ✓ *300.00 F ✓
42	2		*Air-con condenser top bush	0.00	0.00	nn X *10.00 F
43	2		*Air-con condenser bottom bush	0.00	0.00	nn X *10.00 F
44	1		*Air-con suction hose	0.00	0.00	? X *90.00 F

LKK Auto Consultants hence notify the Repairer of the following:  
 • To reserve before/after any painting  
 • To display damaged parts during reserve  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modifications is allowed  
 • Supplemental items must be reserved and is subject to final approval from Insurance Company  
 Acknowledged by Repairer  
 Signature:  
 Date:

Accord Auto Services Pte Ltd/SLL7895H/29/04/2019 16:23. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1		*Air-con discharge hose	0.00	0.00	? *110.00 F
46	1		*Air-con pipe (receiver)	0.00	0.00	? *90.00 F
47	1		*Air-con ambient sensor	0.00	0.00	? *25.00 F
48	1		*Air-con ambient sensor clip	0.00	0.00	? *10.00 F
49	1		*Radiator assy	0.00	0.00	bt *700.00 F ✓
50	2		*Radiator top bracket	0.00	0.00	bt *30.00 F ✓
51	2		*Radiator bottom bush	0.00	0.00	? *20.00 F
52	1		*Radiator top hose	0.00	0.00	? *15.00 F
53	1		*Radiator bottom hose	0.00	0.00	? *15.00 F
54	1		*Air-con fan cowling	0.00	0.00	? *60.00 F ✓
55	1		*Air-con fan balde	0.00	0.00	? *35.00 Fx
56	1		*Air-con fan motor	0.00	0.00	? *150.00 F ✓
57	1		*Radiator fan cowling	0.00	0.00	? *70.00 F ✓
58	1		*Radiator fan blade	0.00	0.00	? *40.00 F ✓
59	1		*Radiator fan motor	0.00	0.00	PNX *190.00 F
60	1		*Radiator spare tank	0.00	55	dev *25.00 F ✓
61	1		*Washer tank	0.00	40	di *45.00 F ✓
62	1		*Washer tank neck	0.00	15	di *20.00 F ✓
63	1		*Washer tank cover	0.00	0.00	di *10.00 F ✓
64	2		*Washer tank motor	0.00	0.00	X *70.00 F
65	1		*Front LH air bag (passenger side)	0.00	0.00	act *1,100.00 F ✓
66	1		*Front RH air bag (driver side)	0.00	0.00	act *720.00 F ✓
67	1		*Front LH seat belt	0.00	0.00	act *380.00 F ✓
68	1		*Front RH seat belt	0.00	0.00	act *380.00 F ✓
69	1		*Airbag sensor	0.00	0.00	act *90.00 F ✓
70	1		*Steering angle sensor	0.00	70	act *130.00 F ✓
71	1		*Dashbaord	0.00	0.00	di *600.00 F ✓

F=Franchise part.

<b>Sub Total (\$\$)</b>	<b>11,347.00</b>
<b>+ Margin on L,N Items 10.00% (\$\$)</b>	<b>1,134.70</b>
<b>Total Parts (\$\$)</b>	<b>12,481.70</b>

Accord Auto Services Pte Ltd/SLL7895H/29/04/2019 16:23. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	Bonnet insulator pad clip	30 <del>we</del> 50.00
2	1	Front bumper clip	we / 20 50.00
3	1	Front number plate with holder	bt - 45 55.00
4	1	Front RH fender protector clip	we 18.00
5	1	Front RH fender splash shield clip	we / 70 50.00
6	1	Front windscreen glass sealant/gum	we - 80.00
7	1	IU bracket sticker	we 10.00
8	1	Radiator coolant	we 40.00
9	1	Support panel top garnish clip	we / 10 30.00
<b>Sub Total (\$)</b>			<b>383.00</b>

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	Spray painting on all affected area.	New	800. 900.00
2	Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	New	800. 1,200.00
3	To check wiring system & light.	New	30. 120.00
4	To remove and replace front windscreen glass.	New	120 150.00
5	To remove and replace air-con condenser, hoses, piping, fan assy & etc., vacuum and top up gas.	New	120 300.00
6	To remove and replace radiator, hoses, fan assy & etc..	New	100 250.00
7	To remove and replace front LH & RH airbag assy, airbag sensor, steering angle sensor.	New	200. 350.00
8	To remove and replace front LH & RH seat belt.	New	100. 300.00
9	To remove and replace dashboard.	New	180. 380.00
10	To remain and adjust front main chassis.	New	photo we X 200 300.00
11	Computer diagnostic	New	150. 300.00
<b>Gross Labour Cost (\$)</b>			<b>4,550.00</b>

Accord Auto Services Pte Ltd/SLL7895H/29/04/2019 16:23. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >