

Date : 26/04/2019

TO: AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120

Joy

Our Customer : Unicoat Pte Ltd

Vehicle No : SJP9322J

Model : Mitsubishi Lancer 1.5MIVEC

Manufacture Year : 2009 (COE:31/12/2023)

Date of Accident : 24/04/2019

Total Estimate Repair Days : 10

Total Pages : 2

Attn : Motor Claims Department

Fax : 6415 3727

JMYSRCY2A94004129

Re: Repair Estimate For Third Party Claim against SKN2658K

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts (Nett)				
1	Rear bumper <i>Rebuilt</i>	1	\$847.00	\$847.00	✓
2	Rear bumper side retainer LH <i>new</i>	1	\$22.00	\$22.00	✓
3	Rear fender LH <i>Rebuilt</i>	1	\$838.00	\$838.00	✓
4	Rear absorber LH <i>Rebuilt</i>	1	\$302.00	\$302.00	✓
5	Rear knuckle arm LH <i>Rebuilt</i>	1	\$480.00	\$480.00	✓ 420
6	Rear knuckle arm bearing LH <i>Rebuilt</i>	1	\$453.00	\$453.00	✓ 390
7	Rear lower arm LH <i>Rebuilt</i>	1	\$226.00	\$226.00	✓
8	Rear door LH <i>Rebuilt</i>	1	\$1,108.00	\$1,108.00	✓
9	Rear door frame LH <i>Rebuilt</i>	1	repair	repair	+
10	Rear door outer moulding LH <i>new</i>	1	\$151.00	\$151.00	+
11	Rear door weatherstrip LH <i>new</i>	1	\$189.00	\$189.00	+
12	Rear door channel LH <i>new</i>	1	\$193.00	\$193.00	+
13	Rear door hinges <i>new</i>	2	\$77.00	\$154.00	+
14	Rear door checker LH <i>new</i>	1	\$87.00	\$87.00	+
15	Rear door sash pillar black sticker LH <i>new</i>	1	\$68.00	\$68.00	✓
16	Rear door power window motor LH <i>new</i>	1	\$363.00	\$363.00	+
17	Rear door power window regulator LH <i>new</i>	1	\$231.00	\$231.00	+
18	Rear door trimboard LH <i>new</i>	1	\$568.00	\$568.00	+
19	Side skirt LH <i>new</i>	1	\$844.00	\$844.00	+
	Total			\$7,124.00	
	Less 10%			\$712.40	
	Sub Total 1			\$6,411.60	
A.	Spare Parts (S/Nett)				
1	Rear tyre LH <i>new</i>	1	\$450.00	\$450.00	+
2	Rear sports rim LH <i>new</i>	1	\$550.00	\$550.00	+
3	Rear bumper clip <i>new</i>	10	\$5.00	\$50.00	+
4	Rear door trimboard clip <i>new</i>	10	\$5.00	\$50.00	+
5	Sealant <i>new</i>	1	\$80.00	\$80.00	+
	Sub-Total 2			\$1,180.00	
	Total for Parts			\$7,591.60	
B.	Labour				
1	To check wiring.			\$90.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,200.00	80

480

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
3	Spray painting all affected parts & areas.			\$1,200.00	800
4	To remove and refit rear windscreen glass.			\$120.00	700
5	To spray anti-rust undercoat.			\$90.00	60
6	To remove and refit rear seats, rear wheelhouse inner garnish, floor carpet & upholstery to facilitate repairs.			\$200.00	80
7	To check and align wheels with computerized wheel alignment.			\$120.00	80
8	To remove and replace rear suspension and undercarriage.			\$258.00	220
	Total Labour			\$3,270.00	
	Total Repair Cost			\$10,861.60	

To remove & refit rear door glass let a 100 80

2170

fittings

Admin L
1/s 28/04/19.

OT Pays

total: 6468.90

1/s: 5150

Yours faithfully,

Aun Teng

f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



PEOPLES AUTO TRADING
BLK 3007 UBI ROAD 1 #01-400
TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	CASH	DATE	Apr 29, 2019 1:30:05 PM
LICENSE NO.	SJP 9322 J		
MILEAGE	169782		
REFERENCE	CUSTOM	MODEL	MITSUBISHI LANCER CY

Front Wheel	SPECS				DIAGNOSIS				ADJUSTMENT			
	min	prev	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-1.20	0.00	1.20			-0.40				-0.40		
PARTIAL TOE	-0.60	0.00	0.60		-1.60		1.10		-1.50		1.10	
STUB R	---	---	---			0°00'				0°00'		
CAMBER	-0°30'	0°00'	0°30'		-0°26'		-0°48' 0°22'		-0°26'		-0°48' 0°20'	
CASTER	2°44'	3°14'	3°44'		2°56'		2°34' 0°22'		2°56'		2°34' 0°22'	
KNOCK-IN	---	---	---		13°42'		14°18' 0°36'		13°42'		14°18' 0°36'	
HEEL ANGLE	---	---	---		13°14'		13°28'		13°14'		13°28'	
Toe out on turns	---	---	---		---		---		---		---	
STEERING	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel	SPECS				DIAGNOSIS				ADJUSTMENT			
	min	prev	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-0.30	0.90	2.10			3.80				3.80		
PARTIAL TOE	-0.10	0.40	1.00		3.60		0.10		3.60		0.10	
STUB R	---	---	---			0°08'				0°08'		
CAMBER	-1°10'	-0°40'	-0°10'		-2°18'		-1°12' 1°04'		-2°18'		-1°12' 1°04'	
THROST ANGLE	-0°08'	0.00	0°08'			0°16'				0°16'		