Augustia try	WIMSG1900	7579/AG	sd302	ro Frence	
Mummin GQ	ASSIGNATION	T (Office)			
menimen GQ Chhia Nyuk pu	em in	19	Date/Lu	30/4/19/059-5	tem
Estimated Cost	I	till ter			
OD TP WS/TPRES/OD RES/EV	ATHOUTMOTES				
	(1B) 1373R		Insued	CHBA 5845S	ži.
at Worl shop m/	SM Automo	tive	Tel	67479241	
I kati Buki	it Ne6#0	01-43			
10/10/10 29097415MKC		Claim Ho			
Sum firange		Excess			
Make of Veh: (Client's Record)			1),0,4	29/04/2019	
CA / REV / REP. / REV 24 HRS			H-O.D. 1	suction is mostly	
Date/Time 10.06cm@ 30/4/19 19	ason Contacted	sukyi	Vehiçle 🛈	2	
Date/Time Action/Instruction (	) Colomate				
		5/h4		DOA: Dold Inole	h
CIBIT CRACE	NA/PTIAN	1777/	h d	80A: 20/4/2010 80A: 29/4/2010	ner.
25 @ 16:24pm sont	amail to	Mevim	en pend	ing estimo	10
. = 17. 50/11	WITH CO		Ci. Pore	23(1770	40

.

1. -

Preli. Report:

Final Report

5,900/- HS

Photos

Others

TOTAL

# ...CLAIM SUBFOLDER...(New Assignment)

LAIM SUBI	FOLDER TRA	CKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sub	mitted	Ins Auth'ed	Status	
Main	29 Apr 2019 30 Apr 2019 09:57 New Assign Cancel Case								
- 1	Main	Re	ference		Claim Details		Docume	nts	Show All
CLAIM SU	BFOLDER DE	TAILS				[Creat	ed by insurer]		
Insured:	On The FI	y, Co. Reg. No.:	53364196M						
Main Claimant:	J & L COU	RIER & TRANSP	ORTATION SER	VICES, C	o. Reg. No.: 533	44701A			
Vehicle Reg No.:	GBJ137	3R			Date of Loss:		4/2019 07:00 - :59 onths and <b>20</b> Days From LTA Reg Date (Man		
Claim Type:	TP				Policy/Cover Note No.:	29097415MKC (Comprehensive) Coverage: 29/09/2018 - 28/09/2019			
Vehicle Reg. No. (Insured):	GBA5845	s			Policy No. (Claimant):				
					Excess:				
Repairer:	Sm Auton	notive - Kaki Buk	tit (HQ) BLOCK	C - 1, KAKI	BUKIT AVE 6, #0	1-43, 41	7883 Kaki Bukit -	Tel:	
Handling Insurer:	MSIG Ins	urance (Singapo	re) Pte. Ltd. (H	<b>(Q)</b> - Tel: +6	5 6827 7888	[Handled	by Chhia Nyuk	<b>Pui -</b> 6594 2	521]
Adjuster:	LKK Auto	<b>Consultants Pte</b>	Ltd (HQ) - Tel:	6256-3561	[Imm.Adv	ice due	01/05/2019]		
Adj Asg. Remarks:	SURVEY A	GREE ON SJE - REG	Q TO ASSIGN LK	K. LIABILITY	DISPUTE (OI N	ON-REPO	RTING) CONTACT	SUKYI CHO	NG 6747 9241
ASSOCIAT	ED MAIL RE	CEIVED						View All	Compose Case Mail
There are no	o mail for this	case.					,		
ALL ASSO	CIATED TAS	KS⊟				View A	Search Tasks	Create Ne	w Task   Complete

No results.

#### > Back to OneMotoring

#### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 4701A

Vehicle Details

Vehicle No.: GBJ1373R

Vehicle to be Exported: No

Intended Deregistration Date: 29 Apr 2019 Vehicle Make: TOYOTA

Vehicle Model: HIACE DX 2.8 AUTO

Primary Colour: White Manufacturing Year: 2018

Engine No.: 1GD8340740
Chassis No.: GDH2012003178

Maximum Power Output:

Open Market Value: \$33,735.00
Original Registration Date: 09 Jan 2019
First Registration Date: 09 Jan 2019

Transfer Count: 0

Actual ARF Paid: \$1,687.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 08 Jan 2029

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$23,303.00
COE Rebate Amount: \$22,588.00
Total Rebate Amount: \$22,588.00

The information contained herein is correct as at 29 Apr 2019

OK

## **View Sent Message**

This mail is associated with:

\*GBJ1373R (592183) [GBA5845S]

TP J & L COURIER & TRANSPORTATION SERVICES Apr 29 2019 7:00AM [On The Fly] Sm Automotive - Kaki Bukit

Resend	View Recipients	Print Message	Delete Message	Forward			
From	LKK Auto Cons	ultants Pte Ltd	(LKK_HQ), sent	on <b>02/05/2019</b>	6:24 PM.		
То	nyukpui_cchia@						
Subject	GBJ1373R [GB	A5845S] TP					

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBJ 1373R on 30/04/2019 We are pending estimate from repairer.

Best Regards,

Denise Tay on behalf of shirley hiew | Case Handler LKK Auto Consultants Pte Ltd

#### **DOCUMENTS SUMMARY**

There are no documents.

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

Fax Number Contact Number EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	29/04/2019 13:29
Date Of Accident	29/04/2019 07:35
Exact Location Of Accident	CORPORATION RD TWDS AYE AFTER BOON LAY WAY
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	GBJ1373R
Insured/Policyholder	
Name Of Registered Owner	J & L COURIER & TRANSPORTATION SERVICES
Co Reg No	53344701A
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-87848491
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	SENDING WIFE TO WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3003681900
Cover Note Number	*
Driver	
Name of Driver	LEE ZI HUI (LI ZIHUI)
NRIC No	S8406798I
Date Of Birth	07/03/1984
Occupation	OUTDOOR
Date Of Driving Pass	20/05/2016
Driving Experience	2 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87848491

NOEMAIL

Address

BLK 216A BOON LAY AVE #05-219

Postcode

641216

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

YES

Was any body injured in the Accident? Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Passenger 1

NAME:

: LYNETTE QUAH HWEE LING

GENDER:

: FEMALE

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

WITH DRIVER

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

**GBA5845S** 

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

96906587

Address

Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 15

# No. Of Passenger (Including Driver)

#### **DETAILS OF INJURED PERSON 1**

Name

LEE ZI HUI (LI ZIHUI)

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

GBJ1373R

Were seat belts worn?

YES

Was this injured conveyed to hospital by

ambulance?

NO

Address

Postcode

## **DETAILS OF INJURED PERSON 2**

Name

LYNETTE QUAH HWEE LING

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

GBJ1373R

Were seat belts worn?

YES

Was this injured conveyed to hospital by

ambulance?

NO

Address

Postcode

#### Accident Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Breads report correctly the details of the accident to appeal up the delits process.
- This form must be completed by the Policyholder and/or the Authorised Driver
- 3 information provided must be as <u>trythful and accurate as possible</u>. Any wirful misrepresentation or withholding of material facts may allow insorance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy rubility on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 2 By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to zooles of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be objectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - (ii) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (iii) investigating the accident and/or my claims;
  - (III) carrying out and/or dealing with my instructions or responding to any enquiries by me.
  - (iv) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about derivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. [collectively the "Purposes"]
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firmt, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GtA to their third party service providers or agents@ncluding their lawyers/faw firms], which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (n) the information so collected under (d) above may be shared / disclosed
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time

Driver Signature (if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: NBIC/FIN No.

#### Accident Sketch Plan

KETCH PLAN				
A: GB3 1373R B: GBA SENSS	CORPORATION ROAD	Z As		
ESCRIBE CIRCUMSTANCES OF THE ACCID	ENT			
I was tra	NECUNG ALG	No COR	PORATION	ROAD ON
VEHILLE IN FRONT OF A	HANES, HE BOATE	AND STOP	I ALSO	manua 7
VEHILLE IN FRONT OF A	HE BOATE	AND STOP	I ALSO	manual T
VEHILLE IN FRONT OF A	HE BOATE	AND STOP	I ALSO	manua 7
VEHICLE IN FRONT OF A	HE BOATE	AND STOP	I ALSO	manual T
VEHICLE IN FRONT OF A	HE BOATE	AND STOP	I ALSO	manual T
VEHICLE IN FRONT OF A	HE BOATE	AND STOP	I ALSO	manual T
VEHICLE IN FRONT OF A	HE BOATE	AND STOP	I ALSO	manual T
VEHICLE IN FRONT OF A	HE BOATE	AND STOP	I ALSO	manual T
STOP NHON SUDDENLY OF ASTOP NHOW STOP NHOW SUDDENLY OF THE RE	HE BOATE	AND STOP	I ALSO	manual T

Orest a September 13 driver is not the policyholder. Out & Time

Page 5 of 15

Reporting Centre Personner's Signature Name NRC/Fin. Inc.

# SM &UTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883 Email: SM\_AUTOMOTIVE@HOTMAIL.COM Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

1373

29/04/2018

Blk 1 Kaki Bukit Ave 6 # 01-43 Singapore 417883

TPMS167 Shirtly

Accident date: 29/04/2018

Estimated repair cost for vehicle no: GBJ1363R TOYOTA HIACE DX 2.8 A '19

CHASSIS: GDH2012003178

		CHA5515: GDH2012005178		
S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid Dented		\$1,712.45
2	2	Rear Boot Lid Hinge	\$171.70	\$343.40
3	2	Rear Boot Lid Shock Absorber	\$281.90	\$563.80 *
4	1	Rear Boot Lid Emblem Logo 7		\$51.10~
5	1	Rear Boot Lid 70km/H Sticker / La		\$30.00
6	1	Rear Boot Lid Hiace Sticker		\$35.75
7	1	Rear Boot Lid Centre Moulding		\$261.60
8	1	Rear Boot Lid Number Plate Zay		\$50.00 +
9	2	Rear Boot Lid Number Plate Lamp J M	\$83.10	\$166.20
10	1	Rear Boot Lid Inner Lock		\$374.25
11	1	Rear Boot Lid Inner Lock Cover № ←		\$162.00
12	1	Rear Boot Lid Inner Power Lock Motor Arc		\$581.45
13	1	Rear Boot Lid Inner Rubber Lt		\$281.35
14	1	Rear Boot Lid Inner Trim Board X46		\$372.25
15	10	Rear Boot Lid Inner Trim Board Clip MC	\$6.50	\$65.00 +
16	1	Rear Boot Lid Windscreen Tut		\$1,217.10
17	1	Rear Boot Lid Windscreen Seal ALL		\$105.00
18	2	Rear Tail Lamp LH Could	\$374.45	\$74 <del>8.90</del> 374.4
19	2	Rear Tail Lamp Lower Cover	\$182.10	\$364.20 +
20	2	Rear Tail Lamp Lower Cover Retainer	\$171.45	\$342.90 /
21	1	Rear Bumper Delad		\$374.40
22	10	Rear Bumper Clip M	\$6.50	\$65.00 30
23	2	Rear Bumper Side Retainer :	\$121.25	\$242.50 —
24	1	Rear Bumper Centre Step Panel Bey		\$271.85
25	1	Rear End Panel Outer Dested		\$591.60
26	1	Rear End Panel Inner Pan		\$781.90
27	1	Rear Floor Panel New		\$1,972.85
28	1	Rear Floor Panel Top Moulding		\$274.45

29	8	Rear Floor Panel Top Moulding Clip	Nece	\$6.50	\$52.00 +
30	1	Rear Floor Panel Plywood 2			\$650.00 +
31	1	Rear Floor Panel Carpet Hu			\$850.00
32	1	Rear Spare Tyre Bracket			\$243.10
33	1	Rear Exhaust			\$1,712.65
34	2	Rear Exhaust Mounting (Ma		\$61.75	\$123.50
35	1	Rear Centre Exhaust			\$1,829.10 +
		Revese Sensor And	250	200(SN)	
		Reer Comen Danged Reer Buyer lones Brulat x04.  Bert	A00	380 Subtotal:-	\$17,863.60
		Pur Rome lover Rought XDY	2004	117	633985
labar	ماء	Bent.	GOLA.		A754 88
Labot	ar cn	arges			
+		0 6		S	N. 580 .
io ren	nove	& refit rear windscreen			\$120.00
C					¢50.00 /
Gum					\$50.00
To ron	20110	& refit rear & centre exhaust			\$380.00 大。
o ren	nove	a rent rear a centre exhaust			\$380.00
Co ron	2010	9. rafit carnet 9. physicad		2000	\$280.00 /00.
o ren	nove	& refit carpet & plywood		0000	\$200.00 700
To che	ock w	viring			\$100,00 30
O CITE	ECK W	annig			\$100,00
Towin	a foo	_			\$100.00
OWIII	giee				\$100.00
Tuff ko	ote				\$150.00 60
i u i i k	ote				\$130.00 60
Panel	hoat	ing			\$1,800,00 80
allei	beat	iiig			\$1,000,00 00
Spray	nain	ting		a 120	\$1,600.00 829
Spray	pain	ung	100	50	\$1,000.00
0 100	1000	ad replace reverse sersor			¢4.590.00
		1	1863	Subtotal:-	\$4,580.00
e cen	ine	and repline New Camera	1	Total	\$22,442,60
				Total:-	\$22,443.60
		L n A . 72	cu cc.	a 1	7 *
		tolel: 73	88. LI	Adria	

# LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature;

Date:

45:59K. 45 30/04/15.

23639.60

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBI	FOLDER TRA	CKING								
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Submitted	Ins Auth'ed	Sta	tus	
Main	29 Apr 2019		30 Apr 2019 09:57 Edit Adj Rpt	S\$5,900 Edit Est	1	\$\$5,900.00 View Rpt		Re	nding for port Cancel Case	Survey
	Main	R	eference	C	laim Deta	ails	Document	s	1	Show All
CLAIM SU	BFOLDER DI	TAILS				[Create	d by insurer]			
Insured:	On The F	y, Co. Reg. No.:	53364196M							
Main Claimant:	J & L COL	JRIER & TRANSP	ORTATION SERVI	ICES, Co.	Reg. No.:	53344701A				
Vehicle Reg No.:	GBJ137	3R			Date of L		19 07:00 - :59 s and <b>20</b> Days Fro	m LTA R	eg Date (M	an Yr)]
Claim Type	TP / 592	183			Policy/Co Note No.		15MKC (Comprehe 2: 29/09/2018 - 28,		9	
Vehicle Reg No. (Insured):	0.0	GBA5845S			Policy No (Claiman					
					Excess:					
Repairer:	Sm Autor	notive - Kaki Bu	kit (HQ) BLOCK C	- 1, KAKI BU	KIT AVE	5, #01-43, 4178	383 Kaki Bukit - Te	l;		
Handling Insurer:	200000000000000000000000000000000000000		re) Pte. Ltd. (HQ	5 10 100		7.				
Adjuster:	01/05/2	Consultants Pte 019]	Ltd (HQ) - Tel: 62	256-3561	[Handled	by XING GUO	QIANG] [Imn	n.Advi	ce due	
Adj Asg. Remarks:	SURVEY A	GREE ON SJE - RE	Q TO ASSIGN LKK.	LIABILITY:	ISPUTE (	OI NON-REPOR	TING) CONTACT: S	UKYI CH	ONG 6747	9241
ASSOCIAT	TED MAIL RE	CEIVED					Vie	ew All	Compose	Case Mail
There are n	o mail for this	case.								
ALL ASSO	CIATED TAS	кѕ⊟				View All	Search Tasks	Create N	ew Task	Complete
Due Date	e Priority	Type Task	Group Subject	ct Hand	er A	ssigned By	Completed On	Cı	reated On	Done?

Merimen e-Claims Page 1 of 3

### Claim Documents

\*GBJ1373R (592183)

[GBA5845S]

TP

J & L COURIER & TRANSPORTATION SERVICES

Apr 29 2019 7:00AM

[On The Fly]

Sm Automotive - Kaki Bukit

Pho	tos/Images		3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnai	I Prin
1	14/05/19 09:41	General View	Load JPG	✓
2	14/05/19 09:41	General View	Load JPG	✓
3	14/05/19 09:41	General View	Load JPG	<b>✓</b>
4	14/05/19 09:41	General View	Load JPG	✓
5	14/05/19 09:41	General View	Load JPG	V
6	14/05/19 09:41	General View	Load JPG	✓
7	14/05/19 09:41	General View	1 Load JPG	<b>✓</b>
8	14/05/19 09:41	General View	Load JPG	V
9	14/05/19 09:41	General View	Load JPG	<b>✓</b>
10	14/05/19 09:41	General View	Load JPG	V
11	14/05/19 09:41	General View	1 Load JPG	V
12	14/05/19 09:41	General View	■ Load JPG	~
13	14/05/19 09:41	General View	■ Load JPG	V
14	14/05/19 09:41	General View	1 Load JPG	~
15	14/05/19 09:41	General View	Load JPG	V
16	14/05/19 09:41	General View	Load JPG	V
17	14/05/19 09:41	General View	Load JPG	V
18	14/05/19 09:41	General View	Load JPG	V
19	14/05/19 09:41	General View	1 Load JPG	~
20	14/05/19 09:41	General View	■ Load JPG	V
21	14/05/19 09:41	General View	Load JPG	<b>✓</b>
22	14/05/19 09:41	General View	Load JPG	<b>✓</b>
23	14/05/19 09:41	General View	Load JPG	✓
24	14/05/19 09:42	General View	Load JPG	~
25	14/05/19 09:42	General View	Load JPG	V
26	14/05/19 09:42	General View	Load JPG	<b>✓</b>
27	14/05/19 09:42	General View	Load JPG	V
28	14/05/19 09:42	General View	£ Load JPG	V
29	14/05/19 09:42	General View	1 Load JPG	<b>✓</b>
30	14/05/19 09:42	General View	Load JPG	V
31	14/05/19 09:42	Replacement Part Photo	■ Load JPG	<b>✓</b>
32	14/05/19 09:42	Replacement Part Photo	1 Load JPG	✓
33	14/05/19 09:42	Replacement Part Photo	€ Load JPG	<b>✓</b>
34	14/05/19 09:42	Replacement Part Photo	■ Load JPG	V
35	14/05/19 09:42	Replacement Part Photo	1 Load JPG	✓
36	14/05/19 09:42	Replacement Part Photo	€ Load JPG	V
37	14/05/19 09:42	Replacement Part Photo	1 Load JPG	V

	tos/Images		3 per page   ✓	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	
38	14/05/19 09:42	Replacement Part Photo	1 Load JPG	13.
39	14/05/19 09:42	Replacement Part Photo	1 Load JPG	-
40	14/05/19 09:42	Replacement Part Photo	1 Load JPG	-
41	14/05/19 09:42	Replacement Part Photo	Load JPG	~
42	14/05/19 09:42	Replacement Part Photo	1 Load JPG	-
43	14/05/19 09:42	Replacement Part Photo	1 Load JPG	4
44	14/05/19 09:42	Replacement Part Photo	1 Load JPG	4
45	14/05/19 09:42	Replacement Part Photo	Load JPG	V
46	14/05/19 09:42	Replacement Part Photo	1 Load JPG	₩.
47	14/05/19 09:42	Replacement Part Photo	Load JPG	V
48	14/05/19 09:42	Replacement Part Photo	1 Load JPG	~
49	14/05/19 09:42	Replacement Part Photo	1 Load JPG	V
50	14/05/19 09:42	Replacement Part Photo	1 Load JPG	V
51	14/05/19 09:42	Replacement Part Photo	1 Load JPG	V
52	14/05/19 09:42	Replacement Part Photo	1 Load JPG	V
53	14/05/19 09:42	Replacement Part Photo	■ Load JPG	-
54	14/05/19 09:42	Replacement Part Photo	1 Load JPG	
55	14/05/19 09:42	Replacement Part Photo	1 Load JPG	
56	14/05/19 09:42	Replacement Part Photo	1 Load JPG	-
57	14/05/19 09:42	Replacement Part Photo	1 Load JPG	
58	14/05/19 09:42	Replacement Part Photo	D Load JPG	-
59		Replacement Part Photo	1 Load JPG	
555	14/05/19 09:42	26.6 Feb. p. 10 1.6 T. p. 1 (rest to rest)	1 Load JPG	-
60	14/05/19 09:42	Replacement Part Photo		1
61	14/05/19 09:42	Replacement Part Photo		_
62	14/05/19 09:42	Replacement Part Photo	1 Load JPG	-
63	14/05/19 09:42	Replacement Part Photo	1 Load JPG	_
64	14/05/19 09:42	Replacement Part Photo	1 Load JPG	-
65	14/05/19 09:42	Replacement Part Photo	1 Load JPG	_
66	14/05/19 09:42	Replacement Part Photo	1 Load JPG	-
67	14/05/19 09:42	Replacement Part Photo	1 Load JPG	-
68	14/05/19 09:42	Replacement Part Photo	1 Load JPG	
69	14/05/19 09:42	Replacement Part Photo	1 Load JPG	_
70	14/05/19 09:42	Replacement Part Photo	1 Load JPG	V
71	14/05/19 09:42	Replacement Part Photo	1 Load JPG	-
72	14/05/19 09:42	Replacement Part Photo	1 Load JPG	~
73	14/05/19 09:42	Replacement Part Photo	1 Load JPG	₹ V
74	14/05/19 09:42	Replacement Part Photo	1 Load JPG	~
75	14/05/19 09:42	Replacement Part Photo	1 Load JPG	V
76	14/05/19 09:42	Replacement Part Photo	€ Load JPG	V
77	14/05/19 09:42	Replacement Part Photo	€ Load JPG	V
78	14/05/19 09:42	Replacement Part Photo	1 Load JPG	V
79	14/05/19 09:42	Replacement Part Photo	1 Load JPG	V
80	14/05/19 09:42	Replacement Part Photo	1 Load JPG	<u> </u>
81	14/05/19 09:42	Replacement Part Photo	1 Load JPG	V
82	14/05/19 09:42	Replacement Part Photo	1 Load JPG	V
83	14/05/19 09:42	Replacement Part Photo	1 Load JPG	
84	14/05/19 09:42	Replacement Part Photo	€ Load JPG	-
85	14/05/19 09:42	Replacement Part Photo	■ Load JPG	
ar of	-11 441 44 431-46			

Page 3 of 3

Pho	hotos/Images		notos/Images		3 per i	page 🗸	4
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	29/04/19 15:28	PRI	0	Load PDF			
2	29/04/19 15:38	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK	0	Load PDF			

# **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Pri	nt
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
		^
		V
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	Ti Ti	

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19007579/AGSD3E2

Date: 21/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29097415MKC

Claimant Vehicle GBJ1373R No:

Insured Vehicle No: **GBA5845S** 

29/04/2019 Nature of Claim: TP Claim No: 592183 Date of Loss:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

**GBJ1373R** 

Make & Model:

TOYOTA HIACE, 2.8 D (A)

Engine No:

1GD8340740

Reg. Date: Colour:

09/01/2019 (Man. Year: 2018) White

Chassis No: Odometer:

GDH2012003178 7104 km

Engine Capacity:

2754 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

**CONDITION OF TYRES** 

Front Tyre Size: Front Left Side:

195/80 R15

Rear Tyre Size:

195/80 R15

Dunlop 6 mm

Rear Left Side: Rear Right Side: Dunlop 6 mm

Dunlop 6 mm Front Right Side: The above values represent the remaining tyre treads depth

Dunlop 6 mm

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,805.60	5,334.89	13,470.71	71.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,830.00	2,060.00	2,770.00	57.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,635.60	7,394.89	16,240.71	68.71
Approved Total (Overridden) (S\$)		5,900.00		
Nett Amount (S\$)	23,635.60	5,900.00	17,735.60	75.04

INSPECTION

Date of Assignment:

30/04/2019

Date Inspected:

30/04/2019 Inspected At:

Sm Automotive - Kaki Bukit (HQ)

BLOCK C - 1, KAKI BUKIT AVE 6, #01-43

Singapore 417883

Estimated Period of Repair:

6.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

Reference
Part Source: (Last Synchronised: 21 May 2019)

Parts: N/A TOYOTA HIACE 2.8 D (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBJ1373R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,712.45 F	*1,712.45 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	343.40 F	*-FL
3	2		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	563.80 F	*- FL
4	1		*REAR BOOT LID EMBLEM LOGO	Necessary	51.10 F	*51.10 FL
5	1		*REAR BOOT LID 70KM/H STICKER	Necessary	30.00 F	*30.00 FL
6	1		*REAR BOOT LID HIACE STICKER	Necessary	35.75 F	*35.75 FL
7	1		*REAR BOOT LID CENTRE MOULDING	Cut	261.60 F	*261.60 FL
8	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*-FL
9	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	166.20 F	*-FL
10	1		*REAR BOOT LID INNER LOCK	Damaged	374.25 F	*374.25 FL
11	1		*REAR BOOT LID INNER LOCK COVER	Not Necessary	162.00 F	*-FL
12	1		*REAR BOOT LID INNER POWER LOCK MOTOR	Not Necessary	581.45 F	*- FL
13	1		*REAR BOOT LID INNER RUBBER	Cut	281.35 F	*281.35 FL
14	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	372.25 F	*-FL
15	10		*REAR BOOT LID INNER TRIM BOARD CLIP	Not Necessary	65.00 F	*- FL
16	1		*REAR BOOT LID WINDSCREEN	Cut	1,217.10 F	*1,217.10 FL
17	1		*REAR BOOT LID WINDSCREEN SEAL	Necessary	105.00 F	*105.00 FL
18	1		*REAR TAIL LAMP	N/S Cracked	748.90 F	*374.45 FL
19	2		*REAR TAIL LAMP LOWER COVER	Repair	364.20 F	*-FL
20	1		*REAR BUMPER	Deformed	374.40 F	*374.40 FL
21	10		*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
22	2		*REAR BUMPER SIDE RETAINER	Necessary	242.50 F	*242.50 FL
23	1		*REAR BUMPER CENTRE STEP PANEL	Bent	271.85 F	*271.85 FL
24	1		*REAR END PANEL OUTER	Dented	591.60 F	*591.60 FL
25	1		*REAR END PANEL INNER	Repair	781.90 F	*-FL
26	1		*REAR FLOOR PANEL	Not Necessary	1,972.85 F	*-FL
27	1		*REAR FLOOR PANEL TOP MOULDING	Bent	274.45 F	*274.45 FL
28	8		*REAR FLOOR PANEL TOP MOULDING CLIP	Not Necessary	52.00 F	*-FL
29	1		*REAR FLOOR PANEL PLYWOOD	Not Necessary	650.00 F	*- FL
30	1		*REAR FLOOR PANEL CARPET	Not Necessary	850.00 F	*- FL
31	1		*REAR SPARE TYRE BRACKET	Not Necessary	243.10 F	*-FL
32	1		*REAR EXHAUST	Not Necessary	1,712.65 F	*-FL
33	2		*REAR EXHAUST MOUNTING	Not Necessary	123.50 F	*- FL
34	1		*REAR CENTRE EXHAUST	Not Necessary	1,829.10 F	*-FL
35	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
36	1		*REAR CAMERA	Damaged	580.00 FS	*380.00 FS
37	4		*REAR BUMPER LOWER BRACKET	Bent	112.00 F	*112.00 FL
38	2		*REAR TAIL LAMP LOWER COVER RETAINER	Not Necessary	342.90 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No. C	Qty	Part No. Particulars	Condition	Repairer's	Amount
			Sub Total (S\$)	18,805.60	6,919.85
			- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	1,584.96
			Total Parts (S\$)	18,805.60	5,334.89
			Report was unsubmitted during this print-out.		

Adjuster Report Page 5 of 5

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
2	GUM	New	50.00	50.00
3	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	0.00
4	TO REMOVE & REFIT CARPET & PLYWOOD	New	280.00	100.00
5	TO CHECK WIRING	New	100.00	30.00
6	TOWING FEE	New	100.00	0.00
7	TUFF KOTE	New	150.00	60.00
8	PANEL BEATING	New	1,800.00	800.00
9	SPRAY PAINTING	New	1,600.00	800.00
10	TO REMOVE AND REPLACE REVERSE SENSOR	New	100.00	50.00
11	TO REMOVE AND REPLACE REAR CAMERA	New	150.00	50.00
	Gross	Labour Cost (S\$)	4,830.00	2,060.00

----

< END OF ESTIMATES >

Report was unsubmitted during this print-out.