

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 5761Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	952.20	952.20
1	REAR BUMPER REFLECTOR LH (CAN'T SEE DAMAGE)	NOT NECESSARY	162.50	-
1	REAR BUMPER REFLECTOR RH (CAN'T SEE DAMAGE)	NOT NECESSARY	162.50	-
1	REAR BUMPER BRACKET LH (CAN'T SEE DAMAGE)	NOT NECESSARY	42.60	-
1	REAR BUMPER BRACKET RH (CAN'T SEE DAMAGE)	NOT NECESSARY	42.60	-
1	REAR BUMPER REINFORCEMENT	DENTED	990.60	990.60
1	REAR BUMPER SPONGE (CAN'T SEE DAMAGE)	NOT NECESSARY	195.20	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	798.50	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	298.00	-
1	EXHAUST MANIFOLD	NOT NECESSARY	182.00	-
1	EXHAUST PIPE	BENT	4,521.80	711.60
2	EXHAUST PIPE MOUNTING	NECESSARY	69.60	69.60
	LESS 10% DISCOUNT		-841.81	-272.40
			7,576.29	2,451.60
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
			100.00	30.00
	<u>LABOUR</u>			
	LABOUR CHARGE. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,500.00	400.00
	TO SPRAY PAINTING ON AFFECTED AREA.		1,500.00	400.00
	TO RUST PROOFING ON AFFECTED AREAS.	NOT NECESSARY	200.00	-
	TO REMOVE, REPLACE AND REINSTALL REAR EXHAUST PIPE.		200.00	60.00
	TO CHECK REAR WIRING (INCLUDE REVERSE SENSOR).		80.00	60.00
			-	-
			-	-
			3,480.00	920.00
	GRAND TOTAL		11,156.29	3,401.60

RECOMMENDED COST OF LUMP SUM REPAIRS	2,700,00
(TO ITS PRE-ACCIDENT CONDITION)	_,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,





Report Ref No. CS1/LAW19007597/Utd3e2

CHUA KANG SENG

Licensed Appraiser