



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2006493  
INV Date 21/09/2020  
Reference CC6/CTI19007601/Uba3n2  
Code CTI



### PROFESSIONAL SERVICE FEE

Vehicle No. SJP 3412Y  
Insured Veh. GBB 4565B  
Claim No. SNM19D201812C02/5  
Policy No. DMCVSN3027061900  
Accident Date 23/04/2019  
Inspection Date 30/04/2019

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI19007601/Uba3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 21-09-2020		
		Code : CTI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBB 4565B	Veh. Inspected	SJP 3412Y	
Policy No.	DMCVSN3027061900	Coverage (\$)	0.00	
Claim No.	SNM19D201812C02/5	Excess (\$)	0.00	
Assign From		Assign Date	30/04/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA WISH (A)	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	ZNE100417605	Colour	GREY	
Odometer	237385	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/65 R15	HABILEAD	6 mm	
L/H Front Tyre	205/65 R15	HABILEAD	6 mm	
R/H Rear Tyre	205/65 R15	HABILEAD	6 mm	
L/H Rear Tyre	205/65 R15	HABILEAD	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	23/04/2019	Inspection Date	30/04/2019	
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 568 GEYLANG ROAD SINGAPORE 389514			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 3412Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	TAIL GATE	BADLY DENTED	1,272.00	1,272.00
1	TAIL GATE CENTRE BADGE	NECESSARY	85.50	85.50
1	TAIL GATE CENTRE CHROME GARNISH	NOT NECESSARY	281.20	-
1	TAIL GATE INNER LOCK	DENTED / JAMMED	238.00	238.00
1	TAIL GATE INNER TRIM BOARD	DEFORMED / TORN	288.00	288.00
2	TAIL GATE DAMPERS @\$288.00	NOT NECESSARY	576.00	-
2	REAR WINDSCREEN INNER MOULDING @\$75.00	NECESSARY	150.00	150.00
1	TAILGATE WIPER MOTOR (NPA)	NOT NECESSARY	-	-
1	TAILGATE WIPER BLADE (NPA)	NOT NECESSARY	-	-
2	RHS & LHS TAILLAMPS @\$725.50	CRACKED	1,451.00	1,451.00
1	REAR TAILGATE TOP SPOILER (NPA)	NOT NECESSARY	-	-
1	REAR TAILGATE TOP SPOILER THIRD BRAKE LIGHT (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER	DENTED / DEFORMED	982.00	566.10
2	REAR BUMPER REFLECTORS @\$75.00	NOT NECESSARY	150.00	-
2	REAR BUMPER SIDE RETAINERS @\$90.00	BENT	180.00	180.00
2	REAR BUMPER BRACKETS @\$178.00	N/S DENTED	356.00	178.00
2	REAR FENDER LH & RH @\$675.00	TO REPAIR SEE LABOUR	1,350.00	-
2	REAR FENDER INNER SIDE TRIM @\$478.00	NOT NECESSARY	956.00	-
1	REAR BOOT WEATHERSTRIP	TWISTED	287.50	287.50
1	REAR END PANEL LOCK CATCH	NOT NECESSARY	66.00	-
1	REAR END PANEL TOP GARNISH	DEFORMED / CRACKED	289.00	289.00
1	REAR END PANEL	DENTED / BENT	782.00	782.00
1	REAR FLOOR BOARD TOP COVER	NOT NECESSARY	245.00	-
2	SET REAR FENDER INNER SHIELD CLIPS	NOT NECESSARY	50.00	-
1	REAR EXHAUST SILENCER ASSEMBLY	TO REPAIR SEE LABOUR	650.00	-
2	REAR EXHAUST SILENCER ASSEMBLY MOUNTINGS	NOT NECESSARY	98.00	-



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-2,695.80	-1,441.78
			8,087.40	4,325.32
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	40.00
1	REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REVERSE CAMERA (SN)	SHORTED	380.00	300.00
1	REAR LICENCE PLATE W/HOLDER (SN)	NOT NECESSARY	75.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	50.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	100.00	50.00
2	REAR FENDER GLASS SEALANT (SN)	NOT NECESSARY	120.00	-
1	TAILGATE TOP SPOILER SEALANT (SN)	NOT NECESSARY	100.00	-
			1,275.00	640.00
	<b><u>LABOUR</u></b>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS.INCLUSIVE O THE REPAIR OF REAR FENDER LH & RH AND REAR EXHAUST SILENCER ASSEMBLY .		1,400.00	1,000.00
	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS.		1,200.00	1,180.00
	TO REMOVE ,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION.		200.00	30.00
	TO REMOVE/REFIX INNER TRIMS, FITTINGS ,GARNISH ETC AT REAR COMPARTMENT SO AS TO FACILITATE REPAIRS AT REAR.		250.00	100.00
	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN.		140.00	120.00
	TO REMOVE AND REFIX REAR LH & RH FENDER GLASS.	NOT NECESSARY	160.00	-
	TO REMOVE AND REPLACE REAR EXHAUST SILENCER ASSEMBLY.	NOT NECESSARY	200.00	-
	TO REMOVE AND REPLACE REVERSE SENSORS AND REVERSE CAMERA AND CHECK FOR PROPER FUNCTION.		150.00	50.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.		210.00	90.00
			3,910.00	2,570.00
GRAND TOTAL			13,272.40	7,535.32
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,000.00

Report Ref No. CC6/CTI19007601/Uba3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.