



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 4734L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	MTG CRACKED	480.00	480.00
1	FR FENDER (CONSISTENT)	BENT	250.00	250.00
1	FR DOOR (CONSISTENT)	BENT	685.00	685.00
1	FR HEADLIGHT (CONSISTENT)	SERVICEABLE	280.00	-
1	FR MIRROR (CONSISTENT)	SERVICEABLE	180.00	-
1	RR FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	350.00	-
1	RR DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	650.00	-
1	FR DOOR HINGE (CONSISTENT)	BENT	150.00	150.00
1	FR DOOR STOPPER (CONSISTENT)	SERVICEABLE	145.00	-
1	FR POWER WINDOW MOTOR (CONSISTENT)	JAMMED	360.00	360.00
1	FR DOOR INNER PANEL (CONSISTENT)	SERVICEABLE	320.00	-
1	FR DOOR LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	120.00	-
1	FR ROCKER PANEL (CONSISTENT)	BENT	150.00	150.00
1	FR MUDGUARD (CONSISTENT)	CRACKED	95.00	95.00
1	FR RIM (CONSISTENT)	BENT	260.00	260.00
1	FR WHEEL BEARING (CONSISTENT)	NECESSARY	100.00	100.00
1	FR KNUCKLE ARM (CONSISTENT)	BENT	195.00	195.00
1	FR LOWER ARM (CONSISTENT)	DISTORTED	210.00	210.00
1	FR LINKAGE (CONSISTENT)	DISTORTED	110.00	110.00
1	FR SUSPENSION (CONSISTENT)	BENT	180.00	180.00
1	FRONT LOWER CROSS MEMBER (CONSISTENT)	BUCKLED	322.00	322.00
1	STEERING RACK & PINION (CONSISTENT)	BENT / JAMMED	1,150.00	1,150.00
30	CLIP @\$2.00 (CONSISTENT)	NECESSARY	60.00	60.00
	LESS 20% DISCOUNT		-	-951.40
			6,802.00	3,805.60
	<u>SPECIAL NETT ITEMS</u>			
1	FRT TYRE (50%)(CONSISTENT)(SN)	PUNCTURE	150.00	75.00
			150.00	75.00

Report Ref No. CC4/ASM19007614/Kba3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO REMOVE AND REFIT DAMAGE PARTS & UNDERCARRIAGE.INCLUSIVE OF THE REPAIR OF RR FENDER,RR DOOR AND FR DOOR LOCK. TO SPRAY PAINTING. HEADLIGHT FOCUS. 4 WHEEL ALIGNMENT.		3,500.00 1,800.00 100.00 150.00 5,550.00	1,800.00 1,200.00 20.00 60.00 3,080.00
GRAND TOTAL			12,502.00	6,960.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,550.00

Report Ref No. CC4/ASM19007614/Kba3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.