

(02/11/14)

Surveyor

REF:

ASM(CAXA)

98428

ASSIGNMENT

From:

Date: 3/5/19

Veh No:

SKU1281H

Yr Regn: 2015 / Jun

Estimated Cost:

Type: ☒ M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SKU1281H

Make:

Volkswagen Jetta 1.4 C.C. 1390

at Workshop m/s

volkswagen

Colour:

Brown

A/C: Insured / Std / NI / NA

of

247 Alexandra Road

Sp. Reading

88934

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

WVW ZZZ16ZFM029911

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)


Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

10:30am

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

57K

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

6

mm

R/Bal.

6

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6

mm

L/Bal.

6

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

27/04/19

D.O.I.

03/05/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

Volkswagen

CA / REV / REP. / 24 HRS ^{up}Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))