KIV FOR

LOD

Preli. Report.

80

612

Others

TOTAL

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies,
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT	
Date Of Report	23/09/2013 15:50	
Date Of Accident	23/09/2013 14:00	
Exact Location Of Accident	T2 Boulevard	

	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHD9124B	
Insured/Policyholder		
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD	
Co Reg No	200303878K	
Vehicle Particulars		
Manufacturer	ТОУОТА	

Model WISH-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident Hire and Reward

Are you claiming under your own insurance policy for repair to your vehicle?

No

Third P

If No, Please state action to be taken Third Party
Vehicle Category Taxi

Insurance Company

Name of Insurance Company

First Capital Insurance Ltd

Type Of Coverage Third Party
Fleet Policy Yes

Policy Number D-12047359MFSH

Cover Note Number

 Name of Driver
 TAN KIM YIAM

 NRIC No
 \$1632448E

 Date Of Birth
 14/05/1964

 Occupation
 Outdoor

 Date Of Driving Pass
 20/05/1983

Driving Experience 30 Years And 4 Months

Gender Male

Mobile Number (Local) +65-96277654

Fax Number Contact Number

Postcode

EMail Address NOEMAIL

Address BLK 708 CHOA CHU KANG STREET 53

#12-16 680708

Was driver an employee of the Insured's Company No

If No, Relationship of the Driver with the Insured Other - Hirer

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

Collision- Chain Collision

Weather Conditions

Clear

Road Surface

Dry

Other Information

Was any foreign vehicle involved in this accident?

No

Was any body injured in the Accident?

No

Was any other material or property damaged?

Yes

Was there any video captured by Car Camera?

Yes

Details of Police Action

Was the accident reported to the police?

No

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

No

If Yes, against whom?

Circumstances of Accident

On 23.09.2013 at about 1400hrs, my taxi and Vehicle C (SHD5483R) were both stationary at extreme left lane along T2 Boulevard queuing towards the taxi stand. Moment later while I was at a stationary, I felt an impact from the rear. Vehicle B (SHC8933U) collided onto my taxi's rear portion and due to the impact, my taxi surged forward and hit onto vehicle C's rear portion. All vehicles have no passenger when the incident occured. /rc

Are accident photos available for attachment?

Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHC8933U

Vehicle Make/Model/Colour

COMFORT TAXI

Details Of Properties

Name of Driver

LIM PK LIM

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SHD5483R

Vehicle Make/Model/Colour

TRANSCAB TAXI

Details Of Properties

Name of Driver

YEO KEE HIANG

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan Pg.1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Sketch Plan

B DIA DICI	
	A: SH D9124 D
-	B: SHC8933V
→ 1301 / 121 121	C. SHD 5483R
T2 BOULEVARD	

cribe Circumstar	nces of the Accident	
	PLS. KEFLOR TO GLA KOPORT	

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

Driver's Signature (if driver is not the policyholder) / Date & Time

DOE Witnessed by Reporting Centre

Accident Scene Photo




Accident Scene Photo



















NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346 TEL NO.6287 6666 FAX NO.6366 8862 CO/GST REG NO.201019626G

SHD 9124B - III

Not Archanker

ROEL

Vehicle No.: Chassis No.: Vehicle Make: Vehicle Model: Date of Accident: Third Party Insurer:

SHD 9124B - ROEL JTDGJ20W205003402* TOYOTA WISH 2.0 BI-FUEL 23.09.2013

PART LIST

			TAKI		LIST
1		1	Rear bumper	\$	Bu 585.36 -
2		1	Rear bumper stay RH	\$	
3		1	Rear bumper stay LH	\$	
4		1	Rear bumper side retainer RH	\$	15 68 76 -
5		1	Rear bumper side retainer LH	\$	
6		1	Rear bumper side support RH	\$	-Su 104.76x
7		1	Rear bumper side support LH	\$	-104.76X
8		1	Rear bumper bracket RH	\$	108.00
9		1	Rear bumper bracket LH	\$	
10)	1	Rear bumper reflectors RH	\$	-34-66-00-X
.11	I	1	Rear bumper reflectors LH	\$	-14-66:00-X
12	?	1	Rear bumper end dust cover / splashield cove	\$	-52-85.97 X
13	3	1	Rear end panel inner	\$	-336.84
14	7	1	Rear end panel outer	\$	PAY 623 76 L
15	õ	1	Rear end panel inner trim	\$	263 84
16	5	1	Tailgate lid	\$	1 1 480 44
17	7	1	Tailgate lid lock - top	\$	12466.56 -
18	3	1	Tailgate lid lock - bottom	\$	-12-39.40-X
15)	1	Tailgate lid inner trim board	\$	5-189.94 X
20)	1	Tailgate lid inner garnish top	\$	S-245.52√
21	!	1	Tailgate lid outer chrome garnish	\$	A-214-48-X
22	?	1	Tailgate lid centre 'TOYOTA' logo badge	\$	ma 66.82 -
23	3	1	Tailgate lid weatherstrip	\$ \$	W 344.28 L
24		1	Tailgate lid switcher opener	\$	1-15.20 X
25	5	1	Tailgate lid damper stay RH	\$	34 269,64 x
26	5	1	Tailgate lid damper stay LH	\$	-1-269.64 X
27	7	1	Tailgate lid inner handle	\$	-S-20.96-X
28	3	1	Tailgate reflector RH	\$	Sh 128,40-v
29)	1	Tailgate reflector LH	\$	128:40 X
30)	1	Tailgate hingh RH	\$	120.00×
31	9	1	Tailgate hingh LH	\$	-20.00X
32	2	1	Tail lamp RH	\$	Str 595.72-X
33		1	Tail lamp LH	\$	Su-595.72-X
			e 17 1 190	32	

ROEL

NO.42 SUNGE! KADUT ST 1 SINGAPORE 729346 TEL NO.6287 6666 FAX NO.6366 8862 CO/GST REG NO.201019626G SHD 9124B - III

				N
34	1	Rear fender LH	\$	R 1,216,32 X
35	1	Rear fender panel deck trim side LH	\$	St. 738-00 X
36	1	Rear fender inner cowling LH	\$	Su-278.52
37	1	Rear fender RH	\$	-7-1,216.32 ×
38	1	Rear fender panel deck trim side RH	\$	S2 728 00 V
39	1	Rear fender inner cowling RH	\$	Ju 278.52 X
40	1	Rear exhaust box	\$	2-946.20 X
41	1	Rear luggage floor panel	\$	2-950-04-X
42	1	Rear luggage floor panel trim board	\$	5'2m-374.28×
43	1	Rear luggage floor panel insulator	\$	144 X
44	1	Front Bumper	\$	Bul cm 585.36 C
45	1	Front Bumper Lower Absorber	\$	130.00-7
46	1	Front Bumper Reinforcement	\$	218717
47	1	Front Bumper side support LH	\$	76-20-
48	1	Front Bumper side support RH	<i>\$</i>	76-20-X
49	1	Front Bumper retainer RH	\$	102.00 x
50	1	Front Bumper retainer LH	\$	
51	1	Front bumper centre grille	\$	5h 139.92 K
52	1	Front bumper lower grille	.\$	129.36-X
53	. 1	Front bumper bracket LH	\$	108.00 X
54	1	Front bumper bracket RH	\$	H 108.00-X
55	1	Front bumper fog lamp outer chrome RH	\$	Sr 190.00 X
56	1	Front bumper fog lamp outer chrome LH	\$	190.00 x
57	1	Front bumper fog lamp RH	\$ \$	1208.00 X
58	1	Front bumper fog lamp LH	\$	208-00-X
59	1	Front bumper fog lamp grille RH	\$	150.00 X
60	1	Front bumper fog lamp grille LH	\$	150.00-X
61	1	Front bumper undertray cover	\$	31-440.00-X
62	1	Front support panel assy	\$ \$	1,222.32 X
63	1	Front support panel side garnish RH	\$	Sh 40,00 X
64	1	Front support panel side garnish LH	\$	fiz-40.00-X
65	1	Front brace panel	\$	1 05.40.7
66	1	Headlamp RH	\$	M54m 672.00 -
67	1	Headlamp LH	\$	5-672.00-X
68	1	Front headlamp bracket LH	\$	5-1-67.56-x-
69	1	Front headlamp bracket RH	\$ \$ \$ \$ \$	1-67.56X
70	1	Radiator Grille	\$	C121462.48
71	1	Front Fender LH	\$	12-837.60 X
72	. 1	Front Fender Liner LH	\$ \$ \$	In-369-14-X
73	1	Front Fender RH	\$	12-837-60-X
74	1	Front Fender Liner RH	\$	5m 360-11X
75	1	Bonnet	\$.	Buc 1,019.16

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346 TEL NO.6287 6666 FAX NO.6366 8862 CO/GST REG NO.201019626G SHD 9124B - III ROEL

76 1 Bonnet centre 'TOYOTA' logo badge

\$ NE 115.44 L

TOTAL	\$ 25,778.61		6862 26
25%	\$ C 444 CH		1715:57
	\$ 19,333.96	•	\$146.20

Specical Nett

1	Reverse sensor	\$	Sn_ 300.00-X
1Set	Rear bumper end dust cover clip	\$	21.60 x
· 1Set	Rear bumper fastener clip	\$	ne 36.00 -
1Set	Rear end panel inner trim clip	\$	24,36.00 €
	Rear fender inner trim clip LH	\$	14,40-X
1Set	Rear fender inner trim clip RH	\$	2214.40×
1Set	Rear fender inner cowling clip LH	\$	22.60 X
1Set	Rear fender inner cowling clip RH	\$	21.60 X
1Set	Front Bumper fastener clip	\$	na 40.00
1Set	Radiator Grille clip	\$	ne 18.00 -
	Front Fender Liner clip	\$	22 60.00 X
2	Bonnet stopper	\$	9.60-X
1	Front Licence Plate	\$	ne 50.00 2552
1	Rear windscreen weatherstrip seal	\$	ma 82.51 30/2
I	Rear windscreen sealant	\$	na 80.00 Com
1	Rear windscreen inner sponge seal	\$	ma 60.00 301n
2	Rear fender 1/4 glass inner sponge seal	\$	22 96.00 X
2	Rear fender 1/4 glass sealant	\$	142.00 X
1	Rear exhaust mounting	\$	
2	CNG Sticker	\$	Su 54.96 X
1	Corporate logo - Trans-Cab	\$	nec 30.00 -
1	Corporate logo - Trans-link		2530.00
1	Corporate logo - 6555-3333	\$ \$	1ac 30.00 -
0		Φ	Mc 30.00 -

TOTAL \$ 1,278.67 - 375

TOTAL PARTS \$ 20,612.63

ROEL

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346 TEL NO.6287 6666 FAX NO.6366 8862 CO/GST REG NO:201019626G SHD 9124B - III

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And		
Renewal Of Parts, Adjust And Realign The	1.	
Same	\$	3,360.00 10001
Towing Fees.	\$	120.00 7
To Check Electrical Lighting Concerned.	\$	170.00 402
Putty and spray painting of the affected		
portion.	\$	3,240.00 12001
To Remove And Refit Rear W/Screen Glass		
To Facilitate Bodywork Repair.	\$	170.00 1201
To transfer of tailgate fittings and conduct		
water seepage test,	\$	170.00 601
To repair and realign rear exhaust pipe.	\$	22-170:00-X
To reinstall rear bumper parking sensor.	\$	170.00 507
To supply and re-do rear luggage floor panel		
insulation padding.	\$	~~ 380.00 X
		<u> </u>
To transfer of end panel fittings, attachment		6 2
and perform water seepage test.	\$	340.00
To transfer of fender fittings, attachment and		100/
perform water seepage test.	\$	340.00 J
To reseal sealant on gap	\$	120.00 30
		2009

TOTAL \$ 8,580.00 - 2560

Over All Total \$ 29,192.63

Total Repair Days

12-DAYS = 8081.70 6 day 201 = \$ 645.36



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En Automo	bile
TRA	NS-CAB AUTO SE	ERVICES PTE LTD	Ref : CS/TP19007687/	Kqd3s2
NO.	2 ANG MO KIO ST	REET 63SINGAPORE 569111	Date: 03-05-2019 Code: TP378	
1.		Policy Particulars	:- THIRD PARTY CLAIM	
	Insured Veh.		Veh. Inspected	SHD 9124B
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	23/09/2013
2.		Vehicle Partic	culars & Condition	
	Make & Model	TOYOTA WISH (A)	c.c	1987
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	JTDGJ20W205003402	Colour	RED
	Odometer	181597	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Conditi	ons of Tyres	
		Size	Make	Balance
	R/H Front Tyre	195/65R15	FALKEN	6 mm
	L/H Front Tyre	195/65R15	FALKEN	6 mm
	R/H Rear Tyre	195/65R15	FALKEN	6 mm
	L/H Rear Tyre	195/65R15	FALKEN	6 mm
1.		Description	on of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR AND FRONT PORTION.	
5.	STORES NO.		Information	
	Accident Date	23/09/2013	Inspection Date	23/09/2013
	Survey held at	TRANS-CAB AUTO SERVICES	PTE LTD	
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a.		Re	emarks	
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W		
5b.		Estimate	Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	6 Working Days	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9124B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS		1	
1	REAR BUMPER	BUCKLED	585.36	585.36
1	REAR BUMPER STAY RH	SERVICEABLE	82.08	
1	REAR BUMPER STAY LH	SERVICEABLE	82.08	
1	REAR BUMPER SIDE RETAINER RH	DISTORTED	68.76	68.76
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	68.76	0. -
া	REAR BUMPER SIDE SUPPORT RH	SERVICEABLE	104.76	984
1	REAR BUMPER SIDE SUPPORT LH	SERVICEABLE	104.76	
1	REAR BUMPER BRACKET RH	BENT	108.00	108.00
1	REAR BUMPER BRACKET LH	TO REPAIR SEE LABOUR	108.00	D=
1	REAR BUMPER REFLECTORS RH	SERVICEABLE	66.00	-
1	REAR BUMPER REFLECTORS LH	SERVICEABLE	66.00	107
1	REAR BUMPER END DUST COVER / SPLASHIELD COVER	SERVICEABLE	85.97	194
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	336,84	-
1	REAR END PANEL OUTER	BENT	623.76	623.76
1	REAR END PANEL INNER TRIM	DENTED	263.84	263.84
1	TAILGATE LID	BENT	1,480.44	1,480.44
1	TAILGATE LID LOCK - TOP	DENTED	466.56	466.56
1	TAILGATE LID LOCK - BOTTOM	TO REPAIR SEE LABOUR	39.40	65 P. C. C.
1	TAILGATE LID INNER TRIM BOARD	SERVICEABLE	189.94	2.0
1	TAILGATE LID INNER GARNISH TOP	SERVICEABLE	245.52	74
1	TAILGATE LID OUTER CHROME GARNISH	SERVICEABLE	214.48	
1	TAILGATE LID CENTRE 'TOYOTA' LOGO BADGE	NECESSARY	66.82	66.82
1	TAILGATE LID WEATHERSTRIP	CUT	344.28	344.28
1	TAILGATE LID SWITCHER OPENER	SERVICEABLE	115.20	
1	TAILGATE LID DAMPER STAY RH	SERVICEABLE	269.64	
1	TAILGATE LID DAMPER STAY LH	SERVICEABLE	269.64	// <u>-</u>
1	TAILGATE LID INNER HANDLE	SERVICEABLE	20.96	53-
1	TAILGATE REFLECTOR RH	SERVICEABLE	128.40	14.
1	TAILGATE REFLECTOR LH	SERVICEABLE	128.40	(-
1	TAILGATE HIGH RH	TO REPAIR SEE LABOUR	120.00	W.
1	TAILGATE HIGH LH	TO REPAIR SEE LABOUR	120.00	0.5

Report Ref No. CS/TP19007687/Kqd3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAIL LAMP RH	SERVICEABLE	595.72	
1	TAIL LAMP LH	SERVICEABLE	595.72	
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,216.32	8
1	REAR FENDER PANEL DECK TRIM SIDE LH	SERVICEABLE	738.00	
1	REAR FENDER INNER COWLING LH	SERVICEABLE	278.52	8.
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,216.32	8
1	REAR FENDER PANEL DECK TRIM SIDE RH	SERVICEABLE	738.00	2.5
1	REAR FENDER INNER COWLING RH	SERVICEABLE	278.52	
1	REAR EXHAUST BOX	TO REPAIR SEE LABOUR	946.20	10
1	REAR LUGGAGE FLOOR PANEL	TO REPAIR SEE LABOUR	950.04	54
1	REAR LUGGAGE FLOOR PANEL TRIM BOARD	SERVICEABLE	374.28	
1	REAR LUGGAGE FLOOR PANEL INSULATOR	NOT NECESSARY	577.68	
1	FRONT BUMPER	BUCKLED / CRACKED	585.36	585.36
1	FRONT BUMPER LOWER ABSORBER	SERVICEABLE	130.00	8
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	318.11	8
1	FRONT BUMPER SIDE SUPPORT LH	SERVICEABLE	76.20	
1	FRONT BUMPER SIDE SUPPORT RH	SERVICEABLE	76.20	
1	FRONT BUMPER RETAINER RH	SERVICEABLE	102.00	8
1	FRONT BUMPER RETAINER LH	SERVICEABLE	102.00	
1	FRONT BUMPER CENTRE GRILLE	SERVICEABLE	139.92	
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	129.36	17
1	FRONT BUMPER BRACKET LH	TO REPAIR SEE LABOUR	108.00	6.0
1	FRONT BUMPER BRACKET RH	TO REPAIR SEE LABOUR	108.00	59
1	FRONT BUMPER FOG LAMP OUTER CHROME RH	SERVICEABLE	190.00	15
1	FRONT BUMPER FOG LAMP OUTER CHROME LH	SERVICEABLE	190.00	59
1	FRONT BUMPER FOG LAMP RH	SERVICEABLE	208.00	5
1	FRONT BUMPER FOG LAMP LH	SERVICEABLE	208.00	- 62
1	FRONT BUMPER FOG LAMP GRILLE RH	SERVICEABLE	150.00	23
1	FRONT BUMPER FOG LAMP GRILLE LH	SERVICEABLE	150.00	8
1	FRONT BUMPER UNDERTRAY COVER	SERVICEABLE	440.00	35

Report Ref No. CS/TP19007687/Kqd3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SUPPORT PANEL ASSY	TO REPAIR SEE LABOUR	1,222.32	
1	FRONT SUPPORT PANEL SIDE GARNISH RH	SERVICEABLE	40.00	8
1	FRONT SUPPORT PANEL SIDE GARNISH LH	SERVICEABLE	40.00	
1	FRONT BRACE PANEL	TO REPAIR SEE	95.49	
1	HEADLAMP RH	MTG CRACKED	672.00	672.00
1	HEADLAMP LH	SERVICEABLE	672.00	85
1	FRONT HEADLAMP BRACKET LH	SERVICEABLE	67.56	
1	FRONT HEADLAMP BRACKET RH	SERVICEABLE	67.56	14
1	RADIATOR GRILLE	CRACKED	462.48	462.48
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	837.60	5
1	FRONT FENDER LINER LH	SERVICEABLE	369.14	38
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	837.60	15
1	FRONT FENDER LINER RH	SERVICEABLE	369.14	
1	BONNET	BUCKLED	1,019.16	1,019.16
1	BONNET CENTRE 'TOYOTA' LOGO BADGE	NECESSARY	115.44	115.44
	LESS 25% DISCOUNT		-6,444.65	-1,715.57
	SPECIAL NETT ITEMS		19,333.96	5,146.69
54	REVERSE SENSOR (SN)	SERVICEABLE	300.00	
823	SET REAR BUMPER END DUST COVER CLIP (SN)	NOT NECESSARY	21.60	100
	SET REAR BUMPER FASTENER CLIP (SN)	NECESSARY	36.00	36.00
22.	SET REAR END PANEL INNER TRIM CLIP (SN)	NECESSARY	36.00	36.00
	SET REAR FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	14.40	30.00
53.5	SET REAR FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	14.40	
	SET REAR FENDER INNER COWLING CLIP LH (SN)	NOT NECESSARY	21.60	
100	SET REAR FENDER INNER COWLING CLIP RH (SN)	NOT NECESSARY	21.60) A
	SET FRONT BUMPER FASTENER CLIP (SN)	NECESSARY	40.00	40.00
107.0	SET RADIATOR GRILLE CLIP (SN)	NECESSARY	18.00	18.00
	SET FRONT FENDER LINER CLIP (SN)	NOT NECESSARY	60.00	10.00
	BONNET STOPPER (SN)	SERVICEABLE	9.60	22
93	FRONT LICENCE PLATE (SN)	DENTED	50.00	25.00
331	REAR WINDSCREEN WEATHERSTRIP SEAL (SN)	NECESSARY	82.51	30.00
	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00

Report Ref No. CS/TP19007687/Kqd3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	60.00	30.00
2	REAR FENDER 1/4 GLASS INNER SPONGE SEAL (SN)	NOT NECESSARY	96.00	14
2	REAR FENDER 1/4 GLASS SEALANT (SN)	NOT NECESSARY	142.00	-
1	REAR EXHAUST MOUNTING (SN)	SERVICEABLE	54.96	9
2	CNG STICKER (SN)	NECESSARY	30.00	30.00
1	CORPORATE LOGO - TRANS-CAB (SN)	NECESSARY	30.00	30.00
1	CORPORATE LOGO - TRANS-LINK (SN)	NECESSARY	30.00	30.00
1	CORPORATE LOGO - 6555-3333 (SN)	NECESSARY	30.00	30.00
			1,278.67	375.00
	LABOUR			0.000
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET LH, REAR END PANEL INNER, TAILGATE LID LOCK - BOTTOM, TAILGATE HIGH RH, TAILGATE HIGH LH, REAR FENDER LH, REAR FENDER RH, REAR EXHAUST BOX, REAR		3,360.00	1,000.00
	LUGGAGE FLOOR PANEL, FRONT BUMPER REINFORCEMENT, FRONT BUMPER BRACKET LH, FRONT BUMPER BRACKET RH, FRONT SUPPORT PANEL ASSY, FRONT BRACE PANEL, FRONT FENDER LH AND FRONT FENDER RH.			
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	The second of the second secon	170.00	40.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,240.00	1,200.00
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.		170.00	120.00
	TO TRANSFER OF TAILGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	50.00
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	NOT NECESSARY	380.00	
	TO TRANSFER OF END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	60.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		340.00	100000000000000000000000000000000000000
	TO RESEAL SEALANT ON GAP.		120.00	30.00
			8,580.00	2,560.00
	GRAND TOTAL		29,192.63	8,081.69



Page No.:5 of 5

RECOMMENDED COST OF LUMP SUM REPAIRS	6,450.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/TP19007687/Kqd3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.