

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 03 May 2019

Preliminary Advice

Vehicle No	: SLB288J	Accident Date	: 20/04/2019
Make	: MERCEDES-BENZ CLA180	Policy No.	: DMPCSN3028931801
Assignment Date	: 30/04/2019	Excess	: S\$1,000.00
Date of Inspection	: 02/05/2019	Est. Duration of Repair	: 12.00
Inspection At	: CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP) 188 PANDAN LOOP SINGAPORE 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,576.91
Revised Amount	:S\$	21,436.73
Check Items (Estimated)	:S\$	8,439.21
Total	:S\$	29,875.94

Lump Sum Repair	:S\$	
-----------------	------	--

Brake System	: In Order
Steering System	: In Order
Tyre Condition (Front)	: 6/6 mm
Tyre Condition (Rear)	: 6/6 mm

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	104,000.00
COE / PARF Rebate	:S\$	50,898.00
Salvage Value	:S\$	
Margin for Repair	:S\$	53,102.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :