



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2004633
INV Date 29/06/2020
Reference CC4/LPC19007703/T1ea3s2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. GBG 7194S
Insured Veh. XD 1029G
Claim No. 18/19/19/VC05/021397
Policy No. Z18VC05000254
Accident Date 02/02/2019
Inspection Date 07/05/2019

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC19007703/T1ea3s2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 29-06-2020	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 1029G	Veh. Inspected	GBG 7194S	
Policy No.	Z18VC05000254	Coverage (\$)	0.00	
Claim No.	18/19/19/VC05/021397	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	02/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VSKYBAM20Z0146759	Colour	GREY	
Odometer	37779	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/70R14	GOODYEAR	6 mm	
L/H Front Tyre	175/70R14	GOODYEAR	6 mm	
R/H Rear Tyre	175/70R14	GOODYEAR	6 mm	
L/H Rear Tyre	175/70R14	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/02/2019	Inspection Date	07/05/2019	
Survey held at	913 BUKIT TIMAH			
Repairer	TAN CHONG MOTOR SALES PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 7194S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	EMBLEM (N)	NECESSARY	48.50	48.50
1	MALE ASSY - HOOD (N)	NOT NECESSARY	54.30	-
1	HOOD (N)	BENT	1,157.90	1,157.90
1	GUIDE- RH (N)	NOT NECESSARY	37.70	-
1	GUIDE - AIR, FRONT RH (N)	NOT NECESSARY	30.20	-
1	GUIDE - LH (N)	NOT NECESSARY	37.70	-
1	GUIDE - AIR, FRONT (N)	NOT NECESSARY	21.50	-
29	CLIP BUMPER / GRILLE @ \$1.20 (N)	NECESSARY	34.80	34.80
1	MOULDING ASSY U SHAPE RAD GRILLE (N)	NOT NECESSARY	205.50	-
1	GRILLE - RADIATOR (N)	CRACKED	278.10	278.10
1	COVER BRACKET FRT BUMPER TOW (N)	NOT NECESSARY	56.30	-
1	ARMATURE ASSY - F (N)	NOT NECESSARY	1,014.80	-
1	ENERGY ABSORBER (N)	NOT NECESSARY	240.20	-
1	BUMPER - FRONT RH HEADLAMP GARNISH (N)	TO REPAIR SEE LABOUR	329.30	-
1	BUMPER - FRONT LH HEADLAMP GARNISH (N)	TO REPAIR SEE LABOUR	329.30	-
1	BRKT - BPR SIDE, R (N)	NOT NECESSARY	20.90	-
1	BRKT - BPR SIDE, L (N)	NOT NECESSARY	20.90	-
1	FASCIA FRT (N)	CUT	682.10	682.10
1	RH HEADLAMP (N)	CRACKED	625.80	625.80
1	LAMP HEADLAMP LH (N)	CRACKED	625.80	625.80
	LESS 20% DISCOUNT		-1,170.32	-690.60
			4,681.28	2,762.40
<u>SPECIAL NETT ITEMS</u>				
2	CLIP GRILLE @ \$5.70 (SN)	NECESSARY	11.40	11.40
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
1	FRT LICENCE PLATE (SMART PLATE WITH CASING) LONG (SN)	DENTED	60.00	60.00
			171.40	91.40



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION.		48.00	48.00
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.	NOT NECESSARY	480.00	-
	APPLY SEALANT TO ALL AFFECTED PANEL JOINT & RESEAL NECESSARY AREA.		300.00	100.00
	REPAIR LH/RH FRONT FENDER, SUPPORT PANEL AND RENEW BONNET AND FRONT BUMPER. INCLUSIVE OF THE REPAIR OF BUMPER - FRONT RH HEADLAMP GARNISH AND BUMPER - FRONT LH HEADLAMP GARNISH.		1,500.00	780.00
	S/PAINT FRONT BUMPER, BONNET, LH/RH FRONT FENDER AND BOTH HEADLAMP GARNISH LH/RH.		1,700.00	500.00
	DISCHARGE / CHARGE A/CON GAS AND R/I A/CON PARTS.	NOT NECESSARY	240.00	-
	SUPPLY AND RENEW FRONT NO. PLATE (SMART PLATE WITH CASING) LONG WHITE / BLACK. (NPA)		-	-
			4,268.00	1,428.00
GRAND TOTAL			9,120.68	4,281.80

RECOMMENDED COST OF REPAIRS			4,281.80
------------------------------------	--	--	-----------------

Report Ref No. CC4/LPC19007703/T1ea3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 7194S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

