

ESTIMATED NORMAL PERIOD FOR REPAIR:

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA	INSURANCE PTE	LTD	Ref: CC4/ASM18017746/Gjb3s2-1		
C/O: SEAH ONG & PARTNERS LLP 36 ROBINSON ROAD #12-03 CITY HOUSESINGAPORE 068877			Date: 27-06-2019  Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)					
	Insured Veh.	SKC 2736B	Veh. Inspected	SJZ 6733Z	
	Policy No.	GA084080/1	Coverage (\$)	0.00	
	Claim No.	19.26426 PD-O	Excess (\$)	0.00	
	Assign From	XIN YI	Assign Date	30/04/2019	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA VIOS	c.c	1497	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	MR053HY9305172767	Colour	SILVER	
	Odometer	192907	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/55R15	BRIDGESTONE	6 mm	
	L/H Front Tyre	195/55R15	BRIDGESTONE	6 mm	
	R/H Rear Tyre	195/55R15	BRIDGESTONE	6 mm	
	L/H Rear Tyre	195/55R15	BRIDGESTONE	6 mm	
4.	Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
	REPAIR CONDITION SEE DETAILS.				
5.	5. General Information				
	Accident Date	26/09/2018	Inspection Date	02/05/2019	
	Survey held at	HUP MOTOR TRADING & SERV	/ICE		
		BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838			
5a.	a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

3 Working Days