

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19007713/KKA3Q2

Date: 17/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800147770

Claimant
Vehicle No : SLG5760C **Insured Vehicle No :** GBJ364Z

Date of Loss: 29/04/2019 Nature of Claim: TP Claim No: 9747395793SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG5760C		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	2ZRR952108
Reg. Date:	05/10/2016 (Man. Year: 2016)	Chassis No:	JTDKB3FU103535416
Colour:	Metallic Pearl White	Odometer:	180583 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Grenlander 9 mm	Rear Left Side:	Davanti 8 mm
Front Right Side:	Grenlander 9 mm	Rear Right Side:	Davanti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,308.89	1,298.60	1,010.29	43.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	945.00	1,375.00	59.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,628.89	2,243.60	2,385.29	51.53
+ GST 7.00/7.00% (\$\$)	324.02	157.05	166.97	51.53
Nett Amount (\$\$)	4,952.91	2,400.65	2,552.26	51.53
+ Car Rental (7.0 x S\$59.99/day) (\$\$)		419.93		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		2,828.03		

INSPECTION

Date of Assignment: 02/05/2019

Date Inspected: 02/05/2019 Inspected At: Esteem Performance Pte Ltd (HQ)
Blk 5033 Ang Mo Kio Ind Park 2, #01-259
Singapore 569536

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT FENDER	Bent	868.70 FL	*868.70 FL
2	1		*LH FRONT FENDER UNDERSHIELD	Distorted	195.60 FL	*195.60 FL
3	10		*LH FRONT FENDER UNDERSHIELD CLIP	Necessary	25.00 FL	*25.00 FL
4	1		*LHF FENDER WORDING HYBRID	Necessary	44.17 FL	*44.17 FL
5	1		*FRONT BUMPER	Buckled	450.80 FL	*450.80 FL
6	10		*FRONT BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
7	1		*FRONT BUMPER REINFORCEMENT-UPPER	Repair	711.50 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT-LOWER	Repair	245.30 FL	*- FL
9	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	107.20 FL	*- FL
10	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	107.20 FL	*107.20 FL
11	1		*LH FRONT HUB CAB	Serviceable	195.65 FL	*- FL
12	1		*LH WING MIRROR (COVER)	Serviceable	87.40 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,078.52	1,731.47
- List Item Discount on L Items 25.00/25.00% (\$\$)	769.63	432.87
Total Parts (\$\$)	2,308.89	1,298.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(FRONT BUMPER,SUPPORT PANEL,LHF FENDER,LH WING MIRROR COVER)	New	1,000.00	400.00
2	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(FRONT BUMPER,SUPPORT PANEL,LHF FENDER,LH WING MIRROR COVER)	New	1,000.00	440.00
3	TO CHECK WIRING	New	50.00	15.00
4	TO DO WHEEL ALIGNMENT	New	120.00	60.00
5	TO TUFF COAT	New	150.00	30.00
Gross Labour Cost (S\$)			2,320.00	945.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >